

ASS. REC. BY:

REF:

CS/CTI17005346/R17b⁵²

Special Instruction:

Surveyor:

Resul

ASSIGNMENT (Office)

From (Person):

Jason Tea

of

CTL

Date/Time:

17032017

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

S3Y

~~8277~~ 7770P

Insured:

GZ 8277X

at Workshop m/s

Carlite Auto

Tel:

6273 3810

of

Bik 1002 Bukit Merah Lane 3 #01-75

Policy No:

Claim No:

SM17D000410

Sum Insured:

Excess:

Make of Veh:

D.O.A.

17-01-2017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wp'

H.O.D. Endorsement:

Date/Time:

17032017 11am

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	S3Y 7770P -x
	GZ 8277X -x
	offer Lump sum \$2000/- (Red: 1014.40 : 33%.)

(08/11/13)

wef

ASS. REC. BY:

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SGY 770Pat Workshop m/s CARLIFE

of _____

Insured: CTI

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

Veh No: SGY 770P Yr Regn: 2011 / MAYType: M. Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MAZDA CX7 2.5L c.c. 2488Colour: BLACK A/C: Insured / Std / NI / NASp. Reading: 158377 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6ER10L2A0208352Gen. Cond: Good / Poor / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 285/60R18R: 1"BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 17/01/17Survey held at CARLIFEDes. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 17/03/17

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 13 FEB 2013

Date/Time, File Pass to?

☐ : PreH. Report☒ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 3Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

TOTAL

Report Format: TPLump Sum / I.B.I: (\$) 2000/-Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$

130



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI17005346/R1tb	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 17-03-2017	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GZ 8277X	Veh. Inspected	SGY 7770P
Policy No.		Coverage (\$)	0.00
Claim No.	SNM17D000410	Excess (\$)	0.00
Assign From	JASON TEA	Assign Date	17/03/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	17/01/2017	Inspection Date	17/03/2017
Survey held at	CARLIFE AUTO ENGINEERING SERVICES BLK 1002 BUKIT MERAH LANE 3 #01-75 SINGAPORE 159719		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Denise Tay (LKKAUTO)

From: CarLife <autolife_sin@yahoo.com.sg>
Sent: Thursday, 8 February 2018 4:33 PM
To: Denise Tay (LKKAUTO)
Subject: Re: RE: SJY 7770P / GZ 8277X ; TP CLAIM ; DOA: 17.01.2017 ; CHINA TAIPING

Yes pls close at yr offer.

Thank you

Regds
Tan

On Thursday, 8 February 2018, 3:02:51 PM GMT+8, Denise Tay (LKKAUTO) <denisetay@lkkauto.com> wrote:

Dear Sir,

Can confirm?

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 7 February 2018 4:20 PM
To: Admin-D (LKKAUTO) <admin-d@lkkauto.com>; 'CarLife' <autolife_sin@yahoo.com.sg>; SUR <sur@lkkauto.com>
Cc: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Subject: RE: SJY 7770P / GZ 8277X ; TP CLAIM ; DOA: 17.01.2017 ; CHINA TAIPING

Dear Sir,

Attached estimate.

Offer at lump sum \$2000, 3Days

Kindly confirm

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, 21 July 2017 10:15 AM
To: 'CarLife' <autolife_sin@yahoo.com.sg>; SUR <sur@lkkauto.com>
Cc: Rasul (LKKAuto) <Rasul@lkkauto.com>
Subject: RE: SJY 7770P / GZ 8277X ; TP CLAIM ; DOA: 17.01.2017 ; CHINA TAIPING

Dear Mr Tan,

Thank you for your email.

Dear Denise,

Kindly assist. Our ref: CS/CTI17005346/R1tb

Best Regards,

Ashley Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CarLife [mailto:autolife_sin@yahoo.com.sg]

Sent: Friday, 21 July, 2017 10:08 AM

To: Ashley Chong (LKK Auto)

Subject: Re: SGY 7770P / GZ 8277X ; TP CLAIM ; DOA: 17.01.2017 ; CHINA TAIPING

Hi Ms. Chong

Repairs completed awaiting your recommendation on Lumpsum basis.

Thank you

Regds

Tan

On Thursday, 20 July 2017, 17:41, Ashley Chong (LKK Auto) <admin-d@lkkauto.com> wrote:

Dear Sir/Madam,

Kindly advise status for SGY 7770P.

If vehicle has been repaired, please finalize with us.

Best Regards,

Ashley Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Virus-free. www.avg.com

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/01/2017 12:32
Date Of Accident	17/01/2017 07:30
Exact Location Of Accident	CARPARK BEHIND BLK 3 DOVER CRESCENT
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJY7770P
Insured/Policyholder	
Name Of Registered Owner	WONG JAI CHUAN
NRIC No	S1801592G
Email Address	wongjames1967@gmail.com
Mobile Phone No	(LOCAL) +65-96720946
Alternative Phone No	Others-96720946

Vehicle Particulars

Manufacturer	MAZDA
Model	CX7 2.5L 5EAT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Private Car

Insurance Company

Name of Insurance Company	Aviva Ltd
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	10588352
Cover Note Number	N.A

Driver

Name of Driver	WONG JAI CHUAN
NRIC No	S1801592G
Date Of Birth	06/04/1967
Occupation	Indoor
Date Of Driving Pass	15/03/1989
Driving Experience	27 Years And 10 Months
Gender	Male
Mobile Number	(Local) +65-96720946
Fax Number	
Contact Number	Others-96720946
E Mail Address	wongjames1967@gmail.com

Sketch Plan

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and shall remain the property of the insurer. A fee will be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available afterwards.
8. Consent under the Personal Data Protection Act (PDPA)
 - (a) I understand, acknowledge, agree and consent that:
 - (i) My insurer, my wife/husband and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer collectively the "Personal Information"; and disclose and transfer such Personal Information to an insurer(s) who have insured my vehicle(s) involved in the accident (all insurer(s) who have insured vehicle(s) involved in the accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 - (b) collectively the "Purposes";
 - (c) all insurer(s) who have insured vehicle(s) involved in the accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (d) my Personal Information may also be disclosed by any of the Insurers and/or GIA to their third party service providers or agents including their lawyers/law firms, which may be located outside of Singapore, for one or more of the above Purposes.


[Signature]
 Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

VERIFIED BY AJAX MARS
 REPORTING OFFICER
 Hashim Kamari

Witnessed by Reporting Centre
 Personnel

Sketch Plan



CAR LIFE AUTO ENGINEERING SERVICES

Mailing address: 20, BINCHANG RISE SINGAPORE 579887

W/shop address: BLK 1002 BUKIT MERAH LANE 3 # 01-75 SINGAPORE 159719

E-mail: autolife_sin@yahoo.com.sg

Tel: 6273 3810 Fax: 6278 7522

Date : 20-Dec-16

Address : WONG JAI CHUAN

Reference : TP 1094/01/17

Vehicle No : SJY 7770P

Make/Model : MAZDA CX7

Insurance Co. : AVIVA

RE : QUOTATION REPAIRS TO SJY 7770P FOR THIRD PARTY CLAIMS.

PARTS REQUIRED

		QTY		AMT \$
1)	FRONT BUMPER	1	\$	973.00 <i>OK</i>
2)	FRONT BUMPER RETAINER	1	\$	48.00 <i>OK</i>
3)	FRONT GRILLE	1	\$	362.00 <i>? x 500</i>
4)	FRONT GRILLE LOGO	1	\$	64.00 <i>CRA</i>
5)	CLIPS	10	\$	78.00 <i>OK</i>
6)	FRONT BUMPER ENFORCEMENT	1	\$	620.00 <i>? x 500</i>
7)	FRONT BUMPER BACKET	1	\$	48.00 <i>OK</i>

LIST PRICE TOTAL	\$	2,193.00
LESS DISCOUNT 20%	\$	438.60
LIST PRICE TOTAL AFTER LESS	\$	1,754.40

NETT PRICE TOTAL \$0.00

TOTAL PARTS COST **\$1,754.40**

LABOUR AND MISCELLANEOUS CHARGES

1)	TO REMOVE & REPLACE FRONT BUMPER, ENFORCEMENT, GRILLE AND TO PANEL BEAT & ALIGN	\$	800.00 <i>300</i> (4 days)
2)	TO PUTTY & SPRAY PAINT FRONT BUMPER & OTHER AFFECTED AREA.	\$	400.00 <i>200</i> (2 PANEL)
3)	TO CHECK & RECTIFY WIRING & FOCUS HEADLAMP	\$	60.00 <i>50</i>

LABOUR TOTAL

RASUL
HP 90000000
\$ 1,260.00

LIK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

TOTAL ESTIMATED REPAIR COST

3 days
4/3
17/03/17 @ 1200
Repairing after repair
\$ 3,014.40

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Mar 2017		04 May 2017 20:51 Edit Adj Rpt	S\$2,000.00 Edit Estimates	S\$2,000.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	KJT LOGISTICS SERVICES PTE LTD, Co. Reg. No.: -		
Main Claimant:	WONG JAI CHUAN		
Vehicle Reg. No.:	SJY7770P	Date of Loss:	17/01/2017 00:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	DMCVSN1679161600
Vehicle Reg. No. (Insured):	GZ8277X	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Car Life Auto Engineering Services (TOWN) BLK 1002 #01-75 BUKIT MERAH LANE 3, 159719 Bukit Merah - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jason Tea - 63896171]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 16/05/2017]		
Adj Asg. Remarks:	AS SPOKEN OVER PHONE ON 17/03/2017. TO CONDUCT PRS ON WP BASIS		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

*SJY7770P
 [GZ8277X]
 TP
 WONG JAI CHUAN
 Jan 17 2017 12:00AM
 [KJT LOGISTICS SERVICES PTE LTD]
 Car Life Auto Engineering Services

Upload Documents Upload Photos Compose New Letter			View View in Browser		
Photos/Images			3 per page		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	12/02/18 17:43	General View		Load JPG	☒
2	12/02/18 17:43	General View		Load JPG	☒
3	12/02/18 17:43	General View		Load JPG	☒
4	12/02/18 17:43	General View		Load JPG	☒
5	12/02/18 17:43	General View		Load JPG	☒
6	12/02/18 17:43	General View		Load JPG	☒
7	12/02/18 17:43	General View		Load JPG	☒
8	12/02/18 17:43	General View		Load JPG	☒
9	12/02/18 17:43	General View		Load JPG	☒
10	12/02/18 17:43	General View		Load JPG	☒
11	12/02/18 17:43	General View		Load JPG	☒
12	12/02/18 17:43	General View		Load JPG	☒
13	12/02/18 17:43	General View		Load JPG	☒
14	12/02/18 17:43	General View		Load JPG	☒
15	12/02/18 17:43	General View		Load JPG	☒
16	12/02/18 17:43	General View		Load JPG	☒
17	12/02/18 17:43	General View		Load JPG	☒
18	12/02/18 17:43	General View		Load JPG	☒
19	12/02/18 17:43	General View		Load JPG	☒
20	12/02/18 17:43	General View		Load JPG	☒
21	12/02/18 17:43	General View		Load JPG	☒
Documentation			1 per page		
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	04/05/17 20:52	OTHER - INSD SAS		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI17005346/R1TBS2
Date: 21/02/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. **Policy No:** DMCVSN1679161600
Claimant Vehicle No : SJY7770P **Insured Vehicle No :** GZ8277X
Date of Loss: 17/01/2017 **Nature of Claim:** TP **Claim No:** N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJY7770P
Make & Model: MAZDA CX-7, 2.5 (A) **Engine No:** L510398421
Reg. Date: 12/05/2011 (Man. Year: 2010) **Chassis No:** JM6ER10L2A0208352
Colour: Black **Odometer:** 158377 km
Engine Capacity: 2488 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair **Steering (Serviceable):** Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 285/60R18 **Rear Tyre Size:** 285/60R18
Front Left Side: Michelin 6 mm **Rear Left Side:** Michelin 6 mm
Front Right Side: Michelin 6 mm **Rear Right Side:** Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,754.40	968.80	785.60	44.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,260.00	530.00	730.00	57.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,014.40	1,498.80	1,515.60	50.28
Approved Total (Overridden) (S\$)		2,000.00		
Nett Amount (S\$)	3,014.40	2,000.00	1,014.40	33.65

INSPECTION

Date of Assignment: 04/05/2017 **Car Life Auto Engineering Services (TOWN)**
Date Inspected: 17/03/2017 **Inspected At:** BLK 1002 #01-75 BUKIT MERAH LANE 3
Estimated Period of Repair: 3.0 days **Singapore 159719**

Adjuster: MOHD RASUL**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Feb 2018)
Parts:	M1-SUV	MAZDA CX-7 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJY7770P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	973.00 FL	*973.00 FL
2	1		*FRONT BUMPER RETAINER	Necessary	48.00 FL	*48.00 FL
3	1		*FRONT GRILLE	Serviceable	362.00 FL	*- FL
4	1		*FRONT GRILLE LOGO	Cracked	64.00 FL	*64.00 FL
5	10		*CLIPS	Necessary	78.00 FL	*78.00 FL
6	1		*FRONT BUMPER ENFORCEMENT	Serviceable	620.00 FL	*- FL
7	1		*FRONT BUMPER BRACKET	Necessary	48.00 FL	*48.00 FL

F=Franchise part, L=ListItemDisc.

Sub Total (\$\$)	2,193.00	1,211.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	438.60	242.20
Total Parts (\$\$)	1,754.40	968.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REPLACE FRONT BUMPER, ENFORCEMENT, GRILLE AND TO PANEL BEAT & ALIGN.	New	800.00	300.00
2	TO PUTTY & SPRAY PAINT FRONT BUMPER & OTHER AFFECTED AREA.	New	400.00	200.00
3	TO CHECK & RECTIFY WIRING & FOCUS HEADLAMP.	New	60.00	30.00
Gross Labour Cost (S\$)			1,260.00	530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >