

ASS. REC. BY: _____ REF: G/C127005478 / R1213 / V Special Instruction: _____

Surveyor: Basel **ASSIGNMENT** (Office)

From (Person): meimen Juel Gub of C12 Date/Time: 20/2/2017 3:48pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: G8A 9632M Insured: XD145K

at Workshop n/s: man meng motor Tel: 6316 1131

of 50 Bukit Batok St 25 #01-06

Policy No: DMCVSN1711921700 Claim No: SMM17DUK567C02/S

Sum Insured: _____ Excess: _____

Make of Veh: _____

(Client's Record) _____ D.O.A. 15/2/2017

CA / REV / REP. / REV 24 HRS (up)

Date/Time: _____ Person Contacted: Ms. Heng H.O.D. Endorsement: _____

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>G8A 9632M - A</u>
	<u>XD145K - CS / M167 / 11617523 / Ngm</u>
<u>21/8/18 @ 12:15pm</u>	<u>confirmed with des heng is \$5400, 12 days by email.</u>
	<u>CRed \$4758.96, 4470)</u>

20/11/13 waf
ASS. REC. BY: *Rom*

REF:

CCE XRAY: 2018/mm

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: *10K*

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: *12* days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No: *GBA 9632M*

Yr Regn: *2008 / APR*

Type: *M.Cycle* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *Suzuki Every PA 660m*

c.c. *658*

Colour: *GREEN*

A/C: Insured / Std / NI / NA

Sp. Reading: *199252*

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *DA4V245439*

Gen. Cond: Good / *Fair* / Poor / Burnt

Steering: *Inorder* / Jammed / Leaked / Burnt or

Brake: *Inorder* / Jammed / Leaked / Burnt or

Modi: Nil / *S/Rim* / STD A/Rim or

Tyre Size: F: *155R22*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / *YOKO* or

Front

Rear

R/Bal. *5* mm

R/Bal. *5* mm

L/Bal. *5* mm

L/Bal. *5* mm

D.O.A. *15/03/17*

D.O.I. *20/03/17*

Survey held at: *Alor Merah*

Des. of Damages: Frt / *Rear* / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 20 AUG 2018

21/8/2018

Date/Time. File Pass to?

☐

: Preli. Report

12/8/2018

☐

: Final Report

Date/Time. File Return to?

2)

Days Of Repair: *12*

Resurvey No. of Trip: *1*

Survey Fee: *150*

Transportation: _____

Add Fee: ☐

: Site Insp (\$

) \$ + RS \$

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format: *MER-TP*

Lump Sum / I.B.I: (\$ *5400*)

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI17005478/R1th3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 20-03-2017



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 145K	Veh. Inspected	GBA 9632M
Policy No.	DMCVSN1711921700	Coverage (\$)	0.00
Claim No.	SNM17D01567C02/5	Excess (\$)	0.00
Assign From	MERIMEN (JOEL GOH)	Assign Date	20/03/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	15/03/2017	Inspection Date	20/03/2017
Survey held at	WOON MENG MOTOR PTE LTD 50 BUKIT BATOK ST 23 #01-06 MIDVIEW BUILDING SINGAPORE 659578		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/03/2017 18:06
Date Of Accident	15/03/2017 18:25
Exact Location Of Accident	JUNCTION OF CORPORATION RD/ BOON LAY DRIVE
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBA9632M
Insured/Policyholder	
Name Of Registered Owner	BESTEVEER PAPER PRODUCTS PTE LTD
Co Reg No	199104644N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	Office-98773933

Vehicle Particulars

Manufacturer	SUZUKI
Model	EVERY-660cc PA (DA64V) (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? No

If No, Please state action to be taken Third Party

Vehicle Category Commercial Vehicle

Insurance Company

Name of Insurance Company	Lonpac Insurance Bhd
Type Of Coverage	Third Party
Fleet Policy	No
Policy Number	Z/16/VC00/099415
Cover Note Number	

Driver

Name of Driver	FOO KEE TECK
NRIC No	S1234759F
Date Of Birth	03/01/1957
Occupation	Indoor
Date Of Driving Pass	28/07/1977
Driving Experience	39 Years And 7 Months
Gender	Male
Mobile Number	(Local) +65-98773933
Fax Number	
Contact Number	
Email Address	NOEMAIL

DETAILS OF INJURED PERSON 1

Name

Approximate Age

Injuries Sustain

Injured person in which vehicle? GBA9632M

Were seat belts worn?

Was injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Please note that you might be able to submit an Own Damage Claim under own policy within 14 days.

() Claim Own Damage (✓) Claim TP () Reporting Only () Claim OD/TP at other workshop

Workshop name:



**SINGAPORE
POLICE FORCE**



J/20170316/2072

1 of 2

POLICE REPORT (NP299)

Report No. J/20170316/2072

Police Station Of Origin
Bukit Batok NPP
103 Bukit Batok Central #01-00 SINGAPORE
650103
Tel No: 1800-5639999

Date/Time Report Made 16/03/2017 14:00	Vide Report No.	Station Diary No. 15
Name Of Informant FOO KEE TECK	Address APT BLK 547 CHOA CHU KANG ST 52 #07-19 SINGAPORE 680547	
ID Type / ID No. NRIC NO / S1234759F	Contact No. Home/Office Mobile 98773933	
Nationality SINGAPORE CITIZEN	Email Address	
Occupation Supervisor	Sex Male	Age 60
Institution/School Name	Date of Birth 03/01/1957	Race Chinese
	Language	
Date/Time Of Incident 15/03/2017 18:25	Location Of Incident 800 CORPORATION ROAD JURONG JUNIOR COLLEGE SINGAPORE 649809 Juntion of Corporation Road and Boon Lay Drive	

Brief details.

On 15/03/2017 at about 1825hrs, I was driving my van (Reg no: GBA9632M) together with 2 passengers.

My wife:

Chua Bee Kwang
S1433796b

Signature Of Officer Recording The Report: J / Sgt MUHAMMAD ASHRAF BIN RAHUMAN SHAH	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 16/03/2017 14:00
Officer In-Charge Of Case: J / Jurong Police Divisional Investigation Branch / Sr Staff Sgt NG YUEBIN, ALAN Contact No.: 67910000	Classification Of Case:

Authentication Stamp





**SINGAPORE
POLICE FORCE**



J/20170316/2072

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. J/20170316/2072

Blk 547 Choa Chu Kang St 52 #07-19

Hp: 98763933

My wife's colleague:

Lew Sheau Yanin

S7984997Y

Blk 113 Jurong East Street 13 #06-422

Hp: 96550086

While I was driving along junction of Corporation Road and Boon Lay Drive, there was taxi (Reg no:SHD5766A) stopped and was picking up passenger. I slowed down my van and stopped as well. Subsequently, a trailer collided at the rear of my van. I came out from my van and spoke to the driver. We exchanged particulars. Both parties informed to claim from their insurance. At that point of time, my passengers and I had injury on our neck and it was painful. There was damage at rear portion of my van. I manage to drive my van to my company afterwards.

My wife and I went to DRS Koo & Neoh Medical Group to get ourselves accessed. Both of us were given 1 day of medical leave on 16/03/2017. On 16/03/2017, my wife and I went for X-ray and the doctor informed there were no serious injuries. My wife colleague also went to DRS Koo & Neoh Medical Group and was referred Ng Teng Fong Hospital.

I am lodging this report for insurance claims

Signature Of Officer Recording The Report:

J / Sgt MUHAMMAD ASHRAF BIN RAHUMAN SHAH

Signature Of Interpreter:

Not applicable

Officer In-Charge Of Case:

J / Jurong Police Divisional Investigation Branch /
Sr Staff Sgt NG YUEBIN, ALAN
Contact No.: 67910000

Signature Of Informant:

Date/Time:

16/03/2017 14:00

Classification Of Case:

Authentication Stamp



SN 114

Signature

Singapore Police Force

• Describe Circumstances of the Accident

Refer to attachment to police report no:
E/OK/9407102/10
D/20170316/2072

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel

16/3/17

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 4644N

Vehicle Details

Vehicle No.: GBA9632M

Vehicle to be Exported: No

Intended De-registration Date: 21 Mar 2017

Vehicle Make: SUZUKI

Vehicle Model: EVERY PA 660 M

Primary Colour: Silver

Manufacturing Year: 2007

Engine No.: K6A7248482

Chassis No.: DA64V245439

Maximum Power Output:-

Open Market Value: \$12,267.00

Original Registration Date: 29 Apr 2008

First Registration Date: 29 Apr 2008

Transfer Count: 1

Actual ARF Paid: \$614.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date:

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 28 Apr 2018

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$13,801.00

COE Rebate Amount: \$1,378.00

Total Rebate Amount: \$1,378.00

The information contained herein is correct as at 21 Mar 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050

42, Sungai Kadut Ave, Singapore 729666 Tel: 63268523

(Email Address : woonmeng@singnet.com.sg)

Co Reg No. 200603678M

GST Reg No. 20-0603678M

Estimate

TP CLAIM

To : China Taiping Insurance (Singapore) Pte Ltd
Motor Claims Dept

Date : 17 Mar 2017

Dear Sirs :

Fax : 6224 4174

RE : ESTIMATE COST FOR SUZUKI EVERY DA64 - GBA9632M ACCIDENT INVOLVING GBA9632M & XD145K ON 15/03/2017

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Rear tailgate.	1pc	868.95 <i>free</i>
2	Rear tailgate hinge @25.03ea.	2pcs	50.06 <i>PA</i>
3	Rear tailgate lock.	1pc	163.05 <i>PA</i>
4	Rear tailgate outer handle.	1pc	48.05 <i>DE</i>
5	Rear tailgate key lock.	1pc	109.05 <i>JPM</i>
6	S.	1pc	23.00 <i>new</i>
7	EVERY.	1pc	25.00 <i>new</i>
8	Rear tailgate inner trim.	1pc	188.02 <i>DE</i>
9	Rear tailgate abosober @\$106.8ea.	2pcs	213.60 <i>PA</i>
10	Rear rubber.	1pc	125.00 <i>new</i>
11	Rear tailgate wiper arm.	1pc	53.75 <i>scr</i>
12	Rear tailgate wiper blade.	1pc	20.60 <i>auto</i>
13	Rear tailgate motor.	1pc	259.80 <i>X Sae</i>
14	Rear tailgate nozzle.	1pc	25.00 <i>X Sae</i>
15	Rear tailgate top light.	1pc	89.00 <i>CRX</i>
16	Rear windscreen glass.	1pc	788.06 <i>Pro</i>
17	Rear muguard o/s.	1pc	442.90 <i>repair</i>
18	Air duct @\$24.2ea	(1pc) 2pcs	48.40 <i>car</i>
Sum Carried Forward			3,541.29

281359

Sum Carried Forward

3,541.29

1481.95

19	Rear bumper.	1pc	540.05	DE ✓
20	Rear bumper retainer @\$20ea.	2pcs	40.00	re ✓
21	Rear bumper lamp @\$90ea.	2pcs	180.00	CRA ✓
22	Rear end panel outer.	1pc	260.05	PT ✓
23	Rear end panel inner.	1pc	288.05	PT ✓
24	Rear pillar o/s.	1pc	520.85	repair ✓
25	Floor panel.	1pc	566.45	repair ✓
26	Rear spare tyre bracket @\$86.9ea.	2pcs	173.80	PT ✓
			6,110.54	
Less 15%			(916.58)	
			5,193.96	

4295.54
15%
3651.20

27	Rear spare tyre.	1pc	220.00	X ✓
28	Rear windscreen sealant.	2pcs	40.00	re ✓
29	Rear sensor.	1set	220.00	re ✓
30	Rear number plate.	1pc	35.00	CRA ✓

295

Labour Charge & Misc

Towing fee.	\$	70.00	✓
To remove, repair, replace & install damaged parts.	\$	2,200.00	1400
To R & R rear windscreen glass.	\$	120.00	✓
To R & R wiring.	\$	60.00	30
To putty & spray painting	\$	1,500.00	1200
Total	\$	9,658.96	

2820

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

All prices quoted are subjected to 7% GST

This is a computer generated document. No signature is required.

Rahul
HP 90010068
12 days
43
16/03/17 @ 1730

3651.20
295.00
2820.00
6766.20
208
5412.96
43-5,400






































...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Mar 2017		20 Mar 2017 15:48 Edit Adj Rpt	S\$5,400.00 Edit Estimates	S\$5,400.00 View Rpt		Pending for Survey Report Cancel Case



















































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, ID: -								
Main Claimant:	BESTEVER PAPER PRODUCTS PTE LTD								
Vehicle Reg. No.:	GBA9632M	Date of Loss:	15/03/2017 00:00 - :59 [106 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM17D01567C02/5	Policy/Cover Note No.:	DMCVSN1711921700						
Vehicle Reg. No. (Insured):	XD145K	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Woon Meng Motor Pte Ltd (Bukit Batok) 50 Bukit Batok Street 23,, #01-06 Midview Building, 659578 Bukit Batok - Tel: 6316 1131								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 29/03/2017]								
Adj Asg. Remarks:	NO ESTIMATES. ASSIGNED AS SJE FOR WP PRS KINDLY PROVIDE US WITH YOUR RECOMMENDATION ON COST OF REPAIRS								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									


























Claim Documents

*GBA9632M (SNM17D01567C02/5)
[XD145K]
TP
BESTEVER PAPER PRODUCTS PTE LTD
Mar 15 2017 12:00AM
[-]
Woon Meng Motor Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images								3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	21/08/18 13:22	General View		Load JPG	<input checked="" type="checkbox"/>					
2	21/08/18 13:22	General View		Load JPG	<input checked="" type="checkbox"/>					
3	21/08/18 13:22	General View		Load JPG	<input checked="" type="checkbox"/>					
4	21/08/18 13:22	General View		Load JPG	<input checked="" type="checkbox"/>					
5	21/08/18 13:22	General View		Load JPG	<input checked="" type="checkbox"/>					
6	21/08/18 13:22	General View		Load JPG	<input checked="" type="checkbox"/>					
7	21/08/18 13:22	General View		Load JPG	<input checked="" type="checkbox"/>					
8	21/08/18 13:22	General View		Load JPG	<input checked="" type="checkbox"/>					
9	21/08/18 13:22	General View		Load JPG	<input checked="" type="checkbox"/>					
10	21/08/18 13:22	General View		Load JPG	<input checked="" type="checkbox"/>					
11	21/08/18 13:22	General View		Load JPG	<input checked="" type="checkbox"/>					
12	21/08/18 13:22	General View		Load JPG	<input checked="" type="checkbox"/>					
13	21/08/18 13:22	General View		Load JPG	<input checked="" type="checkbox"/>					
14	21/08/18 13:22	General View		Load JPG	<input checked="" type="checkbox"/>					
15	21/08/18 13:22	General View		Load JPG	<input checked="" type="checkbox"/>					
16	21/08/18 13:22	General View		Load JPG	<input checked="" type="checkbox"/>					
17	21/08/18 13:22	General View		Load JPG	<input checked="" type="checkbox"/>					
18	21/08/18 13:22	General View		Load JPG	<input checked="" type="checkbox"/>					
19	21/08/18 13:22	General View		Load JPG	<input checked="" type="checkbox"/>					
20	21/08/18 13:22	General View		Load JPG	<input checked="" type="checkbox"/>					
21	21/08/18 13:22	General View		Load JPG	<input checked="" type="checkbox"/>					
22	21/08/18 13:22	General View		Load JPG	<input checked="" type="checkbox"/>					
23	21/08/18 13:22	General View		Load JPG	<input checked="" type="checkbox"/>					
24	21/08/18 13:22	General View		Load JPG	<input checked="" type="checkbox"/>					
25	21/08/18 13:22	General View		Load JPG	<input checked="" type="checkbox"/>					
26	21/08/18 13:22	General View		Load JPG	<input checked="" type="checkbox"/>					
27	21/08/18 13:22	General View		Load JPG	<input checked="" type="checkbox"/>					
28	21/08/18 13:22	General View		Load JPG	<input checked="" type="checkbox"/>					
29	21/08/18 13:22	General View		Load JPG	<input checked="" type="checkbox"/>					
30	21/08/18 13:22	General View		Load JPG	<input checked="" type="checkbox"/>					
31	21/08/18 13:22	General View		Load JPG	<input checked="" type="checkbox"/>					
32	21/08/18 13:22	General View		Load JPG	<input checked="" type="checkbox"/>					
33	21/08/18 13:22	General View		Load JPG	<input checked="" type="checkbox"/>					
34	21/08/18 13:22	General View		Load JPG	<input checked="" type="checkbox"/>					
35	21/08/18 13:22	General View		Load JPG	<input checked="" type="checkbox"/>					
36	21/08/18 13:22	General View		Load JPG	<input checked="" type="checkbox"/>					
37	21/08/18 13:22	General View		Load JPG	<input checked="" type="checkbox"/>					

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
39	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
40	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
41	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
42	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
43	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
44	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
45	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
46	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
47	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
48	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
49	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
50	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
51	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
52	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
53	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
54	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
55	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
56	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
57	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
58	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
59	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
60	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
61	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
62	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
63	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
64	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
65	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
66	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
67	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
68	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
69	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
70	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
71	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
72	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
73	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
74	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
75	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
76	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
77	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
78	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
79	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
80	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
81	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
82	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
83	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
84	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
85	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
86	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
87	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
89	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
90	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
91	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
92	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
93	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
94	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
95	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
96	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
97	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
98	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
99	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
100	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
101	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
102	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
103	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
104	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
105	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
106	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
107	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
108	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
109	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
110	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
111	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
112	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
113	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
114	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
115	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
116	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
117	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
118	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
119	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
120	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
121	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
122	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
123	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
124	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
125	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
126	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
127	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
128	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
129	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
130	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
131	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
132	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
133	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
134	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
135	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
136	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
137	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
138	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
139	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
140	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
141	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
142	21/08/18 13:22	General View	 Load JPG	<input checked="" type="checkbox"/>
143	21/08/18 13:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
144	21/08/18 13:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
145	21/08/18 13:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
146	21/08/18 13:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
147	21/08/18 13:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
148	21/08/18 13:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
149	21/08/18 13:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
150	21/08/18 13:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
151	21/08/18 13:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
152	21/08/18 13:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
153	21/08/18 13:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
154	21/08/18 13:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
155	21/08/18 13:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
156	21/08/18 13:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
157	21/08/18 13:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
158	21/08/18 13:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
159	21/08/18 13:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	20/03/17 15:49	ASSIGNMENT	 Load PDF	
2	20/03/17 15:49	TP GIA REPORT	 Load PDF	
3	20/03/17 15:49	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<div> Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div> <div></div> <div></div> </div> </div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT117005478/R1QH3Q2

Date: 06/09/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN1711921700

Claimant Vehicle
No: GBA9632MInsured Vehicle
No: XD145K

Date of Loss: 15/03/2017

Nature of Claim: TP

Claim
No: SNM17D01567C02/5

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBA9632M**

Make & Model: SUZUKI EVERY, 660cc PA (DA64V) (M)

Engine No: K6A7248482

Reg. Date: 29/04/2008 (Man. Year: 2007)

Chassis No: DA64V245439

Colour: Grey

Odometer: 199252 km

Engine Capacity: 658 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 155 R12C

Rear Tyre Size:

155 R12C

Front Left Side: Yokohama 5 mm

Rear Left Side:

Yokohama 5 mm

Front Right Side: Yokohama 5 mm

Rear Right Side:

Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,708.96	3,925.64	1,783.32	31.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,950.00	2,820.00	1,130.00	28.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,658.96	6,745.64	2,913.32	30.16
Approved Total (Overridden) (S\$)		5,400.00		
(S\$)	9,658.96	5,400.00	4,258.96	44.09
+ GST 7.00/7.00% (S\$)	676.13	378.00	298.13	44.09
Nett Amount (S\$)	10,335.09	5,778.00	4,557.09	44.09

INSPECTION

Date of Assignment: 20/03/2017

Date Inspected: 20/03/2017 Inspected At:

Woon Meng Motor Pte Ltd (Bukit Batok)
50 Bukit Batok Street 23., #01-06 Midview
Building
Singapore 659578

Estimated Period of Repair: 12.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 06 Sep 2018)	
Parts:	N/A	SUZUKI EVERY 660cc PA (DA64V) (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBA9632M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Buckled	868.95 FL	*868.95 FL
2	2		*REAR TAILGATE HINGE	Bent	50.06 FL	*50.06 FL
3	1		*REAR TAILGATE LOCK	Bent	163.05 FL	*163.05 FL
4	1		*REAR TAILGATE OUTER HANDLE	Deformed	48.05 FL	*48.05 FL
5	1		*REAR TAILGATE KEY LOCK	Jammed	109.05 FL	*109.05 FL
6	1		*S	Necessary	23.00 FL	*23.00 FL
7	1		*EVERY	Necessary	25.00 FL	*25.00 FL
8	1		*REAR TAILGATE INNER TRIM	Deformed	188.02 FL	*188.02 FL
9	2		*REAR TAILGATE ABSORBER	Bent	213.60 FL	*213.60 FL
10	1		*REAR RUBBER	Necessary	125.00 FL	*125.00 FL
11	1		*REAR TAILGATE WIPER ARM	Scratched	53.75 FL	*53.75 FL
12	1		*REAR TAILGATE WIPER BLADE	Cut	20.60 FL	*20.60 FL
13	1		*REAR TAILGATE MOTOR	Serviceable	259.80 FL	*- FL
14	1		*REAR TAILGATE NOZZLE	Serviceable	25.00 FL	*- FL
15	1		*REAR TAILGATE TOP LIGHT	Cracked	89.00 FL	*89.00 FL
16	1		*REAR WINDSCREEN GLASS	Broken	788.06 FL	*788.06 FL
17	1		*REAR MUDGUARD O/S	Repair	442.90 FL	*- FL
18	2		*AIR DUCT	Cracked (1 PCS ONLY)	48.40 FL	*24.20 FL
19	1		*REAR BUMPER	Deformed	540.05 FL	*540.05 FL
20	2		*REAR BUMPER RETAINER	Necessary	40.00 FL	*40.00 FL
21	2		*REAR BUMPER LAMP	Cracked	180.00 FL	*180.00 FL
22	1		*REAR END PANEL OUTER	Bent	260.05 FL	*260.05 FL
23	1		*REAR END PANEL INNER	Bent	288.05 FL	*288.05 FL
24	1		*REAR PILLAR O/S	Repair	520.85 FL	*- FL
25	1		*FLOOR PANEL	Repair	566.45 FL	*- FL
26	2		*REAR SPARE TYRE BRACKET	Bent	173.80 FL	*173.80 FL
27	1		*REAR SPARE TYRE	Not Necessary	220.00 FS	*- FS
28	2		*REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
29	1		*SET REAR SENSOR	Not Working	220.00 FS	*220.00 FS
30	1		*REAR NUMBER PLATE	Cracked	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,625.54	4,566.34
- List Item Discount on L Items 15.00/15.00% (\$\$)	916.58	640.70
Total Parts (\$\$)	5,708.96	3,925.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING FEE	New	70.00	70.00
2	TO REMOVE,REPAIR ,REPLACE & INSTALL DAMAGED PARTS	New	2,200.00	1,400.00
3	TO R&R REAR WINDSCREEN GLASS	New	120.00	120.00
4	TO R&R WIRING	New	60.00	30.00
5	TO PUTTY & SPRAY PAINTING	New	1,500.00	1,200.00
Gross Labour Cost (S\$)			3,950.00	2,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >