

22/03/2002

ASS. REC. BY:

REF:

CS/MS617005726/Mirbezi

Jun 18

Special Instruction:

Survivor:

Merimen

ASSIGNMENT (Office)

From (Person):

Lipuel Tan

of

MSH

Date/Time:

22/03/07 807am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PC 7966L

Insured:

FD 7251K

at Workshop m/s

SM-1 Auto

Tel:

9666 6556

of

Bik 8 5m mny Incl Est # 01-68

Policy No:

MSD / VMT / 17-981262-WTT

Claim No:

MSC/V/17-000134

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

15/03/2017

CA / REV / REP. / REV 24 HRS 'Wp'

H.O.D. Endorsement:

Date/Time:

22/03/07 9:00am

Person Contacted:

Mr. Chia

Vehicle IN / OUT

| Date/Time | Action/Instruction (✓) Estimate |
|-----------|---|
| | PC 7966L - X |
| | FD 7251K - X |
| 29/3/17 | Sent poli through merimen (pending part prices) |
| 28/3/18 | Confirm 2/1 \$4K, 4 days |
| | Red: \$12,215.00, 75%. |




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|---|---------------------------|------------|---|
| MSIG INSURANCE (SINGAPORE) PTE LTD | | Ref : CS/MSG17005726/M1rb | | |
| 16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581 | | Date : 22-03-2017 | |  |
| | | Code : MSG | | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | FQ 7251K | Veh. Inspected | PC 7966L | |
| Policy No. | MSD/VMT/17-981262-WTT | Coverage (\$) | 0.00 | |
| Claim No. | MSC/V/17-000434 | Excess (\$) | 0.00 | |
| Assign From | MERIMEN (LIONEL TAN) | Assign Date | 22/03/2017 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | | c.c | 0 | |
| Engine No. | HIDDEN | Year of Reg. | | |
| Chassis No. | | Colour | | |
| Odometer | - | Steering | | |
| Brakes | | Modification | | |
| General | | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | | | mm | |
| L/H Front Tyre | | | mm | |
| R/H Rear Tyre | | | mm | |
| L/H Rear Tyre | | | mm | |
| 4. Description of Damages | | | | |
| | | | | |
| 5. General Information | | | | |
| Accident Date | 15/03/2017 | Inspection Date | | |
| Survey held at | EM-1 AUTO PTE LTD BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C #01-68 SINGAPORE 575643 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
|------|-------------|---------------|--|---------|---------------|------------|--|
| Main | 16 Mar 2017 | | 22 Mar 2017 08:07 Assign | | | | New Assignment Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|------------------------------------|---|--|---|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS | | [Created by insurer] | | | | | | | |
| Insured: | ANDIQ FAIZ SHAZRIZAL BIN MUHAMMAD SYAFIQ, ID: S9521483E, Tel: +6583020144, Email: andiq_rockz95@hotmail.com | | | | | | | | |
| Main Claimant: | YELLOW BUS SERVICES PTE LTD, Co. Reg. No.: 200813143M | | | | | | | | |
| Vehicle Reg. No.: | PC7966L | Date of Loss: | 15/03/2017 14:00 - :59 | | | | | | |
| Claim Type: | TP / MSC/V/17-000434 | Policy/Cover Note No.: | MSD/VMT/17-981262-WTT (Third Party Only) Coverage: 14/03/2017 - 13/03/2018 | | | | | | |
| Vehicle Reg. No. (Insured): | FQ7251K | Policy No. (Claimant): | | | | | | | |
| Repairer: | Em-1 Auto Pte Ltd (HQ) Blk 8 Sin Ming Industrial Estate Sector C, #01-68, 575643 Sin Ming - Tel: 64523298 | | | | | | | | |
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307] | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 23/03/2017] | | | | | | | | |
| Driver/Custodian (Insured): | ANDIQ FAIZ SHAZRIZAL BIN MUHAMMAD SYAFIQ (21 / Male), NRIC: S9521483E, Tel: +6583020144 | | | | | | | | |
| Adj Asg. Remarks: | Please contact the workshop at 64523298 or 9666 6556 Mr Chia Sin Muk to arrange for survey. | | | | | | | | |
| ASSOCIATED MAIL RECEIVED | | View All Compose Case Mail | | | | | | | |
| There are no mail for this case. | | | | | | | | | |
| ALL ASSOCIATED TASKS | | View All Search Tasks Create New Task Complete | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan Tian Pei

Date: 29 Mar 2017

Preliminary Advice

| | | | |
|--------------------|---|-------------------------|--------------|
| Insured Vehicle No | : FQ7251K | | |
| TP Vehicle No | : PC7966L | Accident Date | : 15/03/2017 |
| Make | : ISUZU LT134P | Assignment Date | : 22/03/2017 |
| Date of Inspection | : 28/03/2017 | Est. Duration of Repair | : 4.00 |
| Inspection At | : Em-1 Auto Pte Ltd (HQ) Blk 8 Sin Ming Industrial Estate Sector C, #01-68 Singapore 575643 | | |

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|----------------------|
| Repairer's Estimate (Gross) | :S\$ | 3,570.00 Labour Only |
| Revised Amount | :S\$ | 1,410.00 Labour Only |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 1,410.00 Labour Only |

| | |
|-----------------|------|
| Lump Sum Repair | :S\$ |
|-----------------|------|

Total Loss Consideration

| | |
|--------------------|------|
| New for Old Value | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate | :S\$ |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ |

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.
- Pending parts price.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|--------------------------------------|
| Date Of Report | 16/03/2017 15:30 |
| Date Of Accident | 15/03/2017 14:35 |
| Exact Location Of Accident | WOODLANDS AVE 1 TWDS WOODLANDS AVE 2 |
| Country/State of Loss | Singapore |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|-----------------------------|
| Vehicle Registration Number | PC7966L |
| Insured/Policyholder | |
| Name Of Registered Owner | YELLOW BUS SERVICES PTE LTD |
| Co Reg No | 200813143M |
| Email Address | NOEMAIL |
| Mobile Phone No | |
| Alternative Phone No | Office-84058724 |

Vehicle Particulars

| | |
|--------------|------------------|
| Manufacturer | ISUZU |
| Model | LT134P 49 SEATER |

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? No

If No, Please state action to be taken Third Party

Vehicle Category Commercial Vehicle

Insurance Company

| | |
|---------------------------|---------------------------------------|
| Name of Insurance Company | India International Insurance Pte Ltd |
| Type Of Coverage | Comprehensive |
| Fleet Policy | No |
| Policy Number | M489383 |
| Cover Note Number | |

Driver

| | |
|----------------------|----------------------|
| Name of Driver | WANG SONG |
| Passport No/FIN | G2273367U |
| Date Of Birth | 01/03/1986 |
| Occupation | Outdoor |
| Date Of Driving Pass | 20/01/2014 |
| Driving Experience | 3 Years And 1 Month |
| Gender | Male |
| Mobile Number | (Local) +65-84058724 |
| Fax Number | |
| Contact Number | |
| EEmail Address | NOEMAIL |

| | |
|---|--|
| Address | BLK 327 WOODLANDS STREET 32 #01-07 SINGAPORE |
| Postcode | 730327 |
| Was driver an employee of the Insured's Company | Yes |
| If No, Relationship of the Driver with the Insured | |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |
| | - |

General Information of the Accident

| | |
|--------------------|--|
| Type Of Accident | Collision- Head to Rear (TP Hit Insured) |
| Weather Conditions | Clear |
| Road Surface | Dry |

Other Information

| | |
|---|-----|
| Was any foreign vehicle involved in this accident? | No |
| Was any body injured in the Accident? | No |
| Was any other material or property damaged? | Yes |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | No |
| Number of Passengers (Including Driver) | 1 |

Details of Police Action

| | |
|---|--|
| Was the accident reported to the police? | Yes |
| If Yes, Please state which Police Station | |
| Police Station Name | Woodlands West Npc |
| Police Station Address | ROAD: 9 Marsiling Lane , POSTCODE: 739146 , COUNTRY: Singapore |
| Police Station Contact | TEL NO: - FAX NO: |
| Was notice of intended Prosecution given? | No |
| If Yes, against whom? | |

Circumstances of Accident

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | Yes |
| Was there any video captured by Car Camera? | No |
| Was there any audio recorded? | No |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-------------------------------------|---------|
| Vehicle Registration Number | FQ7251K |
| Vehicle Make/Model/Colour | |
| Details Of Properties | |
| Name of Driver | |
| NRIC/Passport Number | |
| Contact Number | |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

Details of Witness



| | |
|---------------|--|
| Name | |
| Phone Number | |
| Email Address | |

Accident Sketch Plan


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"); the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be based outside of Singapore, for one or more of the above Purposes.

| | | |
|---|---|---|
|  Policyholder's Signature / Date & Time |  Driver's Signature (if driver is not the policyholder) / Date & Time | CITY AUTO PTE LTD Blk 8 Sin Ming Road #01-58/50/52 Sin Ming Ind Est Singapore 575643 Tel: 6453 7735 Fax: 6453 7944 (Claims Section) Witnessed by Reporting Centre Personnel |
|---|---|---|

Sketch Plan



Accident Sketch Plan

Describe Circumstances of the Accident

Please refer to police report 3/00170318/0146.

Declaration

We declare the foregoing particulars are true in every respect

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

CITY AUTO PTE LTD
 Blk 8 Sin Ming Road
 #01-58/60-62 Sin Ming Ind Est
 Singapore 575643
 Tel: 6453 1235 Fax: 6453 7944
 (Claims Section)

Witnessed by Reporting Centre
 Personnel



**SINGAPORE
POLICE FORCE**



J/20170315/2146

1 of 2

POLICE REPORT (NP299)

Report No. J/20170315/2146

Police Station Of Origin
Woodlands West N.P.C.
9 Marsiling Lane SINGAPORE 739146
Tel No: 1800-363 9999

| | | |
|---|---|-------------------------|
| Date/Time Report Made 15/03/2017 17:55 | Vide Report No. | Station Diary No. 86 |
| Name Of Informant WANG SONG | Address APT BLK 327 WOODLANDS STREET 32 #01-07 SINGAPORE 730327 | |
| ID Type / ID No. FIN NO / G2273367U | Contact No. Home/Office 84058724 | Mobile |
| Nationality CHINESE | Email Address | |
| Occupation Bus driver | Sex Male | Age 31 |
| | Date of Birth 01/03/1986 | Race Chinese |
| Institution/School Name | Language | |
| Date/Time Of Incident 15/03/2017 14:35 | Location Of Incident 369 WOODLANDS AVENUE 1 HDB-WOODLANDS SINGAPORE 730369 At the vicinity | |

Brief details.

On the 15/3/2017 at about 1435hrs A1(G2273367U) was involved in a car accident at woodlands Ave 1. A1 was driving V1(PC7966L) and was stationary at the moment as there was a public bus infront of V1 at that point of time. A2 (S9521483E) was driving V2 (FQ7251K) and was swerving through the lanes and collided into V1 rear left side. A1 got out of the vehicle and assisted A2 to the side of the road before assessing the damage. A2 then rested at the side of the road for awhile before exchanging details with

| | |
|--|--------------------------------|
| Signature Of Officer Recording The Report: J / Sgt ELTON DE LAURE | Signature Of Informant: |
| Signature Of Interpreter: Not applicable | Date/Time: 15/03/2017 17:55 |
| Officer In-Charge Of Case: J / Jurong Police Divisional Investigation Branch / WEN JIANQUAN, NICHOLAS Contact No.: 67910000 | Classification Of Case: |

Authentication Stamp



**SINGAPORE
POLICE FORCE**



J/20170315/2146

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. J/20170315/2146

A1. A1 and A2 then proceeded to take pictures of the accident. I would like to state that A1 asked A2 if he required ambulance and A2 said that he does not need one. I would also like to state that there was a witness who saw the incident happen and the details of the witness is A3 (Zainab) and her hp is 81807457. I would like to make this report for record purposes.

Signature Of Officer Recording The Report:

Don Chong
J / Sgt ELTON DE LAURE

Signature Of Interpreter:
Not applicable

Officer In-Charge Of Case:
J / Jirong Police Divisional Investigation Branch /
WEN JIANQUAN, NICHOLAS
Contact No.: 67910000

Signature Of Informant:

王松

Date/Time:
15/03/2017 17:55

Classification Of Case:

Authentication Stamp

W

EM-1 AUTO TRADE

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY REG. NO. 53105453B

Vehicle Number : PC 7966L
Vehicle Model : ISUZU PICKUP BUS
Accident Date : 15.03.2017
Original Reg Date : 01.09.2011

Date : 28.03.2017
Chassis : JALLT134PB7000021
TP Ins. MSIG

ESTIMATE

| | | | | | | |
|----|-------|---------------------------------------|-------|--------|-----|----|
| 1 | 1 pc | Tailgate | | \$3800 | x 2 | SN |
| 2 | 2 pcs | Tailgate Side Lock | @ 85 | \$ 170 | x 2 | SN |
| 3 | 2 pcs | Tailgate Side Lock Catch | @ 65 | \$ 130 | x 2 | SN |
| 4 | 1 pc | Tailgate Weatherstrip | | \$ 320 | ✓ | SN |
| 5 | 2 pcs | Tailgate Hinges | @ 75 | \$ 150 | x 2 | SN |
| 6 | 1 pc | Rear Bumper | | \$1900 | ✓ | SN |
| 7 | 2 pcs | Rear Bumper Side Bracket | @ 120 | \$ 240 | ✓ | SN |
| 8 | 4 pcs | Rear Bumper Reverse Sensor (Original) | @ 360 | \$1440 | | SN |
| 9 | 4 pcs | Rear Bumper Reverse Sensor Holder | @ 60 | \$ 240 | | SN |
| 10 | 1 pc | Taillamp LH | | \$780 | ✓ | SN |
| 11 | 1 pc | Taillamp Inner Sealer LH | | \$ 60 | ✓ | SN |
| 12 | 1 set | Taillamp Clips | | \$ 30 | ✓ | SN |
| 13 | 1 pc | Tailgate Sticker 60km/h | | \$ 15 | ✓ | SN |
| 14 | 1 pc | Tailgate Sticker (REAL MEN DRIVE) | | \$ 90 | ✓ | SN |
| 15 | 1 pc | Rear Corner Carbon Fiber LH | 2500 | \$2500 | ✓ | SN |
| 16 | 1 set | Rear Corner Carbon Fiber Inner Sponge | | \$380 | ✓ | SN |

Labour charge

| | | | |
|------------------------------------|--|----------|-----|
| Panel Beating | | 1,600.00 | 500 |
| Spray painting | | 1,600.00 | 800 |
| Check Wiring | | 50.00 | 30 |
| Anti rust | | ✓ 80.00 | |
| Remove and install tailgate parts. | | ✓ 90.00 | |
| Remove and install reverse sensor. | | 150.00 | 80 |

✓ Authorize
WSP Reg
KPR paint PDR
LBE Auto (MMA)
28/03/2017
4w days

16215.00
L/S 4000h
4w days

EM-1 AUTO TRADE

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY REG. NO. 53105453E

Vehicle Number : PC 7966L
Vehicle Model : ISUZU PICKUP
Accident Date : 15.03.2017
Original Reg Date : 01.09.2011

Date : 28.03.2017
Chassis : JALLT134PB7000021
TP Ins. MSIG

ESTIMATE

| | | | | | |
|----|-------|---------------------------------------|------|------|----|
| 1 | 1 pc | Tailgate | | x TL | SN |
| 2 | 2 pcs | Tailgate Side Lock | | x RL | SN |
| 3 | 2 pcs | Tailgate Side Lock Catch | | x RL | SN |
| 4 | 1 pc | Tailgate Weatherstrip | | ✓ RL | SN |
| 5 | 2 pcs | Tailgate Hinges | | x RL | SN |
| 6 | 1 pc | Rear Bumper | | ✓ TL | SN |
| 7 | 2 pcs | Rear Bumper Side Bracket | | ✓ RL | SN |
| 8 | 4 pcs | Rear Bumper Reverse Sensor (Original) | 1 RL | | SN |
| 9 | 4 pcs | Rear Bumper Reverse Sensor Holder | 1 RL | | SN |
| 10 | 1 pc | Taillamp LH | | ✓ RL | SN |
| 11 | 1 pc | Taillamp Inner Sealer LH | | ✓ | SN |
| 12 | 1 set | Taillamp Clips | | ✓ | SN |
| 13 | 1 pc | Tailgate Sticker 60km/h | | ✓ RL | SN |
| 14 | 1 pc | Tailgate Sticker (REAL MEN DRIVE) | | ✓ RL | SN |
| 15 | 1 pc | Rear Corner Carbon Fiber LH | | ✓ RL | SN |
| 16 | 1 set | Rear Corner Carbon Fiber Inner Sponge | | ✓ RL | SN |

Labour charge

| | | | |
|------------------------------------|--|----------|-----|
| Panel Beating | | 1,600.00 | 500 |
| Spray painting | | 1,600.00 | 800 |
| Check Wiring | | 50.00 | 30 |
| Anti rust | | ✓ 80.00 | |
| Remove and install tailgate parts. | | ✓ 90.00 | |
| Remove and install reverse sensor. | | 150.00 | 80 |

WSP Resin
Kor paint
LKK Auto (M)
28/03/2017
4w/1day
30/3/17

LKK Auto Consultancy hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|--|--|--|-------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 16 Mar 2017 | | 22 Mar 2017 08:07 Edit Adj Rpt | S\$4,000.00 Edit Estimates | S\$4,000.00 View Rpt | | Pending for Survey Report Cancel Case |

| | | | | |
|-------------|------------------|----------------------|------------------|--------------------------|
| Main | Reference | Claim Details | Documents | Show All |
|-------------|------------------|----------------------|------------------|--------------------------|

CLAIM SUBFOLDER DETAILS [Created by insurer]

| | | | |
|-----------------------------|---|------------------------|---|
| Insured: | ANDIQ FAIZ SHAZRIZAL BIN MUHAMMAD SYAFIQ , ID: S9521483E, Tel: +6583020144, Email: andiq_rockz95@hotmail.com | | |
| Main Claimant: | YELLOW BUS SERVICES PTE LTD , Co. Reg. No.: 200813143M | | |
| Vehicle Reg. No.: | PC7966L | Date of Loss: | 15/03/2017 14:00 - :59 |
| Claim Type: | TP / MSC/V/17-000434 | Policy/Cover Note No.: | MSD/VMT/17-981262-WTT (Third Party Only) Coverage: 14/03/2017 - 13/03/2018 |
| Vehicle Reg. No. (Insured): | FQ7251K | Policy No. (Claimant): | |
| | | Excess: | S\$0.00 |
| Repairer: | Em-1 Auto Pte Ltd (HQ) Blk 8 Sin Ming Industrial Estate Sector C, #01-68, 575643 Sin Ming - Tel: 64523298 | | |
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307] | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 21/04/2017] | | |
| Driver/Custodian (Insured): | ANDIQ FAIZ SHAZRIZAL BIN MUHAMMAD SYAFIQ (21 / Male), NRIC: S9521483E, Tel: +6583020144 | | |
| Adj Asg. Remarks: | Please contact the workshop at 64523298 or 9666 6556 Mr Chia Sin Muk to arrange for survey. | | |

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

Claim Documents

*PC7966L (MSC/V/17-000434)

[FQ7251K]

TP



YELLOW BUS SERVICES PTE LTD




















Mar 15 2017 2:00PM



[ANDIQ FAIZ SHAZRIZAL BIN MUHAMMAD SYAFIQ]

Em-1 Auto Pte Ltd

| | | | | | |
|----------------------------------|--|-------------------------------|------------------------------------|---|--|
| Upload Documents | | Upload Photos | Compose New Letter | View View in Browser <input type="button" value="v"/> | |
|----------------------------------|--|-------------------------------|------------------------------------|---|--|

| Assessment Reports | | | | 1 per page <input type="button" value="v"/> | <input checked="" type="checkbox"/> |
|--------------------|----------------|--|---|---|-------------------------------------|
| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | | Thumbnail | Print |
| 1 | 21/03/17 14:45 | Accident Statement From: SC - Reg. No: FQ7251K, Claimant: ANDIQ FAIZ SHAZRIZAL BIN MUHAMMAD SYAFIQ |  | Load HTM | |
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | | Thumbnail | Print |
| 1 | 29/03/17 16:45 | Adjuster Immediate Advice |  | Load HTM | |

| Photos/ Images | | | | 3 per page <input type="button" value="v"/> | <input checked="" type="checkbox"/> |
|----------------|-----------------|-----------------------------------|---|---|-------------------------------------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | Thumbnail | Print |
| 1 | 28/03/18 17:04 | General View |  | Load JPG | <input checked="" type="checkbox"/> |
| 2 | 28/03/18 17:04 | General View |  | Load JPG | <input checked="" type="checkbox"/> |
| 3 | 28/03/18 17:04 | General View |  | Load JPG | <input checked="" type="checkbox"/> |
| 4 | 28/03/18 17:04 | General View |  | Load JPG | <input checked="" type="checkbox"/> |
| 5 | 28/03/18 17:04 | General View |  | Load JPG | <input checked="" type="checkbox"/> |
| 6 | 28/03/18 17:04 | General View |  | Load JPG | <input checked="" type="checkbox"/> |
| 7 | 28/03/18 17:04 | General View |  | Load JPG | <input checked="" type="checkbox"/> |
| 8 | 28/03/18 17:04 | General View |  | Load JPG | <input checked="" type="checkbox"/> |
| 9 | 28/03/18 17:04 | General View |  | Load JPG | <input checked="" type="checkbox"/> |
| 10 | 28/03/18 17:04 | General View |  | Load JPG | <input checked="" type="checkbox"/> |
| 11 | 28/03/18 17:04 | General View |  | Load JPG | <input checked="" type="checkbox"/> |
| 12 | 28/03/18 17:04 | General View |  | Load JPG | <input checked="" type="checkbox"/> |
| 13 | 28/03/18 17:04 | General View |  | Load JPG | <input checked="" type="checkbox"/> |
| 14 | 28/03/18 17:04 | General View |  | Load JPG | <input checked="" type="checkbox"/> |
| 15 | 28/03/18 17:04 | General View |  | Load JPG | <input checked="" type="checkbox"/> |
| 16 | 28/03/18 17:04 | General View |  | Load JPG | <input checked="" type="checkbox"/> |
| 17 | 28/03/18 17:04 | General View |  | Load JPG | <input checked="" type="checkbox"/> |
| 18 | 28/03/18 17:04 | General View |  | Load JPG | <input checked="" type="checkbox"/> |
| 19 | 28/03/18 17:04 | General View |  | Load JPG | <input checked="" type="checkbox"/> |

| Documentation | | | | 1 per page <input type="button" value="v"/> | <input checked="" type="checkbox"/> |
|---------------|----------------|---|---|---|-------------------------------------|
| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | | Thumbnail | Print |
| 1 | 21/03/17 14:45 | TPD PC7966L GIA REPORT |  | Load PDF | |
| 2 | 21/03/17 14:45 | Pre-Repair Survey |  | Load PDF | |

Documents Checklist

| | | | |
|--|-----------------------|----------------------|-----------------------|
| DOCUMENTS CHECKLIST | Reset | Save | Print |
| There are no document checklists configured. | | | |

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17005726/M1RBE2

Date: 29/03/2018

REFERENCE

| | | | |
|-----------------------|--------------------------------------|----------------------|-----------------------|
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. | Policy No: | MSD/VMT/17-981262-WTT |
| Claimant Vehicle No : | PC7966L | Insured Vehicle No : | FQ7251K |
| Date of Loss: | 15/03/2017 | Nature of Claim: | TP |
| | | Claim No: | MSC/V/17-000434 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|------------------------------|-------------|-------------------|
| Reg No: | PC7966L | Engine No: | 6HK1602344 |
| Make & Model: | ISUZU LT134P, 7.8 D (M) | Chassis No: | JALLT134PB7000021 |
| Reg. Date: | 01/09/2011 (Man. Year: 2010) | Odometer: | 173909 km |
| Colour: | Yellow | | |
| Engine Capacity: | 7790 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size: | 11 R22.5 | Rear Tyre Size: | 11 R22.5 |
| Front Left Side: | Bridgestone 8 mm | Rear Left Side: | Bridgestone 8 mm |
| Front Right Side: | Bridgestone 8 mm | Rear Right Side: | Bridgestone 8 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|------------------|-----------------|------------------|--------------|
| Parts | 12,645.00 | 4,745.00 | 7,900.00 | 62.48 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 3,570.00 | 1,410.00 | 2,160.00 | 60.50 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 16,215.00 | 6,155.00 | 10,060.00 | 62.04 |
| Approved Total (Overridden) (S\$) | | 4,000.00 | | |
| (S\$) | 16,215.00 | 4,000.00 | 12,215.00 | 75.33 |
| + GST 7.00/7.00% (S\$) | 1,135.05 | 280.00 | 855.05 | 75.33 |
| Nett Amount (S\$) | 17,350.05 | 4,280.00 | 13,070.05 | 75.33 |

INSPECTION

| | | |
|-----------------------------|--------------------------|--|
| Date of Assignment: | 22/03/2017 | |
| Date Inspected: | 28/03/2017 Inspected At: | Em-1 Auto Pte Ltd (HQ) Blk 8 Sin Ming Industrial Estate Sector C, #01-68 Singapore 575643 |
| Estimated Period of Repair: | 4.0 days | |

Adjuster: MA CHIN FOOK**Manager:** Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 29 Mar 2018)
Parts: N/A ISUZU LT134P 7.8 D (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for PC7966L)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--|-----------------------|-------------|--------------|
| 1 | 1 | | *TAILGATE | Repair | 3,800.00 FS | *- FS |
| 2 | 2 | | *TAILGATE SIDE LOCK | Serviceable | 170.00 FS | *- FS |
| 3 | 2 | | *TAILGATE SIDE LOCK CATCH | Serviceable | 130.00 FS | *- FS |
| 4 | 1 | | *TAILGATE WEATHERSTRIP | Necessary | 320.00 FS | *320.00 FS |
| 5 | 2 | | *TAILGATE HINGES | Repair | 150.00 FS | *- FS |
| 6 | 1 | | *REAR BUMPER | Repair | 1,900.00 FS | *- FS |
| 7 | 2 | | *REAR BUMPER SIDE BRACKET | Bent | 240.00 FS | *240.00 FS |
| 8 | 1 | | *REAR BUMPER REVERSE SENSOR (ORIGINAL) | Shorted - only 1 pc | 1,440.00 FS | *360.00 FS |
| | | | (4 PCS) | | | |
| 9 | 1 | | *REAR BUMPER REVERSE SENSOR HOLDER | Necessary - only 1 pc | 240.00 FS | *60.00 FS |
| | | | (4 PCS) | | | |
| 10 | 1 | | *TAILLAMP LH | Cracked | 780.00 FS | *780.00 FS |
| 11 | 1 | | *TAILLAMP INNER SEALER LH | Serviceable | 60.00 FS | *- FS |
| 12 | 1 | | *SET TAILLAMP CLIPS | Serviceable | 30.00 FS | *- FS |
| 13 | 1 | | *TAILGATE STICKER 60KM/H | Necessary | 15.00 FS | *15.00 FS |
| 14 | 1 | | *TAILGATE STICKER (REAL MEN DRIVE) | Necessary | 90.00 FS | *90.00 FS |
| 15 | 1 | | *REAR CORNER CARBIN FIBER LH | Distorted | 2,900.00 FS | *2,500.00 FS |
| 16 | 1 | | *SET REAR CORNER CARBON FIBER INNER SPONGE | Necessary | 380.00 FS | *380.00 FS |

F=Franchise part. S=SpcNett.

Total Parts (S\$) 12,645.00 4,745.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|-----------------------------------|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | PANEL BEATING | New | 1,600.00 | 500.00 |
| 2 | SPRAY PAINTING | New | 1,600.00 | 800.00 |
| 3 | CHECK WIRING | New | 50.00 | 30.00 |
| 4 | ANTI RUST | New | 80.00 | 0.00 |
| 5 | REMOVE AND INSTALL TAILGATE PARTS | New | 90.00 | 0.00 |
| 6 | REMOVE AND INSTALL REVERSE SENSOR | New | 150.00 | 80.00 |
| Gross Labour Cost (\$\$) | | | 3,570.00 | 1,410.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >