

ASS. REC. BY:

REF:

CS/MSG17006553

At h3n2

Special Instructions:

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person):

Katherine Wray

of

MSG

Date/Time: 4/4/2017 10:10am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKB8511Z

Insured:

SLF5423G

at Workshop m/s:

Premium Automobiles

Tel:

67689911

of

55 461 Road 1

Policy No:

MSD/VCC/17-006024

Claim No:

MSG M/17-000513

Sum Insured:

Excess:

Make of Veh:

D.O.A. 30/3/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS (wp)

H.O.D. Endorsement:

Date/Time:

4/4/2017 11:45am

Person Contacted:

Jack

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKB8511Z-CC6/ACG 1201 9554/K02+292 DUA: 1/11/2012
	SLF5423G-x
12/4-	Revert preli advise
14/12/17-	Confirm \$3579.40, 3days. (Red: 12159.60 : 77%)

ASS. REC. BY: Adrian Ling

16 | 6 | 2011

Veh No: SKB 8511Z Yr Regn: 2011 Jne

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A5 c.c. 1584

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading 147518 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WAUZZZ8T1BA080872

Gen. Cond: **Good** / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/40R18

R: 045/40RB

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

Front Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. *de* mm L/Bal. *06* mm

D.O.A. D.O.I. 10/04/17.

Survey held at Premises

Survey held at Premiere

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

[illegible]

☐: Preli. Report  
☒: Final Report

Resurvey No. of Trip:

Survey Fee:

Transportation:

) Photos

) Others

TOTAL

**Add Fee:** ☐ : Site Insp (\$ ) \$ + RS \$  
☐ : Interview (\$ ) Photos  
☐ : Tech. Invs (\$ ) Others  
☐ : Weekend (\$ )

300
10
310



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17006553/Ath3

16 RAFFLES QUAY  
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 04-04-2017



Code : MSG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLF 5423G	Veh. Inspected	SKB 8511Z
Policy No.	MSD/VCC/17-000024	Coverage (\$)	0.00
Claim No.	MSC/V/17-000513	Excess (\$)	0.00
Assign From	MERIMEN (KATHERINE WONG)	Assign Date	04/04/2017

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	30/03/2017	Inspection Date	10/04/2017
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1. SINGAPORE 408699		

## 5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	31 Mar 2017		04 Apr 2017 10:10 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CAR CLUB PTE. LTD., Co. Reg. No.: 200912077G, Tel: +6591906388		
Main Claimant:	TEO TEOW CHIAW, ID: S7806262B		
Vehicle Reg. No.:	SKB8511Z	Date of Loss:	30/03/2017 17:00 - :59
Claim Type:	TP / MSC/V/17-000513	Policy/Cover Note No.:	MSD/VCC/17-000024 (Comprehensive) Coverage: 01/01/2017 - 31/12/2017
Vehicle Reg. No. (Insured):	SLF5423G	Policy No. (Claimant):	
		Excess:	S\$2,000.00
Repairer:	Premium Automobiles Pte Ltd (HQ) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 05/04/2017]		
Driver/Custodian (Insured):	TEO CHEE WEE (ZHANG ZHIWEI) (), NRIC: S8616266J, Tel: +6591906388		

### ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	31/03/2017 16:37
Date Of Accident	30/03/2017 17:20
Exact Location Of Accident	AYE TOWARDS TUAS
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKB8511Z
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TEO TEOW CHIAW
NRIC No	S7806262B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98301572
Alternative Phone No	Others-98301572

### Vehicle Particulars

Manufacturer	AUDI
Model	A5-2.0 TFSI QUATTRO (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Private Car

### Insurance Company

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	
Cover Note Number	

### Driver

Name of Driver	TEO TEOW CHIAW
NRIC No	S7806262B
Date Of Birth	02/03/1978
Occupation	Indoor
Date Of Driving Pass	06/02/2003
Driving Experience	14 Years And 1 Month
Gender	Male
Mobile Number	(Local) +65-98301572
Fax Number	
Contact Number	Others-98301572
Email Address	NOEMAIL

Address	BLK 809 BUKIT PANJANG RING ROAD #08-972
Postcode	S670609
Was driver an employee of the Insured's Company	No
If No, Relationship of the Driver with the Insured	Owner
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	Collision- Head to Rear (TP Hit Insured)
Weather Conditions	Raining
Road Surface	Wet

#### Other Information

Was any foreign vehicle involved in this accident?	No
Was any body injured in the Accident?	No
Was any other material or property damaged?	Yes
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	No
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	No
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	No
If Yes, against whom?	

#### Circumstances of Accident

TRAVELLING ALONG AYE TOWARDS TUAS. VEHICLE TRAFFIC WAS HEAVY. VEHICLE IN FRONT SLOWED TO A STATIONARY. I FOLLOWS SUIT. SUDDENLY SLF5423G WHO WAS FOLLOWING BEHIND REAR ENDED ME WHEN I WAS STATIONARY.

#### Attachment(s)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLF5423G
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### Details of Witness

Name	
Phone Number	
Email Address	

## Sketch Plan

### SKETCH PLAN


#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

  
\_\_\_\_\_  
Policyholder's Signature / Date & Time

  
\_\_\_\_\_  
Driver's Signature (If driver is not the policyholder) / Date & Time

  
\_\_\_\_\_  
Witnessed by Reporting Centre Personnel

#### Sketch Plan

→ AVE towards Tuoos



A → SK885112

B → SHF542C 5423G  
SLF

### Sketch Plan #2

## Describe Circumstances of the Accident

Travelling along AVE towards Tug. Vehicle traffic was heavy.  
Vehicle in front slowed to a stationary. I followed suit. Suddenly  
SH#54036 who was following behind her ended me when I was stationary.  
SF

### Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &  
Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre  
Personnel





Accident Photo




Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S7806262B



Name

TEO TEOW CHIAW

张潮钊

Race

CHINESE

Date of birth

02-03-1978

Sex

M

Country of birth


SINGAPORE

S7806262B

4242034



NRIC No. S7806262B



Date of issue

02-07-2008

Address

APT BLK 609 BUKIT PANJANG RING ROAD #06-892  
SINGAPORE 670609

NRIC No. S7806262B

Date: 17/02/2010

No: 6407759

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

Estimate : Accident Repairs  
Workshop : Ubi Road 1  
Contact No : 6366 2323  
Fax No : 6841 1183  
Reference : PA/TP/0325/2017/JN  
Date : 3-Apr-17

Vehicle not in workshop. Kindly arrange for survey.

Your insured: **SLF 5423 G**

## MSIG Insurance (Singapore) Pte Ltd

No 4 Shenton Way  
#23-01 SGX Centre 2  
Singapore 068896

Attn: Motor Claims Dept

Tel: 6827 2762 - Fax: 6225 7402

Owner's Name : Mr Teo Teow Chiaw  
Address : Blk 809 Bukit Panjang Ring Road  
#08-972  
Singapore 670609  
Telephone : (HP) 98301572  
Type of Claim : Third Party Claim  
Policy No. :  
Vehicle No : **SKB 8511 Z**  
Model Code : Audi A5 2.0 TFSI QU  
Model / Year : Jun-11  
Engine No : CDN 199023  
Chassis No : WAUZZZ8T1BA080872  
Mileage : -  
Date In :  
Liability : -  
Excess Cost : -  
Estimated By : Johnny Boo / Allan Wu  
Accident Date : 30-Mar-17  
Place of Accident : AYE TOWARDS TUAS

Premium Automobiles (Pte) Ltd  
the Repairer of the following:  
• To resurvey before after spray painting  
• To display damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary item(s) must be resurveyed and  
is subject to final approval

Signature

Date



# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SKB 8511 Z.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check Function and renew according to damage.	S/N \$	280.00	✓ ✓
2	To remove and transfer rear lid convenience lock system and wire harness for tail lights.	S/N \$	280.00	X X
3	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio components.	S/N \$	480.00	? X
4	To dismantle rear bumper and rear lid. Cut out and reweld rear outer, inner and lower rear cross panel. Re-align rear lock carrier. Renew rear bumper and rear lid. Re-organise rear crash management components. Reinstall all parts removed.	\$	3,600.00	600. ✓
5	To respray rear bumper, rear lid and end panelling. To carry out joint sealer works and stone chip treatment.	\$	2,300.00	600 ✓
6	To carry out diagnostic check.	S/N \$	192.00	✓ ✓
<b>TOTAL LABOUR CHARGES</b>		:	<b>\$ 7,132.00</b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SKB 8511 Z.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>del</i>	\$ 1,550.00	✓✓
2	REAR BUMPER LOWER SPOILER <i>del</i>	\$ 225.00	✓✓
3	REAR REINFORCEMENT BEAM <i>del</i>	\$ 541.00	? X
4	REAR BUMPER GUIDE SECTION - LH/RH <i>del</i> <i>110</i> <i>110</i>	2 \$ 134.00	✓✓ <i>134.20 132.40</i>
5	REAR PARKING SENSOR <i>del</i>	\$ 387.00	?
6	REAR LID <i>2</i>	\$ 1,875.00	X
7	REAR LID SEAL <i>MP</i>	\$ 167.00	X
8	AUDI EMBLEM CHROME <i>MP</i>	\$ 105.00	X
9	A5 INSCRIPTION CHROME	\$ 81.00	X
10	2.0T INSCRIPTION CHROME	\$ 81.00	X
11	QUATTRO INSCRIPTION CHROME	\$ 81.00	X
12	REAR CROSS PANEL - OUTER <i>Rys</i>	\$ 750.00	? X
13	REAR CROSS PANEL REINFORCEMENT <i>Rys</i>	\$ 891.00	? X
14	REAR CROSS PANEL - LOWER <i>Rys</i>	\$ 739.00	? X
15	ACRYLIC SEALER <i>del</i>	S/N \$ 180.00	? X
16	CAVITY WAX <i>del</i>	S/N \$ 140.00	? X
17	STONE CHIP <i>del</i>	S/N \$ 180.00	? X
18	SUNDRIES <i>del</i>	\$ 500.00	? X
<b>TOTAL SPARE PARTS</b>		<b>\$ 8,607.00</b>	
<b>TOTAL LABOUR CHARGES</b>		<b>\$ 7,132.00</b>	
<b>GRAND TOTAL</b>		<b>\$ 15,739.00</b>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : Adrian King.  
Surveyed Date : 10/04/17.  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks : Not Authorised, 03 Days.

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd



Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

Estimate : Accident Repairs  
Workshop : Ubi Road 1  
Contact No : 6366 2323  
Fax No : 6841 1183  
Reference : PA/TP/0325/2017/JN  
Date : 3-Apr-17

Vehicle not in workshop. Kindly arrange for survey.

Your insured: **SLF 5423 G**

### MSIG Insurance (Singapore) Pte Ltd

No 4 Shenton Way  
#23-01 SGX Centre 2  
Singapore 068896

Hi Adrian  
3 days - ok - jb

Attn: Motor Claims Dept

Tel: 6827 2762 - Fax: 6225 7402

Owner's Name : Mr Teo Teow Chiaw  
Address : Blk 809 Bukit Panjang Ring Road  
#08-972  
Singapore 670609  
Telephone : (HP) 98301572  
Type of Claim : Third Party Claim  
Policy No. :  
Vehicle No : **SKB 8511 Z**  
Model Code : Audi A5 2.0 TFSI QU  
Model / Year : Jun-11  
Engine No : CDN 199023  
Chassis No : WAUZZZ8T1BA080872  
Mileage : -  
Date In :  
Liability : -  
Excess Cost : -  
Estimated By : Johnny Boo / Allan Wu  
Accident Date : 30-Mar-17  
Place of Accident : AYE TOWARDS TUAS

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SKB 8511 Z.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check Function and renew according to damage.	S/N \$	280.00	\$ 280.00
2	To remove and transfer rear lid convenience lock system and wire harness for tail lights.	S/N \$	280.00	
3	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio components.	S/N \$	480.00	
4	To dismantle rear bumper and rear lid. Cut out and reweld rear outer, inner and lower rear cross panel. Re-align rear lock carrier. Renew rear bumper and rear lid. Re-organise rear crash management components. Reinstall all parts removed.	\$	3,600.00	\$ 600.00
5	To respray rear bumper, rear lid and end panelling. To carry out joint sealer works and stone chip treatment.	\$	2,300.00	\$ 600.00
6	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 7,132.00</u>	<u>\$ 1,672.00</u>

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SKB 8511 Z.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER	\$ 1,550.00	\$ 1,550.00
2	REAR BUMPER LOWER SPOILER	\$ 225.00	\$ 225.00
3	REAR REINFORCEMENT BEAM	\$ 541.00	
4	REAR BUMPER GUIDE SECTION - LH/RH	2 \$ 134.00	\$ 132.40
5	REAR PARKING SENSOR	\$ 387.00	
6	REAR LID	\$ 1,875.00	
7	REAR LID SEAL	\$ 167.00	
8	AUDI EMBLEM CHROME	\$ 105.00	
9	A5 INSCRIPTION CHROME	\$ 81.00	
10	2.0T INSCRIPTION CHROME	\$ 81.00	
11	QUATTRO INSCRIPTION CHROME	\$ 81.00	
12	REAR CROSS PANEL - OUTER	\$ 750.00	
13	REAR CROSS PANEL REINFORCEMENT	\$ 891.00	
14	REAR CROSS PANEL - LOWER	\$ 739.00	
15	ACRYLIC SEALER	S/N \$ 180.00	
16	CAVITY WAX	S/N \$ 140.00	
17	STONE CHIP	S/N \$ 180.00	
18	SUNDRIES	\$ 500.00	
TOTAL SPARE PARTS		: \$ 8,607.00	\$ 1,907.40
TOTAL LABOUR CHARGES		: \$ 7,132.00	\$ 1,672.00
GRAND TOTAL		: \$ 15,739.00	\$ 3,579.40

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name :  
Surveyed Date :  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks :

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the  
progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant

## LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17006553/ATH3N2

Date: 14/12/2017

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VCC/17-000024
Claimant Vehicle No :	SKB8511Z	Insured Vehicle No :	SLF5423G
Date of Loss:	30/03/2017	Nature of Claim:	TP
		Claim No:	MSC/V/17-000513

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SKB8511Z	Engine No:	CDN199023
Make & Model:	AUDI A5, 1.8 SPORTBACK (A)	Chassis No:	WAUZZZ8T1BA080872
Reg. Date:	16/06/2011 (Man. Year: 2011)	Odometer:	147518 km
Colour:	Silver		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	245/40R18	Rear Tyre Size:	245/40R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	8,607.00	1,907.40	6,699.60	77.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,132.00	1,672.00	5,460.00	76.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>15,739.00</b>	<b>3,579.40</b>	<b>12,159.60</b>	<b>77.26</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>1,101.73</b>	<b>250.56</b>	<b>851.17</b>	<b>77.26</b>
<b>Nett Amount (\$\$)</b>	<b>16,840.73</b>	<b>3,829.96</b>	<b>13,010.77</b>	<b>77.26</b>

## INSPECTION

Date of Assignment:	04/04/2017		
Date Inspected:	10/04/2017	Inspected At:	Premium Automobiles Pte Ltd (HQ) 55 Ubi Road 1 Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 14 Dec 2017)
<b>Parts:</b> 143	AUDI A5 1.8 SPORTBACK (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKB8511Z)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,550.00 FS	*1,550.00 FS
2	1		*REAR BUMPER LOWER SPOILER	Deformed	225.00 FS	*225.00 FS
3	1		*REAR REINFORCEMENT BEAM	Not Necessary	541.00 FS	*- FS
4	2		*REAR BUMPER GUIDE SECTION-LH/RH	Cracked	134.00 FS	*132.40 FS
5	1		*REAR PARKING SENSOR	Not Necessary	387.00 FS	*- FS
6	1		*REAR LID	Not Necessary	1,875.00 FS	*- FS
7	1		*REAR LID SEAL	Not Necessary	167.00 FS	*- FS
8	1		*AUDI EMBLEM CHROME	Not Necessary	105.00 FS	*- FS
9	1		*A5 INSCRIPTION CHROME	Not Necessary	81.00 FS	*- FS
10	1		*2.0T INSCRIPTION CHROME	Not Necessary	81.00 FS	*- FS
11	1		*QUATTRO INSCRIPTION CHROME	Not Necessary	81.00 FS	*- FS
12	1		*REAR CROSS PANEL-OUTER	Repair	750.00 FS	*- FS
13	1		*REAR CROSS PANEL REINFORCEMENT	Repair	891.00 FS	*- FS
14	1		*REAR CROSS PANEL-LOWER	Repair	739.00 FS	*- FS
15	1		*ACRYLIC SEALER	Not Necessary	180.00 FS	*- FS
16	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
17	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
18	1		*SUNDRIES	Not Necessary	500.00 FS	*- FS

F=Franchise part. S=SpcNett.

<b>Total Parts (\$\$)</b>	<b>8,607.00</b>	<b>1,907.40</b>
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER REAR PARKING AID.CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	280.00	280.00
2	TO REMOVE AND TRANSFER REAR LID CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS	New	280.00	-
3	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR TAIL LIGHTS,BATTERY MANAGER,FUSE AND RELAY TRAYS,ELECTRICAL AND AUDIO COMPONENTS	New	480.00	-
4	TO DISMANTLE REAR BUMPER AND REAR LID.CUT OUT AND REWELD REAR OUTER,INNER AND LOWER REAR CROSS PANEL,RE-ALIGN REAR LOCK CARRIER.RENEW REAR BUMPER AND REAR LID.RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	3,600.00	600.00
5	TO RESPRAY REAR BUMPER,REAR LID AND END PANELLING,TO CARRY OUT JOINT SEALER WORKS AND STONE CHIP TREATMENT	New	2,300.00	600.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			7,132.00	1,672.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >