

AXA Insurance Singapore Pte Ltd

8 Shenton Way #27-01

AXA Tower

Singapore 068811

Vehicle number	: PC797D
Make / Model	: TOYOTA/HIACE
Chassis number	: JTFST22P100011084
Accident date	: 07 APRIL 2017
Reference	: 1704-12

Qty Particulars

Unit Price - SGD \$

<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT BUMPER distorted	731.90 ✓
1	FRONT BUMPER UPPER BEAM Bt	385.90 ✓
2	FRONT SIDE RETAINER src	231.90 x
1	BUMPER REINFORCEMENT Bt	496.90 ✓
1	FRONT GRILLE crack mounting	381.90 ✓
1	FRONT GRILLE EMBLEM NH	61.00 x
1	SUPPORT PANEL NH	681.90 x
2	FRONT HEADLAMP n/s crack o/s src	1362.70 ✓ @ 681.35
1	FRONT BUMPER LOWER GRILLE mounting crack	461.90 ✓
1	TAILGATE Dented	2519.90 ✓
2	TAILGATE ABSORBER NH	480.50 x
1	TAILGATE LOCK Dem	381.90 ✓
1	TAILGATE LOCK STRIKER NH	163.10 x
2	TAILGATE HINGE NH	282.10 x
1	TAILGATE WEATHERSTRIP NH	380.30 ✓
2	REAR CORNER PANEL o/s cut n/s NH	582.10 ✓ @ 291.05
1	REAR END PANEL Dented	691.80 ✓
2	REAR TAILLAMP o/s crack n/s NH	683.10 ✓ @ 341.55
2	REAR TAILLAMP SEALER NH	120.00 x
1	EXHAUST ASSY Bt	790.46 ✓
2	EXHAUST MOUNTING NH	120.00 x
1	TAILGATE GALSS MOULDING NH	186.43 ✓
1	SPARE TYRE CARRIER NH	390.13 x
		12567.82
Less 25%		3141.95
Subtotal		9425.87
Balance C/F		9425.87
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
Balance B/F		9425.87
1 SET	REAR BUMPER CLIP NH	60.00 30/-
1	TOYOTA STICKER NH	60.00 15/-
1	HIACE STICKER NH	50.00 15/-
1	70KM/H STICKER NH	50.00 15/-
1	WINDSCREEN SEALANT NH	150.00 40/-
1	JOINT SEALANT NH	150.00 40/-

Vehicle number : PC797D

Make Model : TOYOTA/HIACE

Reference : 1704-12

Qty	Particulars	Unit Price - SGD \$
1	REAR REVERSE SENSOR <i>Dem</i>	150.00 120/-
	Subtotal	670.00
	Balance C/F	10095.87
	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
	Balance B/F	10095.87
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	60.00 30/-
2	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH	200.00 80/-
3	REMOVE AND REFIT REAR REVERSE SENSOR	150.00 40/-
4	REMOVE AND RENEW REAR EXHAUST ASSY	150.00 60/-
5	REMOVE AND REFIT REAR WINDSCREEN	150.00 120/-
6	TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO NEW	200.00 60/-
7	PANEL BEATING ON AFFECTED AREAS	1500.00 1000/-
8	SPRAY PAINTING ON AFFECTED AREAS	1200.00 700/-
9	REMOVE AND RENEW STICKERS ON AFFECTED PANEL	1500.00 180/-
10	APPLY ANTI RUST ON AFFECTED AREAS	150.00 40/-
	Subtotal	5260.00
	Grand total	15355.87

11/04/2017 @ 1100m
not done
Hsant 5 dgs.
Brynn
2KK And
Check part prices.

Link Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: