

REF:

CC3 / AIG 1700 7273 / Arbez

ASS. REC. BY: Adrian King

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. 2100480593Claims No. 133833409684Sum Insured: _____ Excess: \$600

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 145

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 18/18 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SPR6817D Yr Regn: 2016 / April ^{August}Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A4 c.c. 1395Colour: white A/C: Insured / Std / NI / NASp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZZF40HA017945Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/60R16R: 205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 11/04/17Survey held at PremiumDes. of Damages Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

00 AIG.

SPR 6817D - CC3 / AIG 1700 7273 / Arbez

EXP: 27/11/16

(15.03pm) 13/4/17 Sent preli through merimen ; seek mandate

(18.57am) 17/4/17 Insurance approved mandate

(18.57am) 18/4/17 Informed Jeffery authorise repair and excess

Confirm \$33,305.72, 18 days

Red: \$18,071.28, 35%.

RECEIVED 28 MAR 2018

Date/Time, File Pass to?

☐

: Preli. Report

1) typist☒

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 18Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

) ___ \$ + RS ___ \$

) Photos

) Others

Report Format: ODLump Sum / I.B.I. (\$ 33,305.72)

TOTAL

200



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG17007273/Arb		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 13-04-2017		
Code : AIG				
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.	Veh. Inspected	SDR 6817D	
	Policy No. 2100480593	Coverage (\$)	0.00	
	Claim No.	Excess (\$)	0.00	
	Assign From	Assign Date	11/04/2017	
2. Vehicle Particulars & Condition				
	Make & Model	c.c	0	
	Engine No. HIDDEN	Year of Reg.		
	Chassis No.	Colour		
	Odometer -	Steering		
	Brakes	Modification		
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date 06/04/2017	Inspection Date	11/04/2017	
	Survey held at PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 SINGAPORE 408699			
5a. Remarks				
	A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

Janite Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Tuesday, 18 April, 2017 8:57 AM
To: 'Claims Department'
Cc: assignments; SUR; Admin-D (LKKAUTO)
Subject: RE: Request Certificate Insurance for vehicle no. SDR 6817D (Vehicle In)
AUTHORISE REPAIR

Dear Jeffery,

Instructed by our client, please proceed to repair the insured vehicle **SDR 6817D (Excess \$600)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

Any check item or supplementary are subjected to further approval from our client.

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 18 April, 2017 8:48 AM
To: 'Claims Department' <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>
Cc: assignments <assignments@lkkauto.com>
Subject: RE: Request Certificate Insurance for vehicle no. SDR 6817D (Vehicle In)

Dear Jeffrey,

Thank you for your email.

Dear Janice,

FYNA. Our Ref: CC3/AIG17007273/Arb

Print Received Message

This mail is associated with :

***SDR6817D (1338334096SG)**

OD

Apr 6 2017 12:00AM

[SASUADIMAI JEGANDHAS]

Premium Automobiles Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 13/04/2017 14:11 PM.
To LKK_HQ
Subject SDR6817D / OD / 06/04/2017 / Coverage & Excess update

Dear LKK Auto Consultants Pte Ltd

Please note that policy is in force and excess amount is \$600.00

Thank you
Dally Amri, Mimi Zarina

Print Received Message

This mail is associated with :

***SDR6817D (1338334096SG)**

OD

Apr 6 2017 12:00AM

[SASUADIMAI JEGANDHAS]

Premium Automobiles Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 17/04/2017 15:03 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$35230.00) - SDR6817D - Claim Handler: Dally Amri, Mimi Zarina

Approved:35230.00:Re-inspection to be done for damage check and hidden parts.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 13 Apr 2017

Preliminary Advice

Vehicle No	: SDR6817D	Accident Date	: 06/04/2017
Make	: AUDI A4	Policy No.	: 2100480593
Assignment Date	: 13/04/2017	Excess	: S\$0.00
Date of Inspection	: 11/04/2017	Est. Duration of Repair	: 10.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (HQ) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	51,323.00
Revised Amount	:S\$	35,230.00
Check Items (Estimated)	:S\$	7,591.00
Total	:S\$	42,821.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	145,000.00
COE / PARF Rebate	:S\$	74,115.00
Salvage Value	:S\$	
Margin for Repair	:S\$	70,885.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have not authorise repair.

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 4912C

Vehicle Details

Vehicle No.: SDR6817D
Vehicle to be Exported: No
Intended De-registration Date: 13 Apr 2017
Vehicle Make: AUDI
Vehicle Model: A4 1.4 TFSI S TRONIC
Primary Colour: White
Manufacturing Year: 2016
Engine No.: CVN016665
Chassis No.: WAUZZZF40HA017945
Maximum Power Output: 110.0 kW (147 bhp)
Open Market Value: \$32,163.00
Original Registration Date: 25 Aug 2016
First Registration Date: 25 Aug 2016
Transfer Count: 0
Actual ARF Paid: \$27,029.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 24 Aug 2026
PARF Rebate Amount: \$20,271.00

Intended COE Rebate Details

COE Expiry Date: 24 Aug 2026
COE Category: B - Car (above 1600cc or 97kW (130bhp))
COE Period(Years): 10
QP Paid: \$57,508.00
COE Rebate Amount: \$53,844.00
Total Rebate Amount: \$74,115.00

The information contained herein is correct as at 13 Apr 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.
Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.
Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution
Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/04/2017 19:00
Date Of Accident	06/04/2017 15:05
Exact Location Of Accident	WEST COAST ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDR6817D
Insured/Policyholder	
Name Of Registered Owner	SASUADIMAI JEGANDHAS
NRIC No	S7764912C
Email Address	JEGANDHAS1@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-91992560
Alternative Phone No	OTHERS-66840895

Vehicle Particulars

Manufacturer	AUDI
Model	A4-1.4 TFSI S TRONIC (A)

Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
--	-------------

Are you claiming under your own insurance policy for repair to your vehicle?	YES
--	-----

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO

Policy Number	
Cover Note Number	

Driver

Name of Driver	SASUADIMAI JEGANDHAS
NRIC No	S7764912C
Date Of Birth	03/06/1977
Occupation	INDOOR
Date Of Driving Pass	18/06/2008
Driving Experience	8 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91992560
Fax Number	
Contact Number	OTHERS-66840895
EMail Address	JEGANDHAS1@YAHOO.COM.SG

Address

BLK 408 YISHUN AVE 6
#06-1266

Postcode

S760408

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle

-
-
-

Insurance Company of Driver's Own Vehicle

-
-
-

General Information of the Accident

Type Of Accident

COLLISION- HEAD TO REAR (INSURED HIT TP)

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

TRAVELLING ALONG WEST COAST ROAD WHEN VEHICLE IN FRONT GBC583U STOP SUDDENLY. COULD NOT REACT IN TIME AND COLLIDED WITH THE CAR IN FRONT.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBC583U

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8 Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

WEST COAST ROAD
[A] [B] [C] [D] [E] [F] [G] [H] [I] [J] [K] [L] [M] [N] [O] [P] [Q] [R] [S] [T] [U] [V] [W] [X] [Y] [Z]

A7506817P
B7605830

Describe Circumstances of the Accident

Travelling along West Coast Road when vehicle in front GDC5P231
slows suddenly could not react in time & collided with the car
in front

We declare the foregoing particulars are true in every respect

Witnessed by Reporting Centre
Personnel

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7764912C



Name

SASUADIMAI JEGANDHAS

சசுஅதிமை ஜெகந்தாஸ்

Race

INDIAN

Date of birth

03-06-1977

Sex

M

S7764912C

Country of birth

INDIA

REPUBLIC OF SINGAPORE



8911714

NRIC No. S7764912C



Nationality

INDIAN

Date of issue

25-02-2008

APT BLK 408 YISHUN AVENUE 3 #01-1266
SINGAPORE 760408

NRIC No: S7764912C

Date: 19/05/2011

No: 888882

Class 2B Motorcycles <= 200 cc 18 Jun 2008
Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg 18 Jun 2008



License No: S7764912C

NP 428A



CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 109)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1980
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

HOTLINE TEL: (65) 8419 3300
FAX: (65) 6415-3723

M.X.1

1. APPLICANT'S NAME OR FIRM	OWN DAMAGE EXCESS	\$5000.00
2. CERTIFICATE NO. 2004000100000	WINDSCREEN EXCESS	\$5100.00
3. VEHICLE REGISTRATION NO.	SUM INSURED	RM 100,000
4. NAME OF INSURED	INSURING WITH CO-PARTY	YES
5. EFFECTIVE DATE OF THE COMMENCEMENT OF INSURANCE FOR THE PURPOSES OF THE ACT	DATE OF EXPIRY OF INSURANCE	21/06/2018
6. DATE OF EXPIRY OF INSURANCE	PERSON OR CLASS OF PERSONS ENTITLED TO DRIVE	ANY PERSON
7. PERSON OR CLASS OF PERSONS ENTITLED TO DRIVE	SUBJECT TO AGE CONDITION AT AGE CONDITION	ANY PERSON
8. LIMITATION AS TO USE	APPROVED REPORTING ENGINEER (A.R.E.) AND APPROVED FRAMEERS	ANY PERSON
9. APPROVED REPORTING ENGINEER (A.R.E.) AND APPROVED FRAMEERS	APPROVED REPORTING ENGINEER (A.R.E.) AND APPROVED FRAMEERS	ANY PERSON
10. LOSS OF USE	LOSS OF USE	ANY PERSON
11. HIRE PURCHASE COMPANY	HIRE PURCHASE COMPANY	ANY PERSON
12. EMPLOYER'S NAME	EMPLOYER'S NAME	ANY PERSON

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 109) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore 26 Aug 2016

AIG Asia Pacific Insurance Pte. Ltd.

504125-200
PREMIUM LEASING - AP
281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE
LENTHE SINGAPORE 159936

AUTHORISED REPRESENTATIVE

ORIGINAL

FLYCO

AIG Building, 7B Shenton Way #07-16 Singapore 079120

Copyright © 2013 AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.

Important: Keep this document in your car

1. The first of these is the fact that the
 2. second of these is the fact that the
 3. third of these is the fact that the
 4. fourth of these is the fact that the
 5. fifth of these is the fact that the
 6. sixth of these is the fact that the
 7. seventh of these is the fact that the
 8. eighth of these is the fact that the
 9. ninth of these is the fact that the
 10. tenth of these is the fact that the

Policy terms and conditions apply. Please call our customer service hotline number (85) 8419-3000 for assistance.

Steps to activate Loss of Use / Car Replacement Benefit and Important Information

- For use of Rental Car in Malaysia, additional excess liability of \$2,000 applies.**

If owner fails to inform Premium Automobiles Pte Ltd that he is traveling into Malaysia using the Rental Car and if any accident happens, the entire cost of repair will be the owner's sole responsibility. Premium Automobiles Pte Ltd reserves the right to pursue the full repair cost against the owner.

Additional egg requirement

Minimum 23 years old to maximum 65 years old with at least 2 years of driving experience

Premium Automobiles Pte Ltd Operations Hours

Monday to Friday: 0900hrs - 1800hrs
Saturday: 0900hrs to 1300hrs except Sundays and Public Holidays
Customer Service Line: 64741223 Facsimile: 67467623
55 Ubi Road 1 Singapore 408899

***Premium Automobiles' Terms & Conditions apply**

IMPORTANT NOTICE
If you sell your motor vehicle, this Notice is IMPORTANT and MUST be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The insured is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

The Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agree to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

Catherine Chong (LKK Auto)

From: Claims Department <claims@premiumauto.com.sg>
Sent: Wednesday, 12 April, 2017 8:14 PM
To: 'Catherine Chong (LKK Auto)'
Cc: 'Claims Department'
Subject: RE: Request Certificate Insurance for vehicle no. SDR 6817D

Dear Catherine,

CI number is 2100480593-00001.

Hope the above information helps.

Many thanks!

Claims Advisor

Tan Eng Su Jeffery

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 12 April, 2017 1:11 PM
To: 'Claims Department'
Subject: RE: Request Certificate Insurance for vehicle no. SDR 6817D

Dear Jeffrey,

Kindly provide us the policy number.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0357/2017/CCS
Date : 10-Apr-17

Vehicle in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Sasuadimai Jegandhas
Address : Blk 408 Yishun Avenue 6
#06-1266
Singapore 760408
Telephone : (HP) 91992560
Type of Claim : Own Damage Claim
Policy No. :
Vehicle No : **SDR 6817 D**
Model Code : Audi A4 SEDAN 1.4 TFSI
Model / Year : ~~Apr-17~~ Aug-16
Engine No : CVN 016665
Chassis No : WAUZZZF40HA017945
Mileage : -
Date In : 6-Apr-17
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 6-Apr-17
Place of Accident : West Coast Road

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before after start of painting
- To display damaged parts for inspection
- Parts prices are subject to quotation
- Third party survey is on a "With and without" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDR 6817 D.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$	360.00 ✓	360
2	To remove and transfer aircon condenser, radiator, additional radiator, electrical fans and control unit. To carry out vacuum / regas and to pressurise cooling system.	S/N \$	960.00 ✓	960
3	To dismantle front bumper, both front fenders and bonnet. Renew front lock carrier and align to position. Renew front bumper, both front fenders, bonnet, bonnet hinges and both headlights. Re-organise front crash management components. Reinstall all parts removed.	\$	5,400.00 3500	3500
4	To dismantle and renew intake manifold and charged air cooler.	S/N \$	900.00 X	X
5	To dismantle both front door panel trims. Renew window slot chrome trims. Reinstall all parts removed.	\$	900.00 500	500
6	To respray front bumper, both front fenders, bonnet, hinges and both front doors.	\$	4,600.00 3300	3300
7	To carry out diagnostic check.	S/N \$	192.00 ✓	192
TOTAL LABOUR CHARGES		:	\$ 13,312.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDR 6817 D.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Delomed</i>	\$ 1,703.00	<i>1362.40</i> X
2	FRONT BUMPER SECURING STRIP <i>new</i>	2 \$ 57.00	X
3	FRONT BUMPER GRILLE - CENTER <i>new damaged</i>	\$ 163.00	<i>130.00</i>
4	FRONT BUMPER AIR GUIDE - LH/RH <i>new</i>	2 \$ 134.00	X
5	RADIATOR GRILLE <i>new</i>	\$ 941.00	<i>752.40</i>
6	FRONT REINFORCEMENT BEAM <i>Best</i>	\$ 674.00	<i>529.20</i>
7	FRONT REINFORCEMENT BEAM BRCKET - LH/RH <i>Best</i>	2 \$ 356.00	<i>284.80</i>
8	FRONT REINFORCEMENT BEAM BOLT SET <i>new</i>	\$ 82.00	X
9	FRONT BUMPER GUIDE - LH/RH <i>new LH Md</i>	2 \$ 62.00	<i>31 23.20</i>
10	FRONT BUMPER TOP COVER <i>Delomed</i>	\$ 104.00	<i>82.80</i>
11	BONNET RELEASE LEVER <i>new damaged</i>	\$ 12.00	<i>9.04</i>
12	FRONT BUMPER FOAM - INNER <i>Delomed</i>	\$ 101.00	<i>80.80</i>
13	FRONT LOCK CARRIER BRACKET <i>new</i>	\$ 112.00	<i>89.20</i>
14	FRONT BUMPER SUPPORT - LH/RH <i>new damaged</i>	2 \$ 46.00	<i>36.00</i>
15	EXTERNAL TEMPERATURE SENSOR <i>new</i>	\$ 51.00	X
16	EXTERNAL TEMPERATURE SENSOR BRACKET <i>new</i>	\$ 15.00	<i>12.00</i>
17	FRONT FENDER - LH/RH <i>Dislodged</i>	2 \$ 1,286.00	<i>1028.80</i>
18	FRONT FENDER ATTACHMENT PARTS <i>not new</i>	\$ 88.00	X
19	FRONT FENDER CLOSING ELEMENT - LH/RH <i>new</i>	2 \$ 58.00	<i>44.00</i>
20	FRONT FENDER BRACKET - FRONT LH/RH <i>new</i>	2 \$ 58.00	<i>46.40</i>
SUB TOTAL SPARE PARTS		\$ 6,103.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDR 6817 D.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	FRONT FENDER BRACKET - CENTER LH/RH <i>Not New</i>	2 \$	84.00 x
22	FRONT FENDER RIVET SET <i>Not New</i>	\$	34.00 -
23	FRONT FENDER BRACKET - REAR LH/RH <i>Not New</i>	2 \$	29.00 x
24	FRONT FENDER BRACE - LH/RH <i>Not New</i>	2 \$	200.00 x
25	FRONT WHEEL SPOILER - LH/RH <i>Not New</i>	2 \$	122.00 x
26	FRONT FENDER STONE CHIP GUARD - LH/RH <i>New</i>	2 \$	90.00 <i>69.20</i>
27	FRONT WHEEL HOUSING LINER - LH/RH <i>Not New</i>	2 \$	416.00 x
28	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>Not New</i>	2 \$	152.00 x
29	LED HEADLIGHT - LH/RH <i>Cracked</i>	2 \$	15,722.00 <i>12577.60</i>
30	MAIN LIGHT POWER MODULE <i>2H Pkgd</i>	2 \$	1,282.00 <i>512.80</i>
31	CONTROL UNIT FOR LIGHT CONTROL <i>2H Pkgd</i>	2 \$	1,268.00 <i>507.20</i>
32	HEADLIGHT COMPENSATING PIECE SET <i>Pkgd</i>	\$	208.00 <i>26.80</i>
33	HEADLIGHT WASHER CYLINDER - LH/RH <i>Not New</i>	2 \$	360.00 x
34	HEADLIGHT WASHER CYLINDER BRACKET <i>New</i>	2 \$	10.00 x
35	WASHER HOSE <i>Not New</i>	\$	75.00 x
36	BONNET <i>Distorted</i>	\$	2,001.00 <i>1600.80</i>
37	BONNET ATTACHMENT PARTS <i>New</i>	\$	103.00 <i>82.00</i>
38	BONNET HINGE - LH/RH <i>Not New</i>	2 \$	514.00 x
39	BONNET IMPACT PROTECTION - CENTER <i>New</i>	\$	23.00 <i>13.16</i>
40	BONNET IMPACT PROTECTION - LH/RH <i>New</i>	2 \$	46.00 <i>36.32</i>
SUB TOTAL SPARE PARTS		\$ 22,739.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDR 6817 D.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	HEADLIGHT TOP TRIM - LH/RH <i>na</i>	2 \$ 38.00	✓ 29.28
42	FRONT FENDER TOP COVER - OUTER LH/RH <i>na</i>	2 \$ 48.00	✓ 37.76
43	FRONT FENDER TOP COVER - INNER LH/RH <i>na</i>	2 \$ 104.00	✓ 81.92
44	BONNET DAMPER <i>na na</i>	2 \$ 196.00	X
45	BONNET STRIKER - LH/RH <i>Bent</i>	2 \$ 86.00	✓ 67.68
46	BONNET LOCK <i>2nd</i>	2 \$ 360.00	✓ 288
47	BONNET BOWDEN CABLE <i>2nd</i>	\$ 49.00	✓ 38.64
48	BONNET BOWDEN CABLE COVER <i>from</i>	\$ 9.00	✓ 6.72
49	FRONT WINDSCREEN COVER - LOWER <i>na na</i>	\$ 81.00	X
50	SIGN ' CAUTION ' STICKER <i>na</i>	\$ 12.00	✓ 9.04
51	STICKER FOR AIR CONDITIONER <i>na</i>	\$ 6.00	✓ 4.64
52	FRONT LOCK CARRIER <i>Cracked</i>	\$ 878.00	✓ 702.40
53	FRONT LOCK CARRIER AIR GUIDE - LH/RH <i>Del'd</i>	2 \$ 44.00	✓ 34.88
54	FRONT LOCK CARRIER AIR GUIDE - UPPER LH/RH <i>Del'd</i>	2 \$ 20.00	✓ 14.72
55	A/C CONDENSER <i>Del'd</i>	\$ 525.00	✓ 419.60
56	RADIATOR <i>Del'd</i>	\$ 576.00	✓ 460.40
57	RADIATOR RUBBER BUSH SET <i>na</i>	\$ 38.00	✓ 29.44
58	COOLANT <i>na</i>	\$ 132.00	✓ 105.28
59	ADDITIONAL RADIATOR <i>na na</i>	\$ 444.00	X
60	RADIATOR FAN RING <i>Cracked</i>	\$ 222.00	✓ 177.20
SUB TOTAL SPARE PARTS		\$ 3,868.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDR 6817 D.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
61	RADIATOR FAN WITH CONTROL UNIT <i>Revised.</i>	\$ 1,949.00	7 1559.20
62	CHARGE AIR COOLER <i>me ~</i>	\$ 625.00	X
63	CHARGE AIR COOLER SEAL <i>me ~</i>	\$ 27.00	X
64	INTAKE MANIFOLD <i>me ~</i>	\$ 505.00	X
65	THROTTLE VALVE ADAPTER <i>me ~</i>	\$ 1,037.00	X
66	THROTTLE VALVE ADAPTER SEAL <i>me ~</i>	\$ 15.00	X.
67	FRONT WINDOW SLOT SEAL - LH/RH <i>cut</i>	2 \$ 518.00	✓ 414.40
68	FRONT NO. PLATE <i>Best</i>	S/N \$ 25.00	✓ 25.00
69	SUNDRIES <i>me ~</i>	\$ 600.00	3560. 3560
TOTAL SPARE PARTS		:	\$ 38,011.00
TOTAL LABOUR CHARGES		:	\$ 13,312.00
GRAND TOTAL		:	\$ 51,323.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 11/04/17
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 10 Days

LKK Auto Consultants hence
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be approved and is subject to final approval from Ins.


Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd



Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dep

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0357/2017/CCS

22-Apr-17

CHANG

1 of 1

SDR 6817 D

Audi A4 SEDAN 1.4 TFSI

Quantity	Description	Unit Price	Amount
----------	-------------	------------	--------


Parts

1	BONNET BOWDEN CABLE - OUTER <i>2pc</i>	\$ 49.00	✓
2	AIRCOND PRESSURE SWITCH CONNECTOR <i>1pc</i>	\$ 20.00	✓
3	AIR FILTER INTAKE AIR DUCT - RH <i>1pc</i>	\$ 17.00	✓
4	AIR FILTER INTAKE AIR GUIDE <i>1pc</i>	\$ 30.00	✓
5	TIMING BELT COVER - UPPER <i>1pc</i>	\$ 63.00	✓

TOTAL PARTS : \$ 179.00

GRAND TOTAL : \$ 179.00

For Premium Automobiles Pte Ltd



Authorised Signature

Adrian Ling
24/04/17.
fl.s.

Janice Lee (LKKAUTO)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Tuesday, June 20, 2017 7:28 PM
To: Adrian Ling (LKKAUTO); SUR; Carrine Leong; Nora Khai; Chang Chee Sing
Subject: FINAL REVISION SDR6817D - OD AIG - SURVEYED 11 APR 17
Attachments: PA03572017 - SDR 6817 D - A4 SEDAN 1.4 TFSI - FRONT (AIG) + SUPP.xls

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$33,446.44 @ 18 days of repairs exclude 3 Sundays and 1 Public Holiday. Please discuss with Mr. Chang/Jeff Tan if days of repairs is not allowed.

You resurveyed on 24 April for check items and added parts.

Your early closure is well appreciated.

Thank you n best regards - jb

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg


Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0357/2017/CCS
Date : 10-Apr-17

Vehicle in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120



Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Sasuadimai Jegandhas
Address : Blk 408 Yishun Avenue 6
#06-1266
Singapore 760408
Telephone : (HP) 91992560
Type of Claim : Own Damage Claim
Policy No. :
Vehicle No : **SDR 6817 D**
Model Code : Audi A4 SEDAN 1.4 TFSI
Model / Year : Apr-17
Engine No : CVN 016665
Chassis No : WAUZZZF40HA017945
Mileage : -
Date In : 6-Apr-17
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 6-Apr-17
Place of Accident : West Coast Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDR 6817 D.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
			\$ 4,521.04
21	FRONT FENDER BRACKET - CENTER LH/RH	2 \$ 84.00	
22	FRONT FENDER RIVET SET	\$ 34.00	
23	FRONT FENDER BRACKET - REAR LH/RH	2 \$ 29.00	
24	FRONT FENDER BRACE - LH/RH	2 \$ 200.00	
25	FRONT WHEEL SPOILER - LH/RH	2 \$ 122.00	
26	FRONT FENDER STONE CHIP GUARD - LH/RH	2 \$ 90.00	\$ 69.20
27	FRONT WHEEL HOUSING LINER - LH/RH	2 \$ 416.00	
28	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	2 \$ 152.00	
29	LED HEADLIGHT - LH/RH	2 \$ 15,722.00	\$ 12,577.60
30	MAIN LIGHT POWER MODULE	2 \$ 1,282.00	\$ 512.80
31	CONTROL UNIT FOR LIGHT CONTROL	2 \$ 1,268.00	\$ 507.20
32	HEADLIGHT COMPENSATING PIECE SET	\$ 208.00	\$ 26.80
33	HEADLIGHT WASHSER CYLINDER - LH/RH	2 \$ 360.00	
34	HEADLIGHT WASHSER CYLINDER BRACKET	2 \$ 10.00	
35	WASHER HOSE	\$ 75.00	
36	BONNET	\$ 2,001.00	\$ 1,600.80
37	BONNET ATTACHMENT PARTS	\$ 103.00	\$ 82.00
38	BONNET HINGE - LH/RH	2 \$ 514.00	
39	BONNET IMPACT PROTECTION - CENTER	\$ 23.00	\$ 18.16
40	BONNET IMPACT PROTECTION - LH/RH	2 \$ 46.00	\$ 36.32
SUB TOTAL SPARE PARTS		\$ 22,739.00	\$ 19,951.92

15430.88

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDR 6817 D.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
			\$ 19,951.92
41	HEADLIGHT TOP TRIM - LH/RH	2 \$ 38.00	\$ 29.28
42	FRONT FENDER TOP COVER - OUTER LH/RH	2 \$ 48.00	\$ 37.76
43	FRONT FENDER TOP COVER - INNER LH/RH	2 \$ 104.00	\$ 81.92
44	BONNET DAMPER	2 \$ 196.00	
45	BONNET STRIKER - LH/RH	2 \$ 86.00	\$ 67.68
46	BONNET LOCK	2 \$ 360.00	\$ 288.00
47	BONNET BOWDEN CABLE	\$ 49.00	\$ 38.64
48	BONNET BOWDEN CABLE COVER	\$ 9.00	\$ 6.72
49	FRONT WINDSCREEN COVER - LOWER	\$ 81.00	
50	SIGN ' CAUTION ' STICKER	\$ 12.00	\$ 9.04
51	STICKER FOR AIR CONDITIONER	\$ 6.00	\$ 4.64
52	FRONT LOCK CARRIER	\$ 878.00	\$ 702.40
53	FRONT LOCK CARRIER AIR GUIDE - LH/RH	2 \$ 44.00	\$ 34.88
54	FRONT LOCK CARRIER AIR GUIDE - UPPER LH/RH	2 \$ 20.00	\$ 14.72
55	A/C CONDENSER	\$ 525.00	\$ 419.60
56	RADIATOR	\$ 576.00	\$ 460.40
57	RADIATOR RUBBER BUSH SET	\$ 38.00	\$ 29.44
58	COOLANT	\$ 132.00	\$ 105.28
59	ADDITIONAL RADIATOR	\$ 444.00	
60	RADIATOR FAN RING	\$ 222.00	\$ 177.20
SUB TOTAL SPARE PARTS		\$ 3,868.00	\$ 22,459.52

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

2507.66

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDR 6817 D.

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
		cf	\$ 22,459.52
61	RADIATOR FAN WITH CONTROL UNIT	\$ 1,949.00	\$ 1,559.20
62	CHARGE AIR COOLER	\$ 625.00	
63	CHARGE AIR COOLER SEAL	\$ 27.00	
64	INTAKE MANIFOLD	\$ 505.00	
65	THROTTLE VALVE ADAPTER	\$ 1,037.00	
66	THROTTLE VALVE ADAPTER SEAL	\$ 15.00	
67	FRONT WINDOW SLOT SEAL - LH/RH	2 \$ 518.00	\$ 414.40
68	FRONT NO. PLATE	S/N \$ 25.00	\$ 25.00
69	SUNDRIES	\$ 600.00	\$ 35.60
	TOTAL SPARE PARTS	:	\$ 38,011.00 \$ 24,634.44 24493.72
	TOTAL LABOUR CHARGES	:	\$ 13,312.00 \$ 8,812.00
	GRAND TOTAL	:	\$ 51,323.00 \$ 33,446.44

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

2034, 2

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315	Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0357/2017/CCS 22-Apr-17 CHANG 1 of 1 SDR 6817 D Audi A4 SEDAN 1.4 TFSI
--	---	---

Quantity	Description	Unit Price	Amount
Parts			
1	BONNET BOWDEN CABLE - OUTER <i>new d</i>	\$ 49.00	
2	AIRCOND PRESSURE SWITCH CONNECTOR <i>new d</i>	\$ 20.00	
3	AIR FILTER INTAKE AIR DUCT - RH <i>new</i>	\$ 17.00	
4	AIR FILTER INTAKE AIR GUIDE <i>new</i>	\$ 30.00	
5	TIMING BELT COVER - UPPER <i>new</i>	\$ 63.00	
TOTAL PARTS :		\$ 179.00	
GRAND TOTAL :		\$ 179.00	

Adrian Ling
[Signature]

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SDR 6817 D

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0357/2017/MAS

29 March 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SDR 6817 D, Audi A4 Sedan 1.4 TFSI S-Tro

With reference to the above-mentioned vehicle, no. **SDR 6817 D**, claimant, **Mr. Sasuadimai Jegandhas**, please find the related document per attached.

1. A copy of the Original invoice no. 85012292– S\$34,995.12
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SDR 6817 D

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408609
Telephone 6388 2323

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 1 18:04

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012292 Date : 27/03/2018 Order : SDR6817D Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SDR6817D (V 30994)	Regn Date: 25/08/2016	Mileage: 50133	WIP No.: 19588
Model: A4 SEDAN 1.4 TFSI S tronic	Chassis: WAUZZZF40HA017945	Engine: CVN 016665	Dept: U
VSB No.:			
You have been assisted by :- UB-Carrine (87)			

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	360.00	1.00	360.00
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE.	25.00	1.00	25.00
Q	EXC	M: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	M: TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR, ADDITIONAL RADIATOR, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM / REGAS AND TO PRESSURIS COOLING SYSTEM.	960.00	1.00	960.00
S	BODYWORK	M: TO DISMANTLE FRONT BUMPER, BOTH FRONT FENDERS AND BONNET. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RENEW FRONT BUMPER, BOTH FRONT FENDERS, BONNET AND BOTH HEADLIGHTS. RE-ORGANISE FRONT CRAS	3500.00	1.00	3,500.00

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408688
Telephone 6388 2323

Customer Service
Service Appointment
24-hour Breakdown Service
Email customer.care@premiumauto.com.sg
6366 2323
9828 1233

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 2 18:04

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012292 Date : 27/03/2018 Order : SDR6817D Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SDR6817D (V 30994)	Regn Date: 25/08/2016	Mileage: 50133	WIP No.: 19588
Model: A4 SEDAN 1.4 TFSI S tronic	Chassis: WAUZZZF40HA017945	Engine: CVN 016665	Dept: U
USB No.:			
You have been assisted by :- UB-Carrine (87)			

		Details	Qty	Unit Price	Amount
S	BODYWORK	MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED M: TO DISMANTLE BOTH FRONT DOOR PANEL TRIMS. RENEW WINDOW SLOT CHROME TRIMS. REINSTALL ALL PARTS REMOVED.	500.00	1.00	500.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET AND BOTH FRONT DOORS.	3300.00	1.00	3,300.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK.	192.00	1.00	192.00
X	A8W0853824A 9B9	STONEGUARD(A)	Less 020%	1.00	44.40
X	AG A13A8JM1	COOLANT ADDITIVE	Less 020%	4.00	32.90
X	A8W0853651 3FZ	GRILLE	Less 020%	1.00	940.50
X	A8W0941773A	HEADLIGHT	Less 020%	1.00	7861.00
X	A8W0941774A	HEADLIGHT	Less 020%	1.00	7861.00
X	A8W0821105A	FENDER	Less 020%	1.00	643.00
X	A8W0821106A	FENDER	Less 020%	1.00	643.00
X	A8W0823029A	HOOD	Less 020%	1.00	2001.00

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Telephone 6385 2323

Customer Service
Service Appointment
24-hour Breakdown Service
Email customer.care@premiumauto.com.sg
6366 2323
9828 1233

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 3 18:04

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012292 Date : 27/03/2018 Order : SDR6817D Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SDR6817D (V 30994)	Regn Date: 25/08/2016	Mileage: 50133	WIP No.: 19588
Model: A4 SEDAN 1.4 TFSI S tronic	Chassis: WAUZZZF40H0017945	Engine: CVN 016665	Dept: U
VSB No.:			
You have been assisted by :- UB-Carrine (87)			

		Details	Qty	Unit Price	Amount
X	A0W0007065C GRU	COVER	1.00	1703.00	1,362.40
X	A0W0007001	COVER	1.00	103.50	82.80
X	A0W0121251K	RADIATOR	1.00	575.50	460.40
X	A0W0016421H	CONDENSER	1.00	524.50	419.60
X	A0W0005594	CARRIER	1.00	878.00	702.40
X	A0W0959455C	ELECTRIC F	1.00	1949.00	1,559.20
X	A0W0007550A	FOAM INSER	1.00	101.00	80.80
X	A0W0007113	BRACKET	1.00	674.00	539.20
X	A0K0973703	HOUSING	1.00	13.70	10.96
X	A0W0098615	ATT PARTS	1.00	102.50	82.00
X	A4M0121275A	MOUNTING	2.00	7.70	12.32
X	A4M0121268A	MOUNTING	2.00	10.70	17.12
X	A0W0007334	SUPPORT	1.00	22.50	18.00
X	A0W0007333	SUPPORT	1.00	22.50	18.00
X	A0W0021467	BRACKET	1.00	29.00	23.20
X	A4G8806305	SPACER	1.00	33.50	26.80
X	A0W0021468	BRACKET	1.00	29.00	23.20
X	A0W0007283	GUIDE	1.00	29.00	23.20

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408609
Telephone 6388 2323

Customer Service
Service Appointment
24-hour Breakdown Service
Email customer.care@premiumauto.com.sg
6366 2323
9828 1233

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 4 18:04

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012292 Date : 27/03/2018 Order : SDR6817D Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SDR6817D (V 30994) Regn Date: 25/08/2016 Mileage: 50133 WIP No.: 19588

Model: A4 SEDAN 1.4 TFSI S tronic Chassis: WAUZZZF40HA017945 Engine: CVN 016665 Dept: U

VSU No.:

You have been assisted by :- UB-Carrine (87)

		Details	Qty	Unit Price	Amount
X	A0W0021092	PLATE	1.00	26.20	26.20
X	A0W0023185B	CATCH	1.00	42.30	42.30
X	A0W0023186B	CATCH	1.00	42.30	42.30
X	A0W0007133	BRACKET	1.00	178.00	178.00
X	A0W0007134	BRACKET	1.00	178.00	178.00
X	A0W0121673A	AIR DUCT	1.00	9.20	9.20
X	A0W0121674A	AIR DUCT	1.00	9.20	9.20
X	A0W0023661D	LEVER(A)BB01-B-2	1.00	11.30	11.30
X	A0W0020536	BRACKET	1.00	15.00	15.00
X	A0W0023509B	LATCH	2.00	100.00	200.00
X	A0W0023745	COVER	1.00	18.30	18.30
X	A0W0023746	COVER	1.00	18.30	18.30
X	A0W0021091	PLATE	1.00	28.00	28.00
X	A4H0023543	COVER	1.00	8.40	8.40
X	A0W0020581B	COVER	1.00	23.60	23.60
X	A0W0023125	PROTECTION	1.00	22.70	22.70
X	A0W0023126	PROTECTION(A)BB09-D-	1.00	22.70	22.70
X	A4E0260749A	WASHER	1.00	3.10	3.10

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Telephone 6388 2323

Customer Service
Service Appointment
24-hour Breakdown Service
Email customer.care@premiumauto.com.sg
6366 2323
9828 1233

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 5 18:04

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012292 Date : 27/03/2016 Order : SDR6817D Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SDR6817D (V 30994) Regn Date: 25/08/2016 Mileage: 50133 WIP No.: 19588

Model: A4 SEDAN 1.4 TFSI S tronic Chassis: WAUZZZF40HA017945 Engine: CVN 016665 Dept: U

VSF No.:

You have been assisted by :- UB-Carrine (07)

		Details	Qty	Unit Price	Amount
X	A3D0260749C	WASHER	1.00	3.70	2.96
X	A8K0005399B	BOLT	2.00	1.40	2.24
X	A8W0023529E	BOWD CABLE	1.00	48.30	38.64
X	A8W0020582B	COVER	1.00	23.60	18.88
X	A8W0021170C	COVER	1.00	51.20	40.96
X	A8W0007683 9B9	GRILLE	1.00	162.50	130.00
X	A8W0021169C	COVER	1.00	51.20	40.96
X	A8W0053823A 9B9	STONEGUARD	1.00	42.10	33.68
X	A8W0010515A	STICKER	1.00	5.80	4.64
X	A8K0010520A	PLATE	1.00	11.30	9.04
X	A8W0121283AR	AIR DUCT	1.00	21.80	17.44
X	A8W0121284AL	AIR DUCT	1.00	21.80	17.44
X	A8W0007771	BRACKET	1.00	111.50	89.20
X	A8W0121207B	COWL	1.00	221.50	177.20
X	A4M0907397AD	CTRL UNIT	1.00	634.00	507.20
X	A7PP941572ABZ00	POWER MOD	1.00	641.00	512.80
X	AHHT001308	NUT	6.00	1.10	5.28
X	AN 91093901	RIVET	4.00	0.60	1.92

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6366 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Telephone 6386 2323

Customer Service
Service Appointment
24-hour Breakdown Service
Email customer.care@premiumauto.com.sg
6366 2323
9828 1233

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 6 18:04

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012292 Date : 27/03/2018 Order : SDR6817D Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SDR6817D (V 30994)	Regn Date: 25/08/2016	Mileage: 50133	WIP No.: 19588
Model: A4 SEDAN 1.4 TFSI S tronic	Chassis: WAUZZZF40HA017945	Engine: CVN 016665	Dept: U
VSB No.:			
You have been assisted by :- UB-Carrine (87)			

		Details	Qty	Unit Price	Amount
X	AN 0385053	RIVET	6.00	0.30	1.44
X	AN 90511508	NUT	4.00	1.60	5.12
X	AN 90808203	BOLT	4.00	1.00	3.20
X	A8W0853284B 2ZZ	WINDOW SLD	1.00	259.00	207.20
X	A8W0853283B 2ZZ	WINDOW SLD	1.00	259.00	207.20
X	A8W0823124	PROTECTION	1.00	22.70	18.16

Parts 24,468.72	Sub-Total	32,705.72
Labour 0.00	7% GST	2,289.40
Sublet 8,837.00	Grand Total	34,995.12
Menus 0.00		
Lubricant 0.00		



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SDR 6817 D

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0357/2017/JT
05th May 2017

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE : CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A4 SEDAN 1.4 TFSI S tronic
Vehicle Chassis No. : WAUZZZF40HA017945
Vehicle Regn No. : **SDR 6817 D**
Vehicle Mileage : 50133 Km
Vehicle Owner : Mr. Sasuadimai Jegandhas
Certificate No : 2100480593-000001
Policy Excess : **S\$642.00 (inclusive of 7% GST)**
Accident Date : 06th April 2017
Place : West Coast Road
Repair Cost : \$ 34,995.12
WIP No. : 19588
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time :
Date : 09/05/2017

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7764912C



Name

SASUADIMAI JEGANDHAS

சேசுடிமை ஜெகன் தாஸ்

Race

INDIAN

Date of birth

03-06-1977

Sex

M

S77B4912C

Country of birth

INDIA

REPUBLIC OF SINGAPORE DRIVING LICENCE



001615797

8911714



NRIC No. S7764912C



Nationality

INDIAN

Date of issue

25-02-2008

APT BLK 408 YISHUN AVENUE 6 #06-1266
SINGAPORE 760408

NRIC No: S7764912C

Date: 19/05/2011

No: 6838802

YOU ARE LICENCED TO DRIVE VEHICLES IN THE FOLLOWING CATEGORIES

Class 2B Motorcycles =< 200 cc
Class 3 Motor Cars =< 3000kg with =< 7 passengers, exclusive of the driver; and other motor vehicles =< 2500kg

18 Jun 2008

18 Jun 2008



Licence No: S7764912C

NP 428A

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Apr 2017		13 Apr 2017 09:35 Edit Adj Rpt	S\$33,305.72 Edit Estimates	S\$33,305.72 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS			[Created by insurer]
Insured:	SASUADIMAI JEGANDHAS, ID: S7764912C, Tel: +6591992560,		Email: jegandhas1@yahoo.com.sg
Vehicle Reg. No.:	SDR6817D	Date of Loss:	06/04/2017 00:00 - :59
Claim Type:	OD / 1338334096SG	Policy/Cover Note No.:	2100480593 (Comprehensive)
		Excess:	S\$600.00
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Dally Amri, Mimi Zarina] MimiZarina.DallyAmri@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 25/04/2017]		
Driver/Custodian:	SASUADIMAI JEGANDHAS (39 / Male), NRIC: S7764912C, Tel: +6591992560		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
- AIG_SG (17/04/2017): Alert - Adj Mandate Approved (S\$35230.00) - SDR6817D - Claim Handler: Dally Amri... - AIG_SG (13/04/2017): SDR6817D / OD / 06/04/2017 / Coverage & Excess update		

ALL ASSOCIATED TASKS						View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SDR6817D (1338334096SG)**

OD

Apr 6 2017 12:00AM

[SASUADIMAI JEGANDHAS]

Premium Automobiles Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser v	
----------------------------------	--	-------------------------------	------------------------------------	------------------------------	------------------------------	--	--

Assessment Reports					1 per page v	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	13/04/17 15:00	Adjuster Immediate Advice		Load HTM		

Photos/Images					3 per page v	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	13/04/17 10:45	General View		Load JPG	☒	
2	13/04/17 10:45	General View		Load JPG	☒	
3	13/04/17 10:45	General View		Load JPG	☒	
4	13/04/17 10:45	General View		Load JPG	☒	
5	13/04/17 10:45	General View		Load JPG	☒	
6	13/04/17 10:45	General View		Load JPG	☒	
7	13/04/17 10:45	General View		Load JPG	☒	
8	13/04/17 10:45	General View		Load JPG	☒	
9	13/04/17 10:45	General View		Load JPG	☒	
10	13/04/17 10:45	General View		Load JPG	☒	
11	13/04/17 10:45	General View		Load JPG	☒	
12	13/04/17 10:45	General View		Load JPG	☒	
13	13/04/17 10:45	General View		Load JPG	☒	
14	13/04/17 10:45	General View		Load JPG	☒	
15	13/04/17 10:45	General View		Load JPG	☒	
16	13/04/17 10:45	General View		Load JPG	☒	
17	13/04/17 10:45	General View		Load JPG	☒	
18	13/04/17 10:45	General View		Load JPG	☒	
19	13/04/17 10:45	General View		Load JPG	☒	
20	13/04/17 10:45	General View		Load JPG	☒	
21	13/04/17 10:45	General View		Load JPG	☒	
22	13/04/17 10:45	General View		Load JPG	☒	
23	13/04/17 10:45	General View		Load JPG	☒	
24	13/04/17 10:45	General View		Load JPG	☒	
25	13/04/17 10:45	General View		Load JPG	☒	
26	13/04/17 10:45	General View		Load JPG	☒	
27	13/04/17 10:45	General View		Load JPG	☒	
28	13/04/17 10:45	General View		Load JPG	☒	
29	13/04/17 10:45	General View		Load JPG	☒	
30	13/04/17 10:45	General View		Load JPG	☒	
31	13/04/17 10:45	General View		Load JPG	☒	
32	13/04/17 10:45	General View		Load JPG	☒	
33	13/04/17 10:45	General View		Load JPG	☒	

34	13/04/17 10:45	General View	1	Load JPG	☒
35	13/04/17 10:45	General View	1	Load JPG	☒
36	13/04/17 10:45	General View	1	Load JPG	☒
37	13/04/17 10:45	General View	1	Load JPG	☒
38	13/04/17 10:45	General View	1	Load JPG	☒
39	13/04/17 10:45	General View	1	Load JPG	☒
40	13/04/17 10:45	General View	1	Load JPG	☒
41	13/04/17 10:45	General View	1	Load JPG	☒
42	13/04/17 10:45	General View	1	Load JPG	☒
43	13/04/17 10:45	General View	1	Load JPG	☒
44	13/04/17 10:45	General View	1	Load JPG	☒
45	13/04/17 10:45	General View	1	Load JPG	☒
46	13/04/17 10:45	General View	1	Load JPG	☒
47	13/04/17 10:45	General View	1	Load JPG	☒
48	13/04/17 10:45	General View	1	Load JPG	☒
49	13/04/17 10:45	General View	1	Load JPG	☒
50	13/04/17 10:45	General View	1	Load JPG	☒
51	13/04/17 10:45	General View	1	Load JPG	☒
52	13/04/17 10:45	General View	1	Load JPG	☒
53	13/04/17 10:45	General View	1	Load JPG	☒
54	13/04/17 10:45	General View	1	Load JPG	☒
55	13/04/17 10:45	General View	1	Load JPG	☒
56	13/04/17 10:45	General View	1	Load JPG	☒
57	13/04/17 10:45	General View	1	Load JPG	☒
58	13/04/17 10:45	General View	1	Load JPG	☒
59	13/04/17 10:45	General View	1	Load JPG	☒
60	13/04/17 10:45	General View	1	Load JPG	☒
61	13/04/17 10:45	General View	1	Load JPG	☒
62	13/04/17 10:45	General View	1	Load JPG	☒
63	13/04/17 10:45	General View	1	Load JPG	☒
64	13/04/17 10:45	General View	1	Load JPG	☒
65	13/04/17 10:45	General View	1	Load JPG	☒
66	13/04/17 10:45	General View	1	Load JPG	☒
67	13/04/17 10:45	General View	1	Load JPG	☒
68	13/04/17 10:45	General View	1	Load JPG	☒
69	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
70	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
71	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
72	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
73	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
74	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
75	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
76	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
77	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
78	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
79	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
80	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
81	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
82	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
83	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒

84	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
85	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
86	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
87	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
88	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
89	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
90	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
91	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
92	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
93	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
94	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
95	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
96	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
97	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
98	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
99	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
100	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
101	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
102	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
103	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
104	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
105	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
106	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
107	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
108	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
109	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
110	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
111	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
112	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
113	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
114	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
115	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
116	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
117	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
118	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
119	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
120	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
121	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
122	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
123	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
124	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
125	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
126	20/03/18 09:55	Reinspection Photo	1	Load JPG	☒
Documentation				1 per page v	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/04/17 10:30	WORKSHOP ESTIMATE	1	Load PDF	
2	13/04/17 10:30	Singapore Accident Statement	1	Load PDF	
3	13/04/17 10:30	Insured Persons NRIC AND DRIVING LICENSE	1	Load PDF	
4	13/04/17 10:30	Certificate of Insurance	1	Load PDF	
5	02/04/18 09:47	Workshop Invoice	1	Load PDF	

Linked Accident Report Documents

View

View in Browser

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	06/04/17 19:18	Accident Statement	1 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	06/04/17 19:06	Accident Photo	1 Load JPG	☒
2	06/04/17 19:06	Accident Photo	1 Load JPG	☒
3	06/04/17 19:06	Accident Photo	1 Load JPG	☒
4	06/04/17 19:06	Accident Photo	1 Load JPG	☒
5	06/04/17 19:06	Accident Photo	1 Load JPG	☒
6	06/04/17 19:06	Accident Photo	1 Load JPG	☒
7	06/04/17 19:06	Accident Photo	1 Load JPG	☒
8	06/04/17 19:06	Accident Photo	1 Load JPG	☒
9	06/04/17 19:06	Accident Photo	1 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	06/04/17 19:15	Sketch Plan	1 Load JPG	☒
2	06/04/17 19:16	Sketch Plan #2	1 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^

v

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG17007273/ARBE2

Date: 02/04/2018

REFERENCE

Insured/Claimant: SASUADIMAI JEGANDHAS Policy No: 2100480593
Date of Loss: 06/04/2017 Nature of Claim: OD Claim No: 1338334096SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDR6817D**
Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A) Engine No: CVN016665
Reg. Date: 25/08/2016 (Man. Year: 2016) Chassis No: WAUZZZF40HA017945
Colour: White Odometer: 0 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$145,000.00
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	38,011.00	24,493.72	13,517.28	35.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,312.00	8,812.00	4,500.00	33.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	51,323.00	33,305.72	18,017.28	35.11
- Excess (\$\$)	600.00	600.00	0.00	0.00
(\$\$)	50,723.00	32,705.72	18,017.28	35.52
+ GST 7.00/7.00% (\$\$)	3,550.61	2,289.40	1,261.21	35.52
Nett Amount (\$\$)	54,273.61	34,995.12	19,278.49	35.52

INSPECTION

Date of Assignment: 13/04/2017

Date Inspected: 11/04/2017 Inspected At:

Premium Automobiles Pte Ltd (HQ)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 18.0 days

Adjuster: ADRIAN LING

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Deformed	1,703.00 FS	*1,362.40 FS
2	2	*FRONT BUMPER SECURING STRIP	Not Necessary	57.00 FS	*- FS
3	1	*FRONT BUMPER GRILLE - CENTER	Damaged	163.00 FS	*130.00 FS
4	2	*FRONT BUMPER AIR GUIDE - LH/RH	Not Necessary	134.00 FS	*- FS
5	1	*RADIATOR GRILLE	Cracked	941.00 FS	*752.40 FS
6	1	*FRONT REINFORCEMENT BEAM	Bent	674.00 FS	*539.20 FS
7	2	*FRONT REINFORCEMENT BEAM BRACKET - LH / RH	Bent	356.00 FS	*284.80 FS
8	1	*SET FRONT REINFORCEMENT BEAM BOLT	Not Necessary	82.00 FS	*- FS
9	1	*FRONT BUMPER GUIDE - LH/RH	N/S Damaged	62.00 FS	*23.20 FS
10	1	*FRONT BUMPER TOP COVER	Deformed	104.00 FS	*82.80 FS
11	1	*BONNET RELEASE LEVER	Damaged	12.00 FS	*9.04 FS
12	1	*FRONT BUMPER FOAM - INNER	Deformed	101.00 FS	*80.80 FS
13	1	*FRONT LOCK CARRIER BRACKET	Cracked	112.00 FS	*89.20 FS
14	2	*FRONT BUMPER SUPPORT - LH/RH	Damaged	46.00 FS	*36.00 FS
15	1	*EXTERNAL TEMPERATURE SENSOR	Not Necessary	51.00 FS	*- FS
16	1	*EXTERNAL TEMPERATURE SENSOR BRACKET	Damaged	15.00 FS	*12.00 FS
17	2	*FRONT FENDER - LH/RH	Distorted	1,286.00 FS	*1,028.80 FS
18	1	*FRONT FENDER ATTACHMENT PARTS	Not Necessary	88.00 FS	*- FS
19	2	*FRONT FENDER CLOSING ELEMENT - LH/RH	Damaged	58.00 FS	*44.00 FS
20	2	*FRONT FENDER BRACKET - FRONT LH/RH	Damaged	58.00 FS	*46.40 FS
21	2	*FRONT FENDER BRACKET - CENTER LH/RH	Not Necessary	84.00 FS	*- FS
22	1	*SET FRONT FENDER RIVET	Not Necessary	34.00 FS	*- FS
23	2	*FRONT FENDER BRACKET - REAR LH/RH	Not Necessary	29.00 FS	*- FS
24	2	*FRONT FENDER BRACE - LH/RH	Not Necessary	200.00 FS	*- FS
25	2	*FRONT WHEEL SPOILER - LH/RH	Not Necessary	122.00 FS	*- FS
26	2	*FRONT FENDER STONE CHIP GUARD - LH/RH	Necessary	90.00 FS	*69.20 FS
27	2	*FRONT WHEEL HOUSING LINER - LH/RH	Not Necessary	416.00 FS	*- FS
28	2	*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	152.00 FS	*- FS
29	2	*LED HEADLIGHT - LH/RH	Cracked	15,722.00 FS	*12,577.60 FS
30	1	*MAIN LIGHT POWER MODULE	O/S Damaged	1,282.00 FS	*512.80 FS
31	1	*CONTROL UNIT FOR LIGHT CONTROL	O/S Damaged	1,268.00 FS	*507.20 FS
32	1	*SET HEADLIGHT COMPENSATING PIECE	Damaged	208.00 FS	*26.80 FS
33	2	*HEADLIGHT WASHER CYLINDER - LH/RH	Not Necessary	360.00 FS	*- FS
34	2	*HEADLIGHT WASHER CYLINDER BRACKET	Not Necessary	10.00 FS	*- FS
35	1	*WASHER HOSE	Not Necessary	75.00 FS	*- FS
36	1	*BONNET	Distorted	2,001.00 FS	*1,600.80 FS
37	1	*BONNET ATTACHMENT PARTS	Necessary	103.00 FS	*82.00 FS
38	2	*BONNET HINGE - LH/RH	Not Necessary	514.00 FS	*- FS
39	1	*BONNET IMPACT PROTECTION - CENTER	Necessary	23.00 FS	*18.16 FS
40	2	*BONNET IMPACT PROTECTION - LH/RH	Necessary	46.00 FS	*36.32 FS
41	2	*HEADLIGHT TOP TRIM - LH/RH	Necessary	38.00 FS	*29.28 FS
42	2	*FRONT FENDER TOP COVER - OUTER LH/RH	Necessary	48.00 FS	*37.76 FS
43	2	*FRONT FENDER TOP COVER - INNER LH/RH	Necessary	104.00 FS	*81.92 FS
44	2	*BONNET DAMPER	Not Necessary	196.00 FS	*- FS
45	2	*BONNET STRIKER - LH/RH	Bent	86.00 FS	*67.68 FS
46	2	*BONNET LOCK	Damaged	360.00 FS	*288.00 FS
47	1	*BONNET BOWDEN CABLE	Damaged	49.00 FS	*38.64 FS
48	1	*BONNET BOWDEN CABLE COVER	Damaged	9.00 FS	*6.72 FS
49	1	*FRONT WINDSCREEN COVER - LOWER	Not Necessary	81.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
50	1	*SIGN CAUTION STICKER	Necessary	12.00 FS	*9.04 FS
51	1	*STICKER FOR AIR CONDITIONER	Necessary	6.00 FS	*4.64 FS
52	1	*FRONT LOCK CARRIER	Cracked	878.00 FS	*702.40 FS
53	2	*FRONT LOCK CARRIER AIR GUIDE - UPPER LH/RH	Deformed	20.00 FS	*14.72 FS
54	1	*A/C CONDENSER	Dented	525.00 FS	*419.60 FS
55	1	*RADIATOR	Dented	576.00 FS	*460.40 FS
56	1	*SET RADIATOR RUBBER BUSH	Necessary	38.00 FS	*29.44 FS
57	1	*COOLANT	Necessary	132.00 FS	*105.28 FS
58	1	*ADDITIONAL RADIATOR	Not Necessary	444.00 FS	*- FS
59	1	*RADIATOR FAN RING	Cracked	222.00 FS	*177.20 FS
60	1	*RADIATOR FAN WITH CONTROL UNIT	Damaged	1,949.00 FS	*1,559.20 FS
61	1	*CHARGE AIR COOLER	Not Necessary	625.00 FS	*- FS
62	1	*CHARGE AIR COOLER SEAL	Not Necessary	27.00 FS	*- FS
63	1	*INTAKE MANIFOLD	Not Necessary	505.00 FS	*- FS
64	1	*THROTTLE VALVE ADAPTER	Not Necessary	1,037.00 FS	*- FS
65	1	*THROTTLE VALVE ADAPTER SEAL	Not Necessary	15.00 FS	*- FS
66	2	*FRONT WINDOW SLOT SEAL - LH/RH	Cut	518.00 FS	*414.40 FS
67	1	*FRONT NO. PLATE	Bent	25.00 FS	*25.00 FS
68	1	*SUNDRIES	Necessary	600.00 FS	*35.60 FS
69	2	*FRONT LOCK CARRIER AIR GUIDE - LH/RH	Deformed	44.00 FS	*34.88 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	38,011.00	24,493.72
-------------------	-----------	-----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR, ADDITIONAL RADIATOR, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM / REGAS AND TO PRESSURISE COOLING SYSTEM	New	960.00	960.00
3	TO DISMANTLE FRONT BUMPER, BOTH FRONT FENDERS AND BONNET. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RENEW FRONT BUMPER, BOTH FRONT FENDERS, BONNET, BONNET HINGES AND BOTH HEADLIGHTS. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,400.00	3,500.00
4	TO DISMANTLE AND RENEW INTAKE MANIFOLD AND CHARGED AIR COOLER	New	900.00	0.00
5	TO DISMANTLE BOTH FRONT DOOR PANEL TRIMS. RENEW WINDOW SLOT CHROME TRIMS. REINSTALL ALL PARTS REMOVED	New	900.00	500.00
6	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, HINGES AND BOTH FRONT DOORS	New	4,600.00	3,300.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			13,312.00	8,812.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >