

ASS. REC. BY:

REF:

CS/AWA17008432/Timb

JANICE

Special Instruction:

Surveyor:

Tan Kah Leong

ASSIGNMENT (Office)

From (Person):

Tan Kah Leong

of

AWA

Date/Time:

28/04/2017 10:19am

Estimated Cost:

Bill to:

OD / FP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKT 9776X

Insured:

FBJ 6909M

at Workshop m/s

Motor Image

Tel:

9073 2232

of

19 Toa Payoh Lorong 8

Policy No:

AVMCSB 0013041602

Claim No:

NSV 17 00538 / HLF

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

24/04/2017

CA / REV / REP. / REV 24 HRS 'wp'

25 Leng Kee Road

03/05/2017 @ before 11:30am

H.O.D. Endorsement:

Date/Time:

28/04/2017 10:40am

Person Contacted:

Jeff

Vehicle IN / OUT

Date/Time

Action/Instruction (  ) Estimate

SKT 9776X - x

FBJ 6909M - x

12/6/17

@ 4:37pm Jeff said vehicle has not send in for repair, pending liability

Surveyor: Taufik

REF: AWA

### ASSIGNMENT

From: \_\_\_\_\_ Date: 03/05/2017

Veh No: SKT 8976X Yr Regn: 2015 / June

Estimated Cost: \_\_\_\_\_

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: SKT 8976X

Make: Subaru XV c.c. 1600

at Workshop m/s Motor Image

Colour: white A/C: Insured / Std / NI / NA

of 25 Leng Kee Road

Sp. Reading: 21445 T/Radio: Insured / Std / NI / NA

Insured: \_\_\_\_\_

Eng/No: \_\_\_\_\_

Policy No. \_\_\_\_\_

C/No: JFI 6P3K (S# 6152770)

Claims No. \_\_\_\_\_

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh: Jeep - 4073 2232

Modi: Nil / SRim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 225/55R17

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value: \_\_\_\_\_

Front Rear

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

R/Bal. 6 mm R/Bal. 6 mm

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

L/Bal. 6 mm L/Bal. 6 mm

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

D.O.A. \_\_\_\_\_ D.O.I. 3/5/17 @ 1045

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

Survey held at Motor Image Leng Kee

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

Confirm 8266.80, 3 days  
Red: 9580, 211.

RECEIVED 22 MAY 2018

Date/Time, File Pass to?  : Preli. Report

Days Of Repair: 3

1) typist  : Final Report

Resurvey No. of Trip: -

Survey Fee: 150

Date/Time, File Return to?

Transportation: \_\_\_\_\_

2) \_\_\_\_\_ Add Fee:  : Site Insp (\$ ) \_\_\_\_\_ S + RS. \_\_\_\_\_ SI

Report Format: TP  : Interview (\$ ) Photos

Lump Sum / I.B.I.: (\$ 2166.80 )  : Tech. Invs (\$ ) Others

: Weekend (\$ )

TOTAL

150



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD

Ref : CS/AWA17008432/T1rb

(SINGAPORE BRANCH)  
60 ANSON ROAD, #08-01 (9th FLOOR)  
MAPLETREE ANSON  
SINGAPORE 079914

Date : 28-04-2017



Code : AWA

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBJ 6909M	Veh. Inspected	SKT 8976X
Policy No.	AVMCSB0013041602	Coverage (\$)	0.00
Claim No.	NSV1700538/HLF	Excess (\$)	0.00
Assign From	TAN KAH LEONG	Assign Date	28/04/2017

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	24/04/2017	Inspection Date	03/05/2017
Survey held at	25 LENG KEE RD		
Repairer	MOTOR IMAGE ENTERPRISES PTE LTD		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**Catherine Chong (LKK Auto)**

**From:** Tan, KahLeong <KahLeong.Tan@awac.com> on behalf of Motorsurvey <Motorsurvey@awac.com>  
**Sent:** Friday, 28 April, 2017 10:19 AM  
**To:** assignments@lkkauto.com  
**Cc:** SUR (sur@lkkauto.com); tengchuen@motorimage.net  
**Subject:** TP Survey assignment for SKT 8976X - DOA: 24/04/2017 Our ref: NSV1700538/HLF

The above captioned accident refers.

Pursuant to the Practice Directions Amendment No. 1 of 2016 which was effective on 1 April 2016, we like to advise that the third party claimant and us do have consensus in the appointment of Mr Mohammed Rasul as the Single Joint Expert to conduct the pre-repair survey of the third party claimant's vehicle.

Please conduct "THIRD PARTY" survey on without prejudice basis. The information as are follows:

3 <sup>rd</sup> Party Vehicle	:	SKT 8976 X
Insured Vehicle	:	FBJ 6909 M
Policy Number	:	AVMCSB0013041602
Name of Workshop	:	Motor Image Enterprises Pte Ltd
Contact Number	:	6703 8631 / 9073 2232
Person to Contact	:	Jeff The
Estimated Cost of repairs	:	\$ 2,659.76

Regards,  
Claims Division

Copy to Motor Image Enterprises Pte Ltd via Email

Note -

- ( x )
1. This is to keep you informed that we have appointed surveyors to conduct inspection to your client's damaged vehicle on a without prejudice basis.
  2. **Please keep our motor surveyor and us informed so as to enable the surveyor to conduct a post repair inspection once your client's vehicle has been repaired and before returning the repaired vehicle to your customer.**
  3. Please quantify your client's claim with all relevant supporting documents once your client's vehicle has been repaired.
  4. Please do not construe this appointment of surveyor and our above request as an admission of liability.

The information contained in this e-mail and any attachments hereto is confidential. If you are not the intended recipient, you must not use or disseminate any of this information. If you have received this e-mail in error, please immediately notify the sender by reply e-mail and permanently delete the original e-mail (and any attachments hereto) and any copies or

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	26/04/2017 15:21
Date Of Accident	24/04/2017 18:45
Exact Location Of Accident	CANTONMENT ROAD
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKT8976X
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAN HIAP KWEE
NRIC No	S7497143A
Email Address	LIFEW1DE@YAHOO.COM
Mobile Phone No	(LOCAL) +65-96953680
Alternative Phone No	OTHERS-96953680

#### **Vehicle Particulars**

Manufacturer	SUBARU
Model	XV-1.6 I-S AWD CVT (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

#### **Insurance Company**

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100419385-01000
Cover Note Number	

#### **Driver**

Name of Driver	TAN HIAP KWEE
NRIC No	S7497143A
Date Of Birth	07/01/1974
Occupation	INDOOR
Date Of Driving Pass	27/07/1995
Driving Experience	21 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96953680
Fax Number	
Contact Number	OTHERS-96953680
EEmail Address	LIFEW1DE@YAHOO.COM

Singapore Accident Statement

Accident Date & Time: 24/4/17 19:45 hrs	
Accident Location: Cantonment Road	
Vehicle Number: SKT8976X	Make/Model: SUZUKI X1
Policyholder Name: TAN HIAP KWEE	
NRIC: S7497143A	Mobile: 96953680
Email: lifewide@yahoo.com	
Insurance Company: AIG	
Policy Number: 2100419385-01000	Cover Note:
Policy Coverage: Comprehensive(✓) Third Party( ) Third Party Fire & Theft( )	
State Action Taken: Claim Own Policy( ) Claim Third Party(✓) Reporting Only( )	
Driver Name: TAN HIAP KWEE	
NRIC: S7497143A	Mobile: 96953680
Date Of Birth: 7/1/74	Driving Pass Date: 27/7/95
Gender: Male(✓) Female( )	Occupation: Indoor(✓) Outdoor( )
Address: 6 Hillview Rise, #11-29 S(667980)	
Is driver an employee of the Insured's Company: Yes( ) No(✓)	
If No, Relationship of the Driver with the Insured:	
Owner(✓) Spouse( ) Friend( ) Relative( ) Children( ) Sibling( )	
Weather Conditions: Clear(✓) Raining( ) Others( )	
Road Surface: Dry(✓) Wet( ) Others( )	
Was any foreign vehicle involved in this accident? Yes( ) No(✓)	
Was any body injured in the Accident? Yes( ) No(✓)	
Was there any video captured by Car Camera? Yes(✓) No( )	
Number of Passengers (Including Driver): 4	
Was the accident reported to the police? Yes( ) No(✓) Attach Police Report, if any	
3 <sup>rd</sup> Party Name: Mani Poovarasa	
Vehicle Number: FB36909M	Make & Model:
NRIC: S88752095	Mobile: 90090441
Witness Details (if any):	
Other Details (if any): Refer to Sketch Plan	

Sketch Plan Pg. 3

Describe Circumstances of the Accident

Step one car at restaurant front, when to lorry  
turning coming out of main road.  
Suddenly, motorist / man; PC was off back (road)  
into my rear at around 15:45 on 24th  
April 2017.


3rd party as of first wanted to settle privately  
so not report was made within 24 hours  
last minute, 3rd party wanted to claim  
insurance. Thus report was only made  
today 26/4/17.

Declaration

We declare the foregoing particulars are true in every respect.

 26/4/17  
Policyholder's Signature / Date &  
Time 14:00

 Driver's Signature (if driver is not the policyholder) / Date  
& Time

  
Witnessed by Reporting Centre  
Personnel

**REPUBLIC OF SINGAPORE**  
**IDENTITY CARD NO. S7497143A**



Name  
**TAN MAP KWEE**  
**(CHEN XIEGU)**  
**陈锡桂**

Race  
**CHINESE**

Date of birth  
**07-01-1974**

Country of birth  
**MALAYSIA**



S7497143A

3485042



NRIC No. **S7497143A**



Date of issue  
**09-07-2006**

**BLK 6 HILLVIEW ROSE #11-20**  
**SINGAPORE 067080**

NRIC No: **S7497143A** Date: **18/08/2018**

MOTORIMAGE ENTERPRISES PTE. LTD.  
25 LENG KEE ROAD  
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS  
WORKSHOP : LENG KEE  
CONTACT NO :  
REFERENCE : INS/IC/LHI/019/2017  
DATE : 27-APR-2017

AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY  
#07-16 AIG BUILDING  
S(079120)  
TEL :  
FAX :

OWNER'S NAME : TAN HIAP KWEE (CHEN XIEGUI) [5YRS/100K SVC]  
ADDRESS : 6 HILLVIEW RISE  
#11-29  
S(667980)  
TELEPHONE NO : 9695 3680

TYPE OF CLAIM : THIRD PARTY CLAIM  
POLICY NO : 2100419385-01000  
VEHICLE NO : SKT8976X  
MODEL CODE : GP3DKDC  
MODEL/YEAR : SUBARU XV 1.6I-S AWD CVT  
ENGINE NO : FB161689120  
CHASSIS NO : JF16P3KC5FG152770  
MILEAGE : 1 KM  
DATE IN : 27/04/2017  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : DENNIS LEONG JIA HUI  
ACCIDENT DATE : 24/04/2017

Print Date : 27/04/2017  
Print Time : 17:45:29

Tanfikh 97495749.  
- WP -

3/5/17 @ 1045.

3 days

  
5/5/17.

\* Resny before photo paint.

tanfikh @ lkkando.com.

MOTORIMAGE ENTERPRISES PTE. LTD.  
25 LENG KEE ROAD  
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKT8976X

-----

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	TO SUPPLY AND REPLACE REAR BUMPER ASSY, BRACKET BUMPER LEFT & RIGHT AND TOW COVER	560 700.00	580 /
2	ZZ/002	TO SPRAY REAR BUMPER ASSY & REAR TAILGATE PANEL	440 1200.00	880 /
3	ZZ/003	TO REMOVE AND CHECK REVERSE SENSOR	150.00	80 /
4	ZZ/004	SUNDRIES	100.00	30 /
TOTAL LABOUR CHARGES			2150.00	

MOTORIMAGE ENTERPRISES PTE. LTD.  
 25 LENG KEE ROAD  
 SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKT8976X  
 -----

DAMAGED PARTS & PRICES

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
1 BUMPER FACE R XUV	57704FJ041	594.00		<i>de ✓</i>
2 BRKT RRH BUMP	57707FJ160	14.40		<i>ne ✓</i>
3 BRKT RLH BUMP	57707FJ170	14.40		<i>ne ✓</i>
4 COVER-REAR BUMPER	57731FG010I6	14.40		<i>ok ✓</i>
SUB TOTAL		637.20	0.00	0.00
LESS DISCOUNT ( NETT-20 %)		127.44	0.00	0.00
GRAND TOTAL		509.76	0.00	0.00
OVERALL TOTAL		509.76		

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.  
25' LENG KEE ROAD  
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SKT8976X

TOTAL LABOUR CHARGES	2150.00	
TOTAL SPARE PARTS CHARGES	509.76	
		<u>2659.76</u>
GRAND TOTAL	2659.76 *	<u>2746.80</u>

\* All charges do not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

MOTORIMAGE ENTERPRISES PTE. LTD.  
25 LENG KEE ROAD  
SINGAPORE 159097

FINALIZED : ACCIDENT/BODY REPAIRS  
WORKSHOP : LENG KEE  
CONTACT NO :  
REFERENCE : INS/IC/LHI/019/2017  
DATE : 27-APR-2017

AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY  
#07-16 AIG BUILDING  
S(079120)  
TEL : 91007211  
FAX :

OWNER'S NAME : TAN HIAP KWEE (CHEN XIEGUI)  
ADDRESS : 6 HILLVIEW RISE  
#11-29  
S(667980)  
TELEPHONE NO : 9695 3680

TYPE OF CLAIM : THIRD PARTY CLAIM  
POLICY NO : 2100419385-01000  
VEHICLE NO : SKT8976X  
MODEL CODE : GP3DKDC  
MODEL/YEAR : SUBARU XV 1.6I-S AWD CVT  
ENGINE NO : FB161689120(5Y100K)  
CHASSIS NO : JF1GP3KC5FG152770  
MILEAGE : 1 KM  
DATE IN : 27/04/2017  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : DENNIS LEONG JIA HUI  
ACCIDENT DATE : 24/04/2017

Print Date : 16/05/2018  
Print Time : 16:54:01

MOTORIMAGE ENTERPRISES PTE. LTD.  
25 LENG KEE ROAD  
SINGAPORE 159097

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKT8976X

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	TO SUPPLY AND REPLACE REAR BUMPER ASSY, BRACKET BUMPER LEFT & RIGHT AND TOW COVER	700.00	580.00 ✓
2	ZZ/002	TO SPRAY REAR BUMPER ASSY & REAR TAILGATE PANEL	1200.00	880.00 ✓
3	ZZ/003	TO REMOVE AND CHECK REVERSE SENSOR	150.00	80.00 ✓
4	ZZ/004	SUNDRIES	100.00	30.00 ✓
TOTAL LABOUR CHARGES			2150.00	1570.00

MOTORIMAGE ENTERPRISES PTE. LTD.  
 25 LENG KEE ROAD  
 SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKT8976X

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	BUMPER FACE R XUV	57704FJ041	594.00			OK
2	BRKT RRH BUMP	57707FJ160	14.40			OK
3	BRKT RLH BUMP	57707FJ170	14.40			OK
4	COVER-REAR BUMPER	57731FG01016	14.40			OK
5	LETTER MARK-REAR	93079FJ060	68.00			OK <i>acc</i>
6	LETTER MARK-REAR	93079FJ100	40.80			OK <i>acc</i>
SUB TOTAL			746.00	0.00	0.00	0.00
LESS DISCOUNT ( NETT-20 %)			149.20	0.00	0.00	0.00
GRAND TOTAL			596.80	0.00	0.00	0.00
OVERALL TOTAL			596.80			

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.  
25 LENG KEE ROAD  
SINGAPORE 159097

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SKT8976X

---

NETT ITEM	746.00
LESS 20 %	-149.20
NETT AMOUNT	596.80
LIST ITEM	0.00
LESS 50 %	0.00
LIST AMOUNT	0.00
SPECIAL NETT AMOUNT	0.00
S/LIST ITEM	0.00
LESS 30 %	0.00
S/LIST AMOUNT	0.00
TOTAL LABOUR CHARGES	1570.00
TOTAL SPARE PARTS CHARGES	596.80
TOTAL CHARGES	2166.80
ADD 7 % GST	151.68
GRAND TOTAL	2318.48



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ALLIED WORLD ASSURANCE COMPANY LTD		Ref : CS/AWA17008432/T1rbe2	
(SINGAPORE BRANCH) 60 ANSON ROAD ,#08-01 (9th FLOOR) MAPLE TREE ANSON SINGAPORE 079914		Date : 25-05-2018	
		Code : AWA	
1. Policy Particulars - THIRD PARTY CLAIM			
Insured Veh.	FBJ 6909M	Veh. Inspected	SKT 8976X
Policy No.	AVMCSB0013041602	Coverage (\$)	0.00
Claim No.	NSV1700538/HLF	Excess (\$)	0.00
Assign From	TAN KAH LEONG	Assign Date	28/04/2017
2. Vehicle Particulars & Condition			
Make & Model	SUBARU XV	c.c	1600
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JF1GP3KC5FG152770	Colour	WHITE
Odometer	21445	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/55 R17	YOKOHAMA	6 mm
L/H Front Tyre	225/55 R17	YOKOHAMA	6 mm
R/H Rear Tyre	225/55 R17	YOKOHAMA	6 mm
L/H Rear Tyre	225/55 R17	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	24/04/2017	Inspection Date	03/05/2017
Survey held at	25 LENG KEE RD		
Repairer	MOTOR IMAGE ENTERPRISES PTE LTD		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKT 8976X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	BUMPER FACE R XUV (N)	DEFORMED	594.00	594.00
1	BRKT RRH BUMP (N)	NECESSARY	14.40	14.40
1	BRKT RLH BUMP (N)	NECESSARY	14.40	14.40
1	COVER-REAR BUMPER (N)	CUT	14.40	14.40
1	LETTER MARK-REAR (N) (ADDITIONAL)	NECESSARY	68.00	68.00
1	LETTER MARK-REAR (N) (ADDITIONAL)	NECESSARY	40.80	40.80
	LESS 20% DISCOUNT		-149.20	-149.20
			596.80	596.80
<b>SPECIAL NETT ITEMS</b>				
1	SUNDRIES (SN)	NECESSARY	100.00	30.00
			100.00	30.00
<b>LABOUR</b>				
	TO SUPPLY AND REPLACE REAR BUMPER ASSY, BRACKET BUMPER LEFT & RIGHT AND TOW COVER.		700.00	580.00
	TO SPRAY REAR BUMPER ASSY & REAR TAILGATE PANEL.		1,200.00	880.00
	TO REMOVE AND CHECK REVERSE SENSOR.		150.00	80.00
			2,050.00	1,540.00
<b>GRAND TOTAL</b>			<b>2,746.80</b>	<b>2,166.80</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>2,166.80</b>

Report Ref No. CS/AWA17008432/T1rbe2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**