

ASS. REC. BY:

REF: CS/26717008510/Gcd3n4 Special Instruction:

Surveyor: Pau Rung**ASSIGNMENT (Office)**From (Person): Yee Pei Li of EGZ Date/Time: 28042017 436pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKX 4627J Insured: YM9229Jat Workshop m/s Z-One Automotive Tel: 6634 2112 / 6634 2292of 8/1 Kaki Bukit Ave 6 # 01-87Policy No: _____ Claim No: YM9229J / SL / p1

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 27042017
(Client's Record)

CA / REV / REP. / REV 24 HRS 'WPI' H.O.D. Endorsement: _____

Date/Time: 02052017 9.47am Person Contacted: Annie Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SKX 4627J - X</u>
	<u>YM 9229J - X</u>
<u>5/5/17</u>	<u>Sent pending Est frm repairer email to Pei Li</u>

REF: EEN

ASSIGNMENT

From: _____ Date: 02.05.2017

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKX 4627J
at Workshop m/s Z-One
of Blk 1 Kaki Bukit Ave 6 # 01-87

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$12K.13K.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKX 4627J Yr Regn: 19 Sep 2007

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Avante cc 1591

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 141475 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHDU41 BR 7.4 1840 46

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/65 R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 02-05-17

Survey held at w/s 4:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

17/4 6.13pm Continued LE \$3500f and 5 days with Yvonne. (Ref 5193.33, 592)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Others

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

TOTAL

250

Report Format: TP

Lump Sum / I.B.I: (\$3500f)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI17008510/Grb		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 02-05-2017		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YM 9229J	Veh. Inspected	SKX 4627J	
Policy No.		Coverage (\$)	0.00	
Claim No.	YM9229J/SL/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	28/04/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	27/04/2017	Inspection Date	02/05/2017	
Survey held at	Z-ONE AUTOMOTIVE PTE LTD 1 KAKI BUKIT AVE 6, BLK C, #01-52 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Celine Fong (LKKAuto)

From: Celine Fong (LKKAuto)
Sent: Wednesday, 17 April 2019 6:13 PM
To: Yvonne Yong
Cc: SUR
Subject: RE: SKX4627J After Paint Photo

Dear Yvonne,

Refer to our tele-conversation earlier.

Confirmed LS \$3,500.00

Days of repair: 5

Best Regards,

Celine Fong

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: celinefong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Yvonne Yong <service@z-one.com.sg>
Sent: Wednesday, 17 April 2019 5:03 PM
To: SUR <sur@lkkauto.com>
Subject: SKX4627J After Paint Photo

Hi ,

Please refer to the attach After Paint Photo

Thank you.

Best Regards,

Yvonne Yong

Z-One Automotive Pte Ltd

1 Kaki Bukit Ave 6, #01-85/87 Autobay @ Kaki Bukit Singapore 417883

Tel: 66342112 Fax: 6634 2122

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Friday, 5 May, 2017 12:42 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR; Admin-D (LKKAuto); assignments
Subject: RE: YM9229J / TP : SKX4627J/LKK / DOA : 27.04.2017

Dear Pei Li,

Please be informed that we have inspected the vehicle **SKX 4627J** on 02.05.2017.
We are pending estimate from repairer.

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Friday, 28 April, 2017 4:36 PM
To: admin-d@lkkauto.com
Subject: OI : YM9229J / TP : SKX4627J/LKK / DOA : 27.04.2017

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and Ergo Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **Z-ONE AUTOMOTIVE PTE LTD,**

ADDRESS : 1 KAKI BUKIT AVE 6
#01-87 AUTOBAY @ KAKI BUKIT
SINGAPORE 417883

PERSON TO CONTACT : GWEN TAY @ 6634 2112 / 6250 2115

ERGO OFFICER-IN-CHARGE : SHAWN LEE

Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident. Advise the consistency of damages to third party vehicle. Obtain estimate and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form and return to us together on your update of the survey status.

Kindly acknowledge receipt of this email.

Thank you.

Best Regards

Yee Pei Li

Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard

#04-01 Suntec Tower Five

Singapore 038985

DID: 65 6829 9194

Fax: 65 6829 9247

Website: www.ergo.com.sg



Have you tried our new travel insurance product yet?

TravelProtect comes with comprehensive benefits at some of the most affordable prices available in the market.

ERGO
TravelProtect
your Global Safety Net

TravelProtect is underwritten by ERGO Insurance Pte. Ltd.



Catherine Chong (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.)
<Survey.Report@ergo.com.sg>
Sent: Friday, 28 April, 2017 4:36 PM
To: admin-d@lkkauto.com
Subject: OI : YM9229J / TP : SKX4627J/LKK / DOA : 27.04.2017
Attachments: SKX4627J - PRS FORM.pdf; RE: SKX4627J - YR INSURED YM9229J - PRI (126 KB)

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and Ergo Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **Z-ONE AUTOMOTIVE PTE LTD.**

ADDRESS : 1 KAKI BUKIT AVE 6
#01-87 AUTOBAY @ KAKI BUKIT
SINGAPORE 417883

PERSON TO CONTACT : GWEN TAY @ 6634 2112 / 6250 2115

ERGO OFFICER-IN-CHARGE : SHAWN LEE

Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident. Advise the consistency of damages to third party vehicle. Obtain estimate and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form and return to us together on your update of the survey status.

Kindly acknowledge receipt of this email.

Thank you.

Best Regards

Yee Pei Li
Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
DID: 65 6829 9194
Fax: 65 6829 9247
Website: www.ergo.com.sg

ERGO

Date: 28.04.2017
Our Reference: YM 9229J/SL/pl
Your Reference: SKX 4627J

Sent via Fax

or

Email

gwentay@z-one.com.sg

To: Z-ONE AUTOMOTIVE PTE LTD

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SKX 4627J
Insured's Vehicle: YM 9229J
Date Of Accident: 27.04.2017

We acknowledge receipt of your request for PRS on: 28.04.2017

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

*

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

- ☒ Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
- ☒ Your request for inspection does not have your client's GIA report, kindly forward a copy.
- ☐ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
- ☒ Our Insured's driver has not reported the accident to us todate.
- ☐ Others: _____

Prepared by:		Pei Li	6829 9194	<u>claims@ergo.com.sg</u>
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job.

Workshop Acknowledgement & Stamp.

Note: Our inspection is on a without admission to liability basis.



Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 6634G

Vehicle Details

Vehicle No.: SKX4627J

Vehicle to be Exported: No

Intended De-registration
Date: 04 May 2017

Vehicle Make: HYUNDAI

Vehicle Model: HD AVANTE 1.6 A

Primary Colour: Black

Manufacturing Year: 2007

Engine No.: G4FC7U153295

Chassis No.: KMH DU41BR7U184046

Maximum Power Output: 89.7 kW (120 bhp)

Open Market Value: \$14,530.00

Original Registration
Date: 19 Sep 2007

First Registration Date: 19 Sep 2007

Transfer Count: 1

Actual ARF Paid: \$15,983.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry
Date: 18 Sep 2017

PARF Rebate Amount: \$7,991.00

Intended COE Rebate Details

COE Expiry Date: 18 Sep 2017

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$19,323.00

COE Rebate Amount: \$669.00

Total Rebate Amount: \$8,660.00

The information contained herein is correct as at 04 May 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE PERFORMANCE Company Registration No. 201118055N

ESTIMATE

SOH LIAN HWA
BLK 712 PASIR RIS ST 72 #14-47 Singapore 510712
Contact : 96309664

Code : C101686
Date in : 28/04/2017
Vehicle Num. : SKX4627J
Model : HYUNDAI AVANTE 1.6A
Chassis/Eng# : KMHU41BR7U184046/G4FC7U153295

Parts and Labour Assessment

Description of part	Qty	Unit Price	Amount
Rear Boot Lid <i>/ BT</i>	1	886.00	886.00 ✓
Rear Boot Lid 'Avante' Emblem <i>= 4 ABC</i>	1	38.90	38.90 ✓
Rear Boot Lid 'Logo' Emblem	1	32.80	32.80 ✓
Rear Boot Lid Hinge L/R <i>X</i>	2	120.80	241.60 X
Rear Boot Lid Inner Upholstery Trim <i>X { NN</i>	1	138.40	138.40 X
Rear Boot Lid Lock Striker <i>X</i>	1	38.10	38.10 X
Rear Boot Lid Mechanism Lock <i>X</i>	1	108.30	108.30 X
Rear Boot Lid No. Plate Lamp Garnish <i>/ de</i>	1	89.50	89.50 ✓
Rear Boot Lid Reflector Lamp L/R <i>LH - CRA</i>	2	178.70	357.40 178.7
Rear Boot Lid Reflector Lamp Stay Clips L/R <i>X</i>	4	7.90	31.60 X
Rear Boot Lid Rubber Guide Stopper L/R <i>X { NN</i>	2	9.20	18.40 X
Rear Boot Lid Weather Strip <i>X</i>	1	94.20	94.20 X
Rear Bumper <i>/ de</i>	1	542.00	542.00 ✓
Rear Bumper Inner Sponge <i>/ CRA</i>	1	122.00	122.00 ✓
Rear Bumper Reinforcement Beam <i>/ CRA</i>	1	282.00	282.00 ✓
Rear Bumper Side Retainer L/R <i>X NN</i>	2	67.40	134.80 X
Rear End Panel <i>/ Bue.</i>	1	637.90	637.90 ✓



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE • PERFORMANCE Company Registration No. 201118055N

Rear End Panel Inner Top Garnish	✓ <i>de</i>	1	89.50	89.50	✓
Rear End Panel Inner Top Garnish Clips	✓ <i>abc</i>	5	6.50	32.50	✓
Rear Fender Inner Upholstery Trim	X <i>NN</i>	1	128.90	128.90	X
Rear Fender LH	X <i>repair</i>	1	1603.00	1,603.00	X
Rear Spare Tyre Panel Inner Top Cardboard With Upholstery	X <i>NN</i>	1	250.00	250.00	X
Rear Taillamp L/R	<i>CH - CRA</i>	2	294.50	589.00	<i>294.5</i>
Rear Taillamp Stay Clips L/R	X <i>NN</i>	4	5.90	23.60	X
Subtotal before discount				6,510.40	
Percentage discount 20%				1,302.08	
Sub-total 1				5,208.32	
Rear Boot Lid Inner Upholstery Trim Clips (Set)(SN)	✓ <i>abc</i>	1	30.00	30.00	✓
Rear Boot Lid No. Plate (SN)	X	1	25.00	25.00	
Rear Boot Lid No. Plate Garnish (SN)	X <i>NN</i>	1	50.00	50.00	
Rear Bumper Clips (Set)(SN)	✓ <i>abc</i>	1	30.00	30.00	✓
Rear Bumper Reverse Sensor (Set)(SN)	✓ <i>DM</i>	1	350.00	350.00	<i>200 -</i>
Rear Fender Inner Upholstery Trim Clips (Set)(SN)	X <i>NN</i>	1	30.00	30.00	<i>260</i>
Subtotal before discount				515.00	
Percentage discount 0%				0.00	
Sub-total 2				515.00	
Parts-total				5,723.32	

LABOUR

Description	Price
Diagnose, replace and/or repair to rectify rear portion electrical system for proper functioning.	120.00

30



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE • PERFORMANCE Company Registration No. 201118055N

To remove, refix / renew reverse sensor assy and rectify for proper functioning.

To transfer tailgate/bootlid mechanism and wiring assy (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical (Tuff-Kote) on repaired and replaced panel.

100.00 40
150.00 x NN
1,200.00 800
1,200.00 600
200.00 60

153.00

Labour Total

2,970.00

Parts & Labour Total

8,693.32

page 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EG117008510/Gcd3n2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 18-04-2019		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YM 9229J	Veh. Inspected	SKX 4627J	
Policy No.		Coverage (\$)	0.00	
Claim No.	YM9229J/SL/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	28/04/2017	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI AVANTE	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	KMH DU41BR7U184046	Colour	BLACK	
Odometer	141475	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	HANKOOK	6 mm	
L/H Front Tyre	185/65 R15	HANKOOK	6 mm	
R/H Rear Tyre	185/65 R15	HANKOOK	6 mm	
L/H Rear Tyre	185/65 R15	HANKOOK	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/04/2017	Inspection Date	02/05/2017	
Survey held at	Z-ONE AUTOMOTIVE PTE LTD 1 KAKI BUKIT AVE 6, BLK C, #01-52 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 4627J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT LID	BENT	886.00	886.00
1	REAR BOOT LID "AVANTE" EMBLEM	NECESSARY	38.90	38.90
1	REAR BOOT LID "LOGO" EMBLEM	NECESSARY	32.80	32.80
2	REAR BOOT LID HINGE L/R @\$120.80	NOT NECESSARY	241.60	-
1	REAR BOOT LID INNER UPHOLSTERY TRIM	NOT NECESSARY	138.40	-
1	REAR BOOT LID LOCK STRIKER	NOT NECESSARY	38.10	-
1	REAR BOOT LID MECHANISM LOCK	NOT NECESSARY	108.30	-
1	REAR BOOT LID NO PLATE LAMP GARNISH	DEFORMED	89.50	89.50
2	REAR BOOT LID REFLECTOR LAMP L/R @\$178.70	N/S CRACKED	357.40	178.70
4	REAR BOOT LID REFLECTOR LAMP STAY CLIPS L/R @\$7.90	NOT NECESSARY	31.60	-
2	REAR BOOT LID RUBBER GUIDE STOPPER L/R @\$9.20	NOT NECESSARY	18.40	-
1	REAR BOOT LID WEATHER STRIP	NOT NECESSARY	94.20	-
1	REAR BUMPER	DEFORMED	542.00	542.00
1	REAR BUMPER INNER SPONGE	CRACKED	122.00	122.00
1	REAR BUMPER REINFORCEMENT BEAM	CRACKED	282.00	282.00
2	REAR BUMPER SIDE RETAINER L/R @\$67.40	NOT NECESSARY	134.80	-
1	REAR END PANEL	BUCKLED	637.90	637.90
1	REAR END PANEL INNER TOP GARNISH	DEFORMED	89.50	89.50
5	REAR END PANEL INNER TOP GARNISH CLIPS @\$6.50	NECESSARY	32.50	32.50
1	REAR FENDER INNER UPHOLSTERY TRIM	NOT NECESSARY	128.90	-
1	REAR FENDER LH	TO REPAIR SEE LABOUR	1,603.00	-
1	REAR SPARE TYRE PANEL INNER TOP CARDBOARD WITH UPHOLSTERY	NOT NECESSARY	250.00	-
2	REAR TAILLAMP L/R @\$294.50	N/S CRACKED	589.00	294.50
4	REAR TAILLAMP STAY CLIPS L/R @\$5.90	NOT NECESSARY	23.60	-
	LESS 20% DISCOUNT		-1,302.08	-645.26
			5,208.32	2,581.04
SPECIAL NETT ITEMS				
1	SET REAR BOOT LID INNER UPHOLSTERY TRIM CLIPS (SN)	NECESSARY	30.00	30.00

Report Ref No. CS/EGI17008510/Gcd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BOOT LID NO PLATE (SN)	NOT NECESSARY	25.00	-
1	REAR BOOT LID NO PLATE GARNISH (SN)	NOT NECESSARY	50.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	350.00	200.00
1	SET REAR FENDER INNER UPHOLSTERY TRIM CLIPS (SN)	NOT NECESSARY	30.00	-
			515.00	260.00
	LABOUR			
	DIAGNOSE, REPLACE AND/OR REPAIR TO RECTIFY REAR PORTION ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		120.00	30.00
	TO REMOVE, REFIX/RENEW REVERSE SENSOR ASSY AND RECTIFY FOR PROPER FUNCTIONING.		100.00	40.00
	TO TRANSFER TAILGATE/BOOTLID MECHANISM AND WIRING ASSY (TO FR).	NOT NECESSARY	150.00	-
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		1,200.00	800.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR FENDER LH.		1,200.00	600.00
	TO APPLY ANTI-RUST CHEMICAL (TUFF-KOTE) ON REPAIRED AND REPLACED PANEL.		200.00	60.00
			2,970.00	1,530.00
	GRAND TOTAL		8,693.32	4,371.04
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,500.00

Report Ref No. CS/EGI17008510/Gcd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.