

ASS. REC. BY:

REF:

CS/LPC 17008521/719602

Special Instruction:

Surveyor:

Tawfik

ASSIGNMENT (Office)

From (Person):

Dny Li

of

LPC

Date/Time: 02052017 1249pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJO 7432H

Insured:

at Workshop m/s

Woon Meng

Tel: 63161131

of

50 Bukit Batok St 25

Policy No:

Z16VP05010277

Claim No:

16/17/17 /VP05/019845

Sum Insured:

Excess:

\$750.00

Make of Veh:

D.O.A.

28042017

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

02052017 1249pm

Person Contacted:

Ms. Heng

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJO 7432H - X

03/5/17@ 11:39am went to Li's via Meimen.

03/5/17@ 3:08pm Mr. Chen informed C/A via Meimen.

03/5/17@ 3:47pm informed Ms. Heng C/A & EX: \$750.

ASS. REG. BY:

Tang Jm

REF:

LPC

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No.

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

<

days

Res: Yes or No

Lum Sum:

:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Ms Hong

Veh No:

SSQ 7432H. Yr Regn: 2009 May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volvo S40

cc 1999

Colour:

Grey.

A/C Insured / Std / NI / NA

Sp. Reading:

84194

T. Radio: Insured / Std / NI / NA

Eng. No:

C/No:

YV1MS434692464258

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A:

D.O.I:

2/5/17

Survey held at:

Woon Meng

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

4/3/5500, 5 days, e-mail Ms Hong
(Red 4272, 44%)

RECEIVED 30 APR 2018

Date/Time File Pass to?

☐

Preli. Report

Days Of Repair:

1: 20/4 12:00

☐

Final Report

Resurvey No. of Trip:

Date/Time File Return to?

2)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format:

MER-OD

Lump Sum / I.B.I: (\$

5500

Survey Fee:

Transportation:

) S + RS S:

) Photos

) Others

TOTAL

1704 34
50

49

10

303 + 10

313



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS/LPC17008521/T1qb

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 02-05-2017



Code : LPC2

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SJQ 7432H
Policy No.	Z16VP05010277	Coverage (\$)	0.00
Claim No.	16/17/17/VP05/019845	Excess (\$)	750.00
Assign From	MERIMEN (ONG LI LI)	Assign Date	02/05/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	28/04/2017	Inspection Date	02/05/2017
Survey held at	WOON MENG MOTOR PTE LTD 50 BUKIT BATOK ST 23 #01-06 MIDVIEW BUILDING SINGAPORE 659578		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Ins Auth'd
Main	29 Apr 2017 Sendback Est	02 May 2017 12:28 S\$9,772.00	02 May 2017 12:49 Assign				

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	WONG YAN LING, ID: S8511175B, Tel: +6592373274, Email: NOEMAIL					
Vehicle Reg. No.:	SJQ7432H	Date of Loss:	28/04/2017 10:00:159			
Claim Type:	OD / 16/17/17/VP05/019845	Policy/Cover Note No.:	Z169P050102774			(Comprehensive)
		Excess:	S\$750.00			
Repairer:	Woon Meng Motor Pte Ltd (Bukit Batok) 50 Bukit Batok Street 23,, #01-05 Midview Bldg, 659578 Bukit Batok - Tel: 6316 1131					
Handling Insurer:	Lonpac Insurance Bhd (HQ) - Tel: +65 62507388 ... [Handled by Ong Li Li]					
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due: 12/05/2017]					
Driver/Custodian:	WONG YAN LING (32 / Female), NRIC: S8511175B, Tel: +6592373274					
Adj Asg. Remarks:	SURVEY & REVERT					

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Assigned On	Done?
No results.									

Shiau Chan (LKKAuto)

From: Admin-D (LKKAuto)
Sent: Wednesday, 3 May, 2017 4:15 PM
To: 'ONG LI LI'; SUR
Cc: 'MT_Claim_SG'; assignments
Subject: RE: (SJQ7432H) 16/17/17/VP05/019845

Dear Li Li,

Thank you for your email.

Dear Shiau Chan,

FYNA. Our Ref: CS/LPC17008521/T1qb

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI [mailto:llong@lonpac.com]
Sent: Wednesday, 3 May, 2017 4:10 PM
To: assignments@lkkauto.com
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: (SJQ7432H) 16/17/17/VP05/019845

Dear LKK

Please proceed to authorise OD repairs as per your surveyor's adjustment if the damages are consistent & within repair limit.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

View Received Message

This mail is associated with :

SJQ7432H (16/17/17/VP05/019845)

OD

Apr 28 2017 10:00AM

[WONG YAN LING]

Woon Meng Motor Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From Lonpac Insurance Bhd (HQ) (LONPAC_HQ), sent on **03/05/2017 15:08 PM**.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$8117.00) - SJQ7432H - Claim Handler: Ong Li Li

Approved:8117.00.

DOCUMENTS SUMMARY

There are no documents.

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ong Li Li

Date: 03 May 2017

Preliminary Advice

Vehicle No	: SJQ7432H	Accident Date	: 28/04/2017
Make	: VOLVO S40	Policy No.	: Z16VP05010277
Assignment Date	: 02/05/2017	Excess	: S\$750.00
Date of Inspection	: 02/05/2017	Est. Duration of Repair	: 5.00
Inspection At	: WOON MENG MOTOR PTE LTD (BUKIT BATOK) 50 BUKIT BATOK STREET 23,, #01-06 MIDVIEW BUILDING SINGAPORE 659578		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,772.00
Revised Amount	:S\$	6,915.50
Check Items (Estimated)	:S\$	1,201.50
Total	:S\$	8,117.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	40,000.00
COE / PARF Rebate	:S\$	19,913.00
Salvage Value	:S\$	
Margin for Repair	:S\$	20,087.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : THE VEHICLE REPAIR ON PART BY PART BASIS AS NO SECOND HAND PARTS AVAILABLE.

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 1175B

Vehicle Details

Vehicle No.: SJQ7432H

Vehicle to be Exported: No

Intended De-registration
Date: 03 May 2017

Vehicle Make: VOLVO

Vehicle Model: S40 2.0L A/T ABS D/AIRBAG 2WD 4DR

Primary Colour: Grey

Manufacturing Year: 2009

Engine No.: B4204S3160479

Chassis No.: YV1MS434B92464258

Maximum Power
Output: 107.0 kW (143 bhp)

Open Market Value: \$31,443.00

Original Registration
Date: 25 May 2009

First Registration Date: 25 May 2009

Transfer Count: 3

Actual ARF Paid: \$31,443.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry
Date: 24 May 2019

PARF Rebate Amount: \$18,865.00

Intended COE Rebate Details

COE Expiry Date: 24 May 2019

COE Category: B - Car (1601cc & above)

COE Period(Years): 10

QP Paid: \$5,101.00

COE Rebate Amount: \$1,048.00

Total Rebate Amount: \$19,913.00

The information contained herein is correct as at 03 May 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.
Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution
Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

Woon Meng Motor Pte Ltd (Co.Reg.No:200603678M)

50 Bukit Batok Street 23,, #01-06 Midview Building

Singapore 659578

Tel: 6316 1131 Fax: 6316 7050 Email: woonmeng@singnet.com.sg

INSURER: Lonpac Insurance Bhd (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	Z16VP05010277	Date of Loss:	28/04/2017
Vehicle Reg. No.:	SJQ7432H	Driveable?	
Driver Age/Info:	32 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	WONG YAN LING	Contact No:	+6592373274
Driver:	WONG YAN LING		
Make/Model:	VOLVO S40, 2.0 (A)	Vehicle Reg. Date:	25/05/2009
Vehicle Colour:	GREY		
Engine No:	B4204S3160479	Chassis No:	YV1MS434B92464258
Odometer:	84194 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	15		
Description of Accident/Loss	REFER TO ATTACHMENT TO POLICE REPORT NO : T/20170428/7500. <i>before repair</i>		
Present Location:	WOON MENG MOTOR PTE LTD (BUKIT BATOK) <i>part by part. tanfukh @ Tanfukh.com</i>		

Tanfukh 97495749.
56 days
Ex \$750
Revent
2/5/17 @ 1730
** Reentry after repair*

COST OF CLAIMS

	Amount
Parts	7,452.00
Miscellaneous Items	0.00
Labour	1,370.00
Paintwork Labour	950.00
Towing	0.00
Gross Total (S\$)	9,772.00
+ GST 7.00% (S\$)	684.04
Nett Amount (S\$)	10,456.04

This claim is handled by: WOON MENG MOTOR PTE LTD

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 May 2017)
Parts: 143 VOLVO S40 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Woon Meng Motor Pte Ltd/SJQ7432H/02/05/2017 12:28
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	0.00	0.00	*1,200.00 F ^h ✓
2	2		*FRONT BUMPER RETAINER	0.00	0.00	*120.00 F ^h ✓
3	1		*FRONT BUMPER LOWER GRILLE	0.00	0.00	- n ^a
4	1		*FRONT FOG LAMP O/S	0.00	0.00	*280.00 F ^h ✓
5	1		*FRONT FOG LAMP GRILLE O/S	0.00	0.00	*95.00 F ^m ✓
6	1		*FRONT BUMPER LOWER LIP	0.00	0.00	*385.00 F ^h ✓
7	1		*FRONT BUMPER REFORCEMENT	0.00	0.00	*1,250.00 F ^h ✓
8	1		*FRONT BUMPER REFORCEMENT FRONT GARNISH	0.00	0.00	*230.00 F ^h ✓
9	1		*FRONT HEADLAMP O/S	0.00	0.00	*700.00 F ^h ✓
10	1		*FRONT HEADLAMP LOWER BRACKET O/S	0.00	0.00	*70.00 F ^h ✓
11	1		*FRONT FENDER O/S	0.00	0.00	*810.00 F ^h ✓
12	1		*FRONT FENDER INNER GARNISH O/S	0.00	0.00	*170.00 F ^h ✓
13	1		*FRONT CENTER GRILLE	0.00	0.00	*620.00 F ^h ✓
14	10		*CLIPS	0.00	0.00	*25.00 F ^h ✓
15	1		*FRONT BUMPER CENTER AIR GRILLE	0.00	0.00	*165.00 F ^h ✓
16	1		*UNDER ENGINE COVER	0.00	0.00	*270.00 F ^h ✓
17	1		*WASHER TANK	0.00	0.00	*90.00 F ^h ✓

F=Franchise part.

Sub Total (S\$)	4770	6,480.00
+ Margin on L,N Items 15.00% (S\$)		972.00
Total Parts (S\$)	5485.50	7,452.00

Woon Meng Motor Pte Ltd/SJQ7432H/02/05/2017 12:28. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			700.
1	TO PUTTY & SPRAY PAINTING.	New	600 950.00
<u>Labour Items</u>			700
2	TO REMOVE, REPLACE, REPAIR & INSTALL FRONT DAMAGED PARTS.	New	600 900.00
3	TO R & R WIRING	New	50 80.00
4	TO WHEEL ALIGNMENT.	New	120.00
5	TO R & R FRONT RADIATOR	New	120.00
6	TO R & R AIR CON SYSTEM. TOP UP AIR CON GAS.	New	150.00
Gross Labour Cost (S\$)			1430 2,320.00

Woon Meng Motor Pte Ltd/SJQ7432H/02/05/2017 12:28. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

5485.50
1430.
6915.50
4585.50

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse
Singapore 199555

Our File No: CS/LPC17008521/T1QBN2

Date: 04/05/2018

REFERENCE

Insured/Claimant: WONG YAN LING Policy No: Z16VP05010277
Date of Loss: 28/04/2017 Nature of Claim: OD Claim No: 16/17/17/VP05/019845

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJQ7432H Engine No: B4204S3160479
Make & Model: VOLVO S40, 2.0 (A) Chassis No: YV1MS434B92464258
Reg. Date: 25/05/2009 (Man. Year: 2009) Odometer: 84194 km
Colour: Grey
Engine Capacity: 1999 cc
Market Value/New Car Price: S\$40,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,452.00	5,485.50	1,966.50	26.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,370.00	730.00	640.00	46.72
Paintwork Labour	950.00	700.00	250.00	26.32
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,772.00	6,915.50	2,856.50	29.23
Approved Total (Overridden) (S\$)		5,500.00		
- Excess (S\$)	0.00	750.00	-750.00	
(S\$)	9,772.00	4,750.00	5,022.00	51.39
+ GST 7.00/7.00% (S\$)	684.04	332.50	351.54	51.39
Nett Amount (S\$)	10,456.04	5,082.50	5,373.54	51.39

INSPECTION

Date of Assignment: 02/05/2017 Present Location:
Date Inspected: 02/05/2017 Inspected At:

Woon Meng Motor Pte Ltd (Bukit Batok)
Woon Meng Motor Pte Ltd (Bukit Batok)
50 Bukit Batok Street 23,, #01-06
Midview Building
Singapore 659578

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 May 2018)
Parts:	143	VOLVO S40 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJQ7432H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER (WCP)	Torn	1,200.00 F	*1,200.00 F
2	2	*FRONT BUMPER RETAINER (WCP)	Necessary	120.00 F	*120.00 F
3	1	*FRONT BUMPER LOWER GRILLE (WCP)(NPA)	Not Necessary	-	-
4	1	*FRONT FOG LAMP O/S (WCP)	Cut	280.00 F	*280.00 F
5	1	*FRONT FOG LAMP GRILLE O/S (WCP)	Missing	95.00 F	*95.00 F
6	1	*FRONT BUMPER LOWER LIP (WCP)	Deformed	385.00 F	*385.00 F
7	1	*FRONT BUMPER REINFORCEMENT (WCP)	Bent	1,250.00 F	*1,250.00 F
8	1	*FRONT BUMPER REINFORCEMENT FRONT GARNISH (WCP)	Cracked	230.00 F	*230.00 F
9	1	*FRONT HEADLAMP O/S (WCP)	Cracked	700.00 F	*700.00 F
10	1	*FRONT HEADLAMP LOWER BRACKET O/S (WCP)	Necessary	70.00 F	*70.00 F
11	1	*FRONT FENDER O/S (WCP)	Repair	810.00 F	*- F
12	1	*FRONT FENDER INNER GARNISH O/S (WCP)	Torn	170.00 F	*170.00 F
13	1	*FRONT CENTER GRILLE (WCP)	Not Necessary	620.00 F	*- F
14	10	*CLIPS (WCP)	Not Necessary	25.00 F	*- F
15	1	*FRONT BUMPER CENTER AIR GRILLE (WCP)	Not Necessary	165.00 F	*- F
16	1	*UNDER ENGINE COVER (WCP)	Deformed	270.00 F	*270.00 F
17	1	*WASHER TANK (WCP)	Not Necessary	90.00 F	*- F

F=Franchise part.

Sub Total (\$\$)	6,480.00	4,770.00
+ Margin on L,N Items 15.00/15.00% (\$\$)	972.00	715.50
Total Parts (\$\$)	7,452.00	5,485.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	TO PUTTY & SPRAY PAINTING.	New	950.00	700.00
<u>Labour Items</u>				
2	TO REMOVE, REPLACE, REPAIR & INSTALL FRONT DAMAGED PARTS.	New	900.00	700.00
3	TO R & R WIRING	New	80.00	30.00
4	TO WHEEL ALIGNMENT.	New	120.00	-
5	TO R & R FRONT RADIATOR	New	120.00	-
6	TO R & R AIR CON SYSTEM. TOP UP AIR CON GAS.	New	150.00	-
Gross Labour Cost (S\$)			2,320.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >