Resurvey No. of Trip:

: Site Insp (\$

Interview (\$

Tech. Invs (\$

Weekend (\$

Add Fee:

Survey Fee:

Transportation.

Photos

Others

TOTAL

S+RS SI

1) typist

2)

Cate/Time. File Return to?

Report Format:

Lump Sum / I.B.I: (\$

Final Report

00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

110	ACIA DACIEIO INCI	URANCE PTE LTD	Ref : CC3/AIG1	Automobile 7008558/Arb
AIG .	ASIA PACIFIC INS	URANCEPIELID	itai . Godinio	
CHA	HENTON WAY #08 RTIS BUILDING GAPORE 079120	3-16	Date: 02-05-201	7
			Code: AIG	
1.		Policy Part	ticulars :- OWN DAMA	
	Insured Veh.		Veh. Inspected	SLJ 8747G
	Policy No.	2100496304	Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From		Assign Date	02/05/2017
2.	Populatives of	Vehicle I	Particulars & Conditio	in a second
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	g.	Steering	
	Brakes		Modification	
	General			
3.		Co	anditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4.		Des	cription of Damages	
-		C.	eneral Information	
5.	Accident Date	29/04/2017	Inspection Date	02/05/2017
_	SAME AND ADDRESS OF THE PARTY O	PREMIUM AUTOMOBILE		201 0.11 E-14-17-17-27-27
	Survey held at	55 UBI ROAD 1 . SINGAPORE 408699	50 4 B 51 B	
5a.			Remarks	AND THE PROPERTY

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

AIG Asia Pacific Insurance Pte. Ltd. To:

AIG Building

78 Shenton Way #07-16 Singapore 079120

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Date: 03 May 2017

Preliminary Advice

Vehicle No

:SLJ8747G

Accident Date

: 29/04/2017

Make

: AUDI A4

Policy No.

:2100496304-00000

Assignment Date : 02/05/2017

Excess

: \$\$0,00

Date of Inspection : 02/05/2017

Point of Impact / General Description of Damages

Est. Duration of Repair

:5.00

Inspection At

: PREMIUM AUTOMOBILES PTE LTD (HQ)

55 UBI ROAD 1

SINGAPORE 408699

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,523.00
Revised Amount	:S\$	14,299.00
Check Items (Estimated)	:S\$	4,293.00
Total	:S\$	18,592.00

Lump Sum Repair :S\$

Total Loss Consideration

ALC: COLLEGE	0.0
New for Old Value	:S\$

:S\$ 150,000.00 Pre-Accident Value COE / PARF Rebate :S\$ 69,639.00

Salvage Value :S\$

Margin for Repair :S\$ 80,361.00

Remarks

(X)	The vehicle is repairable at	our adjusted amount.	We have also conf	firmed excess and	policy coverage
-------	------------------------------	----------------------	-------------------	-------------------	-----------------

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: We have not authorise repair.

Print Received Message

This mail is associated with:

*SLJ8747G (0603029417SG)

OD Apr 29 2017 7:30PM

[CLEMENT TAY MING LIANG(CLEMENT ZHENG MINGLIANG)]

Premium Automobiles Pte Ltd

From

AIG Asia Pacific Insurance Pte, Ltd. (AIG_SG), sent on 04/05/2017 15:25 PM.

LKK_HQ

Subject

Alert - Adj Mandate Approved (S\$14299.00) - SLJ8747G - Claim Handler: Chan, Kian Meng

Approved:14299.00:Re-inspection to be done for damage check and hidden parts.

Print Received Message

This mail is associated with:

*SLJ8747G (0603029417SG)

OD

Apr 29 2017 7:30PM [CLEMENT TAY MING LIANG(CLEMENT ZHENG MINGLIANG)] Premium Automobiles Pte Ltd

From

AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 04/05/2017 13:45 PM.

LKK_HQ

Subject

SLJ8747G / OD / 29/04/2017 / Coverage & Excess update

Dear LKK Auto Consultants Pte Ltd

Please note that policy is in force and excess amount is \$0.00

Thank you

Chan, Klan Meng



Print Sent Message

This mail is associated with:

*SLJ8747G (0603029417SG)

OD

Apr 29 2017 7:30PM [CLEMENT TAY MING LIANG(CLEMENT ZHENG MINGLIANG)] Premium Automobiles Pte Ltd

From

LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 04/05/2017 16:05 PM.

To

AIG_SG; kianmeng.chan@aig.com

CC

sur@lkkauto.com

Subject

Re: SLJ8747G / OD / 29/04/2017 / Coverage & Excess update

Dear Mr. Chan,

Kindly confirm the excess as the driver driving experience is 1 year and 1 Month.

Thank you.

Regards, Janice Lee

<-- Original Message -->

From: AIG_SG To: LKK_HQ

Sent On: 04/05/2017 01:45 PM

Subject: SLJ8747G / OD / 29/04/2017 / Coverage & Excess update

Dear LKK Auto Consultants Pte Ltd

Please note that policy is in force and excess amount is \$0.00

Thank you Chan, Kian Meng

Print Received Message

This mail is associated with:

*SLJ8747G (0603029417SG)

OD

Apr 29 2017 7:30PM [CLEMENT TAY MING LIANG(CLEMENT ZHENG MINGLIANG)] Premium Automobiles Pte Ltd

From

AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 04/05/2017 16:25 PM.

To

Subject

SLJ8747G / OD / 29/04/2017 / Coverage & Excess update

Dear LKK Auto Consultants Pte Ltd

Please note that policy is in force and excess amount is \$3000.00

Thank you

Chan, Kian Meng

Janice Lee (LKKAuto)

From:

Janice Lee (LKKAuto)

Sent:

Thursday, 4 May, 2017 4:59 PM

To:

'Claims Department'

Cc:

SUR

Subject:

RE: SLJ 8747 G Own Damage Claim DOA 29042017

Dear Jeffery,

Instructed by our client, please proceed to repair the insured vehicle SLI 8747G (Excess \$3,000/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

Any check item or supplementary are subjected to further approval from our client.

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Department [mailto:claims@premiumauto.com.sg]

Sent: Wednesday, 3 May, 2017 9:18 PM

To: SUR <sur@lkkauto.com>

Cc: 'Claims Department' <claims@premiumauto.com.sg> Subject: RE: SLJ 8747 G Own Damage Claim DOA 29042017

Dear all,

Any update on the approval for this case? Kindly advise.

Many thanks!

Best regards, Claims Advisor

Tan Eng Su Jeffery

Premium Automobiles Pte Ltd (Reg No 199902277W)

55 Ubi Road I Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify as immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Claims Department [mailto:claims@premiumauto.com.sg]

Sent: Wednesday, 3 May, 2017 10:12 AM

To: 'SUR'

Cc: 'Claims Department'

Subject: SLJ 8747 G Own Damage Claim DOA 29042017

Dear all,

Kindly assist in the vehicle approval for the above mentioned vehicle.

Attached is the estimate for Adrian reference.

Many thanks!

Best regards, Claims Advisor Tan Eng Su Jeffery

Tall Elig Su Jeffery

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road I Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Contact Number

EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy Eability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT
Date Of Report	02/05/2017 10:25
Date Of Accident	29/04/2017 19:30
Exact Location Of Accident	BLK 441 YISHUN AVE 11 LEVEL 3A CARPARK LOT NO 106
Country/State of Loss	SINGAPORE
95-918 100-100-100-100-100-100-100-100-100-100	ETAILS OF OWN VEHICLE
Vehicle Registration Number	SLJ8747G
Insured/Policyholder	
Name Of Registered Owner	CLEMENT TAY MING LIANG(CLEMENT ZHENG MINGLIANG)
NRIC No	S7936671D
Email Address	CLEMENTTAY@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-93681982
Alternative Phone No	OTHERS-91709893
Vehicle Particulars	
Manufacturer	AUDI
Model	A4 SEDAN 1.4 TFSI S
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100496304-00000
Cover Note Number	
Driver	
Name of Driver	SU SHUYIN IRENE
NRIC No	S8308847H
Date Of Birth	28/03/1983
Occupation	INDOOR
Date Of Driving Pass	14/03/2016
Driving Experience	1 YEAR AND 1 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-91709893
Fax Number	

IRENE_SU_SHUYIN@HOTMAIL.COM

Addendum Sheet

GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

Original Report No Name(as shown in NRIC) NRIC/Passport No	Clement Tay Ming Liang	ST161141C
Name(as shown in NRIC)	Clement Tay Ming Liang	
NRIC/Passport No	Noncontral Man Section (Charles a service of the	
	(*Vehicle Driver / Vehicle Owner) (*) Please delete as ap 51936610	propriate
Address		
Contact (Tel)	(H/P):	93661485
(Email)	CO love Sound	19304
Place of Accident	BIK 441 Yohon Ave 11	
Insurance Company	AIG	
to convey to Th	and Perly Claim	

Date: \$5 m Ay 3017

10 Anson Road #06-16 International Plaza Singapore 079903 Phone : + 65-6224 0010 Fax : +65-6224 0030 Operating Hours : Monday to Friday 9am to 5pm

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3, Information provided must be as truthful and accurate as possible: Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.

	ACCIDENT STATEMENT
Date Of Report	02/05/2017 10:25
Date Of Accident	29/04/2017 19:30
Exact Location Of Accident	BLK 441 YISHUN AVE 11 LEVEL 3A CARPARK LOT NO 106
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SLJ8747G
Insured/Policyholder	
Name Of Registered Owner	CLEMENT TAY MING LIANG(CLEMENT ZHENG MINGLIANG)
NRIC No	S7936671D
Email Address	CLEMENTTAY@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-93681982
Alternative Phone No	OTHERS-91709893
Vehicle Particulars	
	THANKS

AUDI Manufacturer

A4 SEDAN 1.4 TFSI S Model

Exact Purpose for which vehicle was being used at PRIVATE USE

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number 2100496304-00000

Cover Note Number

Driver

Name of Driver SU SHUYIN IRENE

NRIC No S8308847H Date Of Birth 28/03/1983 INDOOR Occupation Date Of Driving Pass 14/03/2016

1 YEAR AND 1 MONTH **Driving Experience**

FEMALE Gender

Mobile Number (LOCAL) +65-91709893

Fax Number

Contact Number

EMail Address IRENE_SU_SHUYIN@HOTMAIL.COM Address

BLK 445 YISHUN AVENUE 11 #09-40

Postcode

760445

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

SPOUSE

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION- HEAD TO SIDE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Was any body injured in the Accident?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

I WAS DOING A CARPARK @ BLK 441 YISHUN AVE 11 ON 29/04/2017. WHILE TRYING TO PARK IN AN EMPTY LOT & STATIONARY, I WAS HIT BY SKR5874L ON THE RHS FRONT.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SKR5874L

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

LIM YEE HAO MARCUS

NRIC/Passport Number

S8105719B

Contact Number

96685198

Address

Postcode

Insurance Company Name

AXA INSURANCE PTE LTD

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

funderstand, acknowledge, agree and consent that

- (a) My insurer , my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (Iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' taw yers/law farms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GiA to their third party service providers or agents (including their law yers/law firms), which may be seed outside of Singapore, for one or more of the above Purposes.

2 MAY 17 09: 00 Policyholder's Signature / Date &

Driver's Signature (# driver is not the policyholder) / Date A Tirre

Witnessed by Reporting Centre Personnel

Sketch Plan

Time

B 7 8

A > SLJ B7476 B > SKR 5874 L

Sketch Plan #2

was doing a cor park of Blk 441 Yishwa Que 11 on 2910412017.
*
While trying to pork in an empty lot & stationary, I was 174
SKR5874 L on the RHS Grant.

Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date &

Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel































Accident Photo





CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT(CHAPTER 189) MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA) MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

MJC.1

(1)

AUDI AUTO PROTECTOR

OWN DAMAGE EXCESS WINDSCREEN EXCESS

\$\$600.00

\$\$100.00

CERTIFICATE NO. 2100496304-00000

(for policies with effect from 1st November 2002)

SUM INSURED Market Value

INSURING WITH COE/PARF

1) VEHICLE REGISTRATION NO.

SLJ8748G

2) NAME OF INSURED

CLEMENT TAY MING LIANG (CLEMENT ZHENG MINGLIANG)

3) EFFECTIVE DATE OF THE COMMENCEMENT OF INSURANCE FOR THE PURPOSES OF THE ACT 28 Dec 2016

4) DATE OF EXPIRY OF INSURANCE

27 Dec 2017

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE * SUBJECT TO AGE CONDITION :All Age Condition

b) Any other person who is driving on the Insured's order or with his permission.

This policy will indemnify the insured or any authorised driver only if he/she meets the age conditions.

A Young and/or Inexperienced Driver Excess ("YIDR") of \$\$3,000.00, in additional to the

Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said

Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle

6) LIMITATION AS TO USE *

Use only for social, domestic and pleasure purposes and for the Insured's business.

The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / AUDI AUTHORISED REPAIRERS

1. Audi Customer Service Center - 55 Ubi Road 1 (Tel: 63662323)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118) 3. DPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 65684501)
 Ethoz - 30 Bukit Batok Cres(Tel:66547777) 5. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only
 Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560) 7. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)

Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892)
 Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)

10. SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

LOSS OF USE Loss Of Use 15 days Replacement Car only for repairs at Audi Customer Service Centre

NAMED DRIVER

HIRE PURCHASE COMPANY / EMPLOYER'S LOAN

United Overseas Bank Limited

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act. 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore

10 Jan 2017

AIG Asia Pacific Insurance Pte. Ltd.

504125-266 PREMIUM LEASING -YCL 2B1 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE SINGAPORE 159938

AUTHORISED REPRESENTATIVE

ORIGINAL

REPUBLIC OF SINGAPORE IDENTITY CARD NO. S7936671D





CLEMENT TAY MING LIANG (CLEMENT ZHENG MINGLIANG)

明

CHINESE

21-11-1979

E79366710

SINGAPORE

REPUBLIC OF SINGAPORE IDENTITY CARD NO. \$8308847H




SU SHUYIN, IRENE MRS IRENE TAY SHUYIN

苏 淑

CHINESE Date of birth

SS308847H

28-03-1983 Country/Place of birth SINGAPORE





4454596

HRCH S7936671D



04-12-2009

APT BLK 445 YISHUN AVENUE 11 #09-40 SINGAPORE 760445

NAIC No: S79366710

Date: 22/07/2011

No: 6856862

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES!

PASS DATE

Motor Cars and Motor Tractors the weight of

which unladen does not exceed 2500 kilograms

5246862

NP 428A



Date of Issue 11-12-2013

APT BLK 465 YISHUN AVENUE 11 SINGAPORE 760445

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES).

EFFECTIVE DATE

Class 3A Motor cars without clutch pedals (Auto) with unleden the weight =< 3000kg with =< 7 passengers, exclusive of driver; and other motor vehicles without clutch pedals with unladen weight =< 2500kg

NF 428A

Licence No:S8305847H

Text size +

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

6671D

Vehicle Details

Vehicle No.:

SLJ8747G

Vehicle to be Exported:

Intended De-registration Date:

03 May 2017

Vehicle Make:

AUDI

Vehicle Model:

A4 1.4 TFSI S TRONIC

Primary Colour:

Blue

Manufacturing Year:

2016

Engine No.:

CVN024782

Chassis No.:

WAUZZZF41HA070993

110.0 kW (147 bhp)

Open Market Value:

\$32,219.00

Maximum Power Output:

First Registration Date:

28 Dec 2016

Transfer Count:

Actual ARF Paid:

\$27,107.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date: 27 Dec 2026

Original Registration Date: 28 Dec 2016

PARF Rebate Amount:

\$20,330.00

Intended COE Rebate Details

COE Expiry Date:

27 Dec 2026

COE Category:

B - Car above 1600cc or 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$51,109.00

COE Rebate Amount:

\$49,309.00

Total Rebate Amount:

\$69,639,00

The information contained herein is correct as at 03 May 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer. Please do not use the **Back** or **Forward** buttons on your browser as this may after the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2017 LTA | Privacy Statement | Terms of Use | Disclaimer | Rate the Website | Rate this e-Service

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khal@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

 Estimate
 : Accident Repairs

 Workshop
 : Ubi Road 1

 Contact No
 : 6366 2323

 Fax No
 : 6841 1183

Reference : PA/OD/0420/2017/JT

Date : 2-May-17

Vehicle in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Clement Tay Ming Liang
Address : Apt Blk 445 Yishun Ave 11

#09-40

Singapore 760445

 Telephone
 : (HP) +65 9368 1982

 Type of Claim
 : Own Damage Claim

 Policy No.
 : 2100496304-00000

Vehicle No : SLJ 8747 G

Model Code : Audi A4 Sedan 1.4 TFSI S-troni

 Model / Year
 : Dec-16

 Engine No
 : CVN 024782

Chassis No : WAUZZZF41HA070993

Mileage :

Date In ; 2-May-17

Liability : -

Excess Cost : -

Estimated By : Johnny Boo / Allan Wu

Accident Date : 29-Apr-17

Place of Accident : Blk 441 Yishun Ave 11 Level 34

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLJ 8747 G.

S/N	Nature of Jobs			Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N	\$	360.00
2	To remove and transfer air cond condenser, radiator, charged air cooler, electrical fans and control unit. To carry out vacuum/regas and to pressurize cooling system.	S/N	\$	960.00
3	To remove front fittings, dismantle front bumper, RHS front fender and RHS headlights. Remove and renew front bumper, RHS front fender, RHS front headlights and repair top support. Dismantle and renew lock carrier, carrier support, reorganize front crash management components. Renew headlights, radiator grille, reinstall all parts removed. Re-align bonnet to position.		\$	3,600.00 1250
4	To respray front bumper, rhs front fender and bonnet.		s	2,200.00 1100
5	To replace rhs front rim and carry out wheel alignment.	S/N	\$	280.00
6	To carry out diagnostic checks.	S/N	\$	192.00
	TOTAL LABOUR CHARGES	*	\$	7,592.00

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLJ 8747 G.

			Damage Pa	rts & Prices
S/N	Parts Description	_	S/NETT	REMARKS
1	FRONT BUMPER Distant	\$	1,703.00	/
2	FRONT BUMPER ATTACHMENT PARTS	\$	239.00	7
3	FRONT BUMPER TOWING COVER	\$	47.00	Ž.
4	FRONT BUMPER SECURING STRIP / ~ 2	\$	57.00	K
5	FRONT BUMPER LOWER GRILLE - CENTRE /**	\$	163.00	x
6	FRONT BUMPER CLOSING ELEMENT	\$	171.00	*,
7	FRONT AIR GUIDE - RHS	\$	67.00	2
8	FRONT AIR GRILLE GUIDE - RHS	\$	112.00	?
9	RADIATOR GRILLE	\$	941.00	7
10	LOCK CARRIER BRACKET Carlo	\$	112.00	
11	LOCK CARRIER SUPPORT	\$	23.00	?
12	HEADLIGHT WASHER CYLINDER - RHS MISSING ?	\$	180.00	7
13	HEADLIGHT WASHER CYLINDER BRACKET - RHS	\$	10.00	
14	LED HEADLIGHT - RHS	\$	7,861.00	
15	HEADLIGHT HOSE	\$	29.00	x
16	HEADLIGHT COMPENSATING PIECE - RHS ?	s	34.00	?
17	FRONT FENDER - RHS Juled	\$	643.00	
18	FRONT FENDER ATTACHMENT PARTS - RHS	\$	44.00	7
19	FRONT FENDER BRACEI - RHS	\$	100.00	?
20	FRONT FENDER CLOSING ELEMENT - RHS	\$	27.00	7
	SUB-TOTAL SPARE PARTS	\$	12,563.00	

All charges are not inclusive of GST.

Legend:

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLJ 8747 G.

				Damage Pa	rts & Prices
S/N	Parts Description		- 2	S/NETT	REMARKS
					2
21	FRONT FENDER INNER BRACKET - RHS ?		\$	29.00	7
22	FRONT FENDER OUTER BRACKET - RHS 7		\$	42.00	7
23	FRONT FENDER UPPER BRACKET - RHS ?		\$	79.00	?
24	FRONT WHEEL HOUSE LINER - RHS tom		\$	202.00	1
25	WHEEL HOUSE LINER ATTACHMENT PARTS - RHS	pu	\$	76.00	-
26	FRONT WHEEL SPOILER - RHS		\$	61.00	x
27	FRONT STONE CHIP GUARD		\$	45.00	
28	LOCK CARRIER		\$	878.00	7
29	COOLANT		\$	66.00	2
30	FRONT ALUMINIUM RIM - RHS LAT		\$	465.00	
31	SUNDRIES		S	400.00	7
32	FRONT NUMBER PLATE	S/N	\$	25.00	?
	TOTAL SPARE PARTS	1	\$	14,931.00	
	TOTAL LABOUR CHARGES	12 g	\$	7,592.00	
	GRAND TOTAL	3	\$	22,523.00	8

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved. Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Adria Lij

Surveyed Date

: 510-

Authorised Date

9.

Excess Cost

:

Liability Remarks . Not Authorised, 05 Days

Please Note

: This estimate is based on visual inspection of the affected vehicle.

Should we require further labour charges and spare parts in the

progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant

Merimen e-Claims

...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUBF	OLDER TRAC	KING										
Case	Notified	Est Submitted	Adj Rpt	Adj Submitted		d Ins Auth	ed	d Status				
	03 May 2017 16:11		02 May 2017 17:55 Edit Adj Rpt	S\$14,29 Edit Est	3230000 - all 117	\$14,299.00 View Rpt)		Pending for Survey Report Cancel Case			
	fain.	Ref	erence	Clai	m Details		Docume	ents		Show All		
CLAIM SUI	SFOLDER DET	AILS		The state of the s		[Created	by Insurer]			-		
insured:	CLEMENT T	AY MING LIANG	(CLEMENT ZHENG	MINGLIAN	G). ID: S	- International Contract Contr	the same of the sa	1982				
Vehicle Reg. No.:	The Charles of the Co	CLEMENT TAY MING LIANG(CLEMENT ZHENG MINGLIANG), ID: S7936671D, Tel: +6593681982								in Yr)]		
Claim Type: OD / 0603029417SG					olicy/Cover ote No.:	210049630	04-00000 (Con	nprehensiv	e)	- W. Col. (1)		
				E	ccess:	5\$3,000.0	0					
Repairer:	Premium A	utomobiles Pte I	.td (UBI) 55 Ubi Ro	oad 1, 40869	9 Ubi - Tel:	67689828/	9827/9911					
Handling Insurer:	AIG Asia P	acific Insurance	Pte. Ltd. (SG) - Te	d: 65-6419-3	ю [На	ndled by Chi	an, Kian Men) klanmer	ng.chan@ai	g.com		
Adjuster:	LKK Auto C	onsultants Pte L	td (HQ) - Tel: 6256	6-3561 [H	andled by A	ADRIAN LIN	G] [Final	Rpt due	12/05/2	017]		
Driver/Custo dian:	SU SHUYIN	IRENE (34 / Femal	le), NRIC: S83088	347H, Tel:	+65917098	393						
ASSOCIAT	ED MAIL REC	EIVED						View All	Compos	e Case Mail		
 AIG_SG (04/05/2017):	Alert - Adj Manda	29/04/2017 / Co ate Approved (S\$1 29/04/2017 / Co	14299.00) -	5LJ87470	- Claim Ha	indler: Chan,	Kian				
ALL ASSO	CIATED TASK	S∃				View All	Search Tasks	Create N	lew Task	Complete		
	Priority	Type Task G	roup Subject	Handler	Assign	ned By	Completed (On C	reated On	Done		

Merimen e-Claims Page 1 of 2

Claim Documents

*SLJ8747G (0603029417SG) OD Apr 29 2017 7:30PM [CLEMENT TAY MING LIANG(CLEMENT ZHENG MINGLIANG)] Premium Automobiles Pte Ltd

Vld	eo		1 per	page 🔻	V
No.	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
1	03/05/17 16:42	Video - Accident	0	Load AVI	
Acc	essment Reports		1.000	pagé 🔽	V
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	1 per	Thumbnail	
1	03/05/17 17:06	Adjuster Immediate Advice	0	Load HTM	
		1.511.00.00.00.00.00.00.00.00.00.00.00.00.0			
Pho	otos/Images		3 per	page V	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	-	Thumbnail	-
1	03/05/17 16:39	General View	0	Load JPG	N.
2	03/05/17 16:39	General View	0	Load JPG	V
3	03/05/17 16:39	General View	0	Load JPG	N.
4	03/05/17 16:39	General View	0	Load JPG	8
5	03/05/17 16:39	General View	0	Load 3PG	V
б	03/05/17 16:39	General View	0	Load JPG	[2]
7	03/05/17 16:39	General View	9	Load JPG	\checkmark
8	03/05/17 16:39	General View	0	Load JPG	V
9	03/05/17 16:39	General View	0	Load JPG	V
10	03/05/17 16:39	General View	0	Load JPG	V
11	03/05/17 16:39	General View	0	Load JPG	V
12	03/05/17 16:39	General View	0	Load 3PG	V
13	03/05/17 16:39	General View	0	Load JPG	V
14	03/05/17 16:39	General View	0	Load JPG	V
15	03/05/17 16:39	General View	0	Load JPG	V
15	03/05/17 16:39	General View	0	Load JPG	2
17	03/05/17 16:39	General View	0	Load JPG	V
18	03/05/17 16:39	General View	0	Load JPG	V
19	03/05/17 16:39	General View	0	Load JPG	V
20	03/05/17 16:39	General View	0	Load JPG	Ø
21	03/05/17 16:39	General View	0	Load JPG	V
22	03/05/17 16:39	General View	0	Load JPG	∀
23	03/05/17 16:39	General View	0	Load JPG	3
24			0	Load JPG	-
	03/05/17 16:39	General View	0	1.3100401330241	N N
25	03/05/17 16:39	General View		Load JPG	
26	03/05/17 16:39	General View	0	Load JPG	✓
27	03/05/17 16:39	General View	0	Load JPG	S
28	03/05/17 16:39	General View	0	Load JPG	S
29	03/05/17 16:39	General View	0	Load JPG	V
30	03/05/17 16:39	General View	0	Load JPG	₩.
31	03/05/17 16:39	General View	0	Load JPG	V

Merimen e-Claims Page 2 of 2

Vid	Video		1 per page 🔍		[2]
Νo	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
Doc	Documentation		1 per	1 per page V	
Nο	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnall	Print
1	03/05/17 16:36	Singapore Accident Statement	0	Load PDF	
2	03/05/17 16:36	Certificate of Insurance	0	Load PDF	
3	03/05/17 16:36	Insured Person's AND DRIVER IC AND DRIVING LICENSE	0	Load PDF	
4	03/05/17 16:36	WORKSHOP ESTIMATE	0	Load PDF	
5	26/06/18 14:36	SLJ 8747G ADENDOUM GIA	0	Load PDF	

Linked Accident Report Documents

			View	View in Brown	ser V
Ass	essment Reports		1 per s	page v	V
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	02/05/17 12:22	Accident Statement	0	Load HTM	
2	05/05/17 17:28	Addendum Sheet	0	Load JPG	V
3	05/05/17 17:29	Accident Statement Addm. #1	0	Load HTM	
Pho	otos/Images		3 per (page 🔽	V
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	-
1	02/05/17 12:13	Accident Photo	0	Load JPG	V
2	02/05/17 12:13	Accident Photo	0	Load JPG	V
3	02/05/17 12:13	Accident Photo	0	Load JPG	V
4	02/05/17 12:13	Accident Photo	0	Load JPG	V
5	02/05/17 12:13	Accident Photo	0	Load JPG	V
6	02/05/17 12:13	Accident Photo	0	Load JPG	V
7	02/05/17 12:13	Accident Photo	0	Load JPG	V
8	02/05/17 12:13	Accident Photo	0	Load JPG	V
9	02/05/17 12:13	Accident Photo	0	Load JPG	V
10	02/05/17 12:13	Accident Photo	0	Load JPG	V
11	02/05/17 12:13	Accident Photo	0	Load JPG	V
12	02/05/17 12:13	Accident Photo	Ø	Load JPG	V
Doc	umentation		1 per p	page V	V
No-	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnall	_
1	02/05/17 12:16	Sketch Plan	0	Load JPG	V
2	02/05/17 12:16	Sketch Plan #2	0	Load JPG	V

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
			V
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.			

Adjuster Report Page 1 of 5

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607 198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way #07-16

Singapore 079120

Our File No:

CC3/AIG17008558/ARBQ2

CVN024782

5877 km

WAUZZZF41HA070993

Date:

06/07/2018

REFERENCE

Insured/Claimant: MINGLIANG) CLEMENT TAY MING LIANG(CLEMENT ZHENG

Policy No:

2100496304-

Engine No:

Chassis No:

Odometer:

00000

Date of Loss:

29/04/2017

Nature of Claim:

OD

Claim No:

0603029417SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

Reg. Date:

SLJ8747G

Make & Model:

AUDI A4, 1.4 T (A)

28/12/2016 (Man. Year: 2016)

Colour:

Engine Capacity:

1395 cc

Market Value/New Car Price: S\$150,000.00

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: Front Left Side:

225/50 R17

Rear Tyre Size:

225/50 R17 Pirelli 6 mm

Front Right Side:

Pirelli 6 mm Pirelli 6 mm

Rear Left Side: Rear Right Side:

Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,931.00	11,117.00	3,814.00	25.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,592.00	3,182.00	4,410.00	58.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,523.00	14,299.00	8,224.00	36.51
- Excess (S\$)	3,000.00	3,000.00	0.00	0.00
(S\$)	19,523.00	11,299.00	8,224.00	42.12
+ GST 7.00/7.00% (S\$)	1,366.61	790.93	575.68	42.12
Nett Amount (S\$)	20,889.61	12,089.93	8,799.68	42.12

INSPECTION

Date of Assignment:

02/05/2017

Date Inspected:

02/05/2017 Inspected At:

Premium Automobiles Pte Ltd (HQ)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair:

5.0 days

Adjuster Report Page 2 of 5

Adjuster: ADRIAN LING Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5 (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS \$\$4,293.00 NETT) https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_p... 6/7/2018

Adjuster Report Page 4 of 5

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,703.00 FS	*1,703.00 FS
2	1		*FRONT BUMPER ATTACHMENT PARTS	*Check	239.00 FS	*-FS
3	1		*FRONT BUMPER TOWING COVER	*Check	47.00 FS	*-FS
4	2		*FRONT BUMPER SECURING STRIP	Not Necessary	57.00 FS	*-FS
5	1		*FRONT BUMPER LOWER GRILLE -CENTRE	Not Necessary	163.00 FS	*-FS
6	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	171.00 FS	*-FS
7	1		*FRONT AIR GUIDE -RHS	*Check	67.00 FS	*-FS
8	1		*FRONT AIR GRILLE GUIDE -RHS	*Check	112.00 FS	*- FS
9	1		*RADIATOR GRILLE	*Check	941.00 FS	*-FS
10	1		*LOCK CARRIER BRACKET	Cracked	112.00 FS	*112.00 FS
11	1		*LOCK CARRIER SUPPORT	*Check	23.00 FS	*-FS
12	1		*HEADLIGHT WASHER CYLINDER -RHS	*Check	180.00 FS	*-FS
13	1		*HEADLIGHT WASHER CYLINDER BRACKET -RHS	Missing	10.00 FS	*10.00 FS
14	1		*LED HEADLIGHT -RHS	Cracked	7,861.00 FS	*7,861.00 FS
15	1		*HEADLIGHT HOSE	Not Necessary	29.00 FS	*-FS
16	1		*HEADLIGHT COMPENSATING PIECE -RHS	*Check	34.00 FS	*-FS
17	1		*FRONT FENDER -RHS	Dented	643.00 FS	*643.00 FS
18	1		*FRONT FENDER ATTACHMENT PARTS -RHS	*Check	44.00 FS	*- FS
19	1		*FRONT FENDER BRACEI-RHS	*Check	100.00 FS	*-FS
20	1		*FRONT FENDER CLOSING ELEMENT -RHS	*Check	27.00 FS	*-FS
21	1		*FRONT FENDER INNER BRACKET -RHS	*Check	29.00 FS	*-FS
22	1		*FRONT FENDER OUTER BRACKET -RHS	*Check	42.00 FS	*-FS
23	1		*FRONT FENDER UPPER BRACKET -RHS	*Check	79.00 FS	*-FS
24	1		*FRONT WHEEL HOUSE LINER -RHS	Torn	202.00 FS	*202.00 FS
25	1		*WHEEL HOUSE LINER ATTACHMENT PARTS -RHS	Necessary	76.00 FS	*76.00 FS
26	1		*FRONT WHEEL SPOILER -RHS	Not Necessary	61.00 FS	*-FS
27	1		*FRONT STONE CHIP GUARD	Necessary	45.00 FS	*45.00 FS
28	1		*LOCK CARRIER	*Check	878.00 FS	*-FS
29	1		*COOLANT	*Check	66.00 FS	*-FS
30	1		*FRONT ALUMINIUM RIM -RHS	Cut	465.00 FS	*465.00 FS
31	1		*SUNDRIES	*Check	400.00 FS	*-FS
32	1		*FRONT NUMBER PLATE	*Check	25.00 FS	*-FS
F=Fra	inchise (part. S=Spcf	Vett.	Total Parts (S\$)	14,931.00	11,117.00

Report was unsubmitted during this print-out.

Adjuster Report Page 5 of 5

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

Particulars	Lab.Type	Repairer's	Amount
our Items			
TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,FOG LAMPS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
TO REMOVE AND TRANSFER AIR COND CONDENSER, RADIATOR, CHARGED AIR COOLER, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM / REGAS AND TO PRESSURIES COOLING SYSTEM (*Check)	New	960.00	0.00
TO REMOVE FRONT FITTINGS ,DISMANTLE FRONT BUMPER ,RHS FRONT FENDER AND RHS HEADLIGHTS ,REMOVE AND RENEW FRONT BUMPER ,RHS FRONT FENDER ,RHS FRONT FENDER HEADLIGHTS AND REPAIR TOP SUPPORT .DISMANTLE AND RENEW LOCK CARRIER ,CARRIER SUPPORT ,REORGANIZE FRONT CRASH MANAGEMENT COMPONENTS ,RENEW HEADLIGHTS ,RADIATOR GRILLE ,REINSTALL ALL PARTS REMOVED.RE-ALIGN BONNET TO POSITION	New	3,600.00	1,250.00
TO RESPRAY FRONT BUMPER ,RHS FRONT FENDER AND BONNET	New	2,200.00	1,100.00
TO REPLACE RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labor	ır Cost (S\$)	7,592.00	3,182.00
	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY TO REMOVE AND TRANSFER AIR COND CONDENSER, RADIATOR, CHARGED AIR COOLER, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM / REGAS AND TO PRESSURIES COOLING SYSTEM (*Check) TO REMOVE FRONT FITTINGS, DISMANTLE FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHTS, REMOVE AND RENEW FRONT BUMPER, RHS FRONT FENDER HEADLIGHTS AND REPAIR TOP SUPPORT. DISMANTLE AND RENEW LOCK CARRIER, CARRIER SUPPORT, REORGANIZE FRONT CRASI MANAGEMENT COMPONENTS, RENEW HEADLIGHTS, RADIATOR GRILLE, REINSTALL ALL PARTS REMOVED. RE-ALIGN BONNET TO POSITION TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND BONNET TO REPLACE RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT TO CARRY OUT DIAGNOSTIC CHECKS	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,FOG LAMPS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY TO REMOVE AND TRANSFER AIR COND NEW CONDENSER ,RADIATOR,CHARGED AIR COOLER ,ELECTRICAL FANS AND CONTROL UNIT.TO CARRY OUT VACUUM /REGAS AND TO PRESSURIES COOLING SYSTEM (*Check) TO REMOVE FRONT FITTINGS ,DISMANTLE FRONT BUMPER ,RHS FRONT FENDER AND RHS HEADLIGHTS ,REMOVE AND RENEW FRONT BUMPER ,RHS FRONT FENDER HEADLIGHTS AND REPAIR TOP SUPPORT .DISMANTLE AND RENEW LOCK CARRIER ,CARRIER SUPPORT ,REORGANIZE FRONT CRASH MANAGEMENT COMPONENTS ,RENEW HEADLIGHTS ,RADIATOR GRILLE ,REINSTALL ALL PARTS REMOVED.RE-ALIGN BONNET TO POSITION TO RESPRAY FRONT BUMPER ,RHS FRONT FENDER AND NEW BONNET TO REPLACE RHS FRONT RIM AND CARRY OUT WHEEL NEW ALIGNMENT TO CARRY OUT DIAGNOSTIC CHECKS NEW	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR New 360.00 HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY TO REMOVE AND TRANSFER AIR COND New 960.00 CONDENSER, RADIATOR, CHARGED AIR COOLER, ELECTRICAL FANS AND CONTROL UNIT.TO CARRY OUT VACUUM (REGAS AND TO PRESSURIES COOLING SYSTEM (*Check) TO REMOVE FRONT FITTINGS, DISMANTLE FRONT New 3,600.00 BUMPER, RHS FRONT FENDER AND RHS HEADLIGHTS, REMOVE AND RENEW FRONT BUMPER, RHS FRONT FENDER, RHS FRONT FENDER HEADLIGHTS AND REPAIR TOP SUPPORT, DISMANTLE AND RENEW LOCK CARRIER, CARRIER SUPPORT, REORGANIZE FRONT CRASH MANAGEMENT COMPONENTS, RENEW HEADLIGHTS, RADIATOR GRILLE, REINSTALL ALL PARTS REMOVED.RE-ALIGN BONNET TO POSITION TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND BONNET TO REPLACE RHS FRONT RIM AND CARRY OUT WHEEL New 192.00

< END OF ESTIMATES >