

# 来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267  
RCB No: 199407592C

## ESTIMATE

EST. No .....: EST0016252  
Yong Choy Mui

Page .....: 1 of 1  
Your ref. ....: TP-SGH 1018T EQ  
Job No. ....: 68442  
Our ref .....: 17.04.44  
Payment .....:  
Date .....: 3/5/2017

Attn .....

Vehicle No ....: SJP 8910T  
Vehicle Model : Toyota Camry  
Accident on ...: 26/4/2017

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Front headlamp LH ✓ SCR.	350.00		350.00
1.00	Pc	Front bumper chrome moulding LH ✓ SCR.	33.00		33.00
Total amount of parts supplied - S\$383.00					
1.00		15% of parts supplied:	57.45		57.45
Labour & Misc:					
1.00		To knock dents on front fender LH, to repair front bumper and renew of parts	450.00		<del>450.00</del> 400
1.00		To spray paint	450.00		<del>450.00</del> 400

3 days.

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

Sebastian  
3/5/2017.  
sebastianyeang@lkkauto.com.

Sub-Total 1,340.45  
GST 7.00% 93.83  
Total S\$ 1,434.28

Lunny Simu Repair.

本公司拥有最先进的 CARLINER MARK IV 机械, 可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。  
"Our services include the latest and reliable CARLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."