REF:

(cs/ALC) 17008714 AH3e2

ASSIGNMEN	Į

From: Date:	Veh No: SDB761D. Yr Regn: 2008, Mark.
Estimated Cost:	Type: (M.Can) M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Audi TTC c.c 3189
at Workshop m/s	Colour Silves. A/C: Insured / Std / NI / NA
of	Sp.Reading T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No. 2100682720-09000	C/No: TRUZZZS 1881004811
Claims No. 457866172856	Gen. Cond: Good/ Fair / Poor / Burnt
Sum Insured: Excess: 3000 08/5/1	Steering: Inerder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Interder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 245/45/C17
(Policy Condition)	R: 245/45R17.
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY)FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or
Bal. or Market Value: 50k.	<u>Front</u> <u>Rear</u>
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 06 mm R/Bal. 06 mm
GIA / PR Seen. Consistent?: Yes or No	L/Bal. 06 mm L/Bal. 06 mm
Est. Repairs: 13 days Res.: Yes or No	D.O.A. D.O.I. 04/05/17
Lum Sum: % 3 Val.: Yes or No	Survey held at Premium.
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT	
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
50 Alg.	
	mp Sum \$BK
- ORICITATION DE VISA MICHIEL THE PROPERTY CARE	Ina Mannen
08/5/17(35.11m informed Jack C/A	1 BEX: \$300 by enal.
lump Sum \$13,000 (Red:	18,653 :58%)
RECEIVED	_
	Days Of Repair: \(\sum_{\infty} \)
ALTUPIST Final Report	Resurvey No. of Trip: Survey Fee: 200
Date/Time, File Return to?	:Transportation:
2) Add Fee:	
To	: Interview (\$) Photos
Report Format:	: Tech. Invs (\$) Others
Lump Sum / I.B.I: (\$ 13,000)	;Weekend (\$)
,	TOTAL JUV



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

IG ASIA PACI	FIC INSURANCE PTE LTD	Ref : CC3/AIG170087	714/Ath3				
8 SHENTON V	NAY #08-16	Date: 04-05-2017					
INGAPORE 0							
		Code: AIG					
	Polic	y Particulars : OWN DAMAGE					
Insured '	Veh.	Veh. Inspected	SDB 761D				
Policy N	o. 2100082720	Coverage (\$)	0.00				
Claim No	D.	Excess (\$)	0.00				
Assign F	rom	Assign Date	04/05/2017				
	Ve	hicle Particulars & Condition					
Make &		c.c	0				
Engine I		Year of Reg.					
Chassis		Colour					
Odomet		Steering	Steering				
Brakes		Modification					
General							
General Section of the section of th	Hand Street Co. Laborator Company	Conditions of Tyres					
3. () () () () () () () () () (Size	Make	Balance				
R/H Fro			mm				
L/H Fro			mm				
R/H Rea			mm				
L/H Rea			mm				
Z A STANCE	ii Tyle	でDescription of Damages行い					
4.							
- Asian ma		General Information					
		Inspection Date	04/05/2017				
Accide							
Survey	55 UBI ROAD 1.						
	SINGAPORE 4086		ng paging and promise and another comment of the company of the comment of the company of the co				
5a.	and the state of t	Remarks	The state of the s				

View Received Message

This mail is associated with:

*SDB761D (4578661728SG)
OD
May 2 2017 5:50PM
[HO IM GEK]
Premium Automobiles Pte Ltd

Reply	Reply All Mark as Unread Print Message Delete Message Forward	
rom o	AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 08/05/2017 14:45 PM. LKK_HQ	
ubject	Alert - Adj Mandate Approved (S\$13000.00) - SD8761D - Claim Handler: Chan, Kian Meng	
Approved	ed:13000.00:Limit repair at \$13,000.00.	
Approved	ed:13000.00:Limit repair at \$13,000.00.	
	ed:13000.00:Limit repair at \$13,000.00. MENTS SUMMARY	

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

AIG Asia Pacific Insurance Pte. Ltd. To:

AIG Building

78 Shenton Way #07-16 Singapore 079120

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Pava Ubi Industrial Park Singapore 408933

Date: 05 May 2017

Preliminary Advice

Vehicle No

: SDB761D

Accident Date

: 02/05/2017

Make

Attn:

: AUDITT

Policy No.

:2100082720-09000

Assignment Date

: 04/05/2017

Excess

: \$\$0.00

Date of Inspection : 04/05/2017

Est. Duration of Repair

: 13.00

Inspection At

: PREMIUM AUTOMOBILES PTE LTD (HQ)

55 UBI ROAD 1 SINGAPORE 408699

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	31,653.00
Revised Amount	:S\$	23,661.00
Check Items (Estimated)	:S\$	733.00
Total	:S\$	24,394.00
Lump Sum Repair	:\$\$	13,000.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	50,000.00
COE / PARF Rebate	:S\$	36,655.00
Salvage Value	:S\$	
Margin for Repair	:S\$	13,345.00

Remarks

(x)	The vehicle is repairable at our adjusted amount, We have also confirmed excess and policy coverage. Kindly
	let us have your authorisation.

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(x) Other comments: Repairer agree to repair on lump sum \$13,000/-

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

Attn:

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building

78 Shenton Way #07-16 Singapore 079120

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Date: 05 May 2017

Preliminary Advice

Vehicle No

:SDB761D

Accident Date

: 02/05/2017

Make

: AUDITT

Policy No.

: 2100082720-09000

Assignment Date

: 04/05/2017

Excess

Date of Inspection

: S\$0.00

:04/05/2017

Est. Duration of Repair

: 13.00

Inspection At

: PREMIUM AUTOMOBILES PTE LTD (HQ)

55 UBI ROAD 1

SINGAPORE 408699

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	31,653.00
Revised Amount	:S\$	23,661.00
Check Items (Estimated)	:S\$	733.00
Total	:S\$	24,394.00

Lump Sum Repair

:S\$

Total Loss Consideration

Pre-Accident Value :S\$ 50,000.00 COE / PARF Rebate :S\$ 36,655.00

Salvage Value :S\$

Margin for Repair :S\$ 13,345.00

Remarks

(x)	The vehicle is repairable at our a	djusted amount. We have also confirmed excess and policy coverage. Ki	indly
	let us have your authorisation.	. ,	•

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

) Other comments: Pendina repair Cox

Text size +

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

5099C

Vehicle Details

Vehicle No.:

SDB761D

Vehicle to be Exported: No

Intended De-registration 05 May 2017

Date:

AUDI

Vehicle Make: Vehicle Model:

TTC 3.2 QUATTRO S-TRONIC

Primary Colour:

Silver

Manufacturing Year:

2007

Engine No.:

BUB038226

Chassis No.:

TRUZZZ8J881004811

Maximum Power

Output:

184.0 kW (246 bhp)

Open Market Value:

\$70,098.00

Original Registration Date:

28 Mar 2008

First Registration Date:

28 Mar 2008

Transfer Count:

Actual ARF Paid:

\$70,098.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry

27 Mar 2018

Date:

PARF Rebate Amount: \$35,049.00

Intended COE Rebate Details

COE Expiry Date:

27 Mar 2018

COE Category:

E - Open Category

COE Period(Years):

10

QP Paid:

\$18,670.00

COE Rebate Amount:

\$1,606.00

Total Rebate Amount: \$36,655.00


The information contained herein is correct as at 05 May 2017



Please read through the Privacy Statement, Terms of Use and Disclaimer. Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.


Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution Copyright © 2017 LTA | Privacy Statement | Terms of Use | Disclaimer | Rate the Website | Rate this e-Service








Accident Photo
















Accident Photo













CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT(CHAPTER 189) MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA) MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.X.1

AUDI AUTO PROTECTOR (Named Driver Basis Policy)

OWN DAMAGE EXCESS WINDSCREEN EXCESS

\$\$3000.00(I) S\$100.00

CERTIFICATE NO. 2100082720-09000

(for policies with effect from 1st November 2002)

SUM INSURED Market Value

INSURING WITH COE/PARF

Yes

1) VEHICLE REGISTRATION NO.

SDB761D

2) NAME OF INSURED

Ho Im Gek

3) EFFECTIVE DATE OF THE COMMENCEMENT OF INSURANCE FOR THE PURPOSES OF THE ACT 28 Mar 2017

4) DATE OF EXPIRY OF INSURANCE

27 Mar 2018

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE *

The Insured and any person who is named as a named driver under the policy.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE *
Use only for social, domestic and pleasure purposes and for the Insured's business.
The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / AUDI AUTHORISED REPAIRERS

1. Audi Customer Service Center - 55 Ubi Road 1 (Tel: 63662323)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118) 3. DPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 65684501)
4. Ethoz - 30 Bukit Batok Cres(Tel: 66547777) 5. Glass-Fix - 52 Uhi Ave 3 (Tel: 62780887) - For windscreen only
6. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560) 7. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)
8. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)

10. SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

LOSS OF USE Loss Of Use 15 days Replacement Car only for repairs at Audi Customer Service Centre

NAMED DRIVER

Poey Chin Yang

/ EMPLOYER'S LOAN

HIRE PURCHASE COMPANY HONG LEONG FINANCE LTD

Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).


27 Feb 2017 Issued At Singapore

504125-200 PREMIUM LEASING - AP 281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE SINGAPORE 159938

AIG Asia Pacific Insurance Pte. Ltd.

AUTHORISED REPRESENTATIVE

No. 201009404M



REPUBLIC OF SINGAPORE

IDENTITY CARD NO. \$1825099C





HO IM GEK

CHINESE 08-06-1967 SINGAPORE





NRIC No. \$1825099C

19-02-1994

52 JALAN SUKACHITA SINGAPORE 1335

AB+

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183

Reference : PA/OD/0423/2017/JN

Date : 3-May-17

Vehicle not in workshop. Kindly arrange for survey.

Your insured vehicle no: SDB 761 D

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Ho Im Gek Address : 52 Jalan Sukachita

Singapore 358928

Telephone: (HP) 98305728Type of Claim: Own Damage ClaimPolicy No.: 210082720-09000

Vehicle No : SDB 761 D

Model Code : TTC 3.2 QU

Model / Year : Mar-08

Engine No : BUB038226

Chassis No : TRUZZZ8J881004811

Mileage : Date In :
Liability : Excess Cost : -

Estimated By : Johnny Boo / Allan Wu

Accident Date : 2-May-17

Place of Accident : Marina Blvd Turing into Sheares

Premium Automobiles 55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SDB 761 D.

<u>S/N</u>	Nature of Jobs			Estimated Charges	Surveyor's lecommendation
1	To renew lhs 1/4 glass to facilitate fender renewal.	S/N	\$	300.00	
2	To remove and reinstall rear wire harness for light, battery manager, fuse and relay trays, electrical and audio equipment.	5/N	\$	1,400.00	
3	To remove and reinstall rear seats, back rest, hat tray, abcd pillar trims, luggage compartments trims and seat belts. Dislodge roof liner and disengage curtain air big etc.	S/N	\$	1,600.00	
4	To set up and place vehicle in aluminium repair facility.	S/N	\$	1,200.00	
5	To remove rear fittings, dismantle lhs door, lhs side member trim, rear bumper and rear lid. Cut out and reweld lhs rear fender. Renew lhs door, transfer oldd fittings and align to position. Reinstall all parts removed.		\$	6,600.00	3000
6	To respray lhs door, lhs rear fender, lhs side member trim, lhs sill panel, rear bumper, drain panel, roof channel and carry out aluminium primer works, joint sealer works and stone chip treatment.		, \$	5,400.00	, 27SI.
7	To renew lhs rear rim and carry out wheel alignment.	S/N	\$	280.00	
8	To carry out diagnostic checks.	S/N	\$	280.00	
	TOTAL LABOUR CHARGES	:	\$	17,060.00	

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDB 761 D.

S/N	Parts Description	<u>Damage Parts & Prices</u> S/NETT REMARKS
1	DOOR HANDLE - LH	\$ 137.00 *
2	DOOR HANDLE CAP - LH	\$ 32.00 4
3	SIDE MEMBER TRIM - LH De Lod	\$ 604.00
4	OUTER SILL TRIM STRIP - LH / ~ ~	\$ 213.00 €
5	REAR FENDER - LH PISTOLD	\$ 9,323.00
6	ALUMINIUM RIM - LH	\$ 601.00
7	1/4 GLASS 🗥	\$ 343.00 —
8	ROOF MOLDING - LH My Me	\$ 567.00 <i>+</i>
9	INSULATION STRIP -LH	\$ 15.00 <i>+</i>
10	EDGE PROTECTION - LH	\$ 126.00 ¹ / ₂ .
11	WHEEL HOUSING LINER - LH \sim	PRICE TBC 🔭
12	SOUND ABSORBER WAR	\$ 107.00 / .
13	REAR BUMPER GUIDE SECTION - LH 🖯 ~	\$ 36.00 ₩
14	ALUMINIUM POWDER 7	S/N \$ 500.00 ~
15	ALUMINIUM PRIMER	S/N \$ 185.00 🛩
16	1/4 GLASS SEALANT	S/N \$ 100.00 ~
17	ACRYLIC SEALER	S/N \$ 180.00
18	CAVITY WAX	S/N \$ 140.00 ✓
19	STONE CHIP	S/N \$ 180.00
20	2K ADHESIVE GLUE	S/N \$ 195.00 ~
	SUB - SPARE PARTS	\$ 13,584.00

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDB 761 D.

S/N	Parts Description	<u>Damage Parts & Prices</u> S/NETT REMARKS
21 22	COMBI RIVETS ALL SUNDRIES	\$ 500.00 100
	TOTAL SPARE PARTS	\$ 14,593.00
	TOTAL LABOUR CHARGES	: \$ 17,060.00
	GRAND TOTAL	\$ 31,653.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Surveyed Date **Authorised Date**

Excess Cost

Liability Remarks : : He Authorsed, 13 Pags.

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo **Body Repair Manager** Claims Consultant

LKK Auto Consultants nence notify

the Repairer of the following:

- To resurvey before after all ray hainting
- To display damaged an silfan giresurvey
- Parts prices an un entito commination.
- \bullet Third party survey is on a " $\mathbb M$ mout Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Motor Claims Dept Yr Ref: SDB 761 D Norah Khai 6768 9911 6841 1183 Nora.khai@premiumauto.com.sg Body & Paint Dept PA/OD/0423/2017/MAS

11 Dec 2017

from
Telephone +65Telefax +65EMail
Our department
Our Ref
Your Ref

total pages

Date

Dear Sir.

RE: INSURANCE CLAIM FOR SDB 761 D, Audi TTC 3.2 QU S-TRONIC

With reference to the above-mentioned vehicle, no **SDB 761 D**, claimant, **Ms. Ho Im Gek**, please find the related document per attached.

- 1. A copy of the Original invoice no. 85011886 S\$10,700.00
- 2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai Claims Dept

Encls

AIG - SDB 761 D

Premium Automobiles Pte Ltc Showroom 9 Leng Kee Road Singapore 159090 Telephone (65) 6566 1111 Telefax (65) 6471 3733

Service & Parts Centres 55 Ubi Rd 1 Singapore 408699 Telephone (65) 6336 2323 Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Alexandra Service Centre

281 Alexandra Road -Singapore 159938

281 Alexandra Road Singapore 159938 Main Telephone 6836 2223 Telephone 6388 2223 Main Telefax 6475 1023 6471 3733 Telefax

\$5 Ubi Road 1
Service Appointment
Service Appointment
Service Appointment
Service Appointment

6366 2323 9828 1233

Page 1

18:44

Colombia (138 R 23 No. 199902271W customer.care@premiumauto.com.sg GST Reg. No. 199902271W

Invoice:

85011886

Account: A0006 (T

AIG ASIA PACIFIC INSURANCE PTE LTD

MOTOR CLAIM DEPT

AIG BUILDING

78 SHENTON WAY

#07-16

SINGAPORE 079120 079120

Date:

Order:

Term:

08/12/2017

SDB0761D

30

AIG ASIA PACIFIC INSURANCE PTE LTD

MOTOR CLAIM DEPT

AIG BUILDING

78 SHENTON WAY

#07-16

SINGAPORE 079120

Regn No: SDB0761D

Regn Date: 28/03/2008

Mileage: 17030

WIP NO: 22636

Model: TTC 3.2 QU S-TRONIC Chassis: TRUZZZ8J881004811

Engine: BUB038226

Dept: U

VSB No:

You have been assisted by:- UB-Carrine

(11)

		Details	Qty	Unit Price	Amount
s	SUBLET	To carry out contractial repair as agreed for material and labour.	1.00	13,000.00	13,000.00
Q	EXC	Insurance Excess/Liability	-3000.00	1.00	-3000.00
arts				Sub-Total	10,000.00
	t 13,000.00			7% GST	700.00
lenu	s 0.00				

Lubricant 0.00

Grand Total

10,700.00

Received by

For & on behalf of Premium Automobiles Pte Ltd

Telefax

to AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Motor Claims Dept Yr Ref: SDB 761 D Norah Khai from

6768 9828 6841 1183

Telephone +65-Telefax +65-

Premium Automobiles Pte Ltd

Telephone (65) 6566 1111 Telefax (65) 6471 3733

Service & Parts Centres

Telephone (65) 6366 2323 Telefax (65) 6841 1183

55 Ubi Road 1 Singapore 408699

Mobile +65-

Body Repair Our department Your Claim Ref

PA/OD/ 0423//2017/TF 29 May 2017 Our Ref Date

Showroom

9 Leng Kee Road Singapore 159090

1 total pages

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi TTC 3.2 QU

Vehicle Chassis No. : TRUZZZ8J8810048115

Vehicle Regn No. : SDB 761 D

Vehicle Mileage : 17020 KM

Vehicle Owner : Ms. Ho Im Gek

Certificate No : 210082720-0900

Policy Excess : S\$3,210.00 (inclusive of 7% GST)

Accident Date : 02 May 2017

Place : Marina Blvd Turing Into Sheares

Repair Cost : \$ 10,700.00

WIP No. : 22636

Repairer's Name : Premium Automobiles Pte Ltd

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.


Owner / Insured Signature :

Time :

Date

160-

30/05/17



REPUBLIC OF SINGAPORE

IDENTITY CARD NO. \$1825099C





HO IM GEK

CHINESE Date of Birth 08-06-1967 Country of Birth SINGAPORE



NP 426A

Motor Cars and Motor Tractors the weight of which unleden does not exceed 2500 kilograms







AB+ 19-02-1994

52 JALAN SUKACHITA SINGAPORE 1335



CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT(CHAPTER 189) MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA) MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.X.1

AUDI AUTO PROTECTOR (Named Driver Basis Policy)

OWN DAMAGE EXCESS WINDSCREEN EXCESS S\$3000.00(I)

CERTIFICATE NO. 2100082720-09000

(for policies with effect from 1st November 2002)

S\$100.00

Yes

SUM INSURED INSURING WITH COE/PARF

Market Value

1) VEHICLE REGISTRATION NO.

SDB761D

2) NAME OF INSURED

Ho Im Gek

3) EFFECTIVE DATE OF THE COMMENCEMENT OF INSURANCE FOR THE PURPOSES OF THE ACT

28 Mar 2017

4) DATE OF EXPIRY OF INSURANCE

27 Mar-2018

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE *

The Insured and any person who is named as a named driver under the policy.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE *

Use only for social, domestic and pleasure purposes and for the Insured's business.

The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / AUDI AUTHORISED REPAIRERS

1. Audi Customer Service Center - 55 Ubi Road 1 (Tel: 63662323)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118) 3. DPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 65684501)

4. Ethoz - 30 Bukit Batok Cres (Tel: 66547777) 5. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only

6. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560) 7. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)

8. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd f (Tel: 67475336)

10. SMF Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

10. SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

LOSS OF USE Loss Of Use 15 days Replacement Car only for repairs at Audi Customer Service Centre

NAMED DRIVER

Poev Chin Yang

/ EMPLOYER'S LOAN

HIRE PURCHASE COMPANY HONG LEONG FINANCE LTD

Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore

27 Feb 2017

AIG Asia Pacific Insurance Pte, Ltd.

504125-200 PREMIUM LEASING - AP 281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE SINGAPORE 159938

AUTHORISED REPRESENTATIVE

4041-02/

Merimen e-Claims Page 1 of 1

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adi f	Rot	Adi Si	ubmitted	Ins	Auth'ed		tatus	
Main	05 May 2017 10:28		04 May 2017 14:00 Edit Adj Rpt	S\$1	3,000.00 lit Estimates	S\$13	000.00 Rpt				urve	ng for Report
	Main	Refere	nce	Cl	aim Details	\Box		ocum	ents	\Box	_ 9	how All
CLAIM SU	BFOLDER DET	AILS						[Cre	ated by	/ insure	r]	
Insured:		HO IM GEK,	ID: S1825099C,	Tel: +	6598305728,	Email	: NOEMAI	Ľ				
Vehicle Rec	g. No.:	SDB761D			Date of Loss:			02/0	/2017	17:00 - :	59	
Claim Type	:	OD / 45786	61728SG		Policy/Cover	Note No).:	2100	082720-	-09000 (00 (Comprehensive)	
	·, , ·, , , , , , , , , , , , , , , , ,			~~~	Excess:			S\$3,0	00.00			
Repairer:		Premium Aut	omobiles Pte Ltd	(UBI	55 Ubi Road	1, 4086	599 Ubi - T	oi - Tel: 67689828/9827/9911				
Handling Ir	nsurer:	AIG Asia Paci kianmeng.char	fic Insurance Pt @aig.com	e. Ltd.	(SG) - Tel: 6	5-6419	-3000 [Handle	d by Ch	an, Kiar	Men	9]
Adjuster:		LKK Auto Cor 16/05/2017	sultants Pte Ltd	(HQ)	- Tel: 6256-3	561 [Handled b	y ADR	IAN LI	1G] [l	Final	Rpt due
Driver/Cust	todian:	HO IM GEK (49	/ Female), NRI	IC: S18	25099C, Te	l: +659	8305728					
ASSOCIA	TED MAIL RECE	IVED		· · · · · · · · · · · · · · · · · · ·					View Al	I Cor	npose	Case Mail
		liert - Adj Mandat DB761D / OD / O					aim Hand	ller: Cl	an, Kia	ın		
ALL ASSO	CIATED TASKS	S ⊡			Vie	w All	Search T	asks	Create	New Ta	sk	Complete
Due Date	e Priority 1	Type Task Grou	D Subject	Handi	er Assicu	ned By	Com	pleted	On On	Create	d On	Done?

Merimen e-Claims Page 1 of 2

Claim Documents

*SDB761D (4578661728SG) QD May 2 2017 5:50PM [HO IM GEK] Premium Automobiles Pte Ltd

Up	load Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	,	/iew View in Bro	owser 🗸
Ass	essment Reports	<u>, , , , , , , , , , , , , , , , , , , </u>				1 pe	er page 🔻	V
No	Finalized On	LKK Auto Co	nsultants Pte Ltd (He	Q)			Thumbnail	Print
1	08/05/17 09:47	Adjuster Im	mediate Advice			0	Load HTM	<u></u>
Dha	tos/Images					3 ne	er page 🔻	$\overline{\mathbf{Z}}$
No		LKK Auto Co	nsultants Pte Ltd (He	D)		12 12	Thumbnail	Print
1	05/05/17 09:50	General View	-			0	Load JPG	V
 2	05/05/17 09:50	General Viev				0	Load JPG	V
3	05/05/17 09:50	General Viev	N			0	Load JPG	Z
4	05/05/17 09:50	General Viev	N	***************************************		0	Load JPG	Z
5	05/05/17 09:50	General Viev	N			0	Load JPG	V
 6	05/05/17 09:50	General Viev				0	Load JPG	<u>Z</u>
 7	05/05/17 09:50	General Viev				0	Load JPG	V
8	05/05/17 09:50	General Viev	W			0	Load JPG	2
9	05/05/17 09:50	General Viev	N			0	Load JPG	7
10	05/05/17 09:50	General Viev				0	Load JPG	7
11	05/05/17 09:50	General Viev	N			0	Load JPG	$\overline{\mathbf{Z}}$
12	05/05/17 09:50	General Viev	N			0	Load JPG	Z
13	05/05/17 09:50	General View				0	Load JPG	Ø
14	05/05/17 09:50	General Viev				0	Load JPG	Z
15	05/05/17 09:50	General Viev	W		ochica IIII iii	O	Load JPG	☑
16	05/05/17 09:50	General Viev	N			0	Load JPG	☑
17	05/05/17 09:50	General Viev	N			0	Load JPG	₹.
18	05/05/17 09:50	General Viev				0	Load JPG	3
19	05/05/17 09:50	General Viev	W			0	Load JPG	V
20	05/05/17 09:50	General Viev	N			0	Load JPG	4
21	05/05/17 09:50	General Viev	N			0	Load JPG	☑
22	05/05/17 09:50	General Viev	N			0	Load JPG	4
23	05/05/17 09:50	General Viev	N			0	Load JPG	4
24	05/05/17 09:50	General Viev	N			0	Load JPG	2
			Language and the state of the s					
	umentation					1 pe	rpage 🗸	✓
			nsultants Pte Ltd (H	Q)			Thumbnail	Print
1	05/05/17 09:48	workshop es				9	Load PDF	
2	05/05/17 09:48	Drivers Driv					Load PDF	
3	05/05/17 09:48	Certificate o					Load PDF	
4	05/05/17 09:48	1	ccident Statement				Load PDF Load PDF	
5	10/01/18 16:10	Discharge V	oucner			0	LUGU FUF	

Merimen e-Claims Page 2 of 2

Linked Accident Report Documents

View In Browse				wser 🗸	
Ass	essment Report	5	1 pe	r page 🔻	\square
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	03/05/17 12:12	Accident Statement	0	Load HTM	
<u> </u>	tos/Images	[[3 pe	r page 🗸	☑
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	03/05/17 12:11	Accident Photo	0	Load JPG	Z Z
2	03/05/17 12:11	Accident Photo	0	Load JPG	<u>N</u>
3	03/05/17 12:11	Accident Photo	0	Load JPG	☑
4	03/05/17 12:11	Accident Photo	0	Load JPG	☑
5	03/05/17 12:11	Accident Photo	0	Load JPG	☑
6	03/05/17 12:11	Accident Photo	0	Load JPG	\sqrt
7	03/05/17 12:11	Accident Photo	0	Load JPG	\(\)
8	03/05/17 12:11	Accident Photo	•	Load JPG	\
9	03/05/17 12:11	Accident Photo	0	Load JPG	K
10	03/05/17 12:11	Accident Photo	0	Load JPG	(5)
11	03/05/17 12:11	Accident Photo	0	Load JPG	>
12	03/05/17 12:11	Accident Photo	0	Load JPG	\
13	03/05/17 12:11	Accident Photo	0	Load JPG	₹
14	03/05/17 12:11	Accident Photo	0	Load JPG	\
15	03/05/17 12:11	Accident Photo	•	Load JPG	\
16	03/05/17 12:11	Accident Photo	0	Load JPG	\S
17	03/05/17 12:11	Accident Photo	•	Load JPG	N
18	03/05/17 12:11	Accident Photo	0	Load JPG	☑
19	03/05/17 12:11	Accident Photo	0	Load JPG	2
20	03/05/17 12:11	Accident Photo	0	Load JPG	\
	umentation		[1 pe	rpage 🗸	☑
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print Z
1	03/05/17 12:11	Sketch Plan	O	Load JPG	
2	03/05/17 12:12	Sketch Plan #2	0	Load JPG	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
	^			
	~			
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.				

Page 1 of 4 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way #07-16

Singapore 079120

Our File No:

CC3/AIG17008714/ATH3E2

Date:

10/01/2018

REFERENCE

Insured/Claimant: Date of Loss:

HO IM GEK 02/05/2017

Policy No:

Nature of Claim:

2100082720-09000

OD

Claim No:

4578661728SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SDB761D

Make & Model:

AUDI TT, 3.2 Quattro S-tronic (A)

Engine No:

BUB038226

Reg. Date:

28/03/2008 (Man. Year: 2007)

Chassis No: Odometer:

TRUZZZ8J881004811 17011 km

Colour:

Silver 3189 cc

Engine Capacity: Market Value/New Car Price:

S\$50,000.00

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size:

245/45 R17

Rear Tyre Size:

245/45 R17

Front Left Side:

Goodyear 6 mm Goodyear 6 mm

Rear Left Side:

Goodyear 6 mm

Front Right Side: The above values represent the remaining tyre treads depth

ו	Rear Right Side:	Ċ	soodyear	6 m
!				

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,584.00	12,501.00	2,083.00	14.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	17,060.00	10,810.00	6,250.00	36.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	31,644.00	23,311.00	8,333.00	26.33
Approved Total (Overridden) (S\$)		13,000.00		
- Excess (S\$)	3,000.00	3,000.00	0.00	0.00
(S\$)	28,644.00	10,000.00	18,644.00	65.09
+ GST 7.00/7.00% (S\$)	2,005.08	700.00	1,305.08	65.09
Nett Amount (S\$)	30.649.08	10.700.00	19,949.08	65.09

INSPECTION

Date of Assignment:

04/05/2017

Date Inspected:

04/05/2017 Inspected At:

Premium Automobiles Pte Ltd (HQ)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair:

13.0 days

Adjuster Report Page 2 of 4

Adjuster: ADRIAN LING Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR HANDLE - LH	Repair	137.00 FS	*- FS
2	1		*DOOR HANDLE CAP - LH	Repair	32.00 FS	*-F\$
3	1		*SIDE MEMBER TRIM - LH	Deformed	604.00 FS	*604.00 FS
4	1		*OUTER SILL TRIM STRIP - LH	Not Necessary	213.00 FS	*- FS
5	1		*REAR FENDER - LH	Distorted	9,323.00 FS	*9,323.00 FS
6	1		*ALUMINIUM RIM - LH	Cut	601.00 FS	*601.00 FS
7	1		*1/4 GLASS	Necessary	343.00 FS	*343.00 FS
8	1		*ROOF MOLDING - LH	Not Necessary	567.00 FS	*- FS
9	1		*INSULATION STRIP - LH	Not Necessary	15.00 FS	*-FS
10	1		*EDGE PROTECTION - LH	Not Necessary	126.00 FS	*-FS
11	1		*WHEEL HOUSING LINER - LH (NPA)	Not Necessary	0.00 FS	*- FS
12	1		*SOUND ABSORBER	Not Necessary	107.00 FS	*-FS
13	1		*REAR BUMPER GUIDE SECTION - LH	Not Necessary	36.00 FS	*- FS
14	1		*ALUMINIUM POWDER	Necessary	500.00 FS	*500.00 FS
15	1		*ALUMINIUM PRIMER	Necessary	185.00 FS	*185.00 FS
16	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
17	1		*ACRYLIC SEALER	Necessary	180.00 FS	*180.00 FS
18	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
19	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
20	1		*2K ADHESIVE GLUE	Necessary	195.00 FS	*195.00 FS
21	1		*COMBI RIVETS	Necessary	500.00 FS	*100.00 FS
22	1		*SUNDRIES	Necessary	500.00 FS	*50.00 FS
F=Fra	inchise	part. S=SpcN	ett.	Total Parts (S\$)	14,584.00	12,501.00

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

Particulars	Lab.Type	Repairer's	Amount
our Items			
TO RENEW LHS 1/4 GLASS TO FACILITATE FENDER RENEWAL	New	300.00	300.00
TO REMOVE AND REINSTALL REAR WIRE HARNESS FOR LIGHT, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT	New	1,400.00	1,400.00
TO REMOVE AND REINSTALL REAR SEATS, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENTS TRIMS AND SEAT BELTS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIR BIG ETC	New	1,600.00	1,600.00
TO SET UP AND PLACE VEHICLE IN ALUMINIUM REPAIR FACILITY	New	1,200.00	1,200.00
TO REMOVE REAR FITTINGS, DISMANTLE LHS DOOR, LHS SIDE MEMBER TRIM, REAR BUMPER AND REAR LID. CUT OUT AND REWELD LHS REAR FENDER. RENEW LHS DOOR TRANSFER OLD FITTINGS AND ALIGN TO POSITION. REINSTALL ALL PARTS REMOVED	New ,	6,600.00	3,000.00
TO RESPRAY LHS DOOR, LHS REAR FENDER, LHS SIDE MEMBER TRIM, LHS SILL PANEL, REAR BUMPER, DRAIN PANEL, ROOF CHANNEL AND CARRY OUT ALUMINIUM PRIMER WORKS, JOINT SEALER WORKS AND STONE CHIP TREATMENT	New	5,400.00	2,750.00
TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
TO CARRY OUT DIAGNOSTIC CHECKS	New	280.00	280.00
	ur Cost (S\$)	17,060.00	10,810.00
	TO RENEW LHS 1/4 GLASS TO FACILITATE FENDER RENEWAL TO REMOVE AND REINSTALL REAR WIRE HARNESS FOR LIGHT, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT TO REMOVE AND REINSTALL REAR SEATS, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENTS TRIMS AND SEAT BELTS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIR BIG ETC TO SET UP AND PLACE VEHICLE IN ALUMINIUM REPAIR FACILITY TO REMOVE REAR FITTINGS, DISMANTLE LHS DOOR, LHS SIDE MEMBER TRIM, REAR BUMPER AND REAR LID. CUT OUT AND REWELD LHS REAR FENDER. RENEW LHS DOOR TRANSFER OLD FITTINGS AND ALIGN TO POSITION. REINSTALL ALL PARTS REMOVED TO RESPRAY LHS DOOR, LHS REAR FENDER, LHS SIDE MEMBER TRIM, LHS SILL PANEL, REAR BUMPER, DRAIN PANEL, ROOF CHANNEL AND CARRY OUT ALUMINIUM PRIMER WORKS, JOINT SEALER WORKS AND STONE CHIP TREATMENT TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	TO RENEW LHS 1/4 GLASS TO FACILITATE FENDER TO RENEWAL TO REMOVE AND REINSTALL REAR WIRE HARNESS FOR LIGHT, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT TO REMOVE AND REINSTALL REAR SEATS, BACK REST, New HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENTS TRIMS AND SEAT BELTS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIR BIG ETC TO SET UP AND PLACE VEHICLE IN ALUMINIUM REPAIR NEW FACILITY TO REMOVE REAR FITTINGS, DISMANTLE LHS DOOR, LHS SIDE MEMBER TRIM, REAR BUMPER AND REAR LID. CUT OUT AND REWELD LHS REAR FENDER. RENEW LHS DOOR, TRANSFER OLD FITTINGS AND ALIGN TO POSITION. REINSTALL ALL PARTS REMOVED TO RESPRAY LHS DOOR, LHS REAR FENDER, LHS SIDE NEW MEMBER TRIM, LHS SILL PANEL, REAR BUMPER, DRAIN PANEL, ROOF CHANNEL AND CARRY OUT ALUMINIUM PRIMER WORKS, JOINT SEALER WORKS AND STONE CHIP TREATMENT TO RENEW LHS REAR RIM AND CARRY OUT WHEEL NEW ALIGNMENT	TO RENEW LHS 1/4 GLASS TO FACILITATE FENDER RENEWAL TO REMOVE AND REINSTALL REAR WIRE HARNESS FOR New 1,400.00 LIGHT, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT TO REMOVE AND REINSTALL REAR SEATS, BACK REST, New 1,600.00 HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENTS TRIMS AND SEAT BELTS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIR BIG ETC TO SET UP AND PLACE VEHICLE IN ALUMINIUM REPAIR New 1,200.00 FACILITY TO REMOVE REAR FITTINGS, DISMANTLE LHS DOOR, LHS SIDE MEMBER TRIM, REAR BUMPER AND REAR LID. CUT OUT AND REWELD LHS REAR FENDER. RENEW LHS DOOR, TRANSFER OLD FITTINGS AND ALIGN TO POSITION. REINSTALL ALL PARTS REMOVED TO RESPRAY LHS DOOR, LHS REAR FENDER, LHS SIDE New 5,400.00 MEMBER TRIM, LHS SILL PANEL, REAR BUMPER, DRAIN PANEL, ROOF CHANNEL AND CARRY OUT ALUMINIUM PRIMER WORKS, JOINT SEALER WORKS AND STONE CHIP TREATMENT TO RENEW LHS REAR RIM AND CARRY OUT WHEEL New 280.00 ALIGNMENT

< END OF ESTIMATES >