

SDU6118Y

TP: AXA

Kenneth @ LKK

03/03/14 @ 1100hrs
(LOT 2 CASE)Vehicle Insured : SJG 227 H
Accident Date : 21-Feb-2014

Our Ref : 140110 (AXA) / QUEK

MR SHAM KEAT MIN
Singapore

ESTIMATED COST OF REPAIR FOR VOLKSWAGEN JETTA 1.4TSI (2009) SDU6118Y

- 1 pc rear bumper - top
- 1 pc rear bumper - bottom
- 1 pc o/s rear bumper reflector
- 1 pc o/s rear bumper side bracket
- 1 pc rear bumper centre bracket
- 1 pc rear bumper sponge
- 1 pc rear bumper reinforcement
- 1 pc rear bumper towing cover
- 1 pc o/s taillamp assy
- 1 pc o/s taillamp lower bracket
- 1 pc bootlid logo
- 1 pc bootlid "JETTA" emblem
- 1 pc bootlid "TSI" emblem
- 1 pc o/s bootlid lamp assy

980.00
 540.00
 50.00
 SVC 64.00
 SVC 115.00
 SVC 100.00
 SVC 530.00
 70.00
 290.00
 SVC 76.00
 90.00
 75.00
 70.00
 190.00

Less 10% :

3,241.00
 -324.10
 2,916.90

- 1 pc reverse sensor

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

To focus taillamps. To check rear
wiring and lighting operation.

To remove and refit rear upholstery
trimming, roof lining, seats,
speaker board in order to
facilitate repairing works.

220.00 sn X

500.00 200

50.00 15

120.00 X

Not Authorised

- LKK Auto Consultants Pte Ltd
- Resurvey before/after Spray Painting.
- Damaged parts to stay when Re-inspection.
- Parts prices to be confirmed.
- Third Party Liability without insurance.
- No illegal modification is allowed.

Con't Page 2 ...

CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

興(龔)汽車私人有限公司

民通道 (大牌 34 座) 門牌 114 號

34 Sin Ming Drive, #01-114, Singapore 575708.

6452 7018 (5 Lines) Fax: 6458 3895

ail: service@kkinhin.com.sg

No. : 25804

Date : 26-Feb-2014

PAGE : 1



CO. REG. NO: 199402370D

GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

新民通道 (大牌 34 座) 門牌 114 號

Blk 34 Sin Ming Drive, #01-114, Singapore 575708.

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Email: service@kkinhin.com.sg

Vehicle Insured : SJG 227 H

Our Ref : 140110

Page : 2

No. : 25804

To apply undersealing.

~~ 80.00 X

To putty and respray on affected portions.

600.00 220k ✓

To remove and refit reverse sensor assy.

80.00 50k ✓

Total : S\$ 4,566.90

=====

Singapore Dollars Four Thousand Five Hundred and Sixty Six and Cents Ninety Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

1080.00 - Park ✓
- 107.

972.00 ✓

485.00 ✓

1457.00 ✓

P/P = \$ 1457.00 ✓