



TeamWork Garage Pte Ltd
53 Ubi Avenue 1 #01-23/24 Spore 408934
Paya Ubi Industrial Park
Tel : 6844 2475 Fax : 6844 2474
E-mail : claims@teamworkgarage.com
ROC number : 201015366H

Direct Asia Insurance Singapore Pte Ltd
88 South Bridge Road
Singapore 058716

3RD PARTY CLAIM ESTIMATION

Vehicle number	: FBG2460G
Make / Model	: APRILLA/ RS125S
Chassis number	: ZD4PY0002BS006921
Accident date	: 26 April 2017
Reference	: 1705-14

589.43
75.1
439.24
439.24

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT HEAD FARING <i>CRACK</i>	589.43 ✓
1	FRONT HEADLAMP <i>HW</i>	483.22 ✓
1 SET	FRONT WING MIRROR <i>HW</i>	289.34 ✓
1	FRONT WINDSCREEN VISOR <i>HW</i>	137.43 ✓
2	FRONT OUTER AIR GUIDE <i>HW</i>	238.44 ✓
2	FRONT SIGNAL LAMP <i>o/s broken HW</i>	150.20 ✓
1	HANDLE BAR <i>HW</i>	384.55 ✓
1 SET	FRONT HANDLE BAR BALANCER <i>HW</i>	120.46 ✓
1	FRONT CLUTCH LEVER <i>HW</i>	157.30 ✓
1	RH SIDE FAIRING <i>HW</i>	583.44 ✓
1	LH SIDE FAIRING <i>HW</i>	583.44 ✓
1	REAR LH FAIRING <i>HW</i>	439.24 ✓
1	REAR RH FAIRING <i>HW</i>	439.24 ✓
1	LOWER CLUTCH LEVER <i>HW</i>	174.32 ✓
1	RH LOWER STAND <i>HW</i>	89.30 ✓
1	REAR PILLION STAND <i>HW</i>	83.54 ✓
1	REAR EXHAUST <i>HW</i>	790.47 ✓
1	REAR EXHAUST BRACKET <i>HW</i>	153.44 ✓
1	REAR LH SIGNAL LAMP <i>HW</i>	87.30 ✓
1	FRONT FORK <i>HW</i>	1500.43 ✓
		7474.53
		Less 10 %
		Subtotal
		Balance C/F
		6727.08
		6727.08
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
		Balance B/F
		6727.08
1	FORK SEAL <i>HW</i>	160.00 ✓
1	SEAL OIL <i>HW</i>	80.00 ✓
		Subtotal
		Balance C/F
		6967.08
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
		Balance B/F
		6967.08
1	CHECK WIRING AND LIGHTNING SYSTEM	50.00 <i>HW</i>
2	ALIGN CHASSIS FRAME	700.00 <i>HW</i>
3	SPRAY PAINTING ON AFFECTED AREAS	600.00 <i>150/-</i>
4	REMOVE AND REFIT STICKER ON AFFECTED AREAS	300.00 <i>120/-</i>
		Subtotal
		1650.00
		Grand total
		8617.08

1543.01
- 10%
1388.71

150
120
270

1388.71
270
1658.71

L/S 1,300.00

1658.71
4/5 1300/-

08/05/2017 e 1400
HA
2100 3 1400
2000