

ASS. REC. BY:

REF:

CS/FCI 700 9022 / U + bn2

Special Instructions:

Surveyor:

ms

ASSIGNMENT (Office)

From (Person):

Cencler

of

FCL

Date/Time: 8/5/2017 6:56pm

Estimated Cost:

Bill to:

OD / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJ483817

Insured:

SID6849M

at Workshop m/s

Tanlim Motor

Tel:

68585151

of

SI Refu Lane 10

Policy No:

Claim No:

D17054649 MF5M

Sum Insured:

Excess:

Make of Veh:

D.O.A.

25/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

sup

H.O.D. Endorsement:

Date/Time:

9/5/2017 8:52am

Person Contacted:

William

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJ483817 x

SID6849M-CC3/A7M 16015831 / Hyb 392

DCA: 17/8/2016

17/2017 2:35pm - According to Riza, vehicle still pending arrangement with owner.

30/12/17 2:59pm Email to FCL temporary close file

(08/11/13) waf
ASS. REC. BY: MORIS

REF:

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: SJU83817
at Workshop m/s Carhu
of _____
Insured: SHID 0849M
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 251

IDAC Accident Rpt: _____ Consistent? : Yes or No

IA / PR Seen: 2 Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJU83817 Yr Regn: 12 09
Type: CA / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CA
Make: Toyota corolla Altis 1598
Colour: (7-21) A/C: Insured / Std / Nil / NA
Sp. Reading: 240975 T/Radio: Insured / Std / Nil / NA
Eng/No: _____
C/No: MRO53ZEE106159258
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Good / Jammed / Leaked / Burnt or
Brake: Good / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 195/65R15
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 2/5/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

14/5/18 confirmed 2/5 \$600 with Sam (Red: 1640.75 : 73%)

RECEIVED 16 MAY 2018

Date/Time, File Pass to?

☐ : Preli. Report

1) 16/5 TYPRT

☒ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

Photos

Others

TOTAL

Report Format : TP

Lump Sum / I.B.I. : \$ 600

110

50

22

182

Catherine Chong (LKK Auto)

From: Catherine Chong (LKK Auto) <admin-d@lkkauto.com>
Sent: Saturday, 30 December, 2017 2:59 PM
To: 'Claim Workflow System'; 'ASSIGNMENTS@LKKAUTO.COM'
Cc: 'SERENELER@FIRST-INSURANCE.COM.SG'
Subject: RE: SURVEY ASSESSMENT - D17004649MFSH/1

Dear Sir / Madam,

Please be informed that we are unable to conduct the inspection after some attempts to inform the workshop to present the vehicle.

This case has been pending for a long time due to the unavailability of the owner, therefore we decided to temporarily close this case.

Kindly advise us if there is any arrangement made and will be glad to re-open the case accordingly.

"Wishes you a Happy New Year 2018"

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ashley Chong (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 9 May, 2017 8:53 AM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; ASSIGNMENTS@LKKAUTO.COM
Cc: SERENELER@FIRST-INSURANCE.COM.SG; sur@lkkauto.com
Subject: RE: SURVEY ASSESSMENT - D17004649MFSH/1

Dear Sir/Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Ashley Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@first-insurance.com.sg]
Sent: Monday, 8 May, 2017 6:55 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; SERENELER@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17004649MFSH/1

MOTOR SURVEY ASSIGNMENT

Date	08-05-2017	Our Ref No. D17004649MFSH
Accident Date	02-05-2017	Claim Type. Third Party
Insured Vehicle	SHD6849M	Third Party Vehicle. SJU8381T
Survey Location	51 DEFU LANE 10	
Contact Person.	LAM WEI SHONG WILLIAM	
Contact No.	68585151/ 0	Fax No. 68580877
Survey Type	WITHOUT PREJUDICE: EST. COR PROVD - \$2,240.75 (LIABILITY UNCLEAR)	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TAN LIM MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/222246)



PRI Documents



Close X

PRI Header Details

Claim No	D17004649MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & TAN LIM N
Workshop Name	TAN LIM MOTOR PTE LTD (Contact Person : LAM WEI SHONG WILLIAM)	Survey Location & Contact Details	51 DEFU LANE 10 Mobile: 0 , Phone: 68585151 , Fax: 68580877 EmailId: WEI.SHONG@TLMOTOR.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: EST. COR PROVIDED - \$2,240.75 (		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD6849M	TP Vehicle No	SJU8381T
PRI Recieved Date	08-05-2017 04:01:28 PM	Surveyor Appointed Date	08-05-2017 06:55:57 PM	Surveyor Accept Date	09-05-2017 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	09-05-2017	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Date

Job Remarks

Action

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle
Vehicle Owner ParticularsOwner ID Type: **Business**

Owner ID: 5825E

Vehicle Details

Vehicle No.: SJU8381T

Vehicle to be Exported: Yes

Intended De-registration
Date: 03 May 2017

Vehicle Make: TOYOTA

Vehicle Model: COROLLA ALTIS 1.6 AUTO

Primary Colour: Silver

Manufacturing Year: 2009

Engine No.: 3ZZ4944926

Chassis No.: MR053ZEE106159258

Maximum Power Output: 80.0 kW (107 bhp)

Open Market Value: \$17,853.00

Original Registration
Date: 30 Dec 2009

First Registration Date: 30 Dec 2009

Transfer Count: 0

Actual ARF Paid: \$17,853.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry
Date: 29 Dec 2019

PARF Rebate Amount: \$10,711.00

Intended COE Rebate Details

COE Expiry Date: 29 Dec 2019

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$18,150.00

COE Rebate Amount: \$4,815.00

Total Rebate Amount: \$15,526.00

The information contained herein is correct as at 03 May 2017

OK



Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)



陳林摩呀私人有限公司

TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216

Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

First Capital Insured's Veh No : SHD6849M

Date of Accident : 02 May 2017

Messrs Global Advance Leasing

Estimate To Repair SJU8381T - Toyota Corolla Altis 1.6

Chassis No : MR053ZEE106159258

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	front bumper	\$ 435.00
02	2 ps	front bumper side retainer @ \$68.00	\$ 136.00
03	10 ps	front bumper fastener clips @ \$4.50	\$ 45.00
04	1 pc	o/s headlamp	\$ 625.00
			\$ 1,241.00
		Less 25 %	\$ 310.25
			\$ 930.75
		<u>LABOUR & MISC. CHARGES</u>	
01		To check electrical lighting concerned.	\$ 60.00
02		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 500.00
03		Putty and spray painting of the affected portion.	\$ 750.00
			\$ 1,310.00
		Total	\$ 2,240.75

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-548
252
411

not allocated
LKK

2/5 600/2
14/5/18

- confirmed w Date : 05 May 2017
Marcus 4s \$600.00

2 day

Take photo After rep-

Ref: LKK 2

14/05/18 @ 10:40

1PC
X

20
120
200



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17009023/Utn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 18-05-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6849M	Veh. Inspected	SJU 8381T	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17004649MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	08/05/2017	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA COROLLA ALTIS (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	MR053ZEE106159258	Colour	GREY	
Odometer	240975	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	FALKEN	6 mm	
L/H Front Tyre	195/65 R15	FALKEN	6 mm	
R/H Rear Tyre	195/65 R15	FALKEN	6 mm	
L/H Rear Tyre	195/65 R15	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/05/2017	Inspection Date	14/05/2018	
Survey held at	TAN LIM MOTOR PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJU 8381T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DEFORMED / TORN	435.00	435.00
2	FRONT BUMPER SIDE RETAINER @\$68.00	BENT (1 PC ONLY)	136.00	68.00
10	FRONT BUMPER FASTENER CLIPS @\$4.50	NECESSARY	45.00	45.00
1	O/S HEADLAMP	NOT NECESSARY	625.00	-
	LESS 25% DISCOUNT		-310.25	-137.00
			930.75	411.00
LABOUR				
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		60.00	20.00
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.		500.00	120.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		750.00	200.00
			1,310.00	340.00
GRAND TOTAL			2,240.75	751.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				600.00

Report Ref No. CS/FC117009023/Utnb2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.