

ASS. REC. BY:

REF: CS3/ACC/17009141/Ah3

Special Instruction:

Surveyor:
meimen

Adnan

ASSIGNMENT (Office)

From (Person):

Chiruey Ying

of

ACC

Date/Time: 11/5/2017 11:34am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SX7161M

Insured:

SLC9426M

at Workshop m/s

N 31 Automotive

Tel:

68420051

of

2 Kaki Bukit Ave 2 #01-17118

Policy No:

2400468826

Claim No:

1633595010567

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 7/5/2017

CA / REV / REP. / REV 24 HRS (wp)

H.O.D. Endorsement:

Date/Time: 11/5/2017 11:40am

Person Contacted:

Huixin

Vehicle IN/OUT

Date/Time

Action/Instruction (*) Estimate

SX7161M - CS/CTZ17001550 / Ah3m2

D.O.A. 2/1/2017

SLC9426M - X

Survey: 11/5/2017; dismantle: 12/5/2017; after repair: 15/5/2017



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CS3/AIG17009141/Ah3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 11-05-2017	
		Code : AIG	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SLC 9426M	Veh. Inspected	SGX 7161M
Policy No.	2100468826	Coverage (\$)	0.00
Claim No.	1633595010SG	Excess (\$)	0.00
Assign From	MERIMEN (CHIN LEE YING)	Assign Date	11/05/2017
2. Vehicle Particulars & Condition			
Make & Model	c.c 0		
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	07/05/2017	Inspection Date	11/05/2017
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

CSS/ALG17009141/PMS Survey Department Check List

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin: Case handler to make sure all information created by the assignment team are ACCURATE

(1) Office Assign Form

C Reference No.
C Customer Code
N Assign From
C Assign Date
C Veh No (Inspected)
C Veh No (Insured)
C D.O.A.
C Policy No
C Claim No
C Insurance Authorisation (CA /REV/REP)
C Report Type (Must Tally with Remarks Description)
C Weekend Charges
N Survey held at/Repairer
C Excess

Y-Date	N-Date
✓	
✓	
✓	
✓	
✓	
✓	
✓	
✓	
✓	
✓	
✓	
✓	
✓	
✓	

Y-Date	N-Date

Surveyor: Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C Vehicle No
C Regn Month/Year
N Vehicle Type
N Make & Model
C Engine Capacity. (C.C)
N Colour
C Odometer. (Sp. Reading)
C Chassis No
N General Condition
N Steering
N Brake
N Modification (Modi)
C Tyre Size
N Tyre Make
C Tyre Balance
C Date of Inspection
N Survey held
N Des. of Damages

✓	
✓	
✓	
✓	
✓	
✓	
✓	
✓	
✓	
✓	
✓	
✓	
✓	
✓	
✓	

(2) System - (Views/Merimen)

C Damaged Vehicle Photographs Uploaded

✓	
---	--

--	--

(3) Workshop Estimate/Assignment Form

N ALL Parts condition
C Market Value for OD cases
C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
C Days of repair
C Finalised Amount
C Re-inspection Cases to Finalize within 5 Days

(4) System - (Views/Merimen)

C Resurvey photo Uploaded

✓	
---	--

--	--

Check By:

Ashley 12/1/2017

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2017

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRE

CLAIM SUBFOLDER TRACKING

Case	Notified	Ext Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 May 2017 Edit Reg		11 May 2017 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by adjuster]						
Insured:	TEO KIM CHE, ID: S1314158D								
Main Claimant:	YES CAR LEASING PTE. LTD., Co. Reg. No.: 201426231K								
Vehicle Reg. No.:	SGX7161M	Date of Loss:	07/05/2017 17:00 - :59						
Claim Type:	TP / 1633595010SG	Policy/Cover Note No.:	2100468826 (Comprehensive) Coverage: 30/05/2016 - 29/05/2017						
Vehicle Reg. No. (Insured):	SLC9426M	Policy No. (Claimant):							
		Excess:							
Repairer:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ] Bennie-WZ.Tan@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 22/05/2017]								
ASSOCIATED MAIL RECEIVED			View All Compose Case Mail						
There are no mail for this case.									
ALL ASSOCIATED TASKS			View All Search Tasks Create New Task Complete						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Your password will expire in 14 days. [Click here to change it.](#)

- FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLC9426M AND SGX7161M ON 07/05/2017

From: Chin, Lee-Ying
To: assignments, Admin A
Cc: Fong, Andy-SY
Sent: 5/11/2017 11:34:03 AM

Attachments:  image001.jpg  image002.jpg  image003.jpg  image004.jpg  image005.jpg  image006.jpg  09052017112635.pdf

Hi LKK,

Kindly assist to survey this case. vehicle is in.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

From: Chin Hui Xin [mailto:huixin@n51.com.sg]

Sent: Tuesday, May 09, 2017 11:27 AM

To: Hassim, Mohd Fitri

Cc: Tan, Lily (AIG); Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Kaur, Baljit

Subject: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLC9426M AND SGX7161M ON 07/05/2017

Dear Sir/Madam,

Please see attached.

Regards,
Melody Chin
N-51 Automotive Pte Ltd
Office : 6842 0051
Fax : 6741 0510
www.n51.com.sg

|

On Tue, May 9, 2017 at 10:50 AM, Hassim, Mohd Fitri <MohdFitri.Hassim@aig.com> wrote:

Your Reference : SGX7161M
Our Reference : 1633595010SG-003

Dear Sir/Madam,

We refer to your email below.

Pursuant to Appendix C of Pre-Action Protocol for NIMA cases, citation 2.9. We will proceed to appoint our in house surveyor for the pre-repair inspection.

Thanks

Mohd Fitri Bin Hassim

AIG

Express Claims Adjuster II

FNOL-Singapore Windscreen | AIG Shared Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 14, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia

Tel: 8001206556 Ext: 1012117

MohdFitri.Hassim@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments hereto) is confidential and may be protected by legal privileges and work product immunities. If you are not the intended recipient, you must not use or disseminate the information. Receipt by anyone other than the intended recipient is not a waiver of any attorney-client or work product privilege. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Chin Hui Xin [<mailto:huixin@n51.com.sg>]

Sent: Tuesday, May 09, 2017 10:40 AM

To: Hassim, Mohd Fitri

Cc: Tan, Lily (AIG); Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Kaur, Baljit

Subject: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLC9426M AND SGX7161M ON 07/05/2017

Dear Sir/Madam,

We refer to your list of motor surveyors proposed.
We do not agree to your list of motor surveyors.

Please see attached.

Thank you

Regards,

Melody Chin

N-51 Automotive Pte Ltd

Office : 6842 0051

Fax : 6741 0510

www.n51.com.sg

||

On Tue, May 9, 2017 at 9:43 AM, Hassim, Mohd Fitri <MohdFitri.Hassim@aig.com> wrote:

Your Reference : SGX7161M
 Our Reference : 1633595010SG-003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
Lim Kok Chong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Roger Gan	ROG Associates
Ricky Teng	RT Appraisal Pte Ltd
Elson Teng	RT Appraisal Pte Ltd
Michael Cheong	RT Appraisal Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Henry Ng	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Steven Foong	LKK Auto Consultants Pte Ltd
Wei Jie	LKK Auto Consultants Pte Ltd
Ma Chin Fook	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks

Mohd Fitri Bin Hassim

AIG

Express Claims Adjuster II

FNOL-Singapore Windscreen | AIG Shared Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 14, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia

Tel: 8001206556 Ext: 1012117

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit Autohub
2 Kaki Bukit Ave 2, #01-17
Singapore 417921
Tel No. : +65 6744 0510 / 6842 0051 Fax No. : +65 6741 0510
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

Our Ref: SGX 7161 M
Your ref: SLC 9426 M

09 May 2017

AIG ASIA PACIFIC INSURANCE PTE. LTD.
NO: 78 SHENTON WAY
#07-16 CHARTIS BUILDING
SINGAPORE 079120
Attn: Motor Claims Department

BY EMAIL MohdFitri.Hassim@aig.com ONLY

Dear Sir/Madam,

NAME OF CLAIMANT : YES CAR LEASING PTE LTD
VEHICLE NUMBER : SGX 7161 M
YOUR INSURED VEHICLE NUMBER : SLC 9426 M
ACCIDENT ON 07 May 2017 ALONG HDB ESTATE OPEN CARPARK OF BLK 484 PASIR RIS
DR 4 #10-379 S(510484) AT ABOUT 16:55 HOURS

We refer to your email / fax dated 09 May 2017 wherein there is no agreement to the appointment to the appointment of Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

TWINCAR AUTOMOTIVE PTE LTD
Kaki Bukit Autohub
2 Kaki Bukit Avenue 2
#01-17
Singapore 417921
6842 0051 / 6744 0510 (Melody)

Contact Person:

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,



Twincar Automotive Pte Ltd

FOR SURVEYOR:

Please initial here after completion of pre-repair inspection. Thank you!

Appointed surveyor :

(Name & Signature) :

Date & Time of Inspection:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/05/2017 18:07
Date Of Accident	07/05/2017 16:55
Exact Location Of Accident	HDB ESTATE OPEN CARPARK OF BLK 484 PASIR RIS DR4
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGX7161M
Insured/Policyholder	
Name Of Registered Owner	YES CAR LEASING PTE. LTD.
Co Reg No	201426231K
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97297769
Alternative Phone No	OFFICE-64035155

Vehicle Particulars

Manufacturer	TOYOTA
Model	ESTIMA 2.4 A
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5072644775-02
Cover Note Number	

Driver

Name of Driver	KOH SEE KAW
NRIC No	S1592805J
Date Of Birth	04/07/1963
Occupation	OUTDOOR
Date Of Driving Pass	26/09/1983
Driving Experience	33 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97297769
Fax Number	
Contact Number	OTHERS-97297769
Email Address	NOEMAIL

Address	BLK 353 WOODLANDS AVE 1 #05-757
Postcode	730353
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RENTAL
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION- HEAD TO SIDE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	REVERT
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLC9426M
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	TEO KIM CHE
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law firms/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:

- (i) processing, handling and/or dealing with my claims, including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law firms/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law firms/law firms), which may be based outside of Singapore, for one or more of the above Purposes.




Policyholders Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

Vehicle A - SGX 7161 M
Vehicle B - SGX 9426 M



Sketch Plan #2

Describe Circumstances of the Accident

I WAS PARTICIPATING IN THE OPEN SPACE CARRIAGE AT 11:05 APPROX 01-15 475-487. I WAS TRAVELLING TOWARDS ABOUT 485 DIRECTION TO THE CARRIAGE END. WHILE TRAVELLING, STAFFING PERSONS PRESENTLY A VEHICLE STARTED MOVING OUT FROM THE LOT AND HIT STAFFING CAR. THE LEFT SIDE OF MY VEHICLE CRASHED FROM MY VEHICLE. AND REALIZED A VEHICLE BEARING (SVC 0436M) HAD COLLIDED IN MY LEFT SIDE OF MY VEHICLE INCLUDING MY VEHICLE LEFT FRONT AND REAR RIMS.

THE WHOLE ACCIDENT FOOTAGE WAS CAPTURED DOWN BY MY IN-CAR CAMERA.

VEHICLE A - SUV 7161M
VEHICLE B - SVC 0436M

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

8/5/2017

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 6231K

Vehicle Details

Vehicle No.: SGX7161M

Vehicle to be Exported: No

Intended De-registration Date: 11 May 2017

Vehicle Make: TOYOTA

Vehicle Model: ESTIMA 2.4 A

Primary Colour: Silver

Manufacturing Year: 2007

Engine No.: 2AZF057046

Chassis No.: ACR500043448

Maximum Power Output: 125.0 kW (167 bhp)

Open Market Value: \$28,714.00

Original Registration Date: 03 Sep 2007

First Registration Date: 03 Sep 2007

Transfer Count: 1

Actual ARF Paid: \$31,586.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 02 Sep 2017

PARF Rebate Amount: \$15,793.00

Intended COE Rebate Details

COE Expiry Date: 02 Sep 2017

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$18,539.00

COE Rebate Amount: \$573.00

Total Rebate Amount: \$16,366.00

The information contained herein is correct as at 11 May 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.
Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.
Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution
Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

Undercarriage

NAC	INC	Item	CON	AC	Qty
1372	995163	Frt LH Shock Absorber			
1373	991944	Frt LH Shock Absorber Mounting			
1374	990632	Frt LH Coil Spring			
1375	995198	Frt LH Knuckle Arm			
1376	995199	Frt LH Knuckle Arm Bearing			
1377	995178	Frt LH Lower Arm			
1378	995169	Frt LH Upper Arm			
1379	995183	Frt LH Tie Rod			
1380	995143	Frt LH Drive Shaft			
1381	990561	Frt LH Control Arm			
1382	992062	Frt LH Trailing Arm			
1383	991848	Frt LH Leaf Spring			
1384	991293	Frt LH Brake Disc Rotor			
1385	991281	Frt LH Brake Caliper			
1386	991292	Frt LH Brake Pipe			
1387	991287	Frt LH Brake Hose			
1388	991295	Frt LH Brake Sensor Wire			
1389	991989	Frt Stay Bar Bracket			
1390	994455	Steering Rack & Pinion			
1391	994435	Steering Cross Member			
1392	994519	Frt Sub Frame			
1393	992003	Frt Sub Frame Mounting			
1394	991217	Frt Anti Roll Bar			
1395	991219	Frt Anti Roll Bar Linkage			
1396	990887	Engine Block			
1397	990890	Engine Block Gasket			
1398	990972	Engine Oil Sump			
1399	990960	Engine Oil			
1400	992224	Gear Box Assy			
1401	992229	Gear Box Gasket			
1402	992241	Gear Box Oil Sump			
1403	992257	Gear Oil			
1404	990534	Centre Exhaust Pipe Assy			
1405	990532	Centre Exhaust Mounting			
1406	991134	Floor Panel			
1407	993719	Rear LH Shock Absorber			
1408	993723	Rear LH Shock Absorber Mounting			
1409	993170	Rear LH Coil Spring			
1410	993550	Rear LH Knuckle Arm			
1411	993551	Rear LH Knuckle Arm Bearing			
1412	993597	Rear LH Lower Arm			
1413	993884	Rear LH Upper Arm			
1414	995161	Rear LH Drive Shaft			
1415	995216	Rear LH Control Arm			
1416	993881	Rear LH Trailing Arm			
1417	993573	Rear LH Leaf Spring			
1418	992941	Rear LH Brake Disc Rotor			
1419	992937	Rear LH Brake Caliper Assy			
1420	990434	Rear LH Brake Pipe			
1421	992946	Rear LH Brake Hose			
1422	993819	Rear Sub Frame			
1423	993820	Rear Sub Frame Mounting			
1424	992813	Rear Anti Roll Bar			
1425	990168	Rear Anti Roll Bar Linkage			
1426	990202	Axle Beam			
1427	990170	Rear Axle Panhard Rod			
1428	990810	Differential Assy			
1429	992706	Propeller Shaft			

NAC	INC	Item	CON	AC	Qty
1428	991935	Frt RH Shock Absorber			
1429	991944	Frt RH Shock Absorber Mounting			
1430	990632	Frt RH Coil Spring			
1431	991844	Frt RH Knuckle Arm			
1432	991845	Frt RH Knuckle Arm Bearing			
1433	991851	Frt RH Lower Arm			
1434	992064	Frt RH Upper Arm			
1435	992040	Frt RH Tie Rod			
1436	991692	Frt RH Drive Shaft			
1437	990661	Frt RH Control Arm			
1438	992062	Frt RH Trailing Arm			
1439	991848	Frt RH Leaf Spring			
1440	991293	Frt RH Brake Disc Rotor			
1441	991281	Frt RH Brake Caliper			
1442	991292	Frt RH Brake Pipe			
1443	991287	Frt RH Brake Hose			
1444	991295	Frt RH Brake Sensor Wire			
1445	993720	Rear RH Shock Absorber			
1446	993723	Rear RH Shock Absorber Mounting			
1447	993173	Rear RH Coil Spring			
1448	993550	Rear RH Knuckle Arm			
1449	993551	Rear RH Knuckle Arm Bearing			
1450	993601	Rear RH Lower Arm			
1451	993885	Rear RH Upper Arm			
1452	993322	Rear RH Drive Shaft			
1453	993178	Rear RH Control Arm			
1454	995117	Rear RH Trailing Arm			
1455	995110	Rear RH Leaf Spring			
1456	992942	Rear RH Brake Disc Rotor			
1457	992938	Rear RH Brake Caliper Assy			
1458	990434	Rear RH Brake Pipe			
1459	992947	Rear RH Brake Hose			

No of Items: 10

Assessor:

Condition (CON)

(01) Bent (2) Denied (3) Distorted (4) Cracked (5) Cut (6) Scratched
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary (12) Missing
(13) Torn (14) Unconfirmed (15) Not Working

MOTOR CAR (LH)

ACTION (AC)

(1) Replace (✓) (2) Repair (D) (3) Check (S)
(4) No Comment (N/C)

Aug 2005

Left Portion

NAC	INC	Item	CON	AC	Qty
1255	995326	Frt LH Door	DD	✓	
1256	995140	Frt LH Door Protector			
1257	995104	Frt LH Door Hinge			
1258	995142	Frt LH Door Wing Mirror			
1259	995102	Frt LH Door Garnish	NEC	✓	
1260	991593	Frt LH Door Glass Outer Moulding			
1261	991588	Frt LH Door Glass Inner Moulding			
1262	995103	Frt LH Door Glass			
1263	991595	Frt LH Door Glass Regulator			
1264	991596	Frt LH Door Glass Regulator Motor			
1265	991662	Frt LH Door Rubber	NEC	✓	
1266	991636	Frt LH Door Outer Handle			
1267	991607	Frt LH Door Inner Handle			
1268	991625	Frt LH Door Lock w/Key			
1269	991624	Frt LH Door Lock			
1270	991562	Frt LH Door Central Lock			
1271	991675	Frt LH Door Switch			
1272	991617	Frt LH Door Inner Trim Board			
1273	991568	Frt LH Door Checker			
1274	991575	Frt LH Door Felt			
1275	991688	Frt LH Door Wire Harness			
1276	991683	Frt LH Door Window Glass Pillar			
1277	991640	Frt LH Door Outer Pillar			
1278	991613	Frt LH Door Inner Pillar			
1279	991646	Frt LH Door Pillar Inner Garnish			
1280	990554	Centre Pillar LH			
1281	990542	Centre Inner Pillar LH			
1282	990517	Centre Pillar Upper Garnish LH			
1283	990564	Centre Pillar Lower Garnish LH			
1284	991670	Frt LH Door Step Garnish			
1285	994052	Rocker Panel LH			
1286	994049	Rocker Panel Inner Panel LH			
1287	994046	Rocker Panel Garnish LH			
1288	994055	Rocker Panel Outer Side Skirt LH			
1004	991300	Frt Bumper			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1029	995153	Frt LH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1096	995070	Frt LH Fender	DD	R	
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
		Frt LH Wheel Rim	CUT	✓	
		" " " Tyre			7075

Vehicle No: **SGX 7161M**

NAC	INC	Item	CON	AC	Qty
1289	995156	Rear LH Door	DD	✓	
1290	993282	Rear LH Door Protector			
1291	995194	Rear LH Door Hinge			
1292	993228	Rear LH Door Garnish	NEC	✓	
1293	993278	Rear LH Door Glass Outer Moulding			
1294	993231	Rear LH Door Glass Inner Moulding			
1295	995190	Rear LH Door Glass			
1296	993238	Rear LH Door Glass Regulator			
1297	995192	Rear LH Door Glass Regulator Motor			
1298	993294	Rear LH Door Rubber	NEC	✓	
1299	993275	Rear LH Door Outer Handle			
1300	993250	Rear LH Door Inner Handle			
1301	993261	Rear LH Door Lock			
1302	993256	Rear LH Door Inner Trim Board			
1303	993218	Rear LH Door Checker			
1304	993230	Rear LH Door Glass Channel			
1305	993242	Rear LH Door Glass Triangle Garnish			
1306	993285	Rear LH Door 1/4 Glass			
1307	993288	Rear LH Door 1/4 Glass Rubber			
1308	993287	Rear LH Door 1/4 Glass Pillar			
1309	993305	Rear LH Door Step Garnish			
1310	993309	Rear LH Door Switch			
1311	994070	Roof Top Panel			
1312	994098	Roof Top Moulding			
1313	994085	Roof Top Air-bag			
1314	994084	Roof Top Air-bag Sensor			
1315	994083	Roof Top Air-bag Control Unit			
1141	992958	Rear Bumper	DD	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	DIS	✓	
1149	993045	Rear Bumper Reinforcement			
1151	993077	Rear Bumper Sponge			
1153	993040	Rear Bumper Protector			
1155	993026	Rear Bumper Moulding			
1157	993023	Rear Bumper Lower Spoiler			
1163	993851	Rear LH Taillamp			
1218	993436	Rear LH Fender	DD	R	
1219	993449	Rear LH Fender Protector			
1136	990247	Sticker			
		Rear LH Wheel Rim	CUT	✓	
		" " " Tyre			7075

No of Items: 17

Assessor: _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 May 2017 Edit Reg		11 May 2017 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:

TEO KIM CHE, ID: S1314158D

Main Claimant:

YES CAR LEASING PTE. LTD., Co. Reg. No.: 201426231K

Vehicle Reg. No.:

SGX7161M

Date of Loss:

07/05/2017 17:00 - :59

Claim Type:

TP / 1633595010SG

Policy/Cover Note No.:

2100468826 (Comprehensive)
Coverage: 30/05/2016 - 29/05/2017

Vehicle Reg. No. (Insured):

SLC9426M

Policy No. (Claimant):

Excess:

Repairer:

N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ]
Bennie-WZ.Tan@aig.com

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 22/05/2017]

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGX7161M (1633595010SG)**
[SLC9426M]

TP

YES CAR LEASING PTE. LTD.

May 7 2017 5:00PM

[TEO KIM CHE]

N-51 Automotive Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	Use Viewer
Assessment Reports						1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)				Thumbnail	Print
1	12/05/17 16:26	Accident Statement From:OD - Reg. No: SLC9426M, Claimant: TEO KIM CHE				Load HTM	
Photos/Images						3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print
1	16/05/17 16:34	General View				Load JPG	☒
2	16/05/17 16:34	General View				Load JPG	☒
3	16/05/17 16:34	General View				Load JPG	☒
4	16/05/17 16:35	General View				Load JPG	☒
5	16/05/17 16:35	General View				Load JPG	☒
6	16/05/17 16:35	General View				Load JPG	☒
7	16/05/17 16:35	General View				Load JPG	☒
8	16/05/17 16:35	General View				Load JPG	☒
9	16/05/17 16:35	General View				Load JPG	☒
10	16/05/17 16:35	General View				Load JPG	☒
11	16/05/17 16:35	General View				Load JPG	☒
12	16/05/17 16:35	General View				Load JPG	☒
13	16/05/17 16:35	General View				Load JPG	☒
14	16/05/17 16:35	General View				Load JPG	☒
15	16/05/17 16:35	General View				Load JPG	☒
16	16/05/17 16:35	General View				Load JPG	☒
17	16/05/17 16:35	General View				Load JPG	☒
18	16/05/17 16:35	General View				Load JPG	☒
19	16/05/17 16:35	General View				Load JPG	☒
20	16/05/17 16:35	General View				Load JPG	☒
21	16/05/17 16:35	General View				Load JPG	☒
22	16/05/17 16:35	General View				Load JPG	☒
23	16/05/17 16:35	General View				Load JPG	☒
24	16/05/17 16:35	General View				Load JPG	☒
25	16/05/17 16:35	General View				Load JPG	☒
26	16/05/17 16:35	General View				Load JPG	☒
27	16/05/17 16:35	General View				Load JPG	☒
28	16/05/17 16:35	General View				Load JPG	☒
29	16/05/17 16:35	General View				Load JPG	☒
30	16/05/17 16:35	General View				Load JPG	☒
31	16/05/17 16:35	General View				Load JPG	☒
32	16/05/17 16:35	General View				Load JPG	☒
33	16/05/17 16:35	General View				Load JPG	☒
34	16/05/17 16:35	General View				Load JPG	☒
35	16/05/17 16:36	Reinspection Photo				Load JPG	☒

36	16/05/17 16:36	Reinspection Photo		Load JPG	☒
37	16/05/17 16:36	Reinspection Photo		Load JPG	☒
38	16/05/17 16:36	Reinspection Photo		Load JPG	☒
39	16/05/17 16:36	Reinspection Photo		Load JPG	☒
40	16/05/17 16:36	Reinspection Photo		Load JPG	☒
41	16/05/17 16:36	Reinspection Photo		Load JPG	☒
42	16/05/17 16:36	Reinspection Photo		Load JPG	☒
43	16/05/17 16:36	Reinspection Photo		Load JPG	☒
44	16/05/17 16:36	Reinspection Photo		Load JPG	☒
45	16/05/17 16:36	Reinspection Photo		Load JPG	☒
46	16/05/17 16:36	Reinspection Photo		Load JPG	☒
47	16/05/17 16:36	Reinspection Photo		Load JPG	☒
48	16/05/17 16:36	Reinspection Photo		Load JPG	☒
49	16/05/17 16:36	Reinspection Photo		Load JPG	☒
50	16/05/17 16:36	Reinspection Photo		Load JPG	☒
51	16/05/17 16:36	Reinspection Photo		Load JPG	☒
52	16/05/17 16:36	Reinspection Photo		Load JPG	☒
53	16/05/17 16:36	Reinspection Photo		Load JPG	☒
54	16/05/17 16:36	Reinspection Photo		Load JPG	☒
55	16/05/17 16:36	Reinspection Photo		Load JPG	☒
56	16/05/17 16:36	Reinspection Photo		Load JPG	☒
57	16/05/17 16:36	Reinspection Photo		Load JPG	☒
58	16/05/17 16:36	Reinspection Photo		Load JPG	☒
59	16/05/17 16:36	Reinspection Photo		Load JPG	☒
60	16/05/17 16:36	Reinspection Photo		Load JPG	☒
61	16/05/17 16:37	Reinspection Photo		Load JPG	☒
62	16/05/17 16:37	Reinspection Photo		Load JPG	☒
63	16/05/17 16:37	Reinspection Photo		Load JPG	☒
64	16/05/17 16:37	Reinspection Photo		Load JPG	☒
65	16/05/17 16:37	Reinspection Photo		Load JPG	☒
66	16/05/17 16:37	Reinspection Photo		Load JPG	☒
67	16/05/17 16:37	Reinspection Photo		Load JPG	☒
68	16/05/17 16:37	Reinspection Photo		Load JPG	☒
69	16/05/17 16:37	Reinspection Photo		Load JPG	☒
70	16/05/17 16:37	Reinspection Photo		Load JPG	☒
71	16/05/17 16:37	Reinspection Photo		Load JPG	☒
72	16/05/17 16:37	Reinspection Photo		Load JPG	☒
73	16/05/17 16:37	Reinspection Photo		Load JPG	☒
74	16/05/17 16:37	Reinspection Photo		Load JPG	☒
75	16/05/17 16:37	Reinspection Photo		Load JPG	☒
76	16/05/17 16:37	Reinspection Photo		Load JPG	☒
77	16/05/17 16:37	Reinspection Photo		Load JPG	☒
78	16/05/17 16:37	Reinspection Photo		Load JPG	☒
79	16/05/17 16:37	Reinspection Photo		Load JPG	☒
80	16/05/17 16:37	Reinspection Photo		Load JPG	☒
81	16/05/17 16:37	Reinspection Photo		Load JPG	☒
82	16/05/17 16:37	Reinspection Photo		Load JPG	☒
83	16/05/17 16:37	Reinspection Photo		Load JPG	☒
84	16/05/17 16:37	Reinspection Photo		Load JPG	☒
85	16/05/17 16:37	Reinspection Photo		Load JPG	☒
86	16/05/17 16:37	Reinspection Photo		Load JPG	☒

87	14/06/17 15:05	Photo After Spray		Load JPG	☒
88	14/06/17 15:05	Photo After Spray		Load JPG	☒
89	14/06/17 15:05	Photo After Spray		Load JPG	☒
90	14/06/17 15:05	Photo After Spray		Load JPG	☒
91	14/06/17 15:05	Photo After Spray		Load JPG	☒
92	14/06/17 15:05	Photo After Spray		Load JPG	☒
93	14/06/17 15:05	Photo After Spray		Load JPG	☒
94	14/06/17 15:05	Photo After Spray		Load JPG	☒
95	14/06/17 15:05	Photo After Spray		Load JPG	☒
96	14/06/17 15:05	Photo After Spray		Load JPG	☒
97	14/06/17 15:05	Photo After Spray		Load JPG	☒
98	14/06/17 15:05	Photo After Spray		Load JPG	☒
99	14/06/17 15:05	Photo After Spray		Load JPG	☒
100	14/06/17 15:05	Photo After Spray		Load JPG	☒
101	14/06/17 15:05	Photo After Spray		Load JPG	☒
102	14/06/17 15:05	Photo After Spray		Load JPG	☒
103	14/06/17 15:05	Photo After Spray		Load JPG	☒
104	14/06/17 15:05	Photo After Spray		Load JPG	☒
105	14/06/17 15:05	Photo After Spray		Load JPG	☒
106	14/06/17 15:05	Photo After Spray		Load JPG	☒
107	14/06/17 15:05	Photo After Spray		Load JPG	☒
				1 per page	☒
Documentation				Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			
1	11/05/17 15:01	ACKNOWLEDGEMENT EMAIL AIG DD 11052017		Load PDF	
2	11/05/17 16:00	TP GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG17009141/AH3E2
Date: 12/07/2017

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100468826
Claimant Vehicle No: SGX7161M Insured Vehicle No: SLC9426M
Date of Loss: 07/05/2017 Nature of Claim: TP Claim No: 1633595010SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGX7161M
Make & Model: TOYOTA ESTIMA, 2.4 (A)
Reg. Date: 03/09/2007 (Man. Year: 2007) Engine No: 2AZF057046
Colour: Silver Chassis No: ACR500043448
Engine Capacity: 2362 cc Odometer: 181387 km
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm
The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 11/05/2017
Date Inspected: 11/05/2017 Inspected At: N-51 Automotive Pte Ltd (HQ)
BLK 2 KAKI BUKIT, #01-17/18 KAKI
BUKIT AUTOHUB
Singapore 417921
Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: Ashley Chong Chin Yan

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT LH SHOCK ABSORBER	* Check	0.00 F	*-F
2	1		*FRT LH SHOCK ABSORBER MOUNTING	* Check	0.00 F	*-F
3	1		*FRT LH KNUCKLE ARM	* Check	0.00 F	*-F
4	1		*FRT LH KNUCKLE ARM BEARING	* Check	0.00 F	*-F
5	1		*FRT LH LOWER ARM	* Check	0.00 F	*-F
6	1		*REAR LH SHOCK ABSORBER	* Check	0.00 F	*-F
7	1		*REAR LH SHOCK ABSORBER MOUNTING	* Check	0.00 F	*-F
8	1		*REAR LH KNUCKLE ARM	* Check	0.00 F	*-F
9	1		*REAR LH KNUCKLE ARM BEARING	* Check	0.00 F	*-F
10	1		*REAR LH LOWER ARM	* Check	0.00 F	*-F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >