

145. CASE OWNER

CC 1/111700

LKK-
IDAC

Survivor:

DOI:

Date / Time :

Registered in Meriminen:

Pre-assign / CCU / FTE



Insured Vehicle No. _____

Name of Insured

Insured Tel No. _____

Excess Sec II :\$8

Is driver the owner?

(YES / NO)

Nature of Accident :

If **NO**, Driver Name / Age :

Driver Tel No.: _____

(V/L YES NO)

Claim No.

Policy No.

Make / Model :

Place of Accident :

OL GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability :

Final ? Yes / No



INSRS:
WSP:
Tel :
Liability
RMKS:



INRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:

[illegible]

ASS. REC. BY:

REF: TJ /

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC51294Yr Regn: 12, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Renault Latitudec.c. 1995Colour n. white / Red

A/C: Insured / Std / NI / NA

Sp. Reading 34887

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VFIABL15AUC

276555

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil S/Rim / STD A/Rim orTyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Long Long

Front

Rear

R/Bal. 8 mmR/Bal. 8 mmL/Bal. 8 mmL/Bal. 8 mmD.O.A. 6/5/17D.O.I. 9/5/17

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

11/15 112 poss to Carhous

11/15 112 poss to Carhous

7/6/18 11/15 112 poss to Carhous 112 poss to Carhous (4+2x101.46+2740)

4 repair days + 1 PM + 1 Sunday = 6 days.

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS \$ _____

Photos _____

Others _____

TOTAL

Report Format: _____

Lump Sum / I.B.I. (\$) _____

Add Fee:

☐

Site Insp (\$ _____)

☐

Interview (\$ _____)

☐

Tech Invs (\$ _____)

☐

Weekend (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC3/III17009146/Kzb3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 11-05-2017		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKP 8938C	Veh. Inspected	SHC 5129U	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	11/05/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	06/05/2017	Inspection Date	09/05/2017	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5129U - INDIA*Not Authorised**11 Sep @ 4500/***AAD1705-091**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

SHC5129U - CANDY

VF1ABL15AUC276555

RENAULT

LATITUDE

06.05.2017

INDIA**PART****LIST**

1	1	BUMPER COVER FRT	\$	<i>R</i> 1,259.42	X
2	1	BUMPER LOWER GRILLE FRT	\$	<i>R</i> 266.80	X
3	1	BUMPER UNDERTRAY FRT	\$	<i>R</i> 472.83	X
4	1	BUMPER FOG LAMP GRILLE RH	\$	<i>R</i> 181.75	X
5	1	BUMPER RETAINER FRT RH	\$	<i>R</i> 150.77	X
6	1	BUMPER SUPPORT FRT RH	\$	<i>R</i> 123.88	X
7	1	RADIATOR GRILLE	\$	<i>R</i> 1,707.78	} X
8	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>R</i> 225.36	
9	1	RADIATOR GRILLE FRAME	\$	<i>R</i> 1,353.75	
10	1	WIPER RESERVOIR	\$	<i>R</i> 348.25	
11	1	WIPER RESERVOIR NECK	\$	<i>R</i> 136.11	
12	1	WIPER RESERVOIR MOTOR	\$	<i>R</i> 270.06	
13	1	FRAME FULL SUPPORT PANEL	\$	<i>R</i> 615.90	
14	1	BONNET	\$	<i>R</i> 1,941.63	
15	1	BONNET INSULATOR	\$	<i>R</i> 405.73	
16	1	BONNET HINGE RH	\$	<i>R</i> 348.31	
17	1	HEADLAMP RH	\$	<i>R</i> 1,184.43	} X
18	1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15	
19	1	FENDER PANEL FRT RH	\$	<i>R</i> 783.83	✓
20	1	FENDER WHEELARCH FRT RH	\$	<i>R</i> 139.52	X
21	1	FENDER INSULATOR RH	\$	<i>R</i> 130.84	X
22	1	WHEEL HOUSING PANEL FRT RH	\$	<i>R</i> 5,173.47	X
23	1	DOOR FRT RH	\$	<i>R</i> 2,844.66	✓
24	1	DOOR MOULDING FRT RH	\$	<i>R</i> 410.27	X
25	1	DOOR HINGE UPPER RH	\$	<i>R</i> 261.28	X
26	1	DOOR HINGE LOWER RH	\$	<i>R</i> 300.55	X
27	1	DOOR HANDLE OUTER FRT RH	\$	<i>R</i> 477.76	✓
28	1	DOOR HANDLE COVER FRT RH	\$	<i>R</i> 13.22	✓

TRANS-CAB AUTO SERVICES PTE LTD**AAD1705-091**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5129U - INDIA

29	1	DOOR LOCK FRT RH	\$	<i>R</i> 908.75 <i>X</i>
30	1	DOOR CATCH FRT RH	\$	<i>R</i> 131.23 <i>X</i>
31	1	DOOR SEAL FRT RH	\$	<i>Cur</i> 59.40 <i>✓</i>
32	1	DOOR PANEL REAR RH	\$	<i>R</i> 2,844.66 <i>X</i>
33	1	DOOR HINGE REAR UPPER RH	\$	<i>R</i> 274.50 <i>✓</i>
34	1	DOOR HINGE REAR LOWER RH	\$	<i>R</i> 300.55 <i>✓</i>
35	1	DOOR MOULDING REAR RH	\$	<i>R</i> 176.82 <i>X</i>
36	1	ROCKER PANEL INNER RH	\$	<i>R</i> 1,024.79 <i>X</i>
37	1	ROCKER PANEL CENTER RH	\$	<i>R</i> 990.25 <i>X</i>
38	1	FENDER PANEL REAR RH	\$	<i>R</i> 3,299.13 <i>X</i>
39	1	BUMPER COVER REAR	\$	<i>R</i> 1,108.46 <i>X</i>

TOTAL \$ 32,798.84

10% \$ 3,279.88

\$ 29,518.95

Specical Nett

1	1SET	FRONT BUMPER CLIP	\$	<i>nn</i> 66.00 <i>X</i>
2	1	DOOR STICKER "Trans-cab"	\$	<i>nn</i> 80.00 <i>60.00</i>
3	1	DOOR STICKER "Classic"	\$	<i>nn</i> 30.00 <i>15.00</i>
4	1	DOOR STICKER "6555-3333"	\$	<i>nn</i> 80.00 <i>60.00</i>
5	1	RIM RH FRT	\$	<i>R</i> 385.00 <i>X</i>
6	1	TYRE RH FRT	\$	<i>R</i> 330.00 <i>X</i>

TOTAL \$ 971.00

TOTAL PARTS \$ 30,489.95

Panel beating, knocking and straightening the
necessary portion, remove and renewal of parts,
adjust and realign the same

\$ 4,200.00 *6000*

To Check Electrical Lighting Concerned.

\$ 170.00 *200*

Putty and spray painting of the affected portion.

\$ 4,500.00 *9000*

To check steering geometry and computer wheel
alignment

\$ 220.00 *600*

TRANS-CAB AUTO SERVICES PTE LTD**AAD1705-091**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5129U - INDIA

To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	1201
To transfer of Front fender fittings, attachment and perform water seepage test.	\$	380.00	~ 380.00 X
To transfer of Bonnet fittings, attachment and perform water seepage test.	\$	380.00	~ 380.00 X
To rust-proofing of the affected areas.	\$	170.00	601
Towing Fee	\$	150.00	~ 150.00 X
To transfer of tire, rim and on wheel balancing.	\$	170.00	~ 170.00 X

TOTAL	\$	10,510.00
Over All Total	\$	40,999.95

(PARTS BY PARTS) Repair Days**15 Days****4 days**

UKX Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 3876K

Vehicle Details

Vehicle No.: SHC5129U
Vehicle to be Exported: Yes
Intended De-registration Date: 08 May 2017
Vehicle Make: RENAULT
Vehicle Model: LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour: Red
Manufacturing Year: 2013
Engine No.: M9R8839C000872
Chassis No.: VF1ABL15AUC276555
Maximum Power Output: 127.0 kW (170 bhp)
Open Market Value: \$19,998.00
Original Registration Date: 27 Dec 2013
First Registration Date: 27 Dec 2013
Transfer Count: 0
Actual ARF Paid: \$12,498.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 26 Dec 2021
PARF Rebate Amount: \$9,373.00

Intended COE Rebate Details

COE Expiry Date: 26 Dec 2021
COE Category: A - Car (1600cc & below)
COE Period(Years): 8
PQP Paid: \$62,740.00
COE Rebate Amount: \$36,324.00

Total Rebate Amount: \$45,697.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.
The information contained herein is correct as at 08 May 2017

OK



Please read through the Privacy Statement, Terms of Use and Disclaimer.
Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.
Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution
Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

Print Received Message

This mail is associated with :

***SHC5129U (MCA170157)**

[SKP8938C]

TP

TRANS-CAB SERVICES PTE LTD

May 6 2017 12:00AM

[COMFORTDELGRO RENT-A-CAR PTE LTD]

Trans-cab Auto Services Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 12/09/2019 14:04 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$5660.00) - SHC5129U - Claim Handler: Lalitha Krishnan

Approved:5660.00:Offer \$5,660 global

...CLAIM SUBFOLDER...(Pending for Survey Report)
Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 May 2017 15:30 Edit Reg		09 May 2017 00:00 Edit Adj Rpt	S\$4,500.00 Edit Estimates	S\$4,500.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS		[Created by adjuster]
Insured:	COMFORTDELGRO RENT-A-CAR PTE LTD, Co. Reg. No.: 198105775H	
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K	
Vehicle Reg. No.:	SHC5129U	Date of Loss: 06/05/2017 00:00 - :59 [40 Months and 9 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCA170157	Policy/Cover Note No.: M480822 (Comprehensive)
Vehicle Reg. No. (Insured):	SKP893BC	Policy No. (Claimant): VPX/P1680520
		Excess: S\$750.00
Repairer:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666	
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Lalitha Krishnan - 6347 6139]	
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 22/05/2017]	

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

• III_SG (12/09/2019): Alert - Adj Mandate Approved (S\$5660.00) - SHC5129U - Claim Handler: Lalitha Kri...

• III_SG (23/01/2018): Alert - Adj Mandate Approved (S\$0.00) - SHC5129U - Claim Handler: Lalitha Krishn...

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHC5129U (MCA170157)
[SKP8938C]
TP
TRANS-CAB SERVICES PTE LTD
May 6 2017 12:00AM
[COMFORTDELGRO RENT-A-CAR PTE LTD]
Trans-cab Auto Services Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View In Browser

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	16/09/19 09:23	General View		Load JPG	☒
2	16/09/19 09:23	General View		Load JPG	☒
3	16/09/19 09:23	General View		Load JPG	☒
4	16/09/19 09:23	General View		Load JPG	☒
5	16/09/19 09:23	General View		Load JPG	☒
6	16/09/19 09:23	General View		Load JPG	☒
7	16/09/19 09:23	General View		Load JPG	☒
8	16/09/19 09:23	General View		Load JPG	☒
9	16/09/19 09:23	General View		Load JPG	☒
10	16/09/19 09:23	General View		Load JPG	☒
11	16/09/19 09:23	General View		Load JPG	☒
12	16/09/19 09:23	General View		Load JPG	☒
13	16/09/19 09:23	General View		Load JPG	☒
14	16/09/19 09:23	General View		Load JPG	☒
15	16/09/19 09:23	General View		Load JPG	☒

Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	11/05/17 19:12	TP ESTIMATE- MARKED		Load PDF	
2	11/05/17 19:12	TP GIA REPORT		Load PDF	
3	06/09/19 15:05	WORKSHOP INVOICE		Load PDF	
4	06/09/19 15:05	RENTAL RECEIPT		Load PDF	
5	06/09/19 15:05	RENTAL MILEAGE		Load PDF	
6	06/09/19 15:05	LTA SEARCH		Load PDF	
7	06/09/19 15:05	LOD		Load PDF	
8	17/03/20 09:26	AUTHORISATION TO ACT FORM		Load PDF	
9	17/03/20 09:26	DISCHARGE VOUCHER		Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print	
1	11/05/17 15:55	Singapore Accident Statement		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III17009146/KGS3Q2
Date: 17/03/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: M480822
Claimant SHC5129U Insured Vehicle No : SKP8938C
Vehicle No : SHC5129U
Date of Loss: 06/05/2017 Nature of Claim: TP Claim No: MCA170157

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC5129U Engine No: M9R8839C000872
Make & Model: RENAULT LATITUDE, 2.0 L (A) Chassis No: VF1ABL15AUC276555
Reg. Date: 27/12/2013 (Man. Year: 2013) Odometer: 348887 km
Colour: Metallic White/Red
Engine Capacity: 1995 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Linglong 8 mm Rear Left Side: Linglong 8 mm
Front Right Side: Linglong 8 mm Rear Right Side: Linglong 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30,489.96	3,895.98	26,593.98	87.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,510.00	1,760.00	8,750.00	83.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	40,999.96	5,655.98	35,343.98	86.20
Approved Total (Overridden) (S\$)		4,500.00		
(S\$)	40,999.96	4,500.00	36,499.96	89.02
+ GST 7.00/7.00% (S\$)	2,870.00	315.00	2,555.00	89.02
Nett Amount (S\$)	43,869.96	4,815.00	39,054.96	89.02
+ Loss of Use (6.0 x S\$40.00/day) (S\$)		240.00		
+ Car Rental (6.0 x S\$101.46/day) (S\$)		608.76		
+ Doc/Search Fee (S\$)		6.00		
Nett Liability (S\$)		5,669.76		
Global Sum Settlement (S\$)		5,660.00		

INSPECTION

Date of Assignment: 09/05/2017
Date Inspected: 09/05/2017 Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
2, Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Aug 2019)
Parts:	143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC5129U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Repair	1,259.42 FL	*- FL
2	1		*BUMPER LOWER GRILLE FRT	Serviceable	266.80 FL	*- FL
3	1		*BUMPER UNDERTRAY FRT	Serviceable	472.83 FL	*- FL
4	1		*BUMPER FOG LAMP GRILLE RH	Serviceable	181.75 FL	*- FL
5	1		*BUMPER RETAINER FRT RH	Serviceable	150.77 FL	*- FL
6	1		*BUMPER SUPPORT FRT RH	Serviceable	123.88 FL	*- FL
7	1		*RADIATOR GRILLE	Serviceable	1,707.78 FL	*- FL
8	1		*RADIATOR GRILLE BADGE RENAULT	Serviceable	225.36 FL	*- FL
9	1		*RADIATOR GRILLE FRAME	Serviceable	1,353.75 FL	*- FL
10	1		*WIPER RESERVOIR	Serviceable	348.25 FL	*- FL
11	1		*WIPER RESERVOIR NECK	Serviceable	136.11 FL	*- FL
12	1		*WIPER RESERVOIR MOTOR	Serviceable	270.06 FL	*- FL
13	1		*FRAME FULL SUPPORT PANEL	Serviceable	615.90 FL	*- FL
14	1		*BONNET	Repair	1,941.63 FL	*- FL
15	1		*BONNET INSULATOR	Serviceable	405.73 FL	*- FL
16	1		*BONNET HINGE RH	Repair	348.31 FL	*- FL
17	1		*HEADLAMP RH	Serviceable	1,184.43 FL	*- FL
18	1		*HEADLAMP PANEL FRT RH	Repair	152.15 FL	*- FL
19	1		*FENDER PANEL FRT RH	Bent	783.83 FL	*783.83 FL
20	1		*FENDER WHEELARCH FRT RH	Serviceable	139.52 FL	*- FL
21	1		*FENDER INSULATOR RH	Serviceable	130.84 FL	*- FL
22	1		*WHEEL HOUSING PANEL FRT RH	Repair	5,173.47 FL	*- FL
23	1		*DOOR FRT RH	Bent	2,844.66 FL	*2,844.66 FL
24	1		*DOOR MOULDING FRT RH	Serviceable	410.27 FL	*- FL
25	1		*DOOR HINGE UPPER RH	Repair	261.28 FL	*- FL
26	1		*DOOR HINGE LOWER RH	Repair	300.55 FL	*- FL
27	1		*DOOR HANDLE OUTER FRT RH	Dented	477.76 FL	*477.76 FL
28	1		*DOOR HANDLE COVER FRT RH	Dented	13.22 FL	*13.22 FL
29	1		*DOOR LOCK FRT RH	Repair	908.75 FL	*- FL
30	1		*DOOR CATCH FRT RH	Repair	131.23 FL	*- FL
31	1		*DOOR SEAL FRT RH	Cut	59.40 FL	*59.40 FL
32	1		*DOOR PANEL REAR RH	Repair	2,844.66 FL	*- FL
33	1		*DOOR HINGE REAR UPPER RH	Repair	274.50 FL	*- FL
34	1		*DOOR HINGE REAR LOWER RH	Repair	300.55 FL	*- FL
35	1		*DOOR MOULDING REAR RH	Serviceable	176.82 FL	*- FL
36	1		*ROCKER PANEL INNER RH	Repair	1,024.79 FL	*- FL
37	1		*ROCKER PANEL CENTER RH	Repair	990.25 FL	*- FL
38	1		*FENDER PANEL REAR RH	Repair	3,299.13 FL	*- FL
39	1		*BUMPER COVER REAR	Serviceable	1,108.46 FL	*- FL
40	1		*SET FRONT BUMPER CLIP	Not Necessary	66.00 FS	*- FS
41	1		*DOOR STICKER TRANS-CAB	Necessary	80.00 FS	*60.00 FS
42	1		*DOOR STICKER CLASSIC	Necessary	30.00 FS	*15.00 FS
43	1		*DOOR STICKER 6555-3333	Necessary	80.00 FS	*60.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*RIM RH FRT	Serviceable	385.00 FS	*- FS
45	1		*TYRE RH FRT	Serviceable	330.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
				Sub Total (S\$)	33,769.85	4,313.87
				- List Item Discount on L Items 10.00/10.00% (S\$)	3,279.89	417.89
				Total Parts (S\$)	30,489.96	3,895.98

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	4,200.00	600.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,500.00	900.00
4	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
5	TO TRANSFER OF DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	120.00
6	TO TRANSFER OF FRONT FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
7	TO TRANSFER OF BONNET FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
8	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	60.00
9	TOWING FEE	New	150.00	0.00
10	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
Gross Labour Cost (S\$)			10,510.00	1,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >