

22/03/2002

ASS. REC. BY:

REF:

CS/CTU7009448/Girbe2

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Maimun

Cheng Boon Sen

of

CTL

Date/Time:

16-05-2017 5:10pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJJ 75577

Insured:

SLL 4881M

at Workshop m/s

Trans Eurokars

Tel:

9127 7928

of

12 Sungai Kadut Ave

Policy No:

DMHCSN1717021700

Claim No:

SNM17D02627/CO2

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

0205207

CA / REV / REP. / REV 24 HRS

Wp

No. 5 Ubi Close

@ 19-05-2017 - 4pm

H.O.D. Endorsement:

Date/Time:

16-05-2017 9:21am

Person Contacted:

Ronald

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SJJ 75577 - x

Jowyn 6259 6174

SLL 4881M - x

11/1/18

Vehicle not in & not get start repair

Jowyn called & ask us to submit report.

This case has been repudiate.

(08/11/13)

ASS. REC. BY: Xnl

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Trans Euro Cars

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJJ7557T Yr Regn: 3 / Mar 2017Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 6 c.c. 1998Colour: red A/C: Insured / Std / NI / NASp. Reading: 2934 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JMBGL1071H.0108699Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/55 R17R: 11BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mmL/Bal. 9 mm

D.O.A. _____

Rear

R/Bal. 9 mmL/Bal. 9 mmD.O.I. 19-05-17Survey held at w/s 4:50pmDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Submit preli report

Date/Time, File Pass to?



Preli. Report



Final Report

1) tpart

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS _____ \$

Photos _____

Others _____

TOTAL

Report Format: TP

Lump Sum / I.B.I.: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

200




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI17009448/Grb	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 16-05-2017	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLL 4881M	Veh. Inspected	SJJ 7557T
Policy No.	DMHCSN1717021700	Coverage (\$)	0.00
Claim No.	SNM17D02627/C02	Excess (\$)	0.00
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	16/05/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	02/05/2017	Inspection Date	
Survey held at	NO. 5 UBI CLOSE		
Repairer	TRANS EUROKARS PTE LTD		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 May 2017		16 May 2017 09:10 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	LIM SING HUI, ID: S1543091E		
Vehicle Reg. No.:	SJJ7557T	Date of Loss:	02/05/2017 08:00 - :59
Claim Type:	TP / SNM17D02627/C02	Policy/Cover Note No.:	DMHCSN1717021700
Vehicle Reg. No. (Insured):	SLL4881M	Policy No. (Claimant):	2100506300
	Excess:	S\$0.00	
Repairer:	Trans Eurokars Pte Ltd (Sungei Kadut) 12 Sungei Kadut Ave, 729648 Sungei Kadut - Tel: 63602845		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 25/05/2017]		
Adj Asg. Remarks:	PRS. SURVEY ON WP BASIS. PLS PROVIDE RECOMMENDATION BASED ON COR.		

ASSOCIATED MAIL RECEIVED

View All | Compose Case Mail

There are no mail for this case.

☐
ALL ASSOCIATED TASKS

View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/05/2017 09:33
Date Of Accident	02/05/2017 08:10
Exact Location Of Accident	ECP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJJ7557T
Insured/Policyholder	
Name Of Registered Owner	LIM SING HUI
NRIC No	S1543091E
Email Address	SINGHUI1811@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-81007668
Alternative Phone No	OTHERS-81007668

Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA6
Exact Purpose for which vehicle was being used at time of accident	PRIVATE

Are you claiming under your own insurance policy for repair to your vehicle?	NO
--	----

If No, Please state action to be taken	THIRD PARTY
--	-------------

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100506300
Cover Note Number	

Driver

Name of Driver	LIM SING HUI
NRIC No	S1543091E
Date Of Birth	18/11/1962
Occupation	INDOOR
Date Of Driving Pass	30/12/1983
Driving Experience	33 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81007668
Fax Number	
Contact Number	OTHERS-81007668
EMail Address	SINGHUI1811@YAHOO.COM.SG

Address	16 PASIR RIS LINK #07-61 RIPPLE BAY
Postcode	518166
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION- HEAD TO REAR (TP HIT INSURED)
Weather Conditions	FAIR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE ATTACHED SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLL4481M
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	KHEW GUAN WEI
NRIC/Passport Number	S8528822I
Contact Number	83210568
Address	
Postcode	
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and



(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

while driving along ECP, car in front
stopped, so I stop my car, But the car
behind me hit my car's rear portion


Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date
& Time



Witnessed by Reporting Centre
Personnel

TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS

CHINA TAIPING INSURANCE P/L 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909 ATTN.: MOTOR CLAIMS FAX :		NAME : Mr Lim Sing Hui ADDRESS : No. 16 Pasir Ris Link #07-61 Singapore 518166 TEL : 81007668		WIP : 63740 EXCESS : DATE: 8-May-17	
VEH NO : SJ7557T		DATE IN : 27/3/17		CONTACT PERSON : RONALD 6395 7875	
CHASSIS NO : JM6GL1071H0108699		MILEAGE : 2734		TYPE OF CLAIM : THIRD PARTY CLAIM	
MODEL : MAZDA6 2L		DATE REG.: 31-Mar-17		POLICY NO. :	

NATURE OF WORKS				
S/NO	Parts Description	QTY	REVISED	PRICES
1	REAR BUMPER / <i>cc</i>	1		\$ 1,206.20
2	SENSOR,ULTRASONIC (CENTER) ?	2		\$ 344.40
3	SENSOR,ULTRASONIC (SIDE) ?	2		\$ 387.80
4	RETAINER CENTER, SENSOR ?	2		\$ 34.60
5	RETAINER SIDE, SENSOR ?	2		\$ 34.60
6	TAPE,PROTECTOR, SENSOR <i>cc - MCL</i>	4		\$ 32.40
7	RETAINER(LHS), REAR BUMPER <i>X</i>	1		\$ 39.00
8	RETAINER(RHS), REAR BUMPER <i>X</i>	1		\$ 39.00
9	BRACKET CENTER, REAR BUMPER <i>- MCL</i>	1		\$ 5.10
10	REFLECTOR(LHS) <i>X</i>	1		\$ 50.40
11	REFLECTOR(RHS) <i>X</i>	1		\$ 50.40
12	COVER(LHS), TOWING <i>X</i>	1		\$ 23.70
13	COVER(RHS), TOWING <i>X</i>	1		\$ 23.70
14	REINFORCEMENT REAR ?	1		\$ 512.60
15	FASTENER, REAR BUMPER <i>-</i>	6		\$ 16.80
16	GROMMET, REAR BUMPER <i>-</i>	6		\$ 16.80
17	GROMMET, REAR BUMPER <i>-</i>	1		\$ 2.80
18	CLIP, REAR BUMPER <i>-</i>	4		\$ 14.00
19	BOOT LID <i>X</i>	1		\$ 1,061.90
20	MAZDA, EMBLEM <i>X</i>	1		\$ 27.50
21	6, EMBLEM <i>X</i>	1		\$ 15.70
22	MASCOT,REAR <i>X</i>	1		\$ 46.80
23	SKYACTIV, EMBLEM <i>X</i>	1		\$ 71.10
24	CLIP, BOOT LID GARNISH <i>X</i>	2		\$ 5.20
25	GROMMET, BOOT LID LID GARNISH <i>X</i>	2		\$ 7.80
26	GROMMET, BOOT LID LID GARNISH <i>X</i>	2		\$ 17.60
27	GASKET(LHS), TAILLAMP <i>-</i>	1		\$ 26.30
28	GASKET(RHS), TAILLAMP <i>-</i>	1		\$ 26.30
29	FASTENER, TAILLAMP <i>X</i>	2		\$ 7.80
30	FASTENER, TAILLAMP <i>X</i>	2		\$ 6.60
31	GROMMET, TAILLAMP <i>X</i>	2		\$ 29.80
32	GASKET(LHS), BOOT LID LAMP <i>X</i>	1		\$ 50.00
33	GASKET(RHS), BOOT LID LAMP <i>X</i>	1		\$ 50.00
34	GROMMET, BOOT LID LAMP <i>X</i>	2		\$ 6.20

		TOTAL PARTS	\$ 4,290.90
		LESS 10%	\$ 429.09
		TOTAL PARTS COST	\$ 3,861.81
		<u>Labour Description</u>	
1	TO REPLACE REAR BUMPER, REAR REINFORCEMENT AND BOOT LID. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	630	\$ 2,520.00
2	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT AND BOOT LID.	600	\$ 2,400.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION.	NN X	\$ 250.00
4	TO TRANSFER REVERSE SENSORS.	315	\$ 630.00
5	TO TRANSFER REVERSE CAMERA.	NN X	\$ 630.00
6	TO SUPPLY 1 PC NUMBER PLATE.	NETT NN X	\$ 70.00
7	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150 X	\$ 250.00
8	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
9	SUNDRIES.	NETT 20	\$ 100.00

3-4 Days.

Gene Giomy - 82880282

19/5/17

[Signature]
23/5/17.

TOTAL LABOUR	\$ -	\$ 7,200.00
TOTAL PARTS	\$ -	\$ 3,861.81
TOTAL	\$ -	\$ 11,061.81
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	\$ -
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

444 Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 May 2017		16 May 2017 09:10 Edit Adj Rpt	S\$3,107.03 Edit Estimates	S\$3,107.03 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS [Created by Insurer]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	LIM SING HUI , ID: S1543091E		
Vehicle Reg. No.:	SJJ7557T	Date of Loss:	02/05/2017 08:00 - :59
Claim Type:	TP / SNM17D02627/C02	Policy/Cover Note No.:	DMHCSN1717021700
Vehicle Reg. No. (Insured):	SLL4881M	Policy No. (Claimant):	2100506300
		Excess:	S\$0.00
Repairer:	Trans Eurokars Pte Ltd (Sungei Kadut) 12 Sungei Kadut Ave, 729648 Sungei Kadut - Tel: 63602845		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 25/05/2017]		
Adj Asg. Remarks:	PRS. SURVEY ON WP BASIS. PLS PROVIDE RECOMMENDATION BASED ON COR.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)


























There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)











Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJJ7557T (SNM17D02627/C02)**
[SLL4881M]
TP
LIM SING HUI
May 2 2017 8:00AM
[-]
Trans Eurokars Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Assessment Reports									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)							Thumbnail	Print	
1	06/05/17 09:48	Accident Statement							Load HTM		
Photos/Images									3 per page		<input checked="" type="checkbox"/>
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)							Thumbnail	Print	
1	06/05/17 09:47	SJJ7557T [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
2	06/05/17 09:47	SJJ7557T [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
3	06/05/17 09:47	SJJ7557T [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
4	06/05/17 09:47	SJJ7557T [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
5	06/05/17 09:47	SJJ7557T [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
6	06/05/17 09:47	SJJ7557T [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
7	06/05/17 09:47	SJJ7557T [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
8	06/05/17 09:47	SJJ7557T [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	11/01/18 10:14	General View							Load JPG	<input checked="" type="checkbox"/>	
2	11/01/18 10:14	General View							Load JPG	<input checked="" type="checkbox"/>	
3	11/01/18 10:14	General View							Load JPG	<input checked="" type="checkbox"/>	
4	11/01/18 10:14	General View							Load JPG	<input checked="" type="checkbox"/>	
5	11/01/18 10:14	General View							Load JPG	<input checked="" type="checkbox"/>	
6	11/01/18 10:14	General View							Load JPG	<input checked="" type="checkbox"/>	
7	11/01/18 10:14	General View							Load JPG	<input checked="" type="checkbox"/>	
8	11/01/18 10:14	General View							Load JPG	<input checked="" type="checkbox"/>	
9	11/01/18 10:14	General View							Load JPG	<input checked="" type="checkbox"/>	
10	11/01/18 10:14	General View							Load JPG	<input checked="" type="checkbox"/>	
11	11/01/18 10:14	General View							Load JPG	<input checked="" type="checkbox"/>	
12	11/01/18 10:14	General View							Load JPG	<input checked="" type="checkbox"/>	
13	11/01/18 10:14	General View							Load JPG	<input checked="" type="checkbox"/>	
Documentation									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)							Thumbnail	Print	
1	16/05/17 09:20	REPAIR ESTIMATE							Load PDF		
2	16/05/17 09:20	INSURANCE REPORT							Load PDF		
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)							Thumbnail	Print	
1	06/05/17 09:42	Sketch Plan [Linked Accident Report Documents]							Load TIF		

Linked Accident Report Documents

			View	View in Browser
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	06/05/17 09:48	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	06/05/17 09:47	SJJ7557T	 Load JPG	<input checked="" type="checkbox"/>
2	06/05/17 09:47	SJJ7557T	 Load JPG	<input checked="" type="checkbox"/>
3	06/05/17 09:47	SJJ7557T	 Load JPG	<input checked="" type="checkbox"/>
4	06/05/17 09:47	SJJ7557T	 Load JPG	<input checked="" type="checkbox"/>
5	06/05/17 09:47	SJJ7557T	 Load JPG	<input checked="" type="checkbox"/>
6	06/05/17 09:47	SJJ7557T	 Load JPG	<input checked="" type="checkbox"/>
7	06/05/17 09:47	SJJ7557T	 Load JPG	<input checked="" type="checkbox"/>
8	06/05/17 09:47	SJJ7557T	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	06/05/17 09:42	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<div style="border: 1px solid black; padding: 5px; margin-bottom: 10px;"> Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px; position: relative;"> ^ v </div> </div> <p>Show Remarks To: <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI17009448/GRBE2

Date: 11/01/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSN1717021700

Claimant Vehicle
No: SJJ7557TInsured Vehicle
No: SLL4881M

Date of Loss: 02/05/2017

Nature of Claim: TP

Claim
No: SNM17D02627/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJJ7557T

Make & Model: MAZDA 6, 2.0 V (A)

Engine No: PE20854348

Reg. Date: 31/03/2017 (Man. Year: 2016)

Chassis No: JM6GL1071H0108699

Colour: Red

Odometer: 2934 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Bridgestone 9 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,961.81	1,232.03	2,729.78	68.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,100.00	1,875.00	5,225.00	73.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	11,061.81	3,107.03	7,954.78	71.91
+ GST 7.00/7.00% (\$\$)	774.33	217.49	556.84	71.91
Nett Amount (\$\$)	11,836.14	3,324.52	8,511.62	71.91

INSPECTION

Date of Assignment: 16/05/2017

Date Inspected: 19/05/2017 Inspected At:

Trans Eurokars Pte Ltd (Sungei Kadut)
12 Sungei Kadut Ave
Singapore 729648

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$1,182.60 NETT)

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 11 Jan 2018)
Parts: 143	MAZDA 6 2.0 V (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJJ7557T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,206.20 FL	*1,206.20 FL
2	2		*SENSOR, ULTRASONIC (CENTER)	* Check	344.40 FL	*- FL
3	2		*SENSOR, ULTRASONIC (SIDE)	* Check	387.80 FL	*- FL
4	2		*RETAINER CENTER, SENSOR	* Check	34.60 FL	*- FL
5	2		*RETAINER SIDE, SENSOR	* Check	34.60 FL	*- FL
6	4		*TAPE, PROTECTOR, SENSOR	Necessary	32.40 FL	*32.40 FL
7	1		*RETAINER (LHS), REAR BUMPER	Not Necessary	39.00 FL	*- FL
8	1		*RETAINER (RHS), REAR BUMPER	Not Necessary	39.00 FL	*- FL
9	1		*BRACKET CENTER, REAR BUMPER	Necessary	5.10 FL	*5.10 FL
10	1		*REFLECTOR (LHS)	Not Necessary	50.40 FL	*- FL
11	1		*REFLECTOR (RHS)	Not Necessary	50.40 FL	*- FL
12	1		*COVER(LHS), TOWING	Not Necessary	23.70 FL	*- FL
13	1		*COVER (RHS), TOWING	Not Necessary	23.70 FL	*- FL
14	1		*REINFORCEMENT REAR	* Check	512.60 FL	*- FL
15	6		*FASTENER, REAR BUMPER	Necessary	16.80 FL	*16.80 FL
16	6		*GROMMET, REAR BUMPER	Necessary	16.80 FL	*16.80 FL
17	1		*GROMMET, REAR BUMPER	Necessary	2.80 FL	*2.80 FL
18	4		*CLIP, REAR BUMPER	Necessary	14.00 FL	*14.00 FL
19	1		*BOOT LID	Not Necessary	1,061.90 FL	*- FL
20	1		*MAZDA, EMBLEM	Not Necessary	27.50 FL	*- FL
21	1		*6, EMBLEM	Not Necessary	15.70 FL	*- FL
22	1		*MASCOT, REAR	Not Necessary	46.80 FL	*- FL
23	1		*SKYACTIV, EMBLEM	Not Necessary	71.10 FL	*- FL
24	2		*CLIP, BOOT LID GARNISH	Not Necessary	5.20 FL	*- FL
25	2		*GROMMET, BOOT LID GARNISH	Not Necessary	7.80 FL	*- FL
26	2		*GROMMET, BOOT LID GARNISH	Not Necessary	17.60 FL	*- FL
27	1		*GASKET (LHS), TAILLAMP	Necessary	26.30 FL	*26.30 FL
28	1		*GASKET (RHS), TAILLAMP	Necessary	26.30 FL	*26.30 FL
29	2		*FASTENER, TAILLAMP	Not Necessary	7.80 FL	*- FL
30	2		*FASTENER, TAILLAMP	Not Necessary	6.60 FL	*- FL
31	2		*GROMMET, TAILLAMP	Not Necessary	29.80 FL	*- FL
32	1		*GASKET (LHS), BOOT LID LAMP	Not Necessary	50.00 FL	*- FL
33	1		*GASKET (RHS), BOOT LID LAMP	Not Necessary	50.00 FL	*- FL
34	2		*GROMMET, BOOT LID LAMP	Not Necessary	6.20 FL	*- FL
35	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,390.90	1,366.70
- List Item Discount on L Items 10.00/10.00% (\$\$)	429.09	134.67

Total Parts (\$\$) **3,961.81** **1,232.03**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER, REAR REINFORCEMENT AND BOOT LID. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	New	2,520.00	630.00
2	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT AND BOOT LID	New	2,400.00	600.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION	New	250.00	0.00
4	TO TRANSFER REVERSE SENSORS	New	630.00	315.00
5	TO TRANSFER REVERSE CAMERA	New	630.00	0.00
6	TO SUPPLY 1 PC NUMBER PLATE	New	70.00	0.00
7	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00
8	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	180.00
Gross Labour Cost (\$\$)			7,100.00	1,875.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >