

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17009641/T1gh3e2			
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date: 21-12-2017 Code: FCI2			
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 8129K	Veh. Inspected	GBA 4355X	
	Policy No.	D-15072702MFSH	Coverage (\$)	0.00	
	Claim No.	D17005000MFSH	Excess (\$)	0.00	
	Assign From	LURENE JAW	Assign Date	17/05/2017	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA DYNA 150	c.c	2982	
	Engine No.	HIDDEN	Year of Reg.	2007	
	Chassis No.	JTFAT35Y603000943	Colour	SILVER	
	Odometer	410955	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195/75 R15	BRIDGESTONE	6 mm	
	L/H Front Tyre	195/75 R15	BRIDGESTONE	6 mm	
	R/H Rear Tyre	155 R12	BRIDGESTONE	6 mm	
	L/H Rear Tyre	155 R12	BRIDGESTONE	6 mm	
4.					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S AND UNDERCARRIAGE PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	15/05/2017	Inspection Date	18/05/2017	
	Survey held at	MOVA AUTOMOTIVE PTE LTD			
		BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 . SINGAPORE 159722			
5a.	Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 14 Working Days				