

INS. CASE OWNER:

Janeff.

CC 4 /EQ1701 0234, Upbx

LKK: IDAC

Surveyor:

MARINA

DOI:

26/5/17

Date / Time:

26/5/17

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

YN 87084

Claim No.:

Name of Insured:

MAJOR EXPRESS FREIGHT SERVICES P/L

Policy No.:

Hino

Insured Tel No.:

HP:

Make / Model:

QML69046-000362

Excess Sec II :SS

D.O.A.:

12/5/17

Place of Accident:

HAWAII AIRFIELD COMPLEX

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

MUHAMMAD AMIR BIN CAWAT

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

81361076

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

By 817E



INSRS: WSP: Tel: Liability: RMKS:

Liu's Bro



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:

Date/Time	STAGE	DATE / PIC
20/5/17	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
30/5/17	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
27/3/18	Notification ltr (if non-pickup)	
	After call ltr to OI:	
17/6/17	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
4/12/17	LTA / GIA :	
	Medical Bill:	
	PIR:	
	Mapdate/Reject Instruction:	
	LOD:	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

<b>PRELIMINARY ADVICE</b>	Date/Time:	Sent By:	Confirm with:	Confirm by:
<b>FINALIZATION</b>	Date/Time:	Sent By:	Confirm with:	Confirm by:
Repair Cost:	\$5	days	Reduction: %	Email <input type="checkbox"/> Call <input type="checkbox"/>
<b>FINAL SETTLEMENT</b>	Date/Time:	Confirm with:	Confirm by:	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	% 50	(Agreed / Assessed)	BOLA S/N No.:	NIL
Repair Cost:	\$2450.00	\$5 1225.00		
Loss of Rental (LOR):	\$5	days		
Loss of Use (LOU):	\$5 250.00	(\$ 100 x 5 days)		
Loss of Income (LOI):	\$5	(\$ x days)		
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/>	<input checked="" type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	[Tick only one]		
CIA/LTA Search:	\$5 2.00			
Medical:	\$5 -			
Disbursement:	\$5 -	(e.g. Tow/Independent)		
Legal Cost:	\$5 -			
<b>Total:</b>	\$5 1477.00	<b>Global Sum \$5:</b>	1480.00	
<b>FINAL PAYMENT</b>	Date/Time:	Confirm with:	Confirm by:	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	\$5 1480.00	Name 1:	Liu's Brother Auto Engineering Workshop	
Payee 2: (Strike if N.A.)	\$5 -	Name 2:		
Payee 3: (Strike if N.A.)	\$5 -	Name 3:		

COPY SENT 23/1/2020 6/12 24/1/17 6/12

REF: EQ1

**ASSIGNMENT**

From: \_\_\_\_\_ Date: 26052017  
 Estimated Cost: \_\_\_\_\_  
 OD / TP WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: GY 817E  
 at Workshop m/s: Liv's Brother  
 of: Blk 1 Koka Bukit Arel #01-01  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: GY817E Yr Regn: 8 05  
 Type: M.Car / M.Cycle / Bus / Van / Loary / Taxi / Prime Mover /  
 Truck / Trailer or (No)  
 Make: mit FB511 c.c. 2835  
 Colour: white A/C: Insured / Std / NI / NA  
 Sp.Reading: 490/99 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: FB511 BA 47633  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 195 R15  
 R: \_\_\_\_\_

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rport: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 4 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Thunderer  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal: 6 mm R/Bal: 6/6 mm  
 L/Bal: 6 mm L/Bal: 6/6 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 26/5/17  
 Survey held at \_\_\_\_\_  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
L-f.  
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
<p><u>US \$ 2450 (incl \$ 322.80 / 777)</u></p>	

Date/Time. File Pass to?  : Preli. Report  : Final Report

1) \_\_\_\_\_

Date/Time. File Return to? \_\_\_\_\_

2) \_\_\_\_\_

Report Format : \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_) )  
 : Interview (\$ \_\_\_\_\_) )  
 : Tech. Invs (\$ \_\_\_\_\_) )  
 : Weekend (\$ \_\_\_\_\_) )

Others: \_\_\_\_\_

TOTAL: \_\_\_\_\_



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CC4/EQ117010234/Upb3	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 26-05-2017	
		Code : EQ1	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YN 8778U	Veh. Inspected	GY 8117E
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	26/05/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	12/05/2017	Inspection Date	26/05/2017
Survey held at	LIU'S BROTHER AUTO WORK SHOP BLK 1 KAKI BUKIT AVE 6 #01-01 AUTO BAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417853  
ROB No. 532917931 Tel. 6741-1730 / 731 Fax. 6741-3746 Email. linbro@ymail.com

Invoice/Ref No: GY81117E170512

**Estimate**

<b>Customer</b>			
Name:	EQ Insurance Company Limited	Date:	25/5/2017
Address:	Motor Claims Department 5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110	Vehicle No:	GY81117E
		Model/Make:	Mitsubishi FB511BOJSRDE

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Rh Head Lamp		
2	Grille		
3	Grille Emblem		
4	Panel		
5	Windscreen Glass Weatherstrip		
6	Wiper Nozzle		
7	Wiper Garnish		
	Remove & reinstall Windscreen Glass to facilitate repairs & perform water test To check all wiring & electrical component for proper function Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc To putty & spray painting & including touch up paint on accident affected areas Remove & reinstall Switch Box, disconnect wiring & Etc...	\$ 200.00 \$ 300.00 \$ 800.00 \$ 500.00 \$ 300.00	60 30 600 400 160

Total Parts & Labour of estimate for damaged vehicle	
Total amount in Lump Sum Basis for repaired vehicle	5 -

SDLS: \_\_\_\_\_

*not about  
the  
2/5/17  
Hdy.  
26/5/17  
work please At the repair*



M/s Liu's Brother Auto Engrg Wks

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Text size +

**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 3585C

**Vehicle Details**

Vehicle No.: GY8117E

Vehicle to be Exported: No

Intended De-registration Date: 25 May 2017

Vehicle Make: MITSUBISHI

Vehicle Model: FB511BOJSRDE

Primary Colour: Red

Manufacturing Year: 2005

Engine No.: 4M40GT7138

Chassis No.: FB511BA47633

**Maximum Power Output:-**

Open Market Value: \$19,389.00

Original Registration Date: 13 Aug 2005

First Registration Date: 13 Aug 2005

Transfer Count: 1

Actual ARF Paid: \$970.00

**Intended PARF Rebate Details**

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

**Intended COE Rebate Details**

COE Expiry Date: 12 Aug 2020

COE Category: C - Goods Vehicle &amp; Bus

COE Period(Years): 5

POP Paid: \$25,292.00

COE Rebate Amount: \$16,263.00

**Total Rebate Amount: \$16,263.00****Message**

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 25 May 2017

OK

Land Transport Authority

Please read through the [Privacy Statement](#), [Terms of Use](#) and [Disclaimer](#).

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above: 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

**Catherine Chong (LKK Auto)**

**From:** Shu Pei (LKKAuto) <shupeil@lkkauto.com>  
**Sent:** Thursday, 25 May, 2017 3:40 PM  
**To:** assignments  
**Subject:** FW: Our ref:DM17HO01149/JT- FW: Request for 3rd party survey GY8117E Claims against YN8708U  
**Attachments:** GY8117E Search.pdf, GY8117E170512.pdf

25052017 @ 352pm  
Susan. Veh in  
Marcus.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Janet Tan [mailto:[janet.tan@eqinsurance.com.sg](mailto:janet.tan@eqinsurance.com.sg)]

**Sent:** Thursday, 25 May, 2017 3:37 PM

**To:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Subject:** FW: Our ref:DM17HO01149/JT- FW: Request for 3rd party survey GY8117E Claims against YN8708U

Dear all,

Please assist to attend to the PRS.

Our insured driver has yet to report.

Regards,

Janet Tan

Senior Executive | Claims

**eqnsurance**

EQ Insurance Company Limited

Shankar Road #17-00 Tower BHS MHO Complex Singapore 696110

do 65 444 9002 | tel 65 6223 0453 ext 030 | fax 65 6223 4190

[www.eqinsurance.com.sg](http://www.eqinsurance.com.sg)

 A Member of CityState

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete this message.

 you've got a friend

**From:** Susan Low [mailto:[liusbro@ymail.com](mailto:liusbro@ymail.com)]

**Sent:** Thursday, May 25, 2017 3:20 PM

**To:** Janet Tan <[janet.tan@eqinsurance.com.sg](mailto:janet.tan@eqinsurance.com.sg)>

**Subject:** Re: Our ref:DM17HO01149/JT- FW: Request for 3rd party survey GY8117E Claims against YN8708U



## Hsiao Tong (LKKAuto)

---

**From:** Susan Low <liusbro@gmail.com>  
**Sent:** Tuesday, 27 March 2018 11:41 AM  
**To:** Hsiao Tong (LKKAuto)  
**Subject:** Re: Your ref: GY 8117E \*Our Ref: CC4/EQI17010234/Upb3 [ACCIDENT INVOLVING YN 8708U(EQ) & GY 8117E ON 12/05/2017]

We refer to your email dated 30/05/2017.

Our client's did not fixed any video cam inside his lorry.

But we hereby write to request from the officer in-charge to assist and let us have the accident photographs showing the vehicles involved and/or VVTV/In-car camera video footages of the accident and/or other evidence to support your client's claim stated at your email "Our insured driver reported that your client hit him from behind. "

Please arrange and revert ASAP.

Thank.

Best Regards,

Susan Low  
M/s Liu's Brother Auto Workshop  
No. 1 Kaki Bukit Avenue 6 #01-01  
AutoBay @ Kaki Bukit  
Singapore 417883  
Tel: 67411730 Fax: 67445746

---

**From:** Hsiao Tong (LKKAuto) <chewht@lkkauto.com>  
**To:** Susan Low <liusbro@gmail.com>  
**Sent:** Tuesday, 5 September 2017, 13:47  
**Subject:** RE: Your ref: GY 8117E \*Our Ref: CC4/EQI17010234/Upb3 [ACCIDENT INVOLVING YN 8708U(EQ) & GY 8117E ON 12/05/2017]

Without Prejudice

Hi,

We refer to our email dated 30/05/2017.

Kindly let us have evidences (ie: video footage/ scene photos / PIR) for our consideration of the claim.

Appreciate an early reply.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Hsiao Tong (LKKAuto)

**Sent:** Tuesday, 30 May, 2017 12:12 PM

**To:** 'Susan Low' <[liusbro@gmail.com](mailto:liusbro@gmail.com)>

**Subject:** Your ref: GY 8117E \*Our Ref: CC4/EQ117010234/Upb3 [ACCIDENT INVOLVING YN 8708U(EQ) & GY 8117E ON 12/05/2017]

Your ref: **GY 8117E**

**WITHOUT PREJUDICE**

Our Ref: CC4/EQ117010234/Upb3

Dear Sir/Madam,

**ACCIDENT INVOLVING YN 8708U(EQ) & GY 8117E ON 12/05/2017**

We refer to the above matter.

Please be informed that liability is unclear. Our insured driver reported that your client hit him from behind. Kindly refer to the attached statement from our insured for your easy reference.

We would like to request a copy of the video footage/evidence(IF ANY) for our necessary action.

Appreciate an early reply.

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Text size + -

**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 3585C

**Vehicle Details**

Vehicle No.: GY8117E

Vehicle to be Exported: No

Intended De-registration Date: 25 May 2017

Vehicle Make: MITSUBISHI

Vehicle Model: FB511BOJSRDE

Primary Colour: Red

Manufacturing Year: 2005

Engine No.: 4M40GT7138

Chassis No.: FB511BA47633

**Maximum Power Output:**

Open Market Value: \$19,389.00

Original Registration Date: 13 Aug 2005

First Registration Date: 13 Aug 2005

Transfer Count: 1

Actual ARF Paid: \$970.00

**Intended PARF Rebate Details**

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

**Intended COE Rebate Details**

COE Expiry Date: 12 Aug 2020

COE Category: C - Goods Vehicle &amp; Bus

COE Period(Years): 5

POP Paid: \$25,292.00

COE Rebate Amount: \$16,263.00

**Total Rebate Amount: \$16,263.00****Message**

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 25 May 2017

OK

Land Transport Authority

Please read through the [Privacy Statement](#), [Terms of Use](#) and [Disclaimer](#).

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above: 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

## Hsiao Tong (LKKAuto)

---

**From:** Susan Low <liusbro@gmail.com>  
**Sent:** Thursday, 21 November 2019 1:25 PM  
**To:** Hsiao Tong (LKKAuto)  
**Subject:** Re: Our Ref: GY8117E170512      Your Ref: CC4/EQ117010234/Upb3

We hereby confirm acceptance of your offer (50:50).

Kindly let us have your discharge voucher for our client's execution and your cheque made in our favour as soon as possible.

Thank!

Best Regard

Susan Low

M/s Liu's Brother Auto Engineering Workshop

No. 1 Kaki Bukit Avenue 6 #01-01

AutoBay @ Kaki Bukit

Singapore 417883

Tel: 6741 1730

Fax: 6744 5746

On Saturday, 26 October 2019, 12:59:55 pm SGT, Hsiao Tong (LKKAuto) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)> wrote:

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We are of the opinion that this is a case of conflicting versions. There is no concrete evidence (ie: Video footage) yet to support either party's version. Enclosed herewith in this email is a copy of our insured's accident report for your perusal.

**Sketch Plan**

△ A	A - 7N870BU
△ B	B - 6Y817E

**Accident Sketch Plan Pg. 1**

---

**Describe Circumstances of the Accident**

I was to move forward when front vehicle made immediate braking, i also brake and behind vehicle bump my rear lorry.

Strictly without admission of liability whatever, but with a view towards a resolutions of your client's claim in the above matter without resort to litigation, we are prepared to offer at a global sum of **\$1,480.00(all-in)** towards your client's claim.

Please confirm acceptance.

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Susan Low <[liusbro@ymail.com](mailto:liusbro@ymail.com)>  
**Sent:** Monday, 8 April 2019 11:12 AM  
**To:** Hsiao Tong (LKKAuto) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>  
**Subject:** Our Ref: GY8117E170512 Your Ref: CC4/EQ117010234/Upb3

We refer to our attachment.

Our client's do not have in-car VVTV.

Please assist to let us have your insured VVTV/In-car camera video footages of the accident.

Kindly arrange ASAP.

Thank.

Best Regards,

Susan Low

M/s Liu's Brother Auto Engineering Workshop

No. 1 Kaki Bukit Avenue 6 #01-01

AutoBay @ Kaki Bukit

Singapore 417883

Tel: 67411730 Fax: 67445746



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 19/02/2020

**THIRD PARTY DIRECT SETTLEMENT**

Vehicle No.	YN 8708U	(Insd Veh)	Your Ref. No. : DM17HO01149/JT
	GY 8117E	(TP Veh)	Our Ref. No. : CC4/EQ117010234/Upa3q2
Date of Accident	12/5/2017		

Liability	50%	
Final Repair Cost	: \$ 1,225.00	
Loss of Use	: \$ 250.00	5 days
Rental (If any)	: \$	days
Others:	: \$ 2.00	
	: \$	
	1,477.00	
Final Settlement Sum	: \$ 1,480.00	GLOBAL SUM
Remarks	:	

**Payment Instruction: Payee's Breakdown**

1)	LIU'S BROTHER AUTO ENGINEERING WORKSHOP	: \$ 1,480.00
		: \$

JOANNE LEE

LKK Auto Consultants Pte Ltd



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC4/EQ117010234/Upa3q2

5 MAXWELL ROAD  
#17-00 TOWER BLOCK  
MND COMPLEXSINGAPORE 069110

Date : 19-02-2020



Code : EQI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 8708U	Veh. Inspected	GY 8117E
Policy No.	DMCGGQ16-000362	Coverage (\$)	0.00
Claim No.	DM17HO01149/JT	Excess (\$)	0.00
Assign From	JANET	Assign Date	26/05/2017

## 2. Vehicle Particulars & Condition

Make & Model	mitsubishi FB511 (M)	c.c	2835
Engine No.	HIDDEN	Year of Reg.	2005
Chassis No.	FB511BA47633	Colour	WHITE
Odometer	490199	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15	THUNDERER	6 mm
L/H Front Tyre	195 R15	THUNDERER	6 mm
R/H Rear Tyre	195 R15 (D)	THUNDERER	6/6 mm
L/H Rear Tyre	195 R15 (D)	THUNDERER	6/6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.  
DAMAGES SEE DETAILS.

## 5. General Information

Accident Date	12/05/2017	Inspection Date	26/05/2017
Survey held at	LIU'S BROTHER AUTO WORK SHOP BLK 1 KAKI BUKIT AVE 6 #01-01 AUTO BAY @ KAKI BUKIT SINGAPORE 417883		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GY 8117E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT RH HEAD LAMP	NOT NECESSARY	619.40	-
1	FRONT RH GRILLE	CUT / CRACKED	620.20	620.20
1	FRONT RH GRILLE EMBLEM	NECESSARY	68.30	68.30
1	FRONT RH PANEL	DENTED	1,139.30	1,139.30
1	FRONT RH WINDSCREEN GLASS WEATHERSTRIP	NECESSARY	510.80	510.80
1	FRONT RH WIPER NOZZLE	CRACKED	98.50	98.50
1	FRONT RH WIPER GARNISH	NOT NECESSARY	576.30	-
	LESS 25% DISCOUNT		-	-609.28
			<b>3,632.80</b>	<b>1,827.82</b>
<b>LABOUR</b>				
	REMOVE & REINSTALL WINDSCREEN GLASS TO FACILITATE REPAIRS & PERFORM WATER TEST.		200.00	60.00
	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION.		300.00	30.00
	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS.		800.00	600.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS.		500.00	400.00
	REMOVE & REINSTALL SWITCH BOX, DISCONNECT WIRING & ETCS.		300.00	160.00
			<b>2,100.00</b>	<b>1,250.00</b>
<b>GRAND TOTAL</b>			<b>5,732.80</b>	<b>3,077.82</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,450.00</b>

Report Ref No. CC4/EQ117010234/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.