

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417887  
ROB No: 53291293M Tel: 6741-1730 / 731 Fax: 6744-5746 Email: liubros@gmail.com

Invoice/Ref No: GY8117E170512

**Estimate****Customer**Name: EQ Insurance Company Limited  
Address: Motor Claims Department  
5 Maxwell Road #17-00  
Tower Block MND Complex Singapore 069110Date: 25/5/2017  
Vehicle No: GY8117E  
Model/Make: Mitsubishi  
FB511BQJSRDE

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Rh Head Lamp		
2	Grille		
3	Grille Emblem		
4	Panel		
5	Windscreen Glass Weatherstrip		
6	Wiper Nozzle		
7	Wiper Garnish		
	Remove & reinstall Windscreen Glass to facilitate repairs & perform water test	\$ 200.00	60
	To check all wiring & electrical component for proper function	\$ 300.00	30
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc.	\$ 800.00	600
	To putty & spray painting & including touch up paint on accident affected areas	\$ 500.00	400
	Remove & reinstall Switch Box, disconnect wiring & Etc.	\$ 300.00	100

Total Parts &amp; Labour of estimate for damaged vehicle

Total amount in Lump Sum Basis for repaired vehicle

SDLS:

not about  
the  
2/5/17  
Hony.  
26/5/17  
take photo after repair



M/s Liu's Brother Auto Engrg Wks

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: