

ASS. REC. BY:

REF:

CS/FCL17010 722/Alrbn2

Special Instruction: ^{Jamil}

Surveyor: Rasul

ASSIGNMENT (Office)

Date/Time: 02062017 9:11am

From (Person): CS/Luene Juw of FCL

Bill to:

Estimated Cost:

OD / ~~IP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

Insured:

SHC 898R

To Inspect Vehicle No: 26M 5556D

Tel:

6473 1488

at Workshop m/s Wearnes

of 249 Alexandria Road

Policy No:

Claim No: 017005457 MFSH

Sum Insured:

Excess:

D.O.A. 29052017

Make of Veh: 45 Long Kee Road
(Client's Record)

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS 'DS'

Zakaria

Vehicle IN/OUT OUT

Date/Time: 02062017 9:20am

Person Contacted:

Date/Time | Action/Instruction (✓) Estimate

26M 5556D - X

SHC 898R - NG/INC 15022010 / Alrbn2

D.A. 201215

sent preli to Luene

Confirm \$ 18,065.90, 5 days

Red: \$ 3270.50, 15%

Signature: *[Handwritten Signature]*

REF: FCI

7537A

ASSIGNMENT

From: _____ Date: 02062017

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGM 5556D

at Workshop m/s: WEARNES

of: 45 Long Kee Road

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Takaria

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SGM 5556D Yr Regn: 2013 / SEP

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: LAND ROVER FREELANDER 2.2 cc 1999

Colour: GREEN A/C: Insured / Std / NI / NA

Sp. Reading: 106676 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SALFAZAGODH 3678-21

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/65R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal. 6 mm Rear R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 29/05/17 D.O.I. 02/06/17

Survey held at: WEARNES

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

June (check) *condition photo*

RECEIVED 15 DEC 2017

Date/Time, File Pass to?

1) typist

Date/Time, File Return to?

2) _____

: Preli. Report
 : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Survey Fee: _____
Transportation: _____
S + RS: _____ SI
Photos: 5TP
Others: 10/12/17

11x15: 165
170 + 165
50
50
44
479

TOTAL

Report Format: TP
Lump Sum / I.B.I: (\$ 18,065.90)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FC117010722/R1rb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 02-06-2017



Code : FC12

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 898R	Veh. Inspected	SGM 5556D
Policy No.		Coverage (\$)	0.00
Claim No.	D17005487MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	02/06/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

5. General Information

Accident Date	29/05/2017	Inspection Date	02/06/2017
Survey held at	45 LENG KEE RD		
Repairer	WEARNES AUTOMOTIVE PTE LTD		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

MOTOR SURVEY ASSIGNMENT

Date	31-05-2017	Our Ref No. D17005487MFSH
Accident Date	29-05-2017	Claim Type. Third Party
Insured Vehicle	SHC0898R	Third Party Vehicle. SGM5556D
Survey Location	BODY AND PAINT DEPT 249 ALEXANDRA ROAD	
Contact Person.	MOHD FUAD BIN ZAKARIA	
Contact No.	64731488/ 64791067	Fax No. 64309333
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	WEARNES AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/223518)  PRI Documents  Close 

PRI Header Details

Claim No	D17005487MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & WE LTD
Workshop Name	WEARNES AUTOMOTIVE PTE LTD (Contact Person : MOHD FUAD BIN ZAKARIA)	Survey Location & Contact Details	BODY AND PAINT DEPT 249 ALEXANDRA ROAC Mobile: 64791067 , Phone: 64731488 , Fax: EmailId: MOHD.FUAD@WEARNES.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC0898R	TP Vehicle No	SGM55
PRI Recieved Date	01-06-2017 03:06:11 PM	Surveyor Appointed Date	02-06-2017 09:12:04 AM	Surveyor Accept Date	02-06-

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	02-06-2017	Upload Survey Report *:	<input type="checkbox"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--------------------------

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17005487MFSH

Our Ref: CS/FCI17010722/R1rb

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SGM 5556D .

Please be informed that we had conducted the inspection of the above mentioned vehicle on 02/06/2017 at the premises of M/s WEARNES AUTOMOTIVE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>21,336.40</u> .
Revised Estimate Amount	: S\$ <u>18,065.90</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:
The vehicle sustained damages
at the rear portion.




Yours faithfully

RASUL
Automotive Assessor

Accident Photo



Accident Photo



Accident Photo



Driving License



AUTHORIZATION TO ACT

I, _____ ("the third party Claimant")
of _____ (address),
owner of SGM 5556 D (vehicle no.)
hereby authorize _____ ("The workshop")
to act for me with respect to my claim for repair costs and / or rental and / or loss of use
(“claim”) for my Vehicle No. _____ that was damaged
pursuant to the accident which occurred on _____ (date) along
_____ (location)
involving Vehicle No/s _____ (“The accident”).

I further authorize the workshop to sign the discharge voucher on my behalf to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver / owner / insurers of the other vehicle/s is concerned.

Date this _____ day of _____ (month) 20____ (year)



Signed by "the third party claimant"

Signed by "the workshop"

SERVICE ESTIMATE

75247 - C00001 SL: SERVICE SALES - PC

Mr Ng Chee Keong
343B Pasir Panjang Road

GST Reg.No:M28920628X

Inv.No. . . : B&P 0 Page 1

Inv.date. . : 01/06/2017

WIP No. . . : 56258

Singapore 118679

Veh.In/Out:

*Tel.No. . . :

Reg.No. . . : SGM5556D

Closed by . . . : Mohd Fuad Bin Zakari

Reg.date . . : 13/09/2013

Svc Consultant :

Mileage . . : 0

Remarks : Mr Ng Chee Keong

Chassis No: SALPA2AG0DH367821

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE TAILGATE, REAR BUMPER, REAR BUMPER TREAD PLATE, REAR REFLECTOR LH, PARKING SENSOR, REAR BUMPER REINFORCEMENT, REAR BUMPER LOWER	0	3600.00	0		3,600.00 S	2400 3000 /
800	TO SPRAY PAINT TAILGATE, REAR BUMPER, REAR BUMPER LOWER, LH REAR FENDER	0	4000.00	0		4,000.00 S	3000 /
280	WIRING CHECK AND RESET ALL ELECTRONIC MODULES	0	486.00	0		486.00 S	/ /
	BUMPER COVER REAR FL	1.0 EA	2120.10			2,120.10 S	DB /
	PDC HOLDER REAR RH O	1.0 EA	74.50			74.50 S	new /
	PDC HOLDER REAR INNE	2.0 EA	74.50			149.00 S	new /
	PDC HOLDER REAR LH O	1.0 EA	74.50			74.50 S	new /
	BUMPER BRACKET REAR	1.0 EA	139.70			139.70 S	new /
	BUMPER BRACKET REAR	1.0 EA	139.70			139.70 S	new /

SERVICE ESTIMATE

75247 - C00001 SL: SERVICE SALES - PC

Mr Ng Chee Keong
343B Pasir Panjang Road

Singapore 118679

Closed by : Mohd Fuad Bin Zakari
Svc Consultant :
Remarks : Mr Ng Chee Keong

GST Reg.No: M2892062

Inv.No. : B&P
Inv.date : 01/06/2017
WIP No. : 56258
Veh. In/Out :
*Tel.No. :
Reg.No. : SGM5556D
Reg.date : 13/09/2013
Mileage : 0
Chassis No: SALFA2AG0DH367821

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Any illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	PARKING AID Straight	2pc 1.0 EA	313.60		627.2	1,254.40	S
	BUMPER REFLECTOR REA	1.0 EA	87.20			87.20	S
	BOOT REAR FL2 BH0000	1.0 EA	3975.30			3,975.30	S
	BOOT SEAL FL2 CH1122	1.0 EA	247.60			247.60	S
	BOOT LOCK FL2 EVOQUE	1.0 EA	335.80			335.80	S
	LOGO 'FREELANDER 2'	1.0 EA	239.20			239.20	S
	LOGO REAR FL2 BH0000	1.0 EA	44.90			44.90	S
	BADGE 'Si4 SE'	1.0 EA	166.50			166.50	S
	BUMPER BRACKET REAR	1.0 EA	191.40			191.40	S
	BUMPER TRIM REAR FL2	1.0 EA	207.80			207.80	S
	BUMPER BEAM REAR FL2	1.0 EA	1043.30			1,043.30	S

Rasul
Hp 90010068
5 days
p/p
02/06/17 @ 1540
Resurvey part
? x sur

Gross Total. 18,576.90 2133.90

Labour Total 8,086.00
Parts Total 10,490.90
Package Total 0.00

Net..... 18,576.90
GST @ 7.0% 1,300.38
Total..... 19,877.30
Paid..... 0.00
Please Pay.. 19,877.30

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

SERVICE ESTIMATE

0 - F00003
 FIRST CAPITAL INSURANCE LTD
 36 ROBINSON ROAD
 #16-01, CITY HOUSE
 SINGAPORE
 Singapore 068877

SL: FIRST CAPITAL INSURANCE LTD

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 1
 Inv.date. : 29/11/2017
 WIP No. . : 56258
 Veh.In/Out: 02/06/2017 14/06/2017
 *Tel.No. . :
 Reg.No. . : SGM5556D
 Reg.date . : 13/09/2013
 Mileage .. : 0
 Chassis No: SALFA2AG0DH367821

Closed by : Mandy Neo
 Svc Consultant :
 Remarks : Mr Ng Chee Keong

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE TAILGATE, REAR BUMPER, REAR BUMPER TREAD PLATE, REAR REFLECTOR LH, PARKING SENSOR, REAR BUMPER REINFORCEMENT, REAR BUMPER LOWER	0	3000.00	0		3,000.00	S ✓
800	TO SPRAY PAINT TAILGATE, REAR BUMPER, REAR BUMPER LOWER, LH REAR FENDER	0	3000.00	0		3,000.00	S ✓
280	WIRING CHECK AND RESET ALL ELECTRONIC MODULES	0	486.00	0		486.00	S ✓
802	TO REPLACE REAR WINDSCREEN	0	1200.00	0		1,200.00	S (R)
	BUMPER COVER REAR FL 4	1.0 EA	2120.10			2,120.10	S
	PDC HOLDER REAR RH 0 5	1.0 EA	74.50			74.50	S
	PDC HOLDER REAR INNE 6	2.0 EA	74.50			149.00	S
	PDC HOLDER REAR LH 0 7	1.0 EA	74.50			74.50	S
	BUMPER BRACKET REAR 8	1.0 EA	139.70			139.70	S

9770 4368

SERVICE ESTIMATE

0 - F00003 SI: FIRST CAPITAL INSURANCE LTD

FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01, CITY HOUSE
SINGAPORE
Singapore 068877

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 2
Inv.date. : 29/11/2017
WIP No. . : 56258
Veh.In/Out: 02/06/2017 14/06/2017
*Tel.No. . :
Reg.No. . : SGM5556D
Reg.date. : 13/09/2013
Mileage . : 0
Chassis No: SALFA2AG0DH367821

Closed by : Mandy Neo
Svc Consultant :
Remarks : Mr Ng Chee Keong

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BUMPER BRACKET REAR ^Q	1.0 FA	139.70			139.70	S
	PARKING AID Straight 10	2.0 FA	313.60			627.20	S
	BUMPER REFLECTOR REA 11	1.0 FA	87.20			87.20	S
	ROOT REAR FL2 BH0000 12	1.0 FA	3975.30			3,975.30	S
	ROOT SEAL FL2 CH1122 13	1.0 EA	247.60			247.60	S
	ROOT LOCK FL2 EVOQUE 14	1.0 EA	335.80			335.80	S
	LOGO 'FREELANDER 2' 15	1.0 EA	239.20			239.20	S
	LOGO REAR FL2 BH0000 16	1.0 EA	44.90			44.90	S
	BADGE 'Si4 SE' 17	1.0 EA	166.50			166.50	S
	BUMPER BRACKET REAR 18	1.0 EA	191.40			191.40	S
	BUMPER TRIM REAR FL2 19	1.0 EA	207.80			207.80	S
	WINDSCREEN REAR FL2	1.0 EA	1289.90			1,289.90	S
	ADHESIVE AND SEALER	2.0 EA	116.10			232.20	S
	D PRIMER GLASS & P	1.0 EA	37.40			37.40	S

Supp New
Supp New
Supp New
(A)

Gross Total. 18,065.90
Net..... 18,065.90
GST @ 7.0% 1,264.61
Total..... 19,330.51
Paid..... 0.00
Please Pay.. 19,330.51

Labour Total 7,686.00
Parts Total 10,379.90
Package Total 0.00

GST: S=StdRated; O=OutOfScope; Z=ZeroRated



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R.

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17010722/R1rbn2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 19-12-2017



Code : FC12

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 898R	Veh. Inspected	SGM 5556D
Policy No.	D-15072702MFSH	Coverage (\$)	0.00
Claim No.	D17005487MFSH	Excess (\$)	0.00
Assign From	LURENE	Assign Date	02/06/2017

2. Vehicle Particulars & Condition

Make & Model	LAND ROVER FREELANDER 2 2	c.c	1999
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	SALFA2AG0DH367821	Colour	GREEN
Odometer	106676	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/65 R17	MICHELIN	6 mm
L/H Front Tyre	235/65 R17	MICHELIN	6 mm
R/H Rear Tyre	235/65 R17	MICHELIN	6 mm
L/H Rear Tyre	235/65 R17	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/05/2017	Inspection Date	02/06/2017
Survey held at	45 LENG KEE RD		
Repairer	WEARNES AUTOMOTIVE PTE LTD		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGM 5556D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BUMPER COVER REAR FL (SN)	DEFORMED	2,120.10	2,120.10
1	PDC HOLDER REAR RH O (SN)	NECESSARY	74.50	74.50
2	PDC HOLDER REAR INNE (SN)	NECESSARY	149.00	149.00
1	PDC HOLDER REAR LH O (SN)	NECESSARY	74.50	74.50
1	BUMPER BRACKET REAR (SN)	NECESSARY	139.70	139.70
1	BUMPER BRACKET REAR (SN)	NECESSARY	139.70	139.70
4	PARKING AID STRAIGHT (SN)	NOT WORKING (2 PCS ONLY)	1,254.40	627.20
1	BUMPER REFLECTOR REA (SN)	SCRATCHED	87.20	87.20
1	BOOT REAR FL2 BH0000 (SN)	BENT	3,975.30	3,975.30
1	BOOT SEAL FL2 CH1122 (SN)	NECESSARY	247.60	247.60
1	BOOT LOCK FL2 EVOQUE (SN)	BENT	335.80	335.80
1	LOGO "FREELANDER 2" (SN)	NECESSARY	239.20	239.20
1	LOGO REAR FL2 BH0000 (SN)	NECESSARY	44.90	44.90
1	BADGE "S14 SE" (SN)	NECESSARY	166.50	166.50
1	BUMPER BRACKET REAR (SN)	NECESSARY	191.40	191.40
1	BUMPER TRIM REAR FL2 (SN)	DEFORMED	207.80	207.80
1	BUMPER BEAM REAR FL2 (SN)	SERVICEABLE	1,043.30	-
1	WINDSCREEN REAR FL2 (ADDITIONAL)(SN)	NECESSARY	1,289.90	1,289.90
2	ADHESIVE AND SEALER (ADDITIONAL)(SN)	NECESSARY	232.20	232.20
1	"D" PRIMER GLASS & P (ADDITIONAL)(SN)	NECESSARY	37.40	37.40
			12,050.40	10,379.90
<u>LABOUR</u>				
TO REPLACE REAR WINDSCREEN (ADDITIONAL).			1,200.00	1,200.00
TO REPLACE TAILGATE, REAR BUMPER, REAR BUMPER TREAD PLATE, REAR REFLECTOR LH, PARKING SENSOR, REAR BUMPER REINFORCEMENT, REAR BUMPER LOWER.			3,600.00	3,000.00
TO SPRAY PAINT TAILGATE, REAR BUMPER, REAR BUMPER LOWER, LH REAR FENDER.			4,000.00	3,000.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	WIRING CHECK AND RESET ALL ELECTRONIC MODULES.		486.00	486.00
			9,286.00	7,686.00
GRAND TOTAL			21,336.40	18,065.90
RECOMMENDED COST OF REPAIRS				18,065.90

Report Ref No. CS/FCI17010722/R1rbn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.