

ASS. REC. BY:

REF: CA/MSG-17011010/Ribez

Special Instruction:

Surveyor:

Rasul

ASSIGNMENT (Office)

From (Person):

Christina Wang

of

MSI/1

Date/Time:

06062017 453pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLE 70261

Insured:

GBF 9385A

at Workshop m/s

Motor Image

Tel:

6703 8144

of

25 Long Rd Road

Policy No:

C/N 83005897

Claim No:

517003

Sum Insured:

Excess:

Make of Veh:

D.O.A.

30052017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

08.062017 @ 10am - 1pm

H.O.D. Endorsement:

Date/Time:

06062017 457pm

Person Contacted:

Jeff

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLE 70261 - x
	GBF 9385A - x
12/6/17	Sent preli through menmen
	Confirm \$6652.64 @ 5 days
	Red: \$2,057.52, 24%

Surveyor: Paul
M/M/M

REF: MS16

3099F

ASSIGNMENT

From: _____ Date: 08/06/2017

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLE 7026L

at Workshop m/s MOTOR IMAGE
of 35 Leng Kee Rd

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____


(Client's Record)

Make of Veh: Dennis

(Policy Condition)

10am - 1pm

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS Wp

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLE 7026L Yr Regn: 2016 / July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: SUBARU FORESTER 2.0 XT c.c 1998

Colour WHITE A/C: Insured / Std / NI / NA

Sp.Reading 015588 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 3F12J4K85690 74814

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/55R18

R: 1 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 30/05/17 D.O.I. 08/06/17

Survey held at MOTOR IMAGE

Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 8 / JUN 2017

Date/Time, File Pass to?

☐

: Prel. Report

☒

: Final Report

1) typist

Date/Time, File Return to?

2) _____

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee: 150

Transportation: _____

) \$ + RS \$

) Photos

) Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format: R

Lump Sum / I.B.I: (\$ 6677.64)

10

160



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG17011010/R1rb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 06-06-2017	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBF 9385A	Veh. Inspected	SLE 7026L	
Policy No.	C/N83005897	Coverage (\$)	0.00	
Claim No.	517003	Excess (\$)	0.00	
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	06/06/2017	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	30/05/2017	Inspection Date	08/06/2017	
Survey held at	25 LENG KEE ROAD			
Repairer	MOTOR IMAGE ENTERPRISES PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 May 2017		06 Jun 2017 16:53 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	SAMWOH PREMIX PTE LTD, Co. Reg. No.: 199703387Z		
Main Claimant:	VASUGI D/O MURUGAYAN, ID: S1393099F		
Vehicle Reg. No.:	SLE7026L	Date of Loss:	30/05/2017 10:00 - :59
Claim Type:	TP / 517003	Policy/Cover Note No.:	C/N83005897 (Comprehensive) Coverage: 17/04/2017 - 16/04/2018
Vehicle Reg. No. (Insured):	GBF9385A	Policy No. (Claimant):	
		Excess:	
Repairer:	Motor Image Enterprises Pte Ltd (Leng Kee) 25 Leng Kee Road, 159097 Leng Kee - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 07/06/2017]		
Driver/Custodian (Insured):	TENG SOO GUAN (), NRIC: S15332358		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 12 Jun 2017

Preliminary Advice

Insured Vehicle No	: GBF9385A	Accident Date	: 30/05/2017
TP Vehicle No	: SLE7026L	Assignment Date	: 06/06/2017
Make	: SUBARU FORESTER	Est. Duration of Repair	: 5.00
Date of Inspection	: 08/06/2017		
Inspection At	: MOTOR IMAGE ENTERPRISES PTE LTD (LENG KEE) 25 LENG KEE ROAD SINGAPORE 159097		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,750.16
Revised Amount	:S\$	5,803.60
Check Items (Estimated)	:S\$	850.08
Total	:S\$	6,653.68

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/05/2017 13:59
Date Of Accident	30/05/2017 10:30
Exact Location Of Accident	AYER RAJA EXPRESSWAY TOWARDS CHANGI AIRPORT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLE7026L
Insured/Policyholder	
Name Of Registered Owner	VASUGI D/O MURUGAYAN
NRIC No	S1393099F
Email Address	VASMN59@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-97870297
Alternative Phone No	OTHERS-97870297

Vehicle Particulars

Manufacturer	SUBARU
Model	FORESTER-2.0 XT (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY


Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	2100477501

Driver

Name of Driver	VASUGI D/O MURUGAYAN
NRIC No	S1393099F
Date Of Birth	14/03/1959
Occupation	INDOOR
Date Of Driving Pass	08/02/1988
Driving Experience	29 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97870297
Fax Number	
Contact Number	OTHERS-97870297
Email Address	VASMN59@HOTMAIL.COM



COVER NOTE

doi:10.1017/S0022292412001606

AIG Asia Pacific Insurance Pte. Ltd.

Prof.

AUTHORIZED REPRESENTATIVE

recalls

Accident Photo

MSIG
 Motor Insurance (Singapore) Pte. Ltd.
 100 Robinson Road, #11-01, Singapore 068902
 Tel: 65 6337 7888 Fax: 65 6337 7889
 E-mail: msig@msig.com.sg

MOTOR INSURANCE COVER NOTE
 Cover Note No. 63005887

The insured named in the Schedule below hereby appoints its Insurer or assigns to the Insurer the right to recover the sum insured in the event of the insured vehicle being damaged or destroyed for the period in which the vehicle is insured by the Insurer. It is a condition of this cover note that the insured shall be responsible for the payment of the premium for such insurance and shall be responsible for the payment of the premium for such insurance.

SCHEDULE

Agent No.	219102
Name of Insured	Barnett Pte. Ltd.
Make and Description of Vehicle	Nissan Cabstar 3.0 (2017) ABS, Airbag, Sunroof
Vehicle Registration No.	
Year of Manufacture	2016
Engine No.	20000207174
Chassis No.	JN13C2F0400000000
Capacity	1.0 Tonne
Cover Type	Comprehensive
Sum Insured (SGD)	Market Value
Period of Insurance	One year from Date of Registration of the vehicle with LTA
Excess (SGD)	As Agreed
Finance Company	DBS Bank Limited

We hereby certify that this Covering note is issued in accordance with the Provisions of the Motor Vehicle (Third Party Risk & Compensation) Act (Cap. 188) and Part IV of the Road Transport Act, 1987 (Statutory) or any Amendment, Act or Act passed in substitution thereof.

Not valid unless countersigned by the Company's Authorized Representative

MSIG Insurance (Singapore) Pte. Ltd.
 Authorized Insurer

[Signature]
 Authorized Representative

[Signature]
 Man Tan
 Senior Vice President, EMEA

Date of Issue: 11/04/2017

This covering note is valid for 31 days from the date of issue.

Identification Card



Accident Photo



Accident Photo




Accident Photo



Identification Card



Accident Photo



MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/LHI/026/2017
DATE : 05-JUN-2017

AIG ASIA PACIFIC INSURANCE PTE LTD
7B SHENTON WAY
#07-16 AIG BUILDING
S(079120)
TEL :
FAX :

OWNER'S NAME : VASUGI D/O MURUGAYAN (97347194 RAJ)
ADDRESS : 19B HILLVIEW AVENUE
#05-03
S(669555)
TELEPHONE NO : 9787 0297

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100477501
VEHICLE NO : SLE7026L
MODEL CODE : SJGDKK8
MODEL/YEAR : FORESTER 2.0XT AWD CVT
ENGINE NO : FA20A971925
CHASSIS NO : JF1SJGKB5GG074814
MILEAGE : 1 KM
DATE IN : 05/06/2017
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DENNIS LEONG JIA HUI
ACCIDENT DATE : 05/06/2017

Print Date : 05/06/2017
Print Time : 20:11:47

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLE7026L

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	REPLACE/REPAIR RR BUMPER, END PANEL, TAILGATE	2240.00	1740 /
2	ZZ/002	RESPRAY RR BUMPER, TAILGATE, END PANEL AND FENDER LH & FENDER RH	2200.00	1320 /
3	ZZ/003	SUPPLY AND INSTALL REVERSE SENSOR	300.00	? 100 /
4	ZZ/004	REMOVE/REFIX RR WINDSCREEN	300.00	250 /
5	ZZ/005	SUPPLY & INSTALL RR WINDSCREEN SOLAR FILM	150.00	/ /
6	ZZ/006	REMOVE/REFIX EXHAUST SYSTEM	150.00	X X m
7	ZZ/007	SUNDRIES	100.00	50 /
TOTAL LABOUR CHARGES			5440.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLE7026L

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	L1ST S/NETT REMARKS
1	R END PANEL	52401SG0109P	288.00	? X <i>see</i>
2	BUMPER FACE R	57704SG012	540.00	<i>PC</i> /
3	BRKT SD R RH	57707SG080	14.40	<i>see</i> /
4	BRKT SD R LH	57707SG090	14.40	<i>see</i> /
5	BEAM COMPL R EU	57711SG0219P	288.00	? <i>RA</i> /
6	PANEL-REAR GATE	60809SG0509P	1072.80	<i>PA</i> /
7	GLASS R/G	63019SG000	799.20	<i>see (photo)</i> /
8	LATCH&ACT ASSY REAR GATE	63032SG002	504.00	X <i>see</i>
9	RUBBER DAM GLS * 2	63232SG000	7.20	<i>see</i> /
10	RUBBER R/G	63232SC010 LONGER 63232SG010	12.60	<i>see</i> /
11	STRIKER R/GATE	63264AG100	21.60	X X <i>see</i>
12	WSTR DR R G	63516SG001	111.60	? X <i>see</i>
13	GARNISH AY RG, B	91111SG000	144.00	<i>PR</i> /
14	PROTR R GARNISH (SUPP)	91713SG000	21.60	? <i>new</i> /
15	PROTECTOR LWR SD	91713SG010	10.80	<i>see</i> /
16	CARGO STEP PANEL (RESIN)	(<i>SN</i>) E775ESG000	230.00	<i>PC</i> /
SUB TOTAL			4080.20	0.00 0.00
LESS DISCOUNT (NETT-20 %)			770.04	0.00 0.00
GRAND TOTAL			3310.16	0.00 0.00
OVERALL TOTAL			3310.16	

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.

25 LENG KEE ROAD

SINGAPORE 259092

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLE7026L

TOTAL LABOUR CHARGES	5440.00
TOTAL SPARE PARTS CHARGES	3310.16
GRAND TOTAL	8750.16 *

9262.80

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	Rasul / Hp 9000008
SURVEYED DATE	:	08/06/12 @ 1030
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00 5 days
LIABILITY	:	0.00
REMARKS	:	Resurvey b4 paint

[Signature]
13/6/12

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/LH1/026/2017
DATE : 05-JUN-2017

AIG ASIA PACIFIC INSURANCE PTE LTD
7B SRENTON WAY
#07-16 AIG BUILDING
S(079120)
TEL : 91007211
FAX :

OWNER'S NAME : VASUGI D/O MURUGAYAN
ADDRESS : 19B HILLVIEW AVENUE
#05-03
S(669555)
TELEPHONE NO : 97870297

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100477501
VEHICLE NO : SLE7026L
MODEL CODE : SJGDKKB
MODEL/YEAR : FORESTER 2.0XT AWD CVT
ENGINE NO : FA2CA971926
CHASSIS NO : JF1SJGKB5GG074814
MILEAGE : 1 KM
DATE IN : 05/06/2017
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DENNIS LEONG JIA HUI
ACCIDENT DATE : 05/06/2017

Print Date : 07/03/2018
Print Time : 19:00:57

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLE7026L

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	REPLACE/REPAIR RR BUMPER,END PANEL,TAILGATE	2240.00	1740.00
2	ZZ/002	RESPRAY RR BUMPER,TAILGATE,END PANEL AND FANDER LH & FANDER RH	2200.00	1320.00
3	ZZ/003	SUPPLY AND INSTALL REVERSE SENSOR	300.00	100.00
4	ZZ/004	REMOVE/REFIX RR WINDSCREEN	300.00	290.00
5	ZZ/005	SUPPLY & INSTALL RR WINDSCREEN SOLAR FILM	150.00	150.00
6	ZZ/006	REMOVE/REFIX EXHAUST SYSTEM	150.00	.00
7	ZZ/007	SUNDRIES	100.00	50.00
TOTAL LABOUR CHARGES			5440.00	3610.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLE7026L

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST	REMARKS
			NETT	LIST	S/NETT		
1	R END PANEL	52401SG0109P	288.00				X
2	BUMPER FACE R	57704SG012	540.00				OK
3	BRKT SD R RH	57707SG080	14.40				OK
4	BRKT SD R LH	57707SG090	14.40				OK
5	BEAM COMPL R EU	(SUPP) 57711SG0219P	288.00				OK
6	PANEL-REAR GATE	60809SG0509P	1072.80				OK
7	GLASS R/G	63019SG000	799.20				OK
8	LATCH/ACT ASSY REAR GATE	63032SG002	504.00				X
9	RUBBER DAM GLS * 2	63232SG000	7.20				OK
10	RUBBER R/G	63232SC010 LONGER 63232SG010	12.60				OK
11	STRIKER R/GATE	63264AG100	21.60				X
12	WSTR DR R G	63516SG001	111.60				X
13	LENS & BODY COMPL/PL (A) car ✓	(SUPP) 84912SG111	432.00				OK
14	GARNISH AT RG, B	91111SG000	144.00				OK
15	PROTR R GARNISH (SUPP)	91713SG000	21.60				OK
16	PROTECTOR LWR SD	91713SG010	10.80				OK
17	ORNAMENT R	(SUPP) 93033SG001	79.20				OK
18	LETTER MK R AT	(SUPP) 93079SG010	64.80				OK
19	LETTER MK R SUB	(SUPP) 93079SG030	64.80				OK
20	CARGO STEP PANEL (RESIN)	E775ESG000	230.00 (SN)				OK
SUB TOTAL			3795.80	0.00	0.00	0.00	
LESS DISCOUNT (NETT-20 %)			713.16	0.00	0.00	0.00	
GRAND TOTAL			3082.64	0.00	0.00	0.00	
OVERALL TOTAL			3082.64				

5/11/14

DAMAGED PARTS & PRICES

S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST	REMARKS
------	-------------------	--------------	------	------	--------	--------	---------

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

total labour	\$ 3610.00
total parts	\$ 3082.64
	\$ 6692.64
	\$ 468.48 GST 7%
total	\$ 7161.12 #

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 May 2017		06 Jun 2017 16:53 Edit Adj Rpt	S\$6,692.64 Edit Estimates	S\$6,692.64 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	SAHWOH PREMIX PTE LTD , Co. Reg. No.: 199703387Z								
Main Claimant:	VASUGI D/O MURUGAYAN , ID: S1393099F								
Vehicle Reg. No.:	SLE7026L	Date of Loss:	30/05/2017 10:00 - :59 [10 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 517003	Policy/Cover Note No.:	C/N83005897 (Comprehensive) Coverage: 17/04/2017 - 16/04/2018						
Vehicle Reg. No. (Insured):	GBF9385A	Policy No. (Claimant):							
		Excess:							
Repairer:	Motor Image Enterprises Pte Ltd (Leng Kee) 25 Leng Kee Road, 159097 Leng Kee - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 06/07/2017]								
Driver/Custodian (Insured):	TENG SOO GUAN () , NRIC: S1533235B								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLE7026L (517003)
 [GBF9385A]
 TP
 VASUGI D/O MURUGAYAN
 May 30 2017 10:00AM
 [SAMWOH PREMIX PTE LTD]
 Motor Image Enterprises Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Assessment Reports									1 per page		☒	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)							Thumbnail		Print	
1	06/06/17 11:04	Accident Statement From: SC - Reg. No: GBF9385A, Claimant: SAMWOH PREMIX PTE LTD							1 Load HTM		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print	
1	12/06/17 17:40	Adjuster Immediate Advice							1 Load HTM		☒	
Photos/Images									3 per page		☒	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)							Thumbnail		Print	
1	06/06/17 16:42	Photos from Christina - Part 1							1 Load JPG		☒	
2	06/06/17 16:42	Photos from Christina - Part 2							1 Load JPG		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print	
1	07/06/18 15:53	General View							1 Load JPG		☒	
2	07/06/18 15:53	General View							1 Load JPG		☒	
3	07/06/18 15:53	General View							1 Load JPG		☒	
4	07/06/18 15:53	General View							1 Load JPG		☒	
5	07/06/18 15:53	General View							1 Load JPG		☒	
6	07/06/18 15:53	General View							1 Load JPG		☒	
7	07/06/18 15:53	General View							1 Load JPG		☒	
8	07/06/18 15:53	General View							1 Load JPG		☒	
9	07/06/18 15:53	General View							1 Load JPG		☒	
10	07/06/18 15:53	General View							1 Load JPG		☒	
11	07/06/18 15:53	General View							1 Load JPG		☒	
12	07/06/18 15:53	General View							1 Load JPG		☒	
13	07/06/18 15:53	General View							1 Load JPG		☒	
14	07/06/18 15:53	General View							1 Load JPG		☒	
15	07/06/18 15:53	General View							1 Load JPG		☒	
16	07/06/18 15:53	General View							1 Load JPG		☒	
17	07/06/18 15:53	General View							1 Load JPG		☒	
18	07/06/18 15:53	General View							1 Load JPG		☒	
19	07/06/18 15:53	General View							1 Load JPG		☒	
20	07/06/18 15:53	General View							1 Load JPG		☒	
21	07/06/18 15:53	General View							1 Load JPG		☒	
22	07/06/18 15:53	General View							1 Load JPG		☒	
23	07/06/18 15:53	General View							1 Load JPG		☒	
24	07/06/18 15:53	General View							1 Load JPG		☒	
25	07/06/18 15:53	General View							1 Load JPG		☒	
26	07/06/18 15:53	General View							1 Load JPG		☒	
27	07/06/18 15:53	General View							1 Load JPG		☒	
28	07/06/18 15:53	General View							1 Load JPG		☒	
29	07/06/18 15:53	General View							1 Load JPG		☒	

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
30	07/06/18 15:53	General View	 Load JPG	☒
31	07/06/18 15:53	General View	 Load JPG	☒
32	07/06/18 15:53	General View	 Load JPG	☒
33	07/06/18 15:53	General View	 Load JPG	☒
34	07/06/18 15:53	General View	 Load JPG	☒
35	07/06/18 15:53	General View	 Load JPG	☒
36	07/06/18 15:57	Reinspection Photo	 Load JPG	☒
37	07/06/18 15:57	Reinspection Photo	 Load JPG	☒
38	07/06/18 15:57	Reinspection Photo	 Load JPG	☒
39	07/06/18 15:57	Reinspection Photo	 Load JPG	☒
40	07/06/18 15:57	Reinspection Photo	 Load JPG	☒
41	07/06/18 15:57	Reinspection Photo	 Load JPG	☒
42	07/06/18 15:57	Reinspection Photo	 Load JPG	☒
43	07/06/18 15:57	Reinspection Photo	 Load JPG	☒
44	07/06/18 15:57	Reinspection Photo	 Load JPG	☒
45	07/06/18 15:57	Reinspection Photo	 Load JPG	☒
46	07/06/18 15:57	Reinspection Photo	 Load JPG	☒
47	07/06/18 15:57	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/06/17 11:04	SLE 7026 GIA RPT From: SC - Reg. No: GBP9385A, Claimant: SAMWON PREMIX PTE LTD	 Load PDF	
2	06/06/17 11:08	ESTIMATE	 Load PDF	
3	06/06/17 11:08	Email from Motor Image arrange survey	 Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	06/06/17 16:44	Email - Scene Photos	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/06/18 09:08	Supplementary	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17011010/R1RBE2

Date: 08/06/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: C/N83005897

Claimant Vehicle No: SLE7026L

Insured Vehicle No: GBF9385A

Date of Loss: 30/05/2017

Nature of Claim: TP

Claim No: 517003

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLE7026L

Make & Model: SUBARU FORESTER, 2.0 XT (A)

Engine No: FA20A971926

Reg. Date: 29/07/2016 (Man. Year: 2016)

Chassis No: JF1SJGK85GG074814

Colour: White

Odometer: 15588 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R18

Rear Tyre Size: 225/55 R18

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,922.80	3,132.64	790.16	20.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,340.00	3,560.00	1,780.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,262.80	6,692.64	2,570.16	27.75
+ GST 7.00/7.00% (S\$)	648.40	468.48	179.92	27.75
Nett Amount (S\$)	9,911.20	7,161.12	2,750.08	27.75

INSPECTION

Date of Assignment: 06/06/2017

Date Inspected: 08/06/2017 Inspected At:

Motor Image Enterprises Pte Ltd (Leng Kee)

25 Leng Kee Road

Singapore 159097

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Jun 2018)
Parts:	M1-SUV	SUBARU FORESTER 2.0 XT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLE7026L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
2	1		*R END PANEL	Serviceable	288.00 FN	*- FN
3	1		*BUMPER FACE R	Deformed	540.00 FN	*540.00 FN
4	1		*BRKT SD R RH	Necessary	14.40 FN	*14.40 FN
5	1		*BRKT SD R LH	Necessary	14.40 FN	*14.40 FN
6	1		*BEAM COMPL R EU	Bent	288.00 FN	*288.00 FN
7	1		*PANEL-REAR GATE	Bent	1,072.80 FN	*1,072.80 FN
8	1		*GLASS R/G	Necessary	799.20 FN	*799.20 FN
9	1		*LATCH & ACT ASSY REAR GATE	Serviceable	504.00 FN	*- FN
10	1		*RUBBER DAM GLS * 2	Necessary	7.20 FN	*7.20 FN
11	1		*RUBBER R/G	Necessary	12.60 FN	*12.60 FN
12	1		*STRIKER R/GATE	Serviceable	21.60 FN	*- FN
13	1		*WSTR DR R G	Serviceable	111.60 FN	*- FN
14	1		*GARNISH AY RG, B	Broken	144.00 FN	*144.00 FN
15	1		*PROTR R GARNISH	Necessary	21.60 FN	*21.60 FN
16	1		*PROTECTOR LWR SD	Necessary	10.80 FN	*10.80 FN
17	1		*CARGO STEP PANEL (RESIN)	Deformed	230.00 FS	*230.00 FS
18	1		*LENS & BODY COMPLJPL	Cracked	432.00 FN	*432.00 FN
19	1		*ORNAMENT R	Necessary	79.20 FN	*79.20 FN
20	1		*LETTER MK R XT	Necessary	64.80 FN	*64.80 FN
21	1		*LETTER MK R SUB	Necessary	64.80 FN	*64.80 FN

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	4,821.00	3,845.80
- Nett Item Discount on N Items 20.00/20.00% (\$\$)	898.20	713.16
Total Parts (\$\$)	3,922.80	3,132.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPLACE/ REPAIR RR BUMPER, END PANEL, TAILGATE	New	2,240.00	1,740.00
2	RESPRAY RR BUMPER, TAILGATE, END PANEL AND FENDER LH & FENDER RH	New	2,200.00	1,320.00
3	SUPPLY AND INSTALL REVERSE SENSOR	New	300.00	100.00
4	REMOVE / REFIX RR WINDSCREEN	New	300.00	250.00
5	SUPPLY & INSTALL RR WINDSCREEN SOLAR FILM	New	150.00	150.00
6	REMOVE / REFIX EXHAUST SYSTEM	New	150.00	0.00
Gross Labour Cost (\$\$)			5,340.00	3,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >