

ASS. REC. BY:

REF: ALC12170110951 Agh3n2

Special Instructions:

Surveyor:

Adrian

ASSIGNMENT (Office)

Date/Time: 7/6/2017 2:44pm

From (Person):

Samy Ray

of CR2

Bill to:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

Insured: SJN1499X

To Inspect Vehicle No:

SGB2772Z

Tel: 81006306

at Workshop m/s

Kah Motor

of

15461 Road 4

Policy No:

UMPCSN 30100 71700

Claim No:

SJM17003219C02

Sum Insured:

Excess:

D.O.A. 29/5/2017

Make of Veh:
(Client's Record)

8/6/2017 @ after 10am

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS (ds)

Date/Time:

7/6/2017 2:48pm

Person Contacted:

Any

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SGB2772Z - A</u>
	<u>SJM14991 - M/LAC13015406/RITC3</u>
<u>20/11/17 @ 3:48pm</u>	<u>confirmed with Any Anal fig 87151.19, 5 days by email.</u>
	<u>(Chd \$15165.71, 68%)</u>

D.O.A. 23/8/2013

REF: CT2

ASSIGNMENT

From: Date: 8/6/2017

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

81B 2772Z

at Workshop m/s

Kah Motor

of

1546, Road 4

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

After 10 am

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt.

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS (bs)

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S6B2772Z.

Yr Regn:

2016 August.

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Odyssey

cc 2356

Colour:

White

A/C: Insured / Std / NI / NA

Sp. Reading

13881

T/Radio: Insured / Std / NI / NA

Eng/No:

JHMRC1890GC 206088

Ci/No:

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / ☒ STD A/Rim or

Tyre Size:

F:

215/55R17.

R:

215/55R17.

BS / ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

08/06/17.

Survey held at

Kah Motor

Des. of Damages: ☒ Frt / ☒ Rear / ☒ O/S / ☒ N/S / ☒ U/C / ☒ Rooftop or

Front ds.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Chrim

RECEIVED 20 NOV 2017

Date/Time, File Pass to?

11/20/11 TURB+

Date/Time, File Return to?

2)

☐

Preli. Report

☐

Final Report

Days Of Repair: 5

Re-survey No. of Trip: 1

Survey Fee:

Transportation:

) \$ + RS. \$ SI

) Photos

) Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format:

WETP

Lump Sum / I.B.I. (\$

7151.19

250



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI17011095/Aqh3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 07-06-2017		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJN 1499X	Veh. Inspected	SGB 2772Z	
Policy No.	DMPCSN3010071700	Coverage (\$)	0.00	
Claim No.	SNM17D03219C02	Excess (\$)	0.00	
Assign From	MERIMEN (JOWYN TAY)	Assign Date	07/06/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	29/05/2017	Inspection Date	08/06/2017	
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

SGB 27722

Policy Type: OD / TP / TP RES / TL / EVA

Typist

Admin (Ashley)

[illegible]

- | | |
|---|---------------------------------------|
| C | Reference No. |
| C | Customer Code |
| N | Assign From |
| C | Assign Date |
| C | Veh No (Inspected) |
| C | Veh No (Insured) |
| C | D.O.A |
| C | Policy No |
| C | Claim No |
| C | Insurance Authorisation (CA /REV/REP) |
| C | Report Type |
| C | Weekend Charges |
| N | Survey held at/Repairer |
| C | Excess |

Surveyor (*Adnan*)

[illegible]

- | | |
|---|------------------------|
| C | Vehicle No |
| C | Regn Month/Year |
| N | Vehicle Type |
| N | Make & Model |
| C | Engine Capacity. (C.C) |
| N | Colour |
| C | Odometer. (Sp.Reading) |
| C | Chassis No |
| N | General Condition |
| N | Steering |
| N | Brake |
| N | Modification (Modi) |
| C | Tyre Size |
| N | Tyre Make |
| C | Tyre Balance |
| C | Date of Inspection |
| N | Survey held |
| N | Des.of Damages |

☒	☐
-------------------------------------	--------------------------

- C Damaged Vehicle Photographs Uploaded

✓	
✓	
✓	

- | | |
|---|---|
| N | ALL Parts condition |
| C | Market Value for OD cases |
| C | Estimate Repair Cost for PRI (RSI, TMI, MSIG) |
| C | Days of repair |
| C | Finalised Amount |
| C | Re-inspection Cases to Finalize within 5 Days |

--	--	--	--

- C Resurvey photo Uploaded

20/11/17

Date _____

21/05/2014

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Jun 2017		07 Jun 2017 14:44 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	LEE SIEW BIN, ID: S6914061J		
Main Claimant:	CHEW EE HUAT, VICTOR, ID: S7217826B		
Vehicle Reg. No.:	SGB2772Z	Date of Loss:	29/05/2017 14:00 - :59
Claim Type:	TP / SNM17D03219C02	Policy/Cover Note No.:	DMPCSN3010071700 (Comprehensive) Coverage: 05/02/2017 - 04/02/2018
Vehicle Reg. No. (Insured):	SJN1499X	Policy No. (Claimant):	SD16V10938/VPC2/R00
		Excess:	S\$0.00
Repairer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: 6221 8611		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 16/06/2017]		
Adj Asg. Remarks:	PLEASE PROCEED TO SURVEY AND ARRANGE FOR DIRECT SETTLEMENT.		

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 20 November, 2017 3:48 PM
To: 'Ary Chua'
Cc: SUR
Subject: RE: Finalise TPDS: SGB2772Z(LIBERTY) & SJN1499X(C/T), DOA: 29/05/2017@14:40PM

Dear Ary,

Confirm final fig \$7,151.19 before GST and 5 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Adrian Ling (LKKAUTO)
Sent: Friday, 3 November, 2017 10:40 AM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Subject: FW: Finalise TPDS: SGB2772Z(LIBERTY) & SJN1499X(C/T), DOA: 29/05/2017@14:40PM

From: Ary Chua [<mailto:arychua@honda.com.sg>]
Sent: Tuesday, 4 July, 2017 10:06 AM
To: Adrian Ling (LKKAUTO)
Subject: Finalise TPDS: SGB2772Z(LIBERTY) & SJN1499X(C/T), DOA: 29/05/2017@14:40PM

Hi Adrian,

Kindly Finalise TPDS: SGB2772Z(LIBERTY) & SJN1499X(C/T), DOA: 29/05/2017@14:40PM

Vehicle No:	SGB2772Z
Final Repair Costs (include GST)	\$7,151.19 + (\$500.58) = \$7,651.77
Repair Period* (Working Day)	05

***NOTES: The Repair Not Includes Public Holiday & Sunday.**

Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

Thank you

Best Regards,

Ary Chua Wai Ngee

Bodyshop Service Advisor

Kah Motor Co.Sdn.Bhd.

E-mail: arychua@honda.com.sg

Fax: 67480770 DID: 68465673 H/P 81006306

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 30/05/2017 14:26
Date Of Accident 29/05/2017 14:40
Exact Location Of Accident JUNCTION HIGHLAND RD & JANSEN RD (LAMP POST 24)
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SGB2772Z
Insured/Policyholder
Name Of Registered Owner CHEW EE HUAT, VICTOR
NRIC No S7217826B
Email Address VCHEW1818@GMAIL.COM
Mobile Phone No (LOCAL) +65-97572578
Alternative Phone No OFFICE-97572578
Vehicle Particulars
Manufacturer HONDA
Model ODYSSEY-2.4 EXV-S (A)
Exact Purpose for which vehicle was being used at time of accident P/USED
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR
Insurance Company
Name of Insurance Company LIBERTY INSURANCE PTE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number SD16V10938/VPC2/R00
Cover Note Number
Driver
Name of Driver CHEW TEE SEAH
NRIC No S0883754F
Date Of Birth 18/11/1944
Occupation INDOOR
Date Of Driving Pass 26/01/1962
Driving Experience 55 YEARS AND 4 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-97898147
Fax Number
Contact Number VCHEW1818@GMAIL.COM
Email Address

Address	8 MINBU ROAD #16-03
Postcode	S308162
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION- HEAD TO SIDE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJN1499X
Vehicle Make/Model/Colour	HYUNDAI/SONATA/WHITE
Details Of Properties	
Name of Driver	TAN YI JIE, XENIA
NRIC/Passport Number	S9529278Z
Contact Number	
Address	
Postcode	
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

Vehicle No SGB2772Z

SKETCH PLAN

Annex D


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



A = SGB2772Z
B = SJN1499X

Please continue to Annex E

Sketch Plan Pg. 2

Annex E

Vehicle No SGB 2772 Z

Describe Circumstances of the Accident

ON 29-5-17 I WAS DRIVING ALONG HIGHLAND RD
SUDDENLY A CAR CAME OUT FROM THE RIGHT SIDE LANE
JANSEN ROAD, AS A RESULT THE MY CAR HIT THE LEFT
SIDE OF THE CAR SJN 1699X BELVAUE I HAVE NO TIME TO
AVOID IT.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &
Time

ARY CHUA
Driver's Signature (if driver is not the policyholder) / Date
& Time

ARY 12.48pm
ARY CHUA 30 MAY 2017
Witnessed by Reporting Centre
Personnel

Addendum Sheet Pg. 1

GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE

IMPORTANT NOTE : Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MEM117071083 Vehicle Registration No : SGB2772Z
Name(as shown in NRIC): Chew Ee Huat, Victor
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
NRIC/Passport No : S7217826B
Address : 8 Minbu Road #16-03 S308162
(H/P): 97572578
Contact (Tel) : _____
(Email): vchew1818@gmail.com
Date of Accident : 29 MAY 2017 Time of Accident : 14:40pm
Place of Accident : Junction Highland Road & Jansen Road (Lamp Post 24)
Insurance Company : Liberty Insurance Pte. Ltd.

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Owner decide to claims TPDS = China Taiping Insurance
Net Own Damage claim = Liberty Insurance.

Signature of Vehicle Owner / Driver
Date: 07 JUN 2017



10 Anson Road #06-16 International Plaza Singapore 079903 Phone : + 65 6224 0010 Fax : +65 6224 0030
Operating Hours : Monday to Friday 9am to 5pm



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair
Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: MB-8100104-3
Company Ref. No.: 3954-X

Surveyor At
02 JUN 2017 10:00am
This Friday

Customer : CHINA TAIPING INSURANCE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
Registration No : SGB2772Z
Chassis No : JHMRC1890GC206088
Model : ODYSSEY 2.4 EXV-S 16YM
Owner's Name : CHEW EE HUAT, VICTOR
Ins Policy No. : SD16V10938/VPC2/R00
Date of Accident : 29/5/2017

Document No. : SQT17002329
Date : 30. May 2017
Customer No. : WZC008
Svc Advisor : ARY CHUA WAI NGEE
Engine No : K24W72012732
Date | Time : 30. May 2017 2:36:43 PM
Surveyor Name : 15 Ubi Road # Singapore 408610
Survey Date : Tel : +65 6841 3838 HP : +65 8100 6308
Authorisation Date : Fax : +65 6745 0770 DID : + 6546 5672
E-mail: bdysa4@honda.com.sg

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 68560)						
	OWNER: CHEW EE HUAT, VICTOR						
	OWNER INSURER: LIBERTY INSURANCE SINGAPORE LTD						
	ACC DATE: 29/05/2017@14:40PM						
	SURVEYED BY:						
	WORKING DAYS: 07						
	REF NO:						
	TP INSURER: CHINA TAIPING INSURANCE PTE LTD						
	TP VEH: SJN1499X						
BO-NUM-COMP-S	NUMBER PLATE WITH CASING-S(N) <i>Best</i>	1	45.00		45.00	3.15	48.15
33100-T6A-Q11	HEADLIGHT ASSYR.WITH LED <i>2nd</i>	1	2237.30	25	1677.97	117.46	1795.43
33900-TY0-003	LIGHT ASSY FR.FOG <i>2nd</i>	1	261.80	25	196.35	13.74	210.09
33905-T6A-003	BRACKETR.FR.FOGLIGHT <i>2nd</i>	1	62.00	25	46.50	3.26	49.76
71104-T6A-921	GARNISHR.FR.BUMPER <i>2nd</i>	1	45.20	25	33.90	2.37	36.27
04711-T6A-900ZZ	FACEFR.BUMPER <i>2nd</i>	1	686.30	25	514.72	36.03	550.75
71152-T6A-921	UPPER MOLDINGMID GRILLE <i>2nd</i>	1	150.60	25	112.95	7.91	120.86
71153-T6A-921	MID MOLDINGMID GRILLE <i>2nd</i>	1	144.20	25	108.15	7.57	115.72
71154-T6A-921	LOWER MOLDINGR.MID GRILLE <i>2nd</i>	1	38.70	25	29.02	2.03	31.05
71159-T6A-921	LOWER MOLDINGL.MID GRILLE <i>2nd</i>	1	38.70	25	29.02	2.03	31.05
71105-T6A-901	GRILLEFR.BUMPER LOWER <i>2nd</i>	1	65.80	25	49.35	3.45	52.80
75700-TA0-A00	EMBLEMFR. <i>2nd</i>	1	25.30	25	18.97	1.33	20.30
90301-ST0-003	NUTPUSH 3MM <i>2nd</i>	2	1.90	25	2.85	0.20	3.05
71121-T6A-003	BASEFR.GRILLE <i>2nd</i>	1	165.70	25	124.27	8.70	132.97
71122-T6A-003	MOLDINGFR.GRILLE <i>2nd</i>	1	258.10	25	193.57	13.55	207.12
71151-T6A-911	BASEMID GRILLE <i>2nd</i>	1	182.80	25	137.10	9.60	146.70
71130-T6A-310ZZ	BEAM COMP.FR.BUMPER <i>2nd</i>	1	9999.99	25	7499.99	525.00	8024.99
71140-T6A-003	BEAMR.FR.BUMPER UPPER <i>2nd</i>	1	34.20	25	25.65	1.80	27.45
71190-T6A-003	BEAML.FR.BUMPER UPPER <i>2nd</i>	1	34.20	25	25.65	1.80	27.45
71193-T6A-003	SPACERR.FR.BUMPER SIDE <i>2nd</i>	1	11.60	25	8.70	0.61	9.31



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: MB-8100104-3

Company Ref. No.: 3954-X

Customer : CHINA TAIPING INSURANCE
 3 ANSON ROAD #16-00
 SPRINGLEAF TOWER
 SINGAPORE 079909

Registration No : SGB2772Z
 Chassis No : JHMRC1890GC206088
 Model : ODYSSEY 2.4 EXV-S 16YM
 Owner's Name : CHEW EE HUAT, VICTOR
 Ins Policy No. : SD16V10938/VPC2/R00
 Date of Accident : 29/5/2017

Document No. : SQT17002329
 Date : 30. May 2017
 Customer No. : WZC008
 Svc Advisor : ARY CHUA WAI NGEE
 Engine No : K24W72012732
 Date | Time : 30. May 2017 2:36:43 PM
 Surveyor Name :
 Survey Date :
 Authorisation Date :
 15 Ubi Road 4 Singapore 408610
 Tel: +65 6841 3838 HP: +65 8100 6308
 Fax: +65 6748 0770 DID: +6846 5673
 E-mail: bdyas4@honda.com.sg

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
71198-T6A-003	SPACERL.FR.BUMPER SIDE	1	11.60	25	8.70	0.61	9.31
71108-T6A-P00	LOWER PLATEFR.BUMPER	1	144.20	25	108.15	7.57	115.72
71112-T6A-921ZE	SPOILER ASSYR.FR.SIDE	1	92.50	25	69.37	4.86	74.23
71117-T6A-921ZE	SPOILER ASSYL.FR.SIDE	1	92.50	25	69.37	4.86	74.23
60100-T6A-000ZZ	HOOD COMP	1	658.30	25	493.72	34.56	528.28
60210-T6A-300ZZ	FENDER COMPR.FR.	1	537.80	25	403.35	28.23	431.58
74105-T6A-000	ENCLOSURER.FR.FENDER	1	25.80	25	19.35	1.35	20.70
60400-T6A-310ZZ	BULKHEAD COMPR.	1	451.80	25	338.85	23.72	362.57
60433-T6D-H00ZZ	SUPPORTR.FR.BULKHEAD UPP SIDE	1	32.90	25	24.67	1.73	26.40
60483-T6D-H00ZZ	SUPPORTL.FR.BULKHEAD UPP SIDE	1	32.90	25	24.67	1.73	26.40
80111-T6A-003	CONDENSER COMP	1	668.60	25	501.45	35.10	536.55
19010-5X6-J02	RADIATOR COMP	1	1320.90	25	990.67	69.35	1060.02
08CLA-P9911LK8	COOLANTANTI-FREEZE	6	23.20	25	104.40	7.31	111.71
90682-SEA-003	CLIP ABUMPER	6	2.30	25	10.35	0.72	11.07
91512-R21-013	CLIPINNER FENDER	6	0.40	25	1.80	0.13	1.93
91501-TR0-003	CLIPINNER FENDER	6	2.30	25	10.35	0.72	11.07
91505-TM8-003	CLIPBUMPER	12	2.00	25	18.00	1.26	19.26
Sum Item					14076.90	985.38	15,062.28
BOSUN	SUNDRIES	1	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT.	1	100.00		100.00	7.00	107.00
BML01I	INSPECT FR. & FOG LIGHTING MECHANISMS & FOCUS	1	180.00		180.00	12.60	192.60
BMC01D	REMOVE & INSTALL RADIATOR WITH FITTINGS.	1	280.00		280.00	19.60	299.60
BMA01D	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.	1	380.00		380.00	26.60	406.60
BOMISC1	CALIBRATION FRONT VIEW CAMERA (N)	1	400.00		400.00	28.00	428.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3300.00		3300.00	231.00	3531.00
BKBH12B	CUT OFF & RENEW BULKHEAD FR R HOUSING COMP.	1	3500.00		3500.00	245.00	3745.00
Sum Labor					8240.00	576.80	8,816.80

Survey By

Printed on 31/5/2017 9:08:23 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages

GST Amount is calculated from individual line(s)



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: MB-8100104-3
Company Ref. No.: 3954-X

Customer : CHINA TAIPING INSURANCE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
Registration No : SGB2772Z
Chassis No : JHMRC1890GC206088
Model : ODYSSEY 2.4 EXV-S 16YM
Owner's Name : CHEW EE HUAT, VICTOR
Ins Policy No. : SD16V10938/VPC2/R00
Date of Accident : 29/5/2017

Document No. : SQT17002329
Date : 30. May 2017
Customer No. : WZC008
Svc Advisor : ARY CHUA WAI NGEE
Engine No : K24W72012732
Date | Time : 30. May 2017 2:36:43 PM
Surveyor Name :
Survey Date :
Authorisation Date :
15 Ubi Road # Singapore 408610
Tel : +65 6841 3838 1/F : +65 8100 6308
Fax : +65 6798 0770 DID : + 6846 5673
Email: bdyas@honda.com.sg

Page 3

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incl GST
Date & Time	08/06/17 11:40am.						
Excess							
Status	Not Authorized.						
Signature	882.						
Total Amount					22,316.90	1,562.18	23,879.08
Total (Inclusive of GST)							23,879.08

050 days.

adrianling @ lkdcauto.com.
96893735.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 31/5/2017 9:08:23 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZC008 / CHINA TAIPING
 Chassis No: JHMRC1890GC206088
 License No: SGB2772Z
 Mileage: 14141
 Engine No: K24W72012732

Document No: SVO17037752
 Printed By: ARYCHUA
 Order Date: 8. June 2017
 Order Time: 12:10:13 PM
 Service Advisor: ARY CHUA WAI NGEE

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	GST Amt	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 68560)						
	OWNER: CHEW EE HUAT, VICTOR						
	OWNER INSURER: LIBERTY INSURANCE SINGAPORE LTD						
	ACC DATE: 29/05/2017@14:40PM						
	SURVEYED BY: ADRIAN LING (LKKAUTO)						
	WORKING DAYS: 05						
	REF NO: SNM17D03219C02/9						
	TP INSURER: CHINA TAIPING INSURANCE PTE LTD						
	TP VEH: SJN1499X						
BO-NUM-COMP-S	NUMBER PLATE WITH CASING-S(N)	1	45.00		45.00	3.15	48.15
33100-T6A-Q11	HEADLIGHT ASSYR.WITH LED	1	2,237.30	25	1,677.97	117.46	1,795.43
71104-T6A-921	GARNISHR.FR.BUMPER	1	45.20	25	33.90	2.37	36.27
04711-T6A-900ZZ	FACEFR.BUMPER	1	686.30	25	514.72	36.03	550.75
71153-T6A-921	MID MOLDINGMID GRILLE	1	144.20	25	108.15	7.57	115.72
75700-TA0-A00	EMBLEMFR.	1	25.30	25	18.97	1.33	20.30
90301-ST0-003	NUTPUSH 3MM	2	1.90	25	2.85	0.20	3.05
71121-T6A-003	BASEFR.GRILLE	1	165.70	25	124.27	8.70	132.97
71122-T6A-003	MOLDINGFR.GRILLE	1	258.10	25	193.57	13.55	207.12
71193-T6A-003	SPACERR.FR.BUMPER SIDE	1	11.60	25	8.70	0.61	9.31
71198-T6A-003	SPACERL.FR.BUMPER SIDE	1	11.60	25	8.70	0.61	9.31
90682-SEA-003	CLIP ABUMPER	6	2.30	25	10.35	0.72	11.07
91501-TR0-003	CLIPINNER FENDER	6	2.30	25	10.35	0.72	11.07
91505-TM8-003	CLIPBUMPER	12	2.00	25	18.00	1.26	19.26
71130-T6A-305ZZ	BEAM COMPFR.BUMPER		286.10		214.57	15.02	
71151-T6A-911	BASEMID GRILLE		182.80		137.10	9.60	
71140-T6A-003	BEAMR.FR.BUMPER UPPER		34.20		25.65	1.80	
71105-T6A-901	GRILLEFR.BUMPER LOWER		65.80		49.35	3.45	
71154-T6A-921	LOWER MOLDINGR.MID GRILLE		38.70		29.02	2.03	
	SUM PARTS:				3,231.19	226.18	3,457.37
		1	10.00		10.00	0.70	10.70
BOSUN	0626						
	SUNDRIES	1	80.00		80.00	5.60	85.60
BML01I	EXT-YJ						
	INSPECT FR.& FOG LIGHTING						
	MECHANISMS & FOCUS						
	HEADLIGHTS.(N)	1	350.00		350.00	24.50	374.50
BOMISC1	EXT-YJ						
	CALIBRATION FRONT VIEW CAMERA.(N)	1	1,680.00		1,680.00	117.60	1,797.60
BKBH12B	EXT-YJ						
	CUT OFF & RENEW BULKHEAD FR R						
	HOUSING COMP.X3						
	STRAIGHTEN ALIGN FR R FRAME &						
	RENEW DAMAGE PARTS.	1	1,800.00		1,800.00	126.00	1,926.00
BP06R	EXT-YBH						
	SPRAY PAINTING ON REPAIRED OR						
	REPLACED AREAS. (4P)						
	SUM LABOUR:				3,920.00	274.40	4,194.40
	TOTAL SGD				7,151.19	500.58	7,651.77
	Total Payable (SGD)						7,651.77

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: S7217626B / CHEW EE HUAT
Chassis No: JHMRC1890GC206088
License No: SGB2772Z
Mileage: 14141
Engine No: K24W72012732

Document No: SVO17037752
Printed By: ARYCHUA
Order Date: 8. June 2017
Order Time: 12:10:13 PM
Service Advisor: ARY CHUA WAI NGEE

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	GST Amt	Amount incld GST
	SUPPLEMENTARY ITEM PARTS & LABOR						
	TP DIRECT SETTLEMENT (J/NO: 68560)						
	OWNER: CHEW EE HUAT, VICTOR						
	OWNER INSURER: LIBERTY INSURANCE SINGAPORE LTD						
	ACC DATE: 29/05/2017@14:40PM						
	SURVEYED BY: ADRIAN LING (LKKAUTO)						
	WORKING DAYS: 5						
	REF NO: SNM17D03219C02/9						
	TP INSURER: CHINA TAIPING INSURANCE PTE LTD						
	TP VEH: SJN1499X						
71130-T6A-305ZZ	BEAM COMPFR BUMPER	286.10		25	214.57	15.02	229.59
71151-T6A-911	BASEMID GRILLE	182.80		25	137.10	9.60	146.70
71140-T6A-003	BEAMR.FR BUMPER UPPER	34.20		25	25.65	1.80	27.45
71105-T6A-901	GRILLEFR BUMPER LOWER	65.80		25	49.35	3.45	52.80
71154-T6A-921	LOWER MOLDINGR.MID GRILLE	38.70		25	29.02	2.03	31.05
	SUM PARTS:				455.69	31.90	487.59
	TOTAL SGD				455.69	31.90	487.59

Total Payable (SGD)

487.59

GST Amount is calculated from individual line(s)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI17011095/AQH3N2

Date: 22/11/2017

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

Claimant: SGB2772Z

Vehicle No :

Date of Loss: 29/05/2017

Policy No: DMPCSN3010071700

Insured Vehicle No : SJN1499X

Nature of Claim: TP

Claim No: SNM17D03219C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGB2772Z

Make & Model: HONDA ODYSSEY, 2.4 EXV-S (A)

Reg. Date: 18/08/2016 (Man. Year: 2016)

Colour: White

Engine Capacity: 2356 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: K24W72012732

Chassis No: JHMRC1890GC206088

Odometer: 13881 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No

Footbrake (Serviceable): Yes

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17

Front Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Tyre Size: 215/55 R17

Rear Left Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	14,176.90	3,241.19	10,935.71	77.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,140.00	3,910.00	4,230.00	51.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	22,316.90	7,151.19	15,165.71	67.96
+ GST 7.00/7.00% (S\$)	1,562.18	500.58	1,061.60	67.96
Nett Amount (S\$)	23,879.08	7,651.77	16,227.31	67.96

INSPECTION

Date of Assignment: 07/06/2017

Date Inspected: 08/06/2017

Inspected At:

Kah Motor Co Sdn Bhd (Ubi)
15 Ubi Road 4
Singapore 408610

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Nov 2017)
 Parts: M1-SUV HONDA ODYSSEY 2.4 EXV-S (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SGB2772Z)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*NUMBER PLATE WITH CASING-S	Bent	45.00 FS	*45.00 FS
2	1		*HEADLIGHT ASSYR. WITH LED	Cut	1,677.97 FS	*1,677.97 FS
3	1		*LIGHT ASSY FR. FOG	Not Necessary	196.35 FS	*- FS
4	1		*BRACKETR.FR. FOGLIGHT	Not Necessary	46.50 FS	*- FS
5	1		*GARNISHR.FR.BUMPER	Cut	33.90 FS	*33.90 FS
6	1		*FACEFR.BUMPER	Deformed	514.72 FS	*514.72 FS
7	1		*UPPER MOLDINGMID GRILLE	Not Necessary	112.95 FS	*- FS
8	1		*MID MOULDINGMID GRILLE	Cut	108.15 FS	*108.15 FS
9	1		*LOWER MOLDINGR. MID GRILLE	Cracked	29.02 FS	*29.02 FS
10	1		*LOWER MOLDINGL. MID GRILLE	Not Necessary	29.02 FS	*- FS
11	1		*GRILLEFR.BUMPER LOWER	Cut	49.35 FS	*49.35 FS
12	1		*EMBLEMFR.	Necessary	18.97 FS	*18.97 FS
13	1		*NUTPUSH 3MM	Necessary	2.85 FS	*2.85 FS
			(2pc)			
14	1		*BASEFR. GRILLE	Cracked	124.27 FS	*124.27 FS
15	1		*MOLDINGFR.GRILLE	Cut	193.57 FS	*193.57 FS
16	1		*BASEMID GRILLE	Damaged	137.10 FS	*137.10 FS
17	1		*BEAM COMP, FR. BUMPER	Bent	7,499.99 FS	*214.57 FS
18	1		*BEAMR.FR. BUMPER UPPER	Cracked	25.65 FS	*25.65 FS
19	1		*BEAML.FR. BUMPER UPPER	Not Necessary	25.65 FS	*- FS
20	1		*SPACERR.FR.BUMPER SIDE	Necessary	8.70 FS	*8.70 FS
21	1		*SPACERL.FR.BUMPER SIDE	Necessary	8.70 FS	*8.70 FS
22	1		*LOWER PLATEFR. BUMPER	Not Necessary	108.15 FS	*- FS
23	1		*SPOLIER ASSYR.FR. SIDE	Repair	69.37 FS	*- FS
24	1		*SPOLIER ASSYL.FR. SIDE	Not Necessary	69.37 FS	*- FS
25	1		*HOOD COMP	Not Necessary	493.72 FS	*- FS
26	1		*FENDER COMPR.FR	Repair	403.35 FS	*- FS
27	1		*ENCLOSURER.FR.FENDER	Not Necessary	19.35 FS	*- FS
28	1		*BULKHEAD COMPFR.	Repair	338.85 FS	*- FS
29	1		*SUPPORTR.FR.BULKHEAD UPP SIDE	Not Necessary	24.67 FS	*- FS
30	1		*SUPPORTL.FR.BULKHEAD UPP SIDE	Not Necessary	24.67 FS	*- FS
31	1		*CONDENSER COMP	Not Necessary	501.45 FS	*- FS
32	1		*RADIATOR COMP	Not Necessary	990.67 FS	*- FS
33	6		*COOLANTANTI-FREEZE	Not Necessary	104.40 FS	*- FS
34	1		*CLIP ABUMPER	Necessary	10.35 FS	*10.35 FS
			(6pc)			
35	6		*CLIPINNER FENDER	Not Necessary	1.80 FS	*- FS
36	1		*CLIPINNER FENDER	Necessary	10.35 FS	*10.35 FS
			(6pc)			
37	12		*CLIPBUMPER	Necessary	18.00 FS	*18.00 FS
38	1		*SUNDRIES	Necessary	100.00 FS	*10.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 14,176.90 3,241.19

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	BODY JOINT SEALANT.	New	100.00	0.00
2	INSPECT FR & FOG LIGHTING MECHANISMS & FOCUS.	New	180.00	80.00
3	REMOVE & INSTALL RADIATOR WITH FITTINGS.	New	280.00	0.00
4	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.	New	380.00	0.00
5	CALIBRATION FRONT VIEW CAMERA.	New	400.00	350.00
6	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.	New	3,300.00	1,800.00
7	CUT OFF & RENEW BULKHEAD FR R HOUSING COMP.	New	3,500.00	1,680.00
Gross Labour Cost (S\$)			8,140.00	3,910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >