

ASS. REC. BY:

REF:

CS / DAL17011266 / TH1657

Special Instructions:

Surveyor: Tan KahASSIGNMENT (Office)From (Person): Motor claim (Chuan Jap) DAL Date/Time: 09062017

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: S6Z 2400X Insured: SJX 7851Uat Workshop m/s Zhong Chung Tel: 9338 2859of Blk 6 Woodlands Road 3993Policy No: _____ Claim No: 70936 / CH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 05062017
(Client's Record)

CA / REV / REP. / REV 24 HRS WP

12.062017

H.O.D. Endorsement: _____

Date/Time: 09062017 230pm Person Contacted: Bini Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>S6Z 2400X - X</u>
	<u>SJX 7851U - X</u>
	<u>lump sum \$3750 (Red: 3185.60; 45%)</u>

*Surround:

Taylor

ASSIGNMENT

From: _____ Date: 12062017

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: S6Z 2400X

at Workshop m/s: Zhong Cheng
of Blk 6 Woodlands Road 399J

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS Wp.

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: S6Z 2400X Yr Regn: 1

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Kia C.C.

Colour: Maroon A/C: Insured / Std / NI / NA

Sp. Reading: 163548 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 1CNAFG521377051271

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/65R15

R: m 4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Bluetan

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 12/6/17 @ 1630

Survey held at Zhong Cheng

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S, a/c

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

w/s will pass GIA later.

Date/Time, File Pass to?

1) 9/18 Typist.

Date/Time, File Return to?

2) _____

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee: 200

Transportation: _____

Add Fee:

☐ : Site Insp (\$) S + RS \$
☐ : Interview (\$) Photos
☐ : Tech. Invs (\$) Others
☐ : Weekend (\$)

Report Format : TP

Lump Sum / I.B.I.: (\$ 3750/-)

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

DIRECT ASIA INSURANCE (SINGAPORE) PL

Ref : CS/DAI17011266/T1tb

88 SOUTH BRIDGE ROAD
SINGAPORE 058716

Date : 09-06-2017



Code : DAI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJX 7851U	Veh. Inspected	SGZ 2400X
Policy No.		Coverage (\$)	0.00
Claim No.	70936/CH	Excess (\$)	0.00
Assign From	MOTORCLAIM (CHARANDEEP)	Assign Date	09/06/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	05/06/2017	Inspection Date	12/06/2017
Survey held at	ZHONG CHENG ENTERPRISE BLK 4 YEW TEE IND 393-H WOODLANDS ROAD SINGAPORE 677969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Catherine Chong (LKK Auto)

From: Motor Claims <motorclaims@directasia.com>
Sent: Friday, 9 June, 2017 1:41 PM
To: assignments@lkkauto.com
Cc: Aaron Wang; Derrick Quok; Kenneth Lim; Charandeep Singh
Subject: PRI Assignment 70936 /CH/Zhong Cheng Enterprise /OD : SJX7851U /TP : SGZ2400X / DOA : 05.06.2017
Attachments: 201706071446.pdf
Importance: High

Dear Sir,

Please arrange to survey SGZ2400X on the without prejudice basis.

Please conduct direct motor survey at the workshop below pre-repair inspection and update us immediately if the repair cost is above \$10K.

Zhong Cheng Enterprise
Blk 6 Woodlands Road 399J Yew Tee Industrial Estate, Singapore 678008
Tel: 9338 2859

Thank you.

Regards,
Claims Department

From: Cheonghoh Law [mailto:mail@cheonghoh.sg]
Sent: Friday, June 09, 2017 12:35 PM
To: Kenneth Lim <kenneth@directasia.com>
Cc: Motor Claims <motorclaims@directasia.com>; Charandeep Singh <charandeep.singh@directasia.com>; Aaron Wang <aaron.wang@directasia.com>; Derrick Quok <derrick@directasia.com>
Subject: Re: FAX - PRS - SGZ2400X - DOA 6/6/2017
Importance: High

Dear Kenneth,

We refer to the above matter and to your email of 8 June 2017.

Our client hereby nominate LKK Auto Consultancy Pte Ltd named in paragraph 2 serial no 3 of your said email to conduct the pre-repair survey of the damages to our client's vehicle arising out of the above mentioned accident.

Please be informed that our client's vehicle, SGZ 2400 X is currently at our client's workshop, Zhong Cheng Enterprise, Blk 6 Woodlands Road 399J Yew Tee Industrial Estate, Singapore 678008.

Contact : Ms Sini - 9338 2859

Kindly proceed to do the needful.

Thanks & regards
Catherine

CHEONGHOH LAW CORPORATION

Blk 53 Chin Swee Road #03-05

Singapore 160053

T: 6337 8700 | F: 6337 3700 | E: mail@cheonghoh.sg

On 8 Jun 2017, at 6:02 PM, Kenneth Lim <kenneth@directasia.com> wrote:

Hi Catherine,

Re-send.

Best Regards,
Kenneth Lim

-----Original Message-----

From: Motor Claims [motorclaims@directasia.com]

Received: Wednesday, 07 Jun 2017, 3:22p.m.

To: mail@cheonghoh.sg [mail@cheonghoh.sg]

CC: Aaron Wang [aaron.wang@directasia.com]; Derrick Quok [derrick@directasia.com]; Kenneth Lim [kenneth@directasia.com]; Charandeep Singh [charandeep.singh@directasia.com]

Subject: FW: FAX - PRS - SGZ2400X - DOA 6/6/2017

WITHOUT PREJUDICE

Your Ref: SGZ2400X
Our Ref: 70936/CH

To: Cheonghoh Law Corporation
Blk 53 Chin Swee Road #03-05
Singapore 160053
Tel: 63378700
Fax: 63373700

Dear Sir,

We refer to your Notice of Accident dated :06.06.2017

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop.

We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

1. STA Inspection Pte Ltd
2. LBS Automotive Appraisal Pte Ltd
3. LKK Auto Consultants Pte Ltd
4. DirectAsia Insurance internal motor surveyors

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best regards
Claims Department

-----Original Message-----

From: Gloria Kwok
Sent: Wednesday, June 07, 2017 3:11 PM
To: Motor Claims <motorclaims@directasia.com>
Subject: FAX - PRS - SGZ2400X - DOA 6/6/2017
Importance: High

Hi TF,

For urgent PRS.

Thank you.

Best Regards,
Gloria

IMPORTANT NOTICE:

This message is intended only for the attention of the addressee and may contain legally privileged and/or confidential information. Its unauthorised use, disclosure, storage or copying is not permitted. If you are not the intended recipient, please permanently delete the original, destroy all copies and inform the sender.

IMPORTANT NOTICE:

This message is intended only for the attention of the addressee and may contain legally privileged and/or confidential information. Its unauthorised use, disclosure, storage or copying is not permitted. If you are not the intended recipient, please permanently delete the original, destroy all copies and inform the sender.

Denise Tay (LKKAUTO)

From: zhong xiong Tan <zhongchengenterprise@hotmail.com>
Sent: Wednesday, 8 August 2018 3:42 PM
To: Denise Tay (LKKAUTO); Taufikh (LKKAUTO)
Cc: SUR
Subject: Re: SGZ 2400X

Dear All,

Ok to accept.

Thank you

Best Regards
Sini Tan
Zhong Cheng Enterprise Pte Ltd
Blk 6, 399J
Yew Tee Industrial Est
S678008
HP: 93382859 Fax: 68942883

From: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Sent: Wednesday, August 8, 2018 3:38 PM
To: zhong xiong Tan; Taufikh (LKKAUTO)
Cc: SUR
Subject: RE: SGZ 2400X

Dear Si Ni,

Parts	\$3,699.00
After 10%	\$3,329.10
Labour:	\$1,410.00
Total:	\$4,739.10
Lump sum	\$3,750.00
Days	5

Please check and confirm

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

ZHONG CHENG

Adjustment of Spare Parts Costs for Repairs SGZ2400X

KIA CAREN

Item	Qty	Vehicle parts description	\$	
1	1	Front bumper	445.00	✓ de
2	1	Front fender (LH)	1080.00	✓ bt
3	1	Headlamp (LH)	557.00	✓ C/A
4	1	Front fender cowling LH	176.00	✓ de
5	1	Headlamp bracket LH	92.00	✓ nec
6	1	Front bumper retainer LH	18.00	nec
7	1 set	Front bumper clip @	40.00	nec
10	1	Front lower arm LH	398.00	bt ✓
11	1	Front knuckle LH	230.00	bt ✓
12	1	Front wheel bearing	355.00	? bt ✓
13	1	Front bar linkage LH	185.00	X nn
14	1	Front shock abs LH	203.00	bt ✓
16	1	Front lower arm RH	398.00	X nn
17	1	Side mirror cover	105.00	✓ cut
			4282.00	3098 3594
		Less 10%	856.4	
			3425.60	2788.20 3234.60
			3833.80	
		Special nett item		
2	1	Rim LH	320.00	X R
		Total parts	<u>320.00</u>	

Adjustment of Labour Costs for Repairs

Spraying of affected areas, bonnet/ bumper/ fender/door

1300.00

500

Carry out body cavity preservation

160.00

30

To remove and replaced damaged parts including straightening and repositioning replacement parts & panel beat, front fender LH, bonnet, bumper etc *	1050.00	600
Check wiring	80.00	30
To remove & refix rear undercarriage items	350	150 200 ? photo
To perform 4 wheel alignment	120	80
To realign headlamp focus	50	20
To dismantle/replace door components	80	x 880
Total labour	3190.00	

~~2363.80~~
~~2788.20~~
~~880~~

~~3668.20~~
~~454 2900~~ *
5 days

3234.60
880

4114.60
454 3300
5 days

ZHONG CHENG

Adjustment of Spare Parts Costs for Repairs SGZ2400X

KIA CAREN

Item	Qty	Vehicle parts description	\$
1	1	Front bumper <i>de</i>	
2	1	Front fender (LH) <i>bl</i>	
3	1	Headlamp (LH) <i>ora</i>	
4	1	Front fender cowling LH <i>de</i>	
5	1	Headlamp bracket LH <i>ne</i>	
6	1	Front bumper retainer LH <i>ne</i>	
7	1 set	Front bumper clip @ <i>ne</i>	
8		Fog lamp cover x	
9		Fog lamp x	
10	1	Front lower arm LH ?	
11	1	Front knuckle LH ?	
12	1	Front wheel bearing ?	
13	1	Front bar linkage LH ?	
14	1	Front shock abs LH ?	
15	1	Front driveshaft LH x	
16	1	Front lower arm RH ?	
17	1	Side mirror cover <i>cut</i>	
18	1	Side mirror LH x	
			<u>0.00</u>
		Less 10%	<u>0</u>
			0.00
		Special nett item	
1	1	Tyre	280.00 x
2	1	Rim LH	320.00 ?
		Total parts	<u>600.00</u>

Taufik 97475749

12/6/17

lump sum

Resing after repair

See @kkanto.com

5 days

Adjustment of Labour Costs for Repairs

Spraying of affected areas, bonnet/ bumper/ fender/door 1300.00 600

Carry out body cavity preservation 160.00 40.

To remove and replaced damaged parts including straightening and repositioning replacement parts & panel beat, front fender LH, bonnet, bumper etc 1050.00 600

Check wiring 80.00 30

To remove & refix rear undercarriage items 350 200? plus

To perform 4 wheel alignment 120 80

To realign headlamp focus 50 20

To dismantle/replace door components 80 x

Total labour 3190.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

DIRECT ASIA INSURANCE (S) PL

Ref : CS/DAI17011266/T1tbs2

20 ANSON ROAD
#08-01 TWENTY ANSONS SINGAPORE 079912

Date : 10-09-2018



Code : DAI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJX 7851U	Veh. Inspected	SGZ 2400X
Policy No.		Coverage (\$)	0.00
Claim No.	70936/CH	Excess (\$)	0.00
Assign From	MOTORCLAIM (CHARANDEEP)	Assign Date	09/06/2017

2. Vehicle Particulars & Condition

Make & Model	KIA	c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	KNAFG521377051271	Colour	MAROON
Odometer	163548	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/65R15	YOKOHAMA	6 mm
L/H Front Tyre	205/65R15	YOKOHAMA	6 mm
R/H Rear Tyre	205/65R15	YOKOHAMA	6 mm
L/H Rear Tyre	205/65R15	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION AND UNDERCARRIAGE.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	05/06/2017	Inspection Date	12/06/2017
Survey held at	ZHONG CHENG ENTERPRISE BLK 6 WOODLANDS RD YEW TEE JTC INDUSTRIAL PARK EATATE 399J SINGAPORE 678008		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGZ 2400X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DEFORMED	445.00	445.00
1	FRONT FENDER (LH)	BENT	1,080.00	1,080.00
1	HEADLAMP (LH)	CRACKED	557.00	557.00
1	FRONT FENDER COWLING LH	DEFORMED	176.00	176.00
1	HEADLAMP BRACKET LH	NECESSARY	92.00	92.00
1	FRONT BUMPER RETAINER LH	NECESSARY	18.00	18.00
1	SET FRONT BUMPER CLIP	NECESSARY	40.00	40.00
1	FRONT LOWER ARM LH	BENT	398.00	398.00
1	FRONT KNUCKLE LH	BENT	230.00	230.00
1	FRONT WHEEL BEARING	BENT	355.00	355.00
1	FRONT BAR LINKAGE	NOT NECESSARY	185.00	-
1	FRONT SHOCK ABS LH	BENT	203.00	203.00
1	FRONT LOWER ARM RH	NOT NECESSARY	398.00	-
1	SIDE MIRROR COVER	CUT	105.00	105.00
	LESS 10% DISCOUNT		-428.20	-369.90
			3,853.80	3,329.10
<u>SPECIAL NETT ITEMS</u>				
1	RIM LH (SN)	TO REPAIR SEE LABOUR	320.00	-
			320.00	-
<u>LABOUR</u>				
	SPRAYING OF AFFECTED AREAS, BONNET / BUMPER / FENDER / DOOR.		1,300.00	500.00
	CARRY OUT BODY CAVITY PRESERVATION.		160.00	30.00
	TO REMOVE AND REPLACED DAMAGED PARTS INCLUDING STRAIGHTENING AND REPOSITIONING REPLACEMENT PARTS & PANEL BEAT, FRONT FENDER LH, BONNET, BUMPER ETC. INCLUSIVE OF THE REPAIR OF RIM LH.		1,050.00	600.00
	CHECK WIRING.		80.00	30.00
	TO REMOVE & REFIX REAR UNDERCARRIAGE ITEMS.		350.00	150.00
	TO PERFORM 4 WHEEL ALIGNMENT.		120.00	80.00

Report Ref No. CS/DAI17011266/T1tbs2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REALIGN HEADLAMP FOCUS.	NOT NECESSARY	50.00	20.00
	TO DISMANTLE / REPLACE DOOR COMPONENTS.		80.00	-
			3,190.00	1,410.00
GRAND TOTAL			7,363.80	4,739.10
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,750.00

Report Ref No. CS/DAI17011266/T1tbs2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.