

22/03/2002

ASS. REC. BY:

REF: CS/AWA17011487 / R1200 Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Hew He Fong of AWA Date/Time: 13062017 328pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLB 4086Z Insured: SKT 6129Mat Workshop m/s Cycle & Carriage Automotive Tel: 9181 9978of 209 Pandan GardenPolicy No: BVPPSB 0534 74 1600 Claim No: NSV 1700 714 / HLF

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 11062017
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement: _____

Date/Time: 13062017 335pm Person Contacted: Edwin Vehicle IN / OUT

Date/Time	Action/Instruction (☒) Estimate
	<u>SLB 4086Z - x</u>
	<u>SKT 6129M - x</u>
<u>11/7</u>	<u>To re-open file submit final report. Final fig \$4,709.00 (Red. 2653/-, 36%)</u>
	<u>4 days. Close re 7/19.</u>
<u>20/8/19</u>	<u>1st DOZ 15/4/19, re-open ref only ↓ re 8/19</u>



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Req No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Lion City Rentals Pte Ltd	Cust No/Name	KL000023/Lion City Rentals Pte Ltd
60 Anson Road	Reg No/Reg Date	SLB4086Z / 06/04/201
Mapletree Anson Level 11-01	Date In/Mileage	/ 107529
Singapore 079914	Chassis No	MMBSTA13AFH018846
Contact No Mobile: 67420984	Engine No	3A92UCT8959
	Make/Model	MIT/ATTRAGE 1.2 CVT MIVEC
	Colour/Trim	T06 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00004	Cash	12/06/2017/ 15:05	QUE	261 / Edwin Caina	63234		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW & RE-ALIGN ACCIDENT DAMAGED PORTION: RENEW RH FENDER & FRT BUMPER				1100	2200.00		
E PNT98000 RESPRAY FRT BUMPER , RH FENDER , BONNET & RH WINGMIRROR				920	1680.00		
M SUNDRY RENEW RH SPORT RIM & TRANSFER TYRE				30	50.00		
A 54900099 CHECK WIRING & ADJUST HEADLAMP AIM				30	50.00		
A 54900099 CONDUCT DIAGNOSTIC CHECK ON VEHICLE SYSTEM					200.00		
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment					120.00		
M SUNDRY APPLY BODY SEALANT & ANTI CORROSION ON AFFECTED AREAS				80	100.00		
M SUNDRY SUNDRIES					30.00		
M HEADLAMP ASSY,RH				1.00	644.00	00.00	CRA- 644.00
M FENDER,FR RH				1.00	451.00	00.00	R 451.00
M FACE,FR BUMPER				1.00	686.00	00.00	FB 686.00
M BRACKET,FR BUMPER,RH				1.00	13.00	00.00	BR 13.00
M GARNISH,FR BUMPER,RH				1.00	124.00	00.00	GA 124.00
M LAMP ASSY,FOG,FR RH				1.00	282.00	00.00	LA 282.00
M WHEEL,DISC				1.00	732.00	00.00	WD 732.00
LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and in subject to final approval from Insurance Company Confirm & accepted by Acknowledged by Repairer Signature: Date: Resu Hp 90010068 4 days P/P 14/06/17 @ 1215 Rem after repair 22/6/17				7% GST on		Nett 7362.00	7,362.00 515.34
Total Payable						7,877.34	
Authorized signatory and company stamp							

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Exceptional Journeys

Surveyor : Rasul - LKK
Company : AWAC
DOA : 11/06/2017
CSE : Edwin
Date of Survey : 14/06/2017

VEHICLE NO : SLB4086Z
MODEL : MIT/ ATTRAGE 1.2 CVT MIVEC
WIP : 30907

Material	:	\$	2,199.00
Labour	:	\$	2,510.00
Sub-Total	:	\$	4,709.00
Less Excess	:	\$	-
Total	:	\$	4,709.00
GST 7%	:	\$	329.63
Grand Total	:	\$	5,038.63
Finalise By/Date	:	JoJo dtd	28/06/2019

Email :

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 4 WORKING DAYS + 2 Days (1) Weekends
+ Days () Public Holiday
+ 1 Survey - 14/06/2017 - Wed
TOTAL DAYS REPAIR TOOK = 7

☒ TP Claim AWAC - SKT6129M

☒ Claim GIA / LTA fee \$ 2.00

☒ Claim Loss ☒ Use ☐ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
ALLIED WORLD ASSURANCE COMPANY, LTD	Cust No/Name /ALLIED WORLD ASSURANCE COMPANY,
MOTOR CLAIM DEPARTMENT	Reg No/Reg Date SLB4086Z / 06/04/2016
60 ANSON ROAD #08-01	Date In/Mileage 13/09/2018/ 130465
MAPLETREE ANSON	Chassis/Package MMBSTA13AFH018846
SINGAPORE 079914	Engine No 3A92UCT8959
Contact No	Make/Model MIT/ATTRAGE 1.2 CVT MIVEC
	Colour/Trim T06 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00040	Cash	28/06/2019/ 09:53	TLE	881 / Jojo Cheng	30907

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M SUNDRY				✓ 1100.00
RENEW RHF FENDER & FRONT BUMPER				
M SUNDRY				✓ 920.00
RESPARY FRONT BUMPER, RHF FENDER & RH WINGMIRROR				
M SUNDRY				✓ 30.00
RENEW RHF SPORT RIM & TRANSFER TYRE				
M SUNDRY				✓ 30.00
CHECK WIRING & ADJUST HEADLAMP AIM				
M SUNDRY				✓ 200.00
CONDUCT DIAGNOSTIC CHECK-ON VEHICLE SYSTEM				
M SUNDRY				✓ 120.00
TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT				
M SUNDRY				✓ 80.00
APPLY BODY SEALANT & ANTI CORROSION ON AFFECTED AREAS				
M SUNDRY				✓ 30.00
SUNDRIES				
M SUNDRY				✓ 644.00
HEADLAMP ASSY, RH				
M SUNDRY				✓ 686.00
FACE, FR BUMPER				
M SUNDRY				✓ 13.00
BRACKET, FR BUMPER, RH				
M SUNDRY				✓ 124.00
GRANISH, FR BUMPER, RH				
M SUNDRY				✓ 732.00
WHEEL, DISC				
Z TEXT				
AWAC TP CLAIM SKT6129M				
DOA: 11/06/2017				
SURVEYOR: RASUL LKK 14/06/2017				
TRANSFER FROM WIP21495 DPS				

Cycle & Carriage celebrates 120 years.
 Visit www.cyclecarriage.com/120 for more info!

Parts	0.00	Nett	4,709.00
Labour	0.00	7% GST on	329.63
Standard Menu	0.00		
Specialist Job	0.00		
Diagnostics Job	0.00	Total Payable	5,038.63
Sundry/Others	4,709.00		
Total(w/o GST)	4,709.00		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLB 4086Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SUNDRIES (SN)	NECESSARY	30.00	30.00
1	HEADLAMP ASSY, RH (SN)	CRACKED	644.00	644.00
1	FENDER, FR RH (SN)	TO REPAIR SEE LABOUR	451.00	-
1	FACE, FR BUMPER (SN)	DEFORMED	686.00	686.00
1	BRACKET, FR BUMPER, RH (SN)	NECESSARY	13.00	13.00
1	GARNISH, FR BUMPER, RH (SN)	SCRATCHED	124.00	124.00
1	LAMP ASSY, FOG, FR RH (SN)	NOT NECESSARY	282.00	-
1	WHEEL, DISC (SN)	SCRATCHED	732.00	732.00
			2,962.00	2,229.00
	<u>LABOUR</u>			
	RENEW & RE-ALIGN ACCIDENT DAMAGED PORTION : RENEW RHF FENDER & FRT BUMPER. INCLUSIVE OF THE REPAIR OF FENDER, FR RH.		2,200.00	1,100.00
	RESPRAY FRT BUMPER, RHF FENDER, BONNET & RH WINGMIRROR.		1,680.00	920.00
	RENEW RHF SPORT RIM & TRANSFER TYRE.		50.00	30.00
	CHECK WIRING & ADJUST HEADLAMP AIM.		50.00	30.00
	CONDUCT DIAGNOSTIC CHECK ON VEHICLE SYSTEM.		200.00	200.00
	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT.		120.00	120.00
	APPLY BODY SEALANT & ANTI CORROSION ON AFFECTED AREAS.		100.00	80.00
			4,400.00	2,480.00
GRAND TOTAL			7,362.00	4,709.00

RECOMMENDED COST OF REPAIRS			4,709.00
------------------------------------	--	--	-----------------

Report Ref No. CS/AWA17011487/R1cbe2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.