

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKP 7079 M.

S/n	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer Assy.	S/N \$ 360.00 ✓
2	To dismantle and renew front bumper, lhs front fender, headlight and bonnet. Re-organise front crash management components, Reinstall all parts removed.	\$ 2,700.00 1250 ✓
3	To respray front bumper, lhs front fender and bonnet.	\$ 2,400.00 1700 ✓
4	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: 5,652.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKP 7079 M.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER / Re	\$ 1,546.00	1236.80
2	FRONT BUMPER GUIDE SECTION - LH - BT	\$ 51.00	40.80
3	FRONT AIR GUIDE GRILLE - LH BT / MC	\$ 90.00	71.92
4	FRONT FENDER - LH / MC	\$ 708.00	566
5	FRONT FENDER ATTACHMENT PARTS BT NN	\$ 56.00	
6	FRONT FENDER BRACKET - LH/ REAR BT / MC	\$ 23.00	18.16
7	FRONT FENDER BRACKET - LH BT / MC	\$ 40.00	31.60
8	POP RIVET / MC	8 \$ 23.00	17.92
9	FRONT FENDER CLOSING ELEMENT BT / BT	\$ 52.00	40.96
10	FRONT FENDER BRACE BT / BT	\$ 81.00	64.80
11	WHEEL HOUSING LINER - LH BT / Re	\$ 146.00	116.80
12	SEALING WASHER / MC NN	\$ 24.00	X
13	WHEEL HOUSING LINER ATTACHMENT PARTS / MC	\$ 75.00	59.44
14	GAS DISCHARGE HEADLIGHT - LH / CPA	\$ 1,708.00	1366.40
15	HEADLIGHT WASHER LIFT CYLINDER - LH / DM	\$ 160.00	127.60
16	BONNET X repair	\$ 2,372.00	
17	EDGE PROTECTION - FRONT X NN	\$ 23.00	
18	SUNDRIES BT / MC	\$ 400.00	61.76
TOTAL SPARE PARTS CHARGES		: \$ 7,578.00	
TOTAL LABOUR CHARGES		: \$ 5,652.00	
GRAND TOTAL		: \$ 13,230.00	15,764

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Gino Qian - 82880282
Surveyed Date : 5 Days.
Authorised Date : 16/6/17
Excess Cost :
Liability :
Remarks : Not Authorised. 

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Johnny Boo
Body Repair Manager


Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0581/2017/JN 22-Jun-17 Chang 1 of 1 SKP 7079 M Audi A3 SB 1.4 TFSI
Quantity	Description	Unit Price	Amount
Labours			
1	To repair frontal horn wiring harness. S/N	\$ 280.00	\$ 280.00
Parts			
1	WASH WATER RESERVOIR / WASH D'S	\$ 173.00	\$ 138.40
2	WATER RESERVOIR SEAL & BUNGS X NN	\$ 20.00	
3	SIGNAL HORN - LH / BR	\$ 173.00	\$ 138.40
4	LHS HEADLIGHT BALLAST	\$ 1,002.00	\$ 801.60
5	LHS HEADLAMP POWER MODULE / WASH NN	\$ 492.00	\$ 393.20
6	LHS HEADLAMP BULB	\$ 394.00	\$ 314.80
GRAND TOTAL :		\$ 2,534.00	\$ 2,066.40

For Premium Automobiles Pte Ltd

Authorised Signature

15316 40