

22/03/2007

ASS. REC. BY:

REF:

CS/CR17011970/agh302

Special Instruction:

Surveyor:

Gao Giang

ASSIGNMENT (Office)

mermen

From (Person):

Angie Foo

of

CT2

Date/Time:

20/6/2017 1:06 pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLM5182P

Insured:

SIF 7803D

at Workshop m/s

Motor image

Tel:

9299 2695 / 6703 8109

of

19 kuning 8 tool payah

Policy No:

DMPCSN 305271600

Claim No:

JNM17D03370C02/3

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

2/6/2017

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

20/6/2017 2:07 pm

Person Contacted:

sage

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLM5182P x
	SIF 7803D x
20/7/18 @ 10:00 am	confirmed with Sage final fig. B1475.20, 3 days by email. (Red 54979.70, 77%)

(08/11/13) ,wef

ASS. REC. BY: XblREF: 67**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Motor Image

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or NoLum Sum: 3 % 3 Val.: Yes or No**CA / REV / REP. / 24 HRS**

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLM5182PYr Regn: 31 Mar 2017Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Subaru XVc.c. 1600Colour: whiteA/C: Insured / Std / NI / NASp. Reading: 2905T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JF16P3KC5HG 205241Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt or _____Brake: Inorder / Jammed / Leaked / Burnt or _____Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /TOYO / YOKO or _____

Front

Rear

R/Bal. 8 mmR/Bal. 8 mmL/Bal. 8 mmL/Bal. 8 mm

D.O.A. _____

D.O.I. 20-06-17Survey held at N/SDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 20 JUL 2018

Date/Time, File Pass to?

1) 2017 11/13

Date/Time, File Return to?

2) _____

☐ : Preli. Report☐ : Final ReportDays Of Repair: 3

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Survey Fee: 190

Transportation: _____

____ S + RS. ____ SI

Photos _____

Others _____

TOTAL

Report Format : MER-TPLump Sum / I.B.I. (\$) 1455.00190



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI17011970/Gqh3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 20-06-2017



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJF 7803D	Veh. Inspected	SLM 5182P
Policy No.	DMPCSN305271600	Coverage (\$)	0.00
Claim No.	SNM17D03370C02/3	Excess (\$)	0.00
Assign From	MERIMEN (ANGIE FOO)	Assign Date	20/06/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	02/06/2017	Inspection Date	20/06/2017
Survey held at	MOTOR IMAGE ENTERPRISES PTE LTD 19 TOA PAYOH LORONG 8 SINGAPORE 319255		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Ret	Adj Submitted	Int Auth'd	Status
Main	20 Jun 2017		20 Jun 2017 13:06 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	NG BOON GEK, ID: S0118935B		
Main Claimant:	KARTINI BTE KHAIRI, ID: S7637763D		
Vehicle Reg. No.:	SLM5182P	Date of Loss:	02/06/2017 17:00 - :59
Claim Type:	TP / SNM17D03370C02/3	Policy/Cover Note No.:	DMPCSN305271600 (Comprehensive)
Vehicle Reg. No. (Insured):	SJF7803D	Policy No. (Claimant):	2100505184
		Excess:	S\$0.00
Repairer:	Motor Image Enterprises Pte Ltd (Toa Payoh) 19 Lorong 8 Toa Payoh, 319255 Toa Payoh - Tel: 67038104		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Angie Foo - 6389 6186]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/06/2017]		
Driver/Custodian (Insured):	WONG HONG YAN (62 / Male), NRIC: S0158502I		
Adj Asg. Remarks:	ESTIMATES AS ATTACHED. ASSIGNED AS SJE FOR WP PRS. KINDLY PROVIDE US WITH YOUR RECOMMENDATION		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 20 July 2018 10:10 AM
To: 'Sayedinah'; SUR
Cc: Daniel Lim; Daniel Jude; Kuan Wei Loong
Subject: RE: SLM5182P-AIG-TP(SJF7803D) CN TAIPING-FINALIZED

Dear Saye,

Confirm final fig \$1,475.20 before GST and 3 repair days.

Kindly send the relevant documents to China Taiping Insurance company.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sayedinah <sayedinah@motorimage.net>
Sent: Monday, 9 July 2018 1:49 PM
To: SUR <sur@lkkauto.com>
Cc: Daniel Lim <daniellim@motorimage.net>; Daniel Jude <danieljude@motorimage.net>; Kuan Wei Loong <weiloong@motorimage.net>
Subject: SLM5182P-AIG-TP(SJF7803D) CN TAIPING-FINALIZED
Importance: High

Hi Guo Qiang,
Attached for your reference

Regards
Sayedinah Ali
Service Executive
Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh Singapore 319255
HP:92992693 DID:67038109 FAX:+65-62535535
Email:sayedinah@motorimage.net
Website:www.tanchong.com :: www.motorimage.net

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/06/2017 13:23
Date Of Accident	02/06/2017 17:30
Exact Location Of Accident	BUKIT BATOK WEST AVE 5 MSCP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLM5182P
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	KARTINI BTE KHAIRI
Passport No/FIN	S7637763D
Email Address	KARTINI_KHAIRI@MOE.EDU.SG
Mobile Phone No	(LOCAL) +65-92369154
Alternative Phone No	OFFICE-92369154

Vehicle Particulars

Manufacturer	SUBARU
Model	XV-1.6 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100505184
Cover Note Number	

Driver

Name of Driver	KARTINI BTE KHAIRI
Passport No/FIN	S7637763D
Date Of Birth	30/11/1976
Occupation	INDOOR
Date Of Driving Pass	07/04/2015
Driving Experience	2 YEARS AND 1 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-92369154
Fax Number	
Contact Number	OFFICE-92369154
EMail Address	KARTINI_KHAIRI@MOE.EDU.SG

Address	BLK391 BUKIT BATOK WEST AVE 5 #06-418 SINGAPORE
Postcode	650391
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJF7803D
Vehicle Make/Model/Colour	SUZUKI SX4
Details Of Properties	
Name of Driver	WONG HONG YAN
NRIC/Passport Number	S0158502I
Contact Number	96850014
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

fw 3/6/17 11:58am
Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel

Sketch Plan



A: 8LM 5182P

B: SJF 7803D

Describe Circumstances of the Accident

Car was parked at Bukit Batok West Ave 5 MSCP at Lot no. 549. Owner found note left at the wiper. Discovered dent at front left bumper at 8.32 pm on 2 June 2017.

Owner called the number left in the note and met with third party driver at 8.45 pm. He apologised and admitted he bumped my car. We exchanged personal details.


Third party driver informed owner that the registered driver is his wife but he was driving at the time of the incident.

While taking photos of each other's NRIC, I noticed that his hands were shaking, similar to one with Parkinson's Disease.

I would like to put on record that the third party driver has been cooperative in my engagement with him.

Declaration

I/We declare the foregoing particulars are true in every respect.

 3.6.2017
Policyholder's Signature / Date &
Time 11.58 am

Driver's Signature (If driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel

MOTORIMAGE ENTERPRISES PTE. LTD.

19 LORONG 8, TOA PAYOH

SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0236/2017
DATE : 17-JUN-2017

CHINA TAIPING INSURANCE (SINGAPORE)PTE LTD

3 ANSON ROAD

#15-00 SPRINGLEAF TOWER

SINGAPORE S(079909)

TEL : 6389 6111

FAX : 6222 1033

OWNER'S NAME : KARTINI BTE KHAIRI
ADDRESS : BLK 391 BUKIT BATOK WEST AVENUE 5
#06-418
S(650391)
TELEPHONE NO : 9236 9154

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100505184
VEHICLE NO : SLM5182P
MODEL CODE : GP3FKDC
MODEL/YEAR : XV 1.6I-S AWD CVT
ENGINE NO : FB16Y592183
CHASSIS NO : JF1GP3KCSHG205241
MILEAGE : 1 KM
DATE IN : 17/06/2017
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH ALI
ACCIDENT DATE : 02/06/2017

Print Date : 17/06/2017

Print Time : 15:34:33

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLM5182P

TOTAL LABOUR CHARGES	3090.00
TOTAL SPARE PARTS CHARGES	0.00
GRAND TOTAL	3090.00 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	Eno Qiang - 82880282
SURVEYED DATE	:	20/6/17
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	before paint photos 3 Days.

[Signature]
2/6/17

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

nce notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

6454.90

MOTORIMAGE ENTERPRISES PTE. LTD.

19 LORONG 8, TOA PAYOH

SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLM5182P

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	REPLACE/REPAIR FRT BUMPER, FRT LH FENDER & FRT PANEL	1680.00	560
2	ZZ/002	RESPRAY FRT FENDER, FRT PANEL AND FRT BUMPER	1260.00	420
3	ZZ/003	CHECK LIGHTINGS AFTER REPAIR	50.00	/
4	ZZ/004	SUNDRIES	100.00	50
TOTAL LABOUR CHARGES			3090.00	

Estimate

Date 06/05/2017

001 / 002

Name	QUOTATION FOR SLM5182P	Tel (Home)	
Address		Tel (Office)	
E-Mail		Tel (Portable)	
		Fax	
		Model Name	G33
		Body Model	GP3FKDC
		Vin-Code	JF1GP3KC5HG-205241

Part Number	Part Code Name	Part Code	Q'ty	Price
57704FJ070	BUMPER FACE-FRONT / <i>ee</i>	FIG-590 57704	1	414.00
57711FJ0519P	BACK BEAM COMPLETE-F RONT <i>X</i>	FIG-590 57711	1	259.20
57705FJ010	ENERGY ABSORBER-FRON T BUMPER <i>X</i>	FIG-590 57705	1	79.20
57707FJ001	BRACKET-FRONT BUMPER CORNER, RIGHT <i>X</i>	FIG-590 57707AF	1	43.20
57707FJ011	BRACKET-FRONT BUMPER CORNER, LEFT <i>X</i>	FIG-590 57707AG	1	43.20
57707FJ141	BRACKET-FRONT BUMPER SIDE, RIGHT - <i>mc</i>	FIG-590 57707F	1	7.20
57707FJ151	BRACKET-FRONT BUMPER SIDE, LEFT - <i>mc</i>	FIG-590 57707G	1	7.20
57731FJ460	COVER-FRONT BUMPER <i>cut X</i>	FIG-590 57731	1	4.70
57731FJ430	COVER-FOG LIGHT, LEFT - <i>cut</i>	FIG-590 849530	1	65.60
53029FJ0009P	PANEL COMPLETE-RADIA TOR <i>X</i>	FIG-505 53010	1	522.00
91165FJ000	BRACKET-GRILL <i>X</i>	FIG-911 91165J	1	28.80
91171FJ010	SEAL <i>X</i>	FIG-911 91171	1	19.80
91122FJ060	FRONT GRILLE-BASE <i>X</i>	FIG-911 91122B	1	180.00
91122FJ080	MOLDING-FRONT GRILLE RING <i>X</i>	FIG-911 91123F	1	198.00
91122FJ100	MOLDING-FRONT GRILLE BAR <i>X</i>	FIG-911 91123E	1	129.60
93013FJ000	ORNAMENT <i>X</i>	FIG-919 91174	1	85.00
		Page-Total		2,086.70

Memo

Grand Total
3,364.90

6094 90

--

Tel

Estimate

Date 06/05/2017

002 / 002

Name	QUOTATION FOR SLM5182P	Tel (Home)	
Address		Tel (Office)	
E-Mail		Tel (Portable)	
		Fax	
		Model Name	G33
		Body Model	GP3FKDC
		Vin-Code	JF1GP3KC5HG-205241

Part Number	Part Code Name	Part Code	Q'ty	Price
84001FJ630	LAMP ASSEMBLY-HEAD L EFT X	FIG-840 84001B	1	853.20 X
84503FJ000	FOG LIGHT ASSEMBLY-F RONT X	FIG-845 84501B	1	425.00 X
		Page-Total		1,278.20
		Sub-Total		3,364.90
		Total Tax		3,364.90
		Grand Total		3,364.90

Memo

Grand Total
3,364.90

--

Tel

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0236/2017
DATE : 17-JUN-2017

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD
#15-00 SPRINGLEAF TOWER
SINGAPORE S(079909)
TEL : 6389 6111
FAX : 6222 1033

OWNER'S NAME : KARTINI BTE KHAIRI
ADDRESS : BLK 391 BUKIT BATOK WEST AVENUE 5
#06-418
S(650391)
TELEPHONE NO : 9236 9154

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100505184
VEHICLE NO : SLM5182P
MODEL CODE : GP3FDC
MODEL/YEAR : XV 1.6I-S AWD CVT
ENGINE NO : FB16Y592183
CHASSIS NO : JF1GP3KC5HG205241
MILEAGE : 1 KM
DATE IN : 17/06/2017
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH ALI**
ACCIDENT DATE : 02/06/2017

Print Date : 24/06/2018
Print Time : 22:34:16

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLM5182P

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	REPLACE/REPAIR FRT BUMPER, FRT LH FENDER & FRT PANEL	1680.00	560.00
2	ZZ/002	RESPRAY FRT FENDER, FRT PANEL AND FRT BUMPER	1260.00	420.00
3	ZZ/003	CHECK LIGHTINGS AFTER REPAIR	50.00	50.00
4	ZZ/004	SUNDRIES	100.00	50.00
TOTAL LABOUR CHARGES			3090.00	1080.00

MOTORIMAGE ENTERPRISES PTE. LTD.
 19 LORONG 8, TOA PAYOH
 SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLM5182P

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	BUMPER FACE F XUV	57704FJ070	414.00			OK
2	BRKT BUMP FRH	57707FJ141	7.20			OK
3	BRKT SD F XUV LH	57707FJ151	7.20			OK
4	COVER FOG F XUV LH	57731FJ430	65.60			OK
SUB TOTAL			494.00	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)			98.80	0.00	0.00	0.00
GRAND TOTAL			395.20	0.00	0.00	0.00
OVERALL TOTAL			395.20			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLM5182P

NETT ITEM	494.00
LESS 20 %	-98.80
NETT AMOUNT	395.20
LIST ITEM	0.00
LESS 50 %	0.00
LIST AMOUNT	0.00
SPECIAL NETT AMOUNT	0.00
S/LIST ITEM	0.00
LESS 30 %	0.00
S/LIST AMOUNT	0.00
TOTAL LABOUR CHARGES	1080.00
TOTAL SPARE PARTS CHARGES	395.20
TOTAL CHARGES	1475.20
ADD 7 % GST	103.26
GRAND TOTAL	1578.46

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Jun 2017		20 Jun 2017 13:06 Edit Adj Rpt	S\$1,475.20 Edit Estimates	S\$1,475.20 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: NG BOON GEK , ID: S0118935B									
Main Claimant: KARTINI BTE KHAIRI , ID: S7637763D									
Vehicle Reg. No.: SLM5182P		Date of Loss: 02/06/2017 17:00 - :59 [2 Months and 2 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM17D03370C02/3		Policy/Cover Note No.: DMPCSN305271600 (Comprehensive)							
Vehicle Reg. No. (Insured): SJF7803D		Policy No. (Claimant): 2100505184							
		Excess: S\$0.00							
Repairer: Motor Image Enterprises Pte Ltd (Toa Payoh) 19 Lorong 8 Toa Payoh, 319255 Toa Payoh - Tel: 67038104									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Angie Foo - 6389 6186]									
Claimant's Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 30/06/2017]									
Driver/Custodian (Insured): WONG HONG YAN (62 / Male), NRIC: S0158502I									
Adj Asg. Remarks: ESTIMATES AS ATTACHED. ASSIGNED AS SJE FOR WP PRS. KINDLY PROVIDE US WITH YOUR RECOMMENDATION									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLM5182P (SNM17D03370C02/3)
[SJF7803D]
TP
KARTINI BTE KHAIRI
Jun 2 2017 5:00PM
[NG BOON GEK]
Motor Image Enterprises Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser		
Assessment Reports			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)		Thumbnail	Print
1	03/06/17 13:33	Accident Statement		Load HTM	
2	05/06/17 11:46	Addendum Sheet		Load TIF	
3	05/06/17 11:47	Accident Statement Addm. #1		Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)		Thumbnail	Print
1	05/06/17 11:46	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
2	05/06/17 11:46	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
3	05/06/17 11:46	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
4	05/06/17 11:46	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
5	05/06/17 11:46	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
6	05/06/17 11:46	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	20/07/18 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
2	20/07/18 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
3	20/07/18 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
4	20/07/18 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
5	20/07/18 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
6	20/07/18 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
7	20/07/18 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
8	20/07/18 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
9	20/07/18 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
10	20/07/18 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
11	20/07/18 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
12	20/07/18 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
13	20/07/18 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
14	20/07/18 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
15	20/07/18 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
16	20/07/18 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
17	20/07/18 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
18	20/07/18 10:14	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
19	20/07/18 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
20	20/07/18 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
21	20/07/18 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
22	20/07/18 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
23	20/07/18 10:14	General View		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
24	20/07/18 10:14	Motor Image Enterprises Pte Ltd (Toa Payoh)	General View		Load JPG <input checked="" type="checkbox"/>
25	20/07/18 10:14	Motor Image Enterprises Pte Ltd (Toa Payoh)	General View		Load JPG <input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	20/06/17 13:07	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	ASSIGNMENT		Load PDF
2	20/06/17 13:07	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	OI GIA REPORT		Load PDF
3	20/06/17 13:07	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	ESTIMATES		Load PDF
No	Finalized On			Thumbnail	Print
1	03/06/17 13:33	Motor Image Enterprises Pte Ltd (Toa Payoh)	Sketch Plan [Linked Accident Report Documents]		Load TIF

Linked Accident Report Documents

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	03/06/17 13:33	Motor Image Enterprises Pte Ltd (Toa Payoh)	Accident Statement		Load HTM
2	05/06/17 11:46	Motor Image Enterprises Pte Ltd (Toa Payoh)	Addendum Sheet		Load TIF
3	05/06/17 11:47	Motor Image Enterprises Pte Ltd (Toa Payoh)	Accident Statement Addm. #1		Load HTM
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	05/06/17 11:46	Motor Image Enterprises Pte Ltd (Toa Payoh)	Accident Photo		Load JPG <input checked="" type="checkbox"/>
2	05/06/17 11:46	Motor Image Enterprises Pte Ltd (Toa Payoh)	Accident Photo		Load JPG <input checked="" type="checkbox"/>
3	05/06/17 11:46	Motor Image Enterprises Pte Ltd (Toa Payoh)	Accident Photo		Load JPG <input checked="" type="checkbox"/>
4	05/06/17 11:46	Motor Image Enterprises Pte Ltd (Toa Payoh)	Accident Photo		Load JPG <input checked="" type="checkbox"/>
5	05/06/17 11:46	Motor Image Enterprises Pte Ltd (Toa Payoh)	Accident Photo		Load JPG <input checked="" type="checkbox"/>
6	05/06/17 11:46	Motor Image Enterprises Pte Ltd (Toa Payoh)	Accident Photo		Load JPG <input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	03/06/17 13:33	Motor Image Enterprises Pte Ltd (Toa Payoh)	Sketch Plan		Load TIF

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT17011970/GQH3E2

Date: 26/07/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN305271600
Claimant Vehicle No :	SLM5182P	Insured Vehicle No :	SJF7803D
Date of Loss:	02/06/2017	Nature of Claim:	TP
		Claim No:	SNM17D03370C02/3

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM5182P		
Make & Model:	SUBARU XV, 1.6 (A)	Engine No:	FB16Y592183
Reg. Date:	31/03/2017 (Man. Year: 2017)	Chassis No:	JF1GP3KC5HG205241
Colour:	White	Odometer:	2905 km
Engine Capacity:	1600 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,464.90	445.20	3,019.70	87.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,990.00	1,030.00	1,960.00	65.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	6,454.90	1,475.20	4,979.70	77.15
+ GST 7.00/7.00% (\$\$)	451.84	103.26	348.58	77.15
Nett Amount (\$\$)	6,906.74	1,578.46	5,328.28	77.15

INSPECTION

Date of Assignment:	20/06/2017	
Date Inspected:	20/06/2017 Inspected At:	Motor Image Enterprises Pte Ltd (Toa Payoh) 19 Lorong 8 Toa Payoh Singapore 319255
Estimated Period of Repair:	3.0 days	

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 26 Jul 2018)
Parts: 144	SUBARU XV 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLM5182P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
2	1		*BUMPER FACE-FRONT	Deformed	414.00 F	*414.00 FL
3	1		*BACK BEAM COMPLETE-FRONT	Not Necessary	259.20 F	*- FL
4	1		*ENERGY ABSORBER-FRONT BUMPER	Not Necessary	79.20 F	*- FL
5	1		*BRACKET-FRONT BUMPER CORNER, RIGHT	Not Necessary	43.20 F	*- FL
6	1		*BRACKET-FRONT BUMPER CORNER, LEFT	Not Necessary	43.20 F	*- FL
7	1		*BRACKET-FRONT BUMPER SIDE, RIGHT	Necessary	7.20 F	*7.20 FL
8	1		*BRACKET-FRONT BUMPER SIDE, LEFT	Necessary	7.20 F	*7.20 FL
9	1		*COVER-FRONT BUMPER	Not Necessary	4.70 F	*- FL
10	1		*COVER-FOG LIGHT, LEFT	Cut	65.60 F	*65.60 FL
11	1		*PANEL COMPLETE-RADIATOR	Not Necessary	522.00 F	*- FL
12	1		*BRACKET-GRILL	Not Necessary	28.80 F	*- FL
13	1		*SEAL	Not Necessary	19.80 F	*- FL
14	1		*FRONT GRILLE-BASE	Not Necessary	180.00 F	*- FL
15	1		*MOLDING-FRONT GRILLE RING	Not Necessary	198.00 F	*- FL
16	1		*MOLDING-FRONT GRILLE BAR	Not Necessary	129.60 F	*- FL
17	1		*ORNAMENT	Not Necessary	85.00 F	*- FL
18	1		*LAMP ASSEMBLY-HEAD LEFT	Not Necessary	853.20 F	*- FL
19	1		*FOG LIGHT ASSEMBLY-FRONT	Not Necessary	425.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,464.90	544.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	98.80
Total Parts (\$\$)	3,464.90	445.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE / REPAIR FRT BUMPER, FRT LH FENDER & FRT PANEL	New	1,680.00	560.00
2	RESPRAY FRT FENDER, FRT PANEL AND FRT BUMPER	New	1,260.00	420.00
3	CHECK LIGHTINGS AFTER REPAIR	New	50.00	50.00
Gross Labour Cost (S\$)			2,990.00	1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >