

ASS. REC. BY:

REF: CS / FCL 7012214 / Tirb

Special Instruction:

Surveyor: TauhidASSIGNMENT (Office)From (Person): W/S Sithara of FCL Date/Time: 22062017 2143pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLE 787X Insured: SHC 7773Xat Workshop m/s Cycle & Carriage Automotive Tel: 65684559 / 65384501of 209 Pandan GardenPolicy No: \_\_\_\_\_ Claim No: D17006134MFSH

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 17062117

(Client's Record)

CA / REV / REP. / REV 24 HRS Wp1 23.06.2017Date/Time: 22062017 449pm Person Contacted: Jian Ye H.O.D. Endorsement: \_\_\_\_\_Vehicle IN 10114

Date/Time	Action/Instruction (✓) Estimate
	<u>SLE 787X - X</u>
	<u>SHC 7773X - CS / FCL 4019410 / Appk3</u> <u>Don: 101014</u>
<u>30/6/17</u>	<u>Sent preli to Sithara.</u>
<u>12/7/17</u>	<u>Change w/s to Auto Insure</u>
<u>18/7/17</u>	<u>Sent preli to Sithara</u>

08/11/17  
Surveyor: Tanpin


REF: TCI

# ASSIGNMENT

From: \_\_\_\_\_ Date: 23062017  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: SLE 287X  
at Workshop m/s Cycle & Carriage  
of 209 Pandan Garden  
Insured: \_\_\_\_\_  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: Jian Ye

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS. Upi

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLE287X Yr Regn: 2017 / July  
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or  
Make: Mitsubishi Attrage c.c. 1193  
Colour: white A/B: \_\_\_\_\_ Insured / Std / NI / NA  
Sp. Reading: 89145 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: MMKTA13NH4-002019  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: In order / Jammed / Leaked / Burnt or  
Brake: In order / Jammed / Leaked / Burnt or  
Modi: Nil / S/Rim / STD A/Rim or  
Tyre Size: F: 195/50R15  
R: 195/50R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or Roadstone

Front Rear  
R/Bal. 6 mm R/Bal. 6 mm  
L/Bal. 6 mm L/Bal. 6 mm  
D.O.A. \_\_\_\_\_ D.O.I. 23/6/17 12pm

Survey held at 180 Pandan Garden

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Confirm with Sum \$5496.06, 8 days
	Red: 14675.81, 46%.
	RECEIVED 17 AUG 2018.

Date/Time, File Pass to?

1) typist

Date/Time, File Return to?

2) \_\_\_\_\_

☐ : Preli. Report  
☒ : Final Report

Days Of Repair: 8

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

\_\_\_\_\_ S + RS \_\_\_\_\_ SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Invs (\$ \_\_\_\_\_)

☐ : Weekend (\$ \_\_\_\_\_)

Report Format: TP

Lump Sum / I.B.I: (\$ 5496.06)

170
50
50
42
312




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17012214/T1rb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 22-06-2017	
		Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SHC 7773X	Veh. Inspected	SLE 287X
Policy No.		Coverage (\$)	0.00
Claim No.	D17006134MFSH	Excess (\$)	0.00
Assign From	CWS (SITHARA)	Assign Date	22/06/2017
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	17/06/2017	Inspection Date	23/06/2017
Survey held at	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD 209 PANDAN GARDENS SINGAPORE 609339		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	20-06-2017	<b>Our Ref No.</b> D17006134MFSH
<b>Accident Date</b>	17-06-2017	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHC7773X	<b>Third Party Vehicle.</b> SLE287X
<b>Survey Location</b>	209 PANDAN GARDENS	
<b>Contact Person.</b>	TAY JIAN YE	
<b>Contact No.</b>	65684555/ 65384501	<b>Fax No.</b> 65651240
<b>Survey Type</b>	WITHOUT PREJUDICE:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**


Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

<b>Cc : Workshop</b>	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	SITHARA	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/224356)  PRI Documents  Close 					
---	--	--	--	--	--

## PRI Header Details

Claim No	D17006134MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & CYC AUTOM
Workshop Name	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD (Contact Person : TAY JIAN YE)	Survey Location & Contact Details	209 PANDAN GARDENS <b>Mobile:</b> 65384501 , <b>Phone:</b> 65684555 , <b>Fax:</b> <b>EmailId:</b> JIANYE.TAY@CYCLECARRIAGE.COM.!		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC7773X	TP Vehicle No	SLE287
PRI Recieved Date	22-06-2017 11:52:23 AM	Surveyor Appointed Date	22-06-2017 04:43:18 PM	Surveyor Accept Date	22-06-

## Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	22-06-2017	Upload Survey Report *:	
-----------------------------	---	----------------------	------------	-------------------------	---

## Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

## Multiple Documents Upload

<a href="#">Upload Multiple Documents</a>	
File Name	Action

## Surveyor Job Remarks

## Janice Lee (LKKAUTO)

---

**From:** Janice Lee (LKKAUTO)  
**Sent:** Friday, June 30, 2017 5:50 PM  
**To:** 'Claim Workflow System'; SITHARA@FIRST-INSURANCE.COM.SG  
**Cc:** SUR; Admin-D (LKKAUTO); assignments  
**Subject:** RE: SURVEY ASSESSMENT - D17006134MFSH/1  
**Attachments:** SLE 287X.pdf

Dear Sithara,

Enclosed preliminary revised for **SLE 287X**

Thank you.

Best Regards,

**Janice Lee (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [janicelee@lkkauto.com](mailto:janicelee@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Thursday, June 22, 2017 5:14 PM  
**To:** 'Claim Workflow System'; assignments  
**Cc:** SITHARA@FIRST-INSURANCE.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D17006134MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]  
**Sent:** Thursday, 22 June, 2017 4:43 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)

**Cc:** [CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG](mailto:CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG); [SITHARA@FIRST-INSURANCE.COM.SG](mailto:SITHARA@FIRST-INSURANCE.COM.SG)

**Subject:** PRI: SURVEY ASSESSMENT - D17006134MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17006134MFSH

Date: 30 June 2017

Our Ref: CS/FCI17012214/T1rb

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SLE 287X**

Please be informed that we had conducted the inspection of the above mentioned vehicle on 23/06/2017 at the premises of M/s CYCLE & CARRIAGE AUTOMOTIVE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>11,588.00</u>
Revised Estimate Amount	: S\$ <u>7,773.00</u>
"Check" Items Amount	: S\$ <u>832.00</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

**Description of Damage:**

The vehicle sustained damages  
at the rear o/s portion



Yours faithfully

TAUFIKH  
Automotive Assessor





Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17006134MFSH

Date: 18 July 2017

Our Ref: CS/FCII7012214/T1rb

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SLE 287X .**

Please be informed that we had conducted the inspection of the above mentioned vehicle on 23/06/2017 at the premises of M/s AUTO INSURE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>9,375.87</u> .
Revised Estimate Amount	: S\$ <u>4,599.75</u> .
"Check" Items Amount	: S\$ <u>1,007.20</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

**Description of Damage:**

The vehicle sustained damages  
at the rear o/s portion



Yours faithfully

TAUFIKH  
Automotive Assessor

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	19/06/2017 17:59
Date Of Accident	17/06/2017 22:30
Exact Location Of Accident	WOODLANDS TOWARDS SLE/BKE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLE287X
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LION CITY RENTALS PTE LTD
Co Reg No	201504621K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-81816239

### Vehicle Particulars

Manufacturer	MITSUBISHI
Model	ATTRAGE-1.2 (A)
Exact Purpose for which vehicle was being used at time of accident	SMOVE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995174
Cover Note Number	

### Driver

Name of Driver	CHONG YUAN KIT, ADRIAN
NRIC No	S8133308D
Date Of Birth	03/11/1981
Occupation	INDOOR
Date Of Driving Pass	25/06/2015
Driving Experience	1 YEAR AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81816239
Fax Number	
Contact Number	
Email Address	YUANKIT1981@GMAIL.COM

Address	BLK 803B KEAT HONG CLOSE #11-124
Postcode	682803
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION- HEAD TO REAR (TP HIT INSURED)
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

please refer to the attached

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC7773X
Vehicle Make/Model/Colour	HYUNDAI SONAT / YELLOW
Details Of Properties	CITYCAB
Name of Driver	GOH ANN BENG
NRIC/Passport Number	S1155787B
Contact Number	
Address	
Postcode	
Insurance Company Name	FIRST CAPITAL INSURANCE LTD
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### Details of Witness

Name	
Phone Number	
Email Address	

### SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**B. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "**Purposes**")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date &  
Time

Driver's Signature (If driver is not the policyholder) / Date  
& Time

Witnessed by Reporting Centre  
Personnel

### Sketch Plan

«Goodland's  
Age 2 Entrance

city club

my car

$$SLK(BKE)$$

### Describe Circumstances of the Accident

ON 17/6/17 at 22:30pm, I just finish driving customer back to Woodlands and when I was entering to Woodland Ave 3 Entrance towards S/E (BKE) at the SHP Road, as I was driving cautiously. Suddenly, city cab vehicle number SHC 4423x was driving fast in lanes on <sup>the line of</sup> my car. Luckily there is no injuries.

### Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S8133308D



Name  
CHONG YUAN KIT, ADRIAN  
(ZHANG YUANJI, ADRIAN)

Race  
CHINESE

Date of Birth  
03-11-1981

Sex  
M

Country of Birth  
SINGAPORE

FOR C&C USE ONLY

REPUBLIC OF SINGAPORE DRIVING LICENCE

Personal Number S8133308D

Name  
CHONG YUAN KIT, ADRIAN  
ZHANG YUANJI, ADRIAN

Birth Date  
03 Nov 1981

Issue Date  
25 Jun 2015

002443546F



SG 50

2433103



2433103

APC No. S8133308D

Date of Issue  
25-10-2004

APT BLK 803B KEAT HONG CLOSE #11-124  
SINGAPORE 682803

NRIC No. S8133308D

Date: 05/02/2016

FOR C&C USE ONLY

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

EFFECTIVE DATE

Class 3 Motor Cars  $\leq$  3000kg with  $\leq$  7 passengers, exclusive of the driver; and other motor vehicles  $\leq$  2500kg

25 Jun 2015

NP 429A

License No: S8133308D





## Auto Insure Pte. Ltd.

6 Marsiling Lane  
Singapore (739145)  
E: [claims@autoinsure.com.sg](mailto:claims@autoinsure.com.sg)  
W: [www.autoinsure.com.sg](http://www.autoinsure.com.sg)  
T: 3157 2626 F: 6368 0081  
GST No.: 201437380M

Page No.1

### AUTOMOBILE ASSESSMENT REPORT

Our Ref: SLE287X  
Your Ref: SHC7773X

Date: 3-Jul-17

BY EMAIL ONLY  
([claims@autoinsure.com.sg](mailto:claims@autoinsure.com.sg))

#### ATTENTION: MOTOR CLAIMS DEPT

email: [motor\\_claims@first-insurance.com.sg](mailto:motor_claims@first-insurance.com.sg)

First Capital Insurance Limited  
6 Raffles Quay #21-00  
Singapore 048580

Car Make and Model : MITSUBISHI ATTRAGE 1.2 CVT  
Date of Accident : 17-Jun-17  
Date of Assessment : 3-Jul-17

We have carried out a physical assessment of SLE287X at our workshop Auto Insure Pte Ltd accordingly and are pleased to submit our report as follow;


#### 4. DESCRIPTION OF DAMAGE

At the time of the inspection observed that this vehicle had sustained damages to rear portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

Estimated Amount : P/P  
Adjusted Amount : \$ 10,000.00  
Est. Repair Days : 6



\*\* Considering that our vehicle is less than 6 months old.  
We will not agree to any repair of parts, only replacement will be done. \*\*

Pursuant to your instruction, we have **NOT AUTHORIZED** repair.  
The assessment was conducted on a "**WITHOUT PREJUDICE**" basis.

If we are not notified of anything within 14 Days from the date hereof, this report shall be treated as correct.

#### Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss of occurrence in which the assessed vehicle is involved.  
No liability or responsibility whatsoever shall be held by  
**AUTO INSURE PTE. LTD.** for any reliance on this report by any third party.

Our Ref: SLE287X  
Your Ref: SHC7773X

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
<b><u>PARTS REPLACEMENT - LIST ITEMS</u></b>				
1	1	REAR BUMPER		\$ <i>dis</i> 1,326.50
2	2	REAR BUMPER SIDE RETAINER		\$ <i>all</i> 118.00
3	1	REAR END PANEL		\$ <i>bt</i> 658.00
4	1	END PANEL TOP GARNISH		\$ <i>un</i> <i>R</i> 428.00
5	1	REAR FLOOR COMPARTMENT PANEL		\$ <i>Rx</i> 1,326.50
6	1	REAR SPARE WHEEL CARRIER		\$ <i>un</i> <i>R</i> 421.50
7	2	REAR BUMPER REFLECTOR		\$ <i>un</i> <i>X</i> 380.00
8	1	REAR BOOT		\$ <i>Rx</i> 866.80
9	1	REAR BOOT CHROME MOULDING		\$ <i>un</i> <i>x</i> 299.50
10	3	REAR BOOT EMBLEM		\$ <i>all</i> 190.00
11	1	REAR BOOT RUBBER MOULDING		\$ <i>un</i> <i>X</i> 180.00
13	1	REAR TAIL LAMP RH		\$ <i>all</i> 585.90
14	1	REAR BOOT LOCK UPPER		\$ <i>un</i> <i>x</i> 203.60
			SUB TOTAL	\$ 6,984.30
			LESS 10%	\$ 698.43
			TOTAL AMOUNT	\$ 6,285.87
S/NO	QTY	<b><u>SPECIAL NETT ITEMS</u></b>		EST. BY WORKSHOP
1	1 SET	REAR BUMPER CLIPS		\$ <i>all</i> 60.00
2	2	REAR REVERSE SENSOR		\$ <i>200. un</i> <i>X</i> 280.00
			SUB TOTAL	\$ 340.00
			TOTAL PARTS COST	\$ 6,625.87



Our Ref: SLE287X

Your Ref: SHC7773X

NO.	DESCRIPTION	EST. BY WORKSHOP
3	<u>LABOUR &amp; PAINTWORK</u>	
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	\$ 1000 1,200.00
2	TO REMOVE / REFIX WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS	\$ 30 100.00
3	<del>TO DIAGNOSE ERASE FAULT MEMORY AFTER REPAIR</del>	\$ -
4	TO REMOVE AND INSTALL REAR REVERSE SENSOR	\$ 30 100.00
6	TO REMOVE / REFIX REAR BOOT MACHANISM	\$ 100 X 100.00
7	TO RESPRAY UNDERCOATING ON PARTS REPLACED	\$ 60 150.00
8	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED	\$ 700 800.00
9	TO REMOVE / REFIX UPHOSTERY. GARNISH AND ATTACHMENT PARTS	\$ 100 200.00
10	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS	\$ 30 100.00
TOTAL BEFORE GST		\$ 9,375.87
GST 7%		\$ 656.31
TOTAL (PARTS & LABOUR):		\$ 10,032.18

10171.87

#### Adjustments / Recommendations

Our estimator have throughly inspected each and every item found on the vehicle and have listed the breakdown of our finding and recommendation.

Our Workshop has agreed to undertake the job at a sum of \$10,000.00 or direct settlement with the third party insurance.

Yours Faithfully,

Jason Heng  
Claims Director

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*Obays*  
*Resurvey before paint.*  
*Taufik 97495749.*  
*62563561*  
*sur@lkkauto.com.*



## Auto Insure Pte. Ltd.

6 Marsiling Lane  
Singapore (739145)  
E: [claims@autoinsure.com.sg](mailto:claims@autoinsure.com.sg)  
W: [www.autoinsure.com.sg](http://www.autoinsure.com.sg)  
T: 3157 2626 F: 6368 0081  
GST No.: 201437380M

# Supplementary Items

Our Ref: SLE287X

Your Ref: SHC7773X

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
<u>PARTS REPLACEMENT - LIST ITEMS</u>				
1	1	REAR FENDER RH		\$ ht✓ 750.00
2	1	REAR TAIL LAMP PANEL RH		\$ ht✓ 245.00
			SUB TOTAL	\$ 995.00
			10% LESS 20%	\$ 199.00
			TOTAL	\$ 796.00



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED. PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI  
MOTORS

Co Reg No : 197701469G

**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Lion City Rentals Pte Ltd	Cust No/Name KL000023/Lion City Rentals Pte Ltd
60 Anson Road	Reg No/Reg Date SLE287X / 04/07/201
Mapletree Anson Level 11-01	Date In/Mileage / 0
Singapore 079914	Chassis No MMBSTA13AHH002049
Contact No Mobile: 67420984	Engine No 3A92UDH5949
	Make/Model MIT/17MY ATTRAGE 1.2 CVT
	Colour/Trim WQ5 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	19/06/2017/ 22:31		465 / Tay Jian Ye	63703
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	TO RENEW REAR BUMPER WELD AND CUT END PANEL , FLOOR PANEL , REAR RH FENDER , REPAIR RH REAR DOOR				2750 3300.00
E PNT88000	TO REMOVE REAR BOOT AND SIDE REAR FENDER TRIM TO FACILITATE REPAIR				160 300.00
E PNT88000	TO REMOVE AND REFIT REAR WINDSCREEN				240 300.00
E PNT98000	PAINT WORK SPRAY REAR BUMPER , REAR RH FENDER , REAR END PANEL , FLOOR PANEL , REAR RH DOOR				1680 2520.00
E PNT88000	TO REMOVE AND REFIT EXHAUST PIPE				260 300.00
A 54900099	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				20 50.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				✓ 200.00
M SUNDRY	TO APPLY BODY SEALANT ON AFFECTED PORTION				160 80 240.00
M SUNDRY	TO APPLY ANTI CORROSION ON AFFECTED PORTION				100 120.00
M SUNDRY	TO APPLY WINDSCREEN SEALANT				✓ 80.00
M SUNDRY	TO SUPPLY PARKING SENSOR				? 220.00
M SUNDRY	SUNDRIES				20 50.00
M FACE,RR BUMPER		1.00	729.00	00.00	dis 729.00
M BRACKET,RR BUMPER,RH		1.00	27.00	00.00	new 27.00
M PANEL,RR END		1.00	414.00	00.00	bt 414.00
M BRACE,RR FLOOR SIDE,RH		1.00	31.00	00.00	bt 31.00
M FLOOR,RR		1.00	933.00	00.00	Rx 933.00
M PANEL,QTR,QTR RH		1.00	745.00	00.00	new 745.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Co Reg No : 197701469G

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Lion City Rentals Pte Ltd	Cust No/Name KL000023/Lion City Rentals Pte Ltd
60 Anson Road	Reg No/Reg Date SLE287X / 04/07/201
Mapletree Anson Level 11-01	Date In/Mileage / 0
Singapore 079914	Chassis No MMBSTA13AHH002049
Contact No Mobile: 67420984	Engine No 3A92UDH5949
	Make/Model MIT/17MY ATTRAGE 1.2 CVT
	Colour/Trim W05 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	19/06/2017/ 22:31		465 / Tay Jian Ye	63703

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
P STOPPER,WINDSHIELD GLASS	2.00	3.00	00.00	6.00
P SPACER,RR WINDOW	3.00	8.00	00.00	24.00
M SHIELD,RR WHEELHOUSE,RH	1.00	39.00	00.00	39.00
M TRIM,TRUNK ROOM SIDE,RH	1.00	158.00	00.00	158.00
M BOARD,TRUNK ROOM FLOOR	1.00	190.00	00.00	190.00
M PIPE,EXHAUST TAIL	1.00	588.00	00.00	588.00
P HANGER,EXHAUST MUFFLER	1.00	24.00	00.00	24.00

# Estimate

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME: Tan Jiam 97495749

SURVEYOR SIGNATURE: [Signature]

DATE: 23/6/17 12pm

REMARKS: Survey before paint WP

Sur@lkkauto.com

10 days

[Signature]  
3/7/17

Confirm & accepted by

7% GST on **Nett 11,588.00**  
**11588.00 811.16**

**Total Payable 12,399.16**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17012214/T1rbq2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 12-09-2018	
			Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHC 7773X		Veh. Inspected	SLE 287X
Policy No.	D-15072702MFSH		Coverage (\$)	0.00
Claim No.	D17006134MFSH		Excess (\$)	0.00
Assign From	SITHARA		Assign Date	22/06/2017
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MITSUBISHI ATTRAGE		c.c	1193
Engine No.	HIDDEN		Year of Reg.	2017
Chassis No.	MMBSTA13AHH002049		Colour	WHITE
Odometer	89145		Steering	IN ORDER
Brakes	IN ORDER		Modification	SPORTS RIM
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/50 R15	ROADSTONE	6 mm	
L/H Front Tyre	195/50 R15	ROADSTONE	6 mm	
R/H Rear Tyre	195/50 R15	ROADSTONE	6 mm	
L/H Rear Tyre	195/50 R15	ROADSTONE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	17/06/2017		Inspection Date	23/06/2017
Survey held at	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD			
Repairer	AUTO INSURE PTE LTD			
<b>5a. Remarks</b>				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 287X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	DISTORTED	1,326.50	1,326.50
2	REAR BUMPER SIDE RETAINER	NECESSARY	118.00	118.00
1	REAR END PANEL	BENT	658.00	658.00
1	END PANEL TOP GARNISH	NOT NECESSARY	428.00	-
1	REAR FLOOR COMPARTMENT PANEL	TO REPAIR SEE LABOUR	1,326.50	-
1	REAR SPARE WHEEL CARRIER	NOT NECESSARY	421.50	-
2	REAR BUMPER REFLECTOR	NOT NECESSARY	380.00	-
1	REAR BOOT	TO REPAIR SEE LABOUR	866.80	-
1	REAR BOOT CHROME MOULDING	NOT NECESSARY	299.50	-
3	REAR BOOT EMBLEM	NECESSARY	190.00	190.00
1	REAR BOOT RUBBER MOULDING	NOT NECESSARY	180.00	-
1	REAR TAIL LAMP RH	CRACKED	585.90	585.90
1	REAR BOOT LOCK UPPER	NOT NECESSARY	203.60	-
1	REAR FENDER RH (ADDITIONAL)	BENT	750.00	750.00
1	REAR TAIL LAMP PANEL RH (ADDITIONAL)	BENT	245.00	245.00
	LESS 10% DISCOUNT		-797.93	-387.34
			7,181.37	3,486.06
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	60.00	60.00
2	REAR REVERSE SENSOR (SN)	NOT NECESSARY	280.00	-
			340.00	60.00
<b><u>LABOUR</u></b>				
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS. INCLUSIVE OF THE REPAIR OF REAR FLOOR COMPARTMENT PANEL AND REAR BOOT.		1,200.00	1,000.00
	TO REMOVE/REFIX WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS.		100.00	30.00
	TO REMOVE AND INSTALL REAR REVERSE SENSOR.		100.00	30.00

Report Ref No. CS/FCI17012214/T1rbq2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607196-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE/REFIX REAR BOOT MECHANISM.	NOT NECESSARY	100.00	-
	TO RESPRAY UNDERCOATING ON PARTS REPLACED.		150.00	60.00
	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED.		800.00	700.00
	TO REMOVE/REFIX UPHOSTERY,GARNISH AND ATTACHMENT PARTS.		200.00	100.00
	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS.		100.00	30.00
			2,750.00	1,950.00
GRAND TOTAL			10,271.37	5,496.06
RECOMMENDED COST OF REPAIRS				5,496.06

Report Ref No. CS/FCI17012214/T1rbq2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.