

ASS. REC. BY:

REF: CS/CTL17012289 / Rlr bnz Special Instruction:

Surveyor:

Rasul

ASSIGNMENT (Office)

Maimen

From (Person):

Jawyn Tay

of

CL

Date/Time: 28062017 455pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKJ 3306R

Insured:

GZ 38793

at Workshop m/s

Performance

Tel:

6319 0174

of

305 Alexandra Road

Policy No:

DMCVSN3013491600

Claim No:

SNM17DX3 716 C02

Sum Insured:

Excess:

D.O.A.

22062017

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

OS

03072017

H.O.D. Endorsement:

Date/Time: 23062017 523pm

Person Contacted:

Caroline

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate	Maimen
	SKJ 3306R - X	
	GZ 38793 - X	
	Confirm PIP \$13,863.10, 8 days	
	Red. \$686.55, 4%	

0801/17

Sirevor
m/min

REF: CTL

7435F

ASSIGNMENT

From: Date: 03/07/2017

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No: SKJ 3306R

at Workshop m/s Performane

of 303 Alexandra Road

Insured:

Policy No.


Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: merma

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS Dg

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SKJ 3306R Yr Regn: 2016 / Feb

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W 318i c.c. 1499

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 12576 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WBA8E360XONT39183

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/50R17

R: 22

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 24/06/17

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 03/07/17

PERFORMANCE

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

) S + RS, SI

) Photos

) Others

TOTAL

300

Report Format :

Lump Sum / I.B.I. (\$)

RECEIVED 06 JUL 2017

[Signature]
6/12/2017



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI17012289/R1rb	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 23-06-2017	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GZ 3879S	Veh. Inspected	SKJ 3306R
Policy No.	DMCVSN3023491600	Coverage (\$)	0.00
Claim No.	SNM17D03716C02	Excess (\$)	0.00
Assign From	MERIMEN (JOWYN TAY)	Assign Date	23/06/2017
2. Vehicle Particulars & Condition			
Make & Model	c.c 0		
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	Colour		
Odometer	-	Steering	
Brakes	Modification		
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	22/06/2017	Inspection Date	03/07/2017
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Jun 2017		23 Jun 2017 16:55 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	WEI LONG ENGINEERING & CONSTRUCTION PTE LTD, Co. Reg. No.: 200819620E		
Main Claimant:	CHIN YAH LING MICHELLE, ID: S7147435F		
Vehicle Reg. No.:	SKJ3306R	Date of Loss:	22/06/2017 10:00 - :59
Claim Type:	TP / SNM17D03716C02	Policy/Cover Note No.:	DMCVSN3023491600 (Comprehensive) Coverage: 29/05/2016 - 22/09/2017
Vehicle Reg. No. (Insured):	GZ3879S	Policy No. (Claimant):	SI17V01861/VPC/R01
		Excess:	S\$0.00
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: 6221 8611		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 05/07/2017]		
Adj Asg. Remarks:	PLEASE PROCEED TO SURVEY AND ARRANGE FOR DIRECT SETTLEMENT.		

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/06/2017 14:10
Date Of Accident	22/06/2017 10:30
Exact Location Of Accident	17 MOHAMED SULTAN RD (PARALLEL PARKING)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKJ3306R
Insured/Policyholder	
Name Of Registered Owner	CHIN YAH LING MICHELLE
NRIC No	S7147435F
Email Address	MICCREATION@YAHOO.COM
Mobile Phone No	(LOCAL) +65-96385125
Alternative Phone No	OFFICE-96385125

Vehicle Particulars

Manufacturer	BMW
Model	318
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SI17V01861/VPC/R01
Cover Note Number	

Driver

Name of Driver	CHIN YAH LING MICHELLE
NRIC No	S7147435F
Date Of Birth	31/12/1971
Occupation	INDOOR
Date Of Driving Pass	27/05/1991
Driving Experience	26 YEARS AND 0 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96385125
Fax Number	
Contact Number	OFFICE-96385125
Email Address	MICCREATION@YAHOO.COM

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -
-
-

Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident DAMAGED WHILST PARKED

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s)
soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GZ3879S

Vehicle Make/Model/Colour TOYOTA SILVER

Details Of Properties

Name of Driver NATARAJAN VENKATESAN

NRIC/Passport Number G8445199W

Contact Number 82858776

Address

Postcode

Insurance Company Name CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Nature Of Damage RIGHT

No. Of Passenger (Including Driver) 1

Details of Witness

Name

Phone Number

Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time
22 JUN 2017

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

22 JUN 2017

Sketch Plan



Sketch Plan Pg. 2

Describe Circumstances of the Accident

My car was parked at 17 Muhammed Sultan Rd, Parallel parking, on 22 June 2017, when I came to collect the car at around 10.30-10.40am, 2 persons were there and told me they hit my car while reversing into the parking lot behind my car. Their vehicle, left back, hit the right side of my car, around the back tyre/fuel tank area. We exchanged particulars and I also took photos of the damage of my car, and the position his vehicle that impact my car.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time
 22 JUN 2017

Driver's Signature (if driver is not the policyholder) / Date & Time

CHIA SAN SAN
 Performance Motors Limited
 305 Alexandra Road
 Sims Darby Performance Centre
 Singapore 159941

Witnessed by Reporting Centre Personnel

22 JUN 2017

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63445773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (MotorRad)
Fax. 64786601 (AfterSales)
64786624 (MotorRad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

22 JUN 2017 @ 6.08 PM

Estimate No. : b1 43144
Date Estimated : 22/06/2017
Prepared By : Merina Chia San San

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -
Chin Yah Ling, Michelle
201 Petir Road
#02-693

Singapore 670201

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKJ3306R	NT39183	04/02/2016	318iA/4Dr	0

DESCRIPTIONVALUETo replace rear right fender including attachments etc
and to knock out dented area caused by accident

4675 4250 5,100.00

To paint rear right fender

3015 797 885.00

To remove and install fuel tank to facilitate repairs
including conduct checks for leak.

/ 451 531.00

To check steering geometry and conduct wheel alignment in
accordance with BMW specifications. (1X).

/ 451 531.00

To replace rear windscreen glass including conduct water
leak tests.

/ 649.00

To supply and install front or rear windscreen solar film.

Xⁿⁿ 451? 531.00To remove and install rear hat-tray, rear seat, carpet
and roof top lining to facilitate repairs.

/ 742 873.00

To remove and install fuse box at the rear section to
facilitate repairs.

/ 451? 531.00

To reconnect electrical components and wirings at the
rear section including conduct checks for proper function.

300 301? 354.00

To remove and install wire harness, control units and
battery at the rear section to facilitate panel replacement.Xⁿⁿ 451? 531.00To conduct checks on the electrical wiring system on
the left/right side member for proper function.Xⁿⁿ 150 177.00To carry out body cavity preservation.
(For cut panel).

/ 451 531.00

Sundries.

/ ? 150.00

nrc.

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 436180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 43144
Date Estimated : 22/06/2017
Prepared By : Merina Chia San San

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKJ3306R	NT39183	04/02/2016	318iA/4Dr	0

Total Labour 1: 11,374.00

PART NUMBER	DESCRIPTION	QTY	PRIC	VALUE
41007298172	RR RH FENDER	1	1,487.45	1,487.45
41217298192	RH C-PILLAR REINFORCEMENT PLATE	1	48.00	48.00
41217298208	RH SILL REINFORCEMENT PLATE	1	48.00	48.00
51312996980	BUMP STOP	10	4.00	40.00
51317258053	COVER WINDSHIELD TOP	1	33.65	33.65
51317258074	REAR WINDOW	1	713.85	713.85
83190301414	BLIND RIVET HEML OCK 813	1	2.65	2.65
83190301421	BLIND RIVET AVIBVLB	12	0.55	6.60
83190301639	SCREW (SF PLUS M5X15)	3	0.55	1.65
83192157298	(DG/SL) BODY ADHESIVE K5B (195ML)	1	281.55	281.55
83192158080	PUNCH RIVET N4	39	0.55	21.45
83192158654	(DG) BODYWORK ADHESIVE K5A (50ML)	1	118.35	118.35
83192211217	(DG) CLEANER R1 (100ML)	1	23.85	23.85
83192211217	(DG) CLEANER R1 (100ML)	1	23.85	23.85
83192289285	(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	263.10
83199407777	(DG/SL) GLASS PRIMER 30ML (VP206)	1	27.85	27.85
83422409985	(S/L) SEAM SEAL 300ML	1	33.80	33.80

Total Parts : 3,175.65

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Complementary item(s) must be resurveyed and subject to final approval by the Insurance Company

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
 Date & Time 03/07/17 @ 1535 Excess S\$ _____
 Surveyor's Name RASUL Sign _____
 Surveyor's Tel 90010068 Authorised Yes / No _____
 Authorised Date _____ Time _____
 RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No _____
 Surveyor's E-mail _____
 No. of Working Days Recommend 8 days

Labour 1 : 11,374.00
 Parts : 3,175.65
 Labour 2 : 16915.60 0.00
 Excess : 0.00
 Total GST @ 7% : 1,018.48
 Grand Total : 15,568.13

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 43144
Date Estimated : 22/06/2017
Prepared By : Merina Chia San San

Page No. :

REPAIR FOR -
Chin Yah Ling, Michelle
201 Petir Road
#02-693

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Singapore 670201

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SKJ3306R	NT39183	04/02/2016	318iA/4Dr	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# To remove and install boot compartment carpet and garnish to facilitate repairs	231.00		231.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

Total Labour :	231.00
Total Parts :	0.00
Total Labour & Parts :	231.00



FINAL REPORT

Estimate No. : b1 43144
Date Estimated : 22/06/2017
Prepared By : Merina Chia San San

Page No. :

REPAIR FOR -

Chin Yah Ling, Michelle
201 Petir Road
#02-693

Singapore 670201

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE	
SKJ3306R	NT39183	04/02/2016	318iA/4Dr	0	
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT		
* To replace rear RH fender and attachments include making good the tail end panel, RH entrance panel, RH roof frame, RH 'C' pillar and knocking out dents caused by the accident	4675.00		4,675.00		
* To spray paint rear RH fender, RH roof frame, RH entrance panel, RH 'C' pillar and tail end panel	3015.00		3,015.00		
To remove and install fuel tank to facilitate repairs include conducting checks for leak	451.00		451.00		
To check steering geometry and conduct wheel alignment in accordance with BMW specifications (1x)	451.00		451.00		
To remove and install rear windscreen glass to facilitate repairs include conducting water leak tests	649.00		649.00		
To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs.	742.00		742.00		
* To remove and install fuse box at the rear section to facilitate repairs.	451.00		451.00		
* To reconnect electrical components and wirings at the rear section including conduct checks for proper function. (For cut panel)	300.00		300.00		
# To remove and install boot compartment carpet and garnish to facilitate repairs	231.00		231.00		
To carry out body cavity preservation for rear RH fender (For cut panel).	451.00		451.00		
Sundries.	150.00		150.00		

Performance Motors Limited

A member of the Simo Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
RR RH FENDER	1,487.45	1.00		1,487.45
BLIND RIVET HEML OCK 813	2.65	1.00		2.65
BLIND RIVET AVIBVLB	0.55	20.00		11.00
SCREW (SF PLUS M5X15)	0.55	3.00		1.65
(DG/SL) BODY ADHESIVE K5B (195ML)	281.55	1.00		281.55
PUNCH RIVET N4	0.55	40.00		22.00
(DG) BODYWORK ADHESIVE K5A (50ML)	118.35	1.00		118.35
(DG) CLEANER R1 (100ML)	23.85	2.00		47.70
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	131.55	2.00		263.10
(DG/SL) GLASS PRIMER 30ML (VP206)	27.85	1.00		27.85
(S/L) SEAM SEAL 300ML	33.80	1.00		33.80

SUPPLEMENTARY ITEMS

Total Labour :	11,566.00
Total Parts :	2,297.10
Total Labour & Parts :	13,863.10
Deduction for Excess :	0.00
Total Repair Costs less Excess:	13,863.10
GST @7%:	970.42
Grand Total :	14,833.52

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT117012289/R1RBN2

Date: 07/12/2017

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3023491600
Claimant Vehicle No :	SKJ3306R	Insured Vehicle No :	GZ3879S
Date of Loss:	22/06/2017	Nature of Claim:	TP
		Claim No:	SNM17D03716C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKJ3306R	Engine No:	F3871238B38B15A
Make & Model:	BMW 318CI, 2.0 (A)	Chassis No:	WBA8E360X0NT39183
Reg. Date:	04/02/2016 (Man. Year: 2015)	Odometer:	12526 km
Colour:	White		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50R17	Rear Tyre Size:	225/50R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,330.60	2,447.10	883.50	26.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,585.00	11,416.00	2,169.00	15.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,915.60	13,863.10	3,052.50	18.05
+ GST 7.00/7.00% (S\$)	1,184.09	970.42	213.67	18.05
Nett Amount (S\$)	18,099.69	14,833.52	3,266.17	18.05

INSPECTION

Date of Assignment:	23/06/2017	
Date Inspected:	03/07/2017	Inspected At: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	8.0 days	

Adjuster: MOHD RASUL

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 07 Dec 2017)	
Parts: 143	BMW 318CI 2.0 (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SKJ3306R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RR RH FENDER	Buckled	1,487.45 FS	*1,487.45 FS
2	1		*RH C-PILLAR REINFORCEMENT PLATE	Serviceable	48.00 FS	*- FS
3	1		*RH SILL REINFORCEMENT PLATE	Serviceable	48.00 FS	*- FS
4	10		*BUMP STOP	Serviceable	40.00 FS	*- FS
5	1		*COVER WINDSHIELD TOP	Serviceable	33.65 FS	*- FS
6	1		*REAR WINDOW	Serviceable	713.85 FS	*- FS
7	1		*BLIND RIVET HEML OCK 813	Necessary	2.65 FS	*2.65 FS
8	1		*BLIND RIVET AVIBVLB (12 Pcs)	Necessary	11.00 FS	*11.00 FS
9	3		*SCREW (SF PLUS M5X15)	Necessary	1.65 FS	*1.65 FS
10	1		*(DG/SL) BODY ADHESIVE K5B (195ML)	Necessary	281.55 FS	*281.55 FS
11	1		*PUNCH RIVET N4 (39 Pcs)	Necessary	22.00 FS	*22.00 FS
12	1		*(DG) BODYWORK ADHESIVE K5A (50ML)	Necessary	118.35 FS	*118.35 FS
13	1		*(DG) CLEANER R1 (100ML)	Necessary	23.85 FS	*23.85 FS
14	1		*(DG) CLEANER R1 (100ML)	Necessary	23.85 FS	*23.85 FS
15	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	263.10 FS	*263.10 FS
16	1		*(DG/SL) GLASS PRIMER 30ML (VP206)	Necessary	27.85 FS	*27.85 FS
17	1		*(S/L) SEAM SEAL 300ML	Necessary	33.80 FS	*33.80 FS
18	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	3,330.60	2,447.10
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR RIGHT FENDER INCLUDING ATTACHMENTS ETC AND TO KNOCK OUT DENTED AREA CAUSED BY ACCIDENT	New	5,100.00	4,675.00
2	TO PAINT REAR RIGHT FENDER	New	3,015.00	3,015.00
3	TO REMOVE AND INSTALL FUEL TANK TO FACILITATE REPAIRS INCLUDING CONDUCT CHECKS FOR LEAKS	New	531.00	451.00
4	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT IN ACCORDANCE WITH BMW SPECIFICATIONS (1X)	New	531.00	451.00
5	TO REPLACE REAR WINDSCREEN GLASS INCLUDING CONDUCT WATER LEAK TESTS	New	649.00	649.00
6	TO SUPPLY AND INSTALL FRONT OR REAR WINDSCREEN SOLAR FILM	New	531.00	-
7	TO REMOVE AND INSTALL REAR HAT-TRSY, REAR SEAT, CARPET AND ROOF TOP LINING TO FACILITATE REPAIRS	New	873.00	742.00
8	TO REMOVE AND INSTALL FUSE BOX AT THE REAR SECTION TO FACILITATE REPAIRS	New	531.00	451.00
9	TO RECONNECT ELECTRICAL COMPONENTS AND WIRINGS AT THE REAR SECTION INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	354.00	300.00
10	TO REMOVE AND INSTALL WIRE HARNESS, CONTROL UNITS AND BATTERY AT THE REAR SECTION TO FACILITATE PANEL REPLACEMENT	New	531.00	-
11	TO CONDUCT CHECKS ON THE ELECTRICAL WIRING SYSTEM ON THE LEFT/RIGHT SIDE MEMBER FOR PROPER FUNCTION	New	177.00	-
12	TO CARRY OUT BODY CAVITY PRESERVATION (FOR CUT PANEL)	New	531.00	451.00
13	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	231.00	231.00
Gross Labour Cost (\$\$)			13,585.00	11,416.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >