

ASS. REC. BY:

REF: CS/EG217012437/Stbgr

Special Instruction:

Surveyor

Sebastian

ASSIGNMENT (Office)

From (Person): Yee Pei Li of EGI Date/Time: 28062017 1:39pm

Estimated Cost: Bill to:

OD / TP + WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKH 6710Y Insured: XE 1866B

at Workshop m/s motor Image Tel: 6703 3114

of 19 Tua Payoh Lorong 8

Policy No: Claim No: DSMFP701655

Sum Insured: Excess:

Make of Veh: D.O.A. 21062017
(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

29062017

H.O.D. Endorsement:


Date/Time: 28062017 1:53pm Person Contacted: Desmond Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKH 6710Y - x
	XE 1866B - x
	Part by Part \$11,472.92 (Red: 6505.08 :36%)

ASSIGNMENT

From: _____ Date: 29062017
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SKH 6710Y
 at Workshop m/s Motor Image
 of 19 Twa Payoh Lorong 8
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 8 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKH 6710Y Yr Regn: 3/1/2013
 Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or
 Make: Subaru xv c.c. 1995
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 160518 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: JF1GP7KC5CG009077
 Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225/50R18
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front		Rear
R/Bal. <u>7</u> mm		R/Bal. <u>7</u> mm
L/Bal. <u>7</u> mm		L/Bal. <u>7</u> mm
D.O.A. <u>21/6/2017</u>		D.O.I. <u>29/6/2017</u>

Survey held at Motor Image
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 06 JUL 2018

Date/Time, File Pass to?

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 8

Resurvey No. of Trip: 1

Survey Fee: 350

Transportation: _____

_____ S + RS _____ SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Report Format :

Lump Sum / I.B.I: (\$ 11,472.92)

350



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ERGO INSURANCE PTE LTD		Ref : CS/EGI17012437/Stb	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 28-06-2017	
		Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	XE 1866B	Veh. Inspected	SKH 6710Y
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	28/06/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	21/06/2017	Inspection Date	29/06/2017
Survey held at	MOTOR IMAGE ENTERPRISES PTE LTD 19 TOA PAYOH LORONG 8 SINGAPORE 319255		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Catherine Chong (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.)
<Survey.Report@ergo.com.sg>
Sent: Wednesday, 28 June, 2017 1:39 PM
To: 'admin-d@lkkauto.com'
Subject: OI : XE1866B / TP : SKH6710Y/LKK / DOA : 21.06.2017
Attachments: XE1866B - SAS.pdf; SKH6710Y - SAS.pdf; SKH6710Y - ESTIMATE.pdf;
SKH6710Y - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and Ergo Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **MOTOR IMAGE ENTERPRISES PTE LTD.**

ADDRESS : 19 TOA PAYOH LORONG 8
SINGAPORE 319255

PERSON TO CONTACT : DESMOND FOO @ 6703 8114

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on DIRECT SETTLEMENT basis. Please inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured and TP's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Thank you.

Best Regards

Yee Pei Li
Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
DID: 65 6829 9194
Fax: 65 6829 9247
Website www.ergo.com.sg



Have you tried our new travel insurance product yet?
TravelProtect comes with comprehensive benefits at some of the most affordable prices available in the market.

ERGO
TravelProtect
your Global Safety Net

TravelProtect is underwritten by ERGO Insurance Pte. Ltd.

 **BUY NOW**

Denise Tay (LKKAuto)

From: Yee Pei Li <peili.yee@ergo.com.sg>
Sent: Friday, 6 July 2018 9:29 AM
To: Denise Tay (LKKAuto)
Subject: RE: XE1866B / TP : SKH6710Y/LKK / DOA : 21.06.2017

Denise,

Claim no. is DSMFP1701655.

RgDS
Pei Li

EMAIL DISCLAIMER

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message.
Any views expressed in this email communication are those of the individual sender. ERGO Insurance Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference.
ERGO Insurance Pte. Ltd. asserts copyright in respect to this email including any attachment. No part may be reproduced by any process or for any purpose without prior written permission.

From: Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]
Sent: Friday, 6 July, 2018 9:23 AM
To: Yee Pei Li
Subject: RE: XE1866B / TP : SKH6710Y/LKK / DOA : 21.06.2017

Dear Pei Li,

Can provide me claim number

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [mailto:Survey.Report@ergo.com.sg]
Sent: Wednesday, 28 June 2017 1:39 PM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Subject: OI : XE1866B / TP : SKH6710Y/LKK / DOA : 21.06.2017

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and Ergo Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".



BENG HENG TYRES BATTERIES PTE LTD

BLK 32 SIN MING DRIVE #01-337 / #01-345 SIN MING INDUSTRIAL ESTATE, SINGAPORE 575706

TEL : 6457 6337 / 6459 3335

FAX : 6457 4230

GST REG. NO.: 201229097E

CO. REG. NO.: 201229097E

CASH SALES
CS201711-0095

CASH

ATTN :

Date : 10-11-2017

Term :

Account No. : CASH

Vehicle No. : SKH6710

WO No : JO201711-0321

REMARKS: BILLING FOR WORKORDER : JO201711-0321 Veh No :SKH6710

S/NO STOCK ID	DESCRIPTION	QUANTITY	UNIT PRICE	AMOUNT
Z-RIM.FP1992.18".5X100.FP	FP1992 18"X8 5X100 FGM FP SPORT RIM	4.00 PCS	205.00	766.36
Z201	MEND TYRE (FRONT RIGHT) FOC	1.00 PCS	0.00	0.00

Eight Hundred Twenty Dollars

FOR BENG HENG TYRES BATTERIES PTE LTD

TOTAL : \$766.36

ADD GST @ 7.00% : \$53.64

TOTAL AMOUNT : \$820.00

L. YAN

Page 1 of 1

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/06/2017 14:46
Date Of Accident	21/06/2017 12:10
Exact Location Of Accident	ALONG WOODLANDS ROAD TOWARD KRANJI ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKH6710Y
Insured/Policyholder	
Name Of Registered Owner	LIM HAN CHEONG (LIN HANCHANG)
NRIC No	S8021995D
Email Address	HANCHEONG18@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97919757
Alternative Phone No	OFFICE-97919757

Vehicle Particulars

Manufacturer	SUBARU
Model	XV 2.0I-S CVT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D17MTPV01000813
Cover Note Number	NA

Driver

Name of Driver	LIM HAN CHEONG (LIN HANCHANG)
NRIC No	S8021995D
Date Of Birth	01/08/1980
Occupation	INDOOR
Date Of Driving Pass	21/10/2002
Driving Experience	14 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97919757
Fax Number	
Contact Number	OFFICE-97919757
Email Address	HANCHEONG18@GMAIL.COM

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -

-

Insurance Company of Driver's Own Vehicle -

-

-

General Information of the Accident

Type Of Accident COLLISION- CHANGE/CROSS LANE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 3

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

While I was travelling along woodland road towards Marsiling, this lorry abruptly swerved into my lane, I already honk him. There was no room for me to avoid the collision. The next moment, his lorry already hit against my rear right side of my car SKH6710Y. No injuries involved.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number XE1866B

Vehicle Make/Model/Colour MAN / TGM 18.250 4X2

Details Of Properties NA

Name of Driver KOH SOO HAP

NRIC/Passport Number S1395770C

Contact Number 84450964

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S8021995D

Name: LIM HAN CHEONG (LIN HANCHANG)

Birth Date: 01 Aug 1980

Issue Date: 16 Aug 2003

000751072F

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S8021995D

Name: LIM HAN CHEONG (LIN HANCHANG)

林 汉 昌

Race: CHINESE

Date of birth: 01-08-1980

Sex: M

Country of birth: SINGAPORE

4615179

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE: 21 Oct 2002

for Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

Licence No: S8021995D

NP 428A

4615179

NRIC No. S8021995D

Date of issue: 11-08-2010

APT BLK 439C SENGKANG WEST AVENUE #12-301
SINGAPORE 793439

NRIC No: S8021995D

Date: 21/10/2011

No: 6938712

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0249/2017
DATE : 27-JUN-2017

SOMPO JAPAN INSURANCE COMPANY (ASIA) PTE LTD
50 RAFFLES PLACE
#03-03
SINGAPORE LAND TOWER S(048623)
TEL : 63224635
FAX : 62266318

OWNER'S NAME : LIM HAN CHEONG *NEW SPMP*
ADDRESS : APT BLK 439C SENGKANG WEST AVENUE
#12-301
S(793439)
TELEPHONE NO : 97919757

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : D17MTPV01000813
VEHICLE NO : SKH6710Y
MODEL CODE : GP7AKHC
MODEL/YEAR : SUBARU XV 2.0I-S AWD CVT
ENGINE NO : FB20R321624
CHASSIS NO : JF1GP7KC5CG009077
MILEAGE : 1 KM
DATE IN : 27/06/2017
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH ALI
ACCIDENT DATE : 21/06/2017

Print Date : 29/06/2017
Print Time : 17:04:53

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKH6710Y

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 ZZ/001	TO REPLACE/REPAIR FRT RHS DOOR, FRT RHS FENDER, RR DOOR, RR BUMPER.	5600.00	2240 /
2 ZZ/002	TO RESPRAY FRT RHS FENDER, FRT RHS DOOR, RR RHS DOOR, RR FENDER AND RR BUMPER.	2970.00	2100 /
3 ZZ/003	TRANSFER/BALANCE/RIM	100.00	50 /
4 ZZ/004	TRANSFER FRT RHS AND REAR RHS DOOR MECHANISM.	450.00	400 /
5 ZZ/005	WHEEL ALIGNMENT	250.00	200 /
6 ZZ/006	REMOVE & REFIX CARPET, SEAT TO FACILITATE REPAIRS.	450.00	400 /
7 ZZ/007	REMOVE & INSTALL REAR RHS QUATER GLASS.	230.00	180 /
8 ZZ/008	TO SUPPLY AND INSTALL REVERSE SENSOR 2 EYES	350.00	300 /
9 ZZ/009	TO SUPPLY & INSTALL REAR RHS QUATER GLASS TINTED FILM.	295.00	245.00 /
10 ZZ/011	TO SUPPLY AND INSTALL RR QUATER GARNISH, SIDE SILL GARNISH AND FRT RHS QUATER GARNISH	190.00	140 /
11 ZZ/012	INSTALL DRIVER SIDE MIRROR ASSY	120.00	70 /
12 ZZ/10	SUNDRIES	150.00	100 /
TOTAL LABOUR CHARGES		11125.00	

8 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sebastian.

29/6/2017.

- Photo before paint.

- Question Mark Item Photo.

90036121 sebastian.yeang@lkkauto.com.

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SKH6710Y

TOTAL LABOUR CHARGES 11125.00
TOTAL SPARE PARTS CHARGES 0.00

GRAND TOTAL 11125.00 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

PLS NOTE : This estimate is based on visual inspection of the
 affected vehicle. Should we require further labour
 charges & spare parts in the process of repairs, we
 shall inform you accordingly.

Estimate

Date 06/27/2017

001 / 003

Name	QUOTATION FOR SKH6710Y	Tel (Home)	
Address		Tel (Office)	
E-Mail		Tel (Portable)	
		Fax	
		Model Name	G33
		Body Model	GP7AKHC
		Vin-Code	JF1GP7KC5CG-009077

Part Number	Part Code Name	Part Code	Q'ty	Price
57120FJ0509P	FENDER COMPLETE-FRON ✓ DT T, RIGHT	FIG-540 57110	1	✓ 198.00
60009FJ0019P	PANEL ASSEMBLY-FRONT ✓ DT DOOR, RIGHT	FIG-605 60010	1	✓ 648.00
61160FJ000TQ	HANDLE-DOOR, OUTER ✓ cut	FIG-607 61160E	1	✓ 43.20
90422FJ001	TAPE-FRONT DOOR, RIGH ? T	FIG-905 90422X	1	X 9.00
90422FJ021	TAPE-FRONT DOOR SASH ? RIGHT	FIG-905 90422A	1	X 36.00
90422FJ041	TAPE-FRONT DOOR SASH ? , REAR RIGHT	FIG-905 90422E	1	X 23.40
61280FJ001	WEATHER STRIP-DOOR, O ✓ NEC. UT RH	FIG-605 61280	1	✓ 126.00
61032FJ200	LATCH & ACTUATOR ASS ? EMBL- FRONT, RIGHT	FIG-607 61176F	1	X 252.00
60409FJ0019P	RRH DOOR ✓ DT	FIG-605 60010	1	✓ 648.00
90422FJ061	TAPE-REAR DOOR SASH ? RIGHT	FIG-905 90422C	1	X 23.40
90422FJ081	TAPE-REAR DOOR SASH, ? CENTER RIGHT	FIG-905 90422G	1	X 27.00
90422FJ121	TAPE-REAR DOOR SASH, ? REAR RIGHT	FIG-905 90422I	1	X 9.00
62280FJ000	WEATHER STRIP-DOOR, R ✓ NEC. EAR OUTER RIGHT	FIG-605 62280A	1	✓ 126.00
63511FJ000	WEATHER STRIP-FRONT ✓ NEC. DOOR, RIGHT	FIG-901 63511	1	✓ ch 119.00
63527FJ000	RUN CHANNEL-FRONT DO ✓ NEC. OR, RIGHT	FIG-901 61234A	1	✓ 90.00
63571VA000	WEATHER STRIP-BODY S ✓ NEC. IDE, FLANGE FRONT	FIG-901 63571B	1	✓ 90.00
Page-Total				2,468.00

Memo

Grand Total
6,853.00

--

Tel

Estimate

Date 06/27/2017

002 / 003

Name	QUOTATION FOR SKH6710Y	Tel (Home)	
Address		Tel (Office)	
E-Mail		Tel (Portable)	
		Fax	
		Model Name	G33
		Body Model	GP7AKHC
		Vin-Code	JF1GP7KC5CG-009077

Part Number	Part Code Name	Part Code	Q'ty	Price	
51439FJ0429P	REAR QUARTER COMPLET ✓ NEC E-OUTER, RIGHT	FIG-522 51410	1	✓ 864.00	NE
59122FJ001	MUD GUARD, REAR RIGHT R	FIG-541 59112	1	X 64.80	R
65209FJ000	GLASS-REAR QUARTER, R ? IGHT	FIG-652 65210A	1	X 504.00	
65245FJ000	DAM RUBBER-REAR QUAR ? TER	FIG-652 65245	1	X 10.80	
65277FJ000	SEAL-WINDOW REAR QUA ? RTER	FIG-652 65277A	1	X 4.70	
63019FJ000	GLASS-REAR GATE X	FIG-621 63011	1	X 799.20	
65245SC000	DAM RUBBER-REAR QUAR ? TER	FIG-621 65245	1	X 21.60	
57704FJ041	BUMPER-FACE, REAR ✓ cut	FIG-591 57704A	1	✓ 594.00	U
57707FJ080	BRACKET-REAR BUMPER ✓ NEC CORNER, RIGHT	FIG-591 57707AC	1	✓ 28.80	NI
57707FJ090	BRACKET-REAR BUMPER ✓ NEC CORNER, LEFT	FIG-591 57707AD	1	✓ 28.80	N
57707FJ160	BRACKET-REAR BUMPER ? SIDE, RIGHT	FIG-591 57707H	1	X 14.40	
57707FJ170	BRACKET-REAR BUMPER ? SIDE, LEFT	FIG-591 57707I	1	X 14.40	
57731FG010I6	COVER-REAR BUMPER ✓ NEC	FIG-591 57731C	1	✓ 14.40	
57707FJ201	BRACKET-REAR BUMPER, ? LOWER	FIG-591 57707N	2	X 14.40	
91112FJ101	GARNISH-FRONT FENDER ✓ cut , RIGHT	FIG-914 91111	1	✓ 180.00	U
91112FJ121	GARNISH-REAR QUARTER ✓ MS , RIGHT	FIG-914 91111D	1	✓ 180.00	N
		Page-Total		3,338.30	

Memo

Grand Total
6,853.00

--

Tel

Estimate

Date 06/27/2017

003 / 003

Name	QUOTATION FOR SKH6710Y	Tel(Home)	
Address		Tel(Office)	
E-Mail		Tel(Portable)	
		Fax	
		Model Name	G33
		Body Model	GP7AKHC
		Vin-Code	JF1GP7KC5CG-009077

Part Number	Part Code Name	Part Code	Q'ty	Price
91112FJ141	GARNISH-SIDE SILL, RI <i>✓ ent</i> GHT	FIG-914 91111W	1	<i>✓</i> 180.00
91036FJ284	DOOR MIRROR UNIT-RIG <i>✓ CRK</i> HT	FIG-912 91031N	1	<i>✓</i> 576.00
91059AJ200	COVER-CAP OUT MIRROR <i>✓ ms</i> , RIGHT	FIG-912 91054D	1	<i>✓</i> 64.80
84401AJ000	LAMP ASSEMBLY-SIDE T <i>✓ CRK</i> URN, MIRROR RIGHT	FIG-912 84401B	1	<i>✓</i> 102.00
91054AJ221	COVER-CAP OUT MIRROR <i>✓ ms</i> , RIGHT LOWER	FIG-912 91054F	1	<i>✓</i> 33.90
91039AJ121	MIRROR-REPAIR, RIGHT ?	FIG-912 91039	1	<i>X</i> 90.00
		Page-Total		1,046.70
		Sub-Total		6,853.00
		Total		6,853.00
		Tax		
		Grand Total		6,853.00

Memo	Grand Total
	6,853.00

	Tel
--	-----

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0249/2017
DATE : 27-JUN-2017

SOMPO JAPAN INSURANCE COMPANY (ASIA) PTE LTD
50 RAFFLES PLACE
#03-03
SINGAPORE LAND TOWER S(048623)
TEL : 63224635
FAX : 62266318

OWNER'S NAME : LIM HAN CHEONG *NEW SPMP*
ADDRESS : APT BLK 439C SENGKANG WEST AVENUE
#12-301
S(793439)
TELEPHONE NO : 97919757

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : D17MTPV01000813
VEHICLE NO : SKH6710Y
MODEL CODE : GP7AKHC
MODEL/YEAR : SUBARU XV 2.0I-S AWD CVT
ENGINE NO : FB20R321624
CHASSIS NO : JF1GP7KC5CG009077
MILEAGE : 1 KM
DATE IN : 27/06/2017
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH ALI
ACCIDENT DATE : 21/06/2017

Print Date : 29/06/2017
Print Time : 17:04:53

MOTORIMAGE ENTERPRISES PTE. LTD.

19 LORONG 8, TOA PAYOH

SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKH6710Y

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	TO REPLACE/REPAIR FRT RHS DOOR, FRT RHS FENDER, RR DOOR, RR BUMPER.	5600.00	2240
2	ZZ/002	TO RESPRAY FRT RHS FENDER, FRT RHS DOOR, RR RHS DOOR, RR FENDER AND RR BUMPER.	2970.00	2100
3	ZZ/003	TRANSFER/BALANCE/RIM	100.00	50
4	ZZ/004	TRANSFER FRT RHS AND REAR RHS DOOR MECHANISM.	450.00	400
5	ZZ/005	WHEEL ALIGNMENT	250.00	200
6	ZZ/006	REMOVE & REFIX CARPET, SEAT TO FACILITATE REPAIRS.	450.00	400
7	ZZ/007	REMOVE & INSTALL REAR RHS QUATER GLASS.	230.00	180
8	ZZ/008	TO SUPPLY AND INSTALL REVERSE SENSOR 2 EYES	350.00	300
9	ZZ/009	TO SUPPLY & INSTALL REAR RHS QUATER GLASS TINTED FILM.	295.00	245.00
10	ZZ/011	TO SUPPLY AND INSTALL RR QUATER GARNISH, SIDE SILL GARNISH AND FRT RHS QUATER GARNISH	190.00	140
11	ZZ/012	INSTALL DRIVER SIDE MIRROR ASSY	120.00	70
12	ZZ/10	SUNDRIES	150.00	100
TOTAL LABOUR CHARGES			11125.00	

8 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sebastian.

29/6/2017.

- Photo before paint.

- Question Mark Item Photo.

90036121 sebastianyeang@lkkauto.com.

MOTORIMAGE ENTERPRISES PTE. LTD.

19 LORONG 8, TOA PAYOH

SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SKH6710Y

TOTAL LABOUR CHARGES	11125.00
TOTAL SPARE PARTS CHARGES	0.00
GRAND TOTAL	11125.00 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

Estimate

Date 06/27/2017

001 / 003

Name	QUOTATION FOR SKH6710Y	Tel (Home)	
Address		Tel (Office)	
E-Mail		Tel (Portable)	
		Fax	
		Model Name	G33
		Body Model	GP7AKHC
		Vin-Code	JF1GP7KC5CG-009077

Part Number	Part Code Name	Part Code	Q'ty	Price
57120FJ0509P	FENDER COMPLETE-FRONT, RIGHT ✓ DT	FIG-540 57110	1	198.00
60009FJ0019P	PANEL ASSEMBLY-FRONT DOOR, RIGHT ✓ DT	FIG-605 60010	1	648.00
61160FJ000TQ	HANDLE-DOOR, OUTER ✓ ent	FIG-607 61160E	1	43.20
90422FJ001	TAPE-FRONT DOOR, RIGHT ?	FIG-905 90422X	1	9.00
90422FJ021	TAPE-FRONT DOOR SASH, RIGHT ?	FIG-905 90422A	1	36.00
90422FJ041	TAPE-FRONT DOOR SASH, REAR RIGHT ?	FIG-905 90422E	1	23.40
61280FJ001	WEATHER STRIP-DOOR, OUTER RH ✓ NEC.	FIG-605 61280	1	126.00
61032FJ200	LATCH & ACTUATOR ASS EMBLY-FRONT, RIGHT ?	FIG-607 61176F	1	252.00
60409FJ000DP	RRH DOOR ✓ DT.	FIG-605 60010	1	648.00
90422FJ061	TAPE-REAR DOOR SASH, RIGHT ?	FIG-905 90422C	1	23.40
90422FJ081	TAPE-REAR DOOR SASH, CENTER RIGHT ?	FIG-905 90422G	1	27.00
90422FJ121	TAPE-REAR DOOR SASH, REAR RIGHT ?	FIG-905 90422I	1	9.00
62280FJ000	WEATHER STRIP-DOOR, REAR OUTER RIGHT ✓ NEC.	FIG-605 62280A	1	126.00
63511FJ000	WEATHER STRIP-FRONT DOOR, RIGHT ✓ NEC.	FIG-901 63511	1	119.00
63527FJ000	RUN CHANNEL-FRONT DOOR, RIGHT ✓ NEC.	FIG-901 61234A	1	90.00
63571VA000	WEATHER STRIP-BODY SIDE, FLANGE FRONT ✓ NEC.	FIG-901 63571B	1	90.00
		Page-Total		2,468.00

Memo

Grand Total
6,853.00

--

Tel

Estimate

Date 06/27/2017

002 / 003

Name	QUOTATION FOR SKH6710Y	Tel (Home)	
Address		Tel (Office)	
E-Mail		Tel (Portable)	
		Fax	
		Model Name	G33
		Body Model	GP7AKHC
		Vir-Code	JF1GP7KC5CG-009077

Part Number	Part Code Name	Part Code	Q'ty	Price
51439FJ0429P ✓	REAR QUARTER COMPLET ✓ Nec E-OUTER, RIGHT	FIG-522 51410	1	864.00
59122FJ001	MUD GUARD, REAR RIGHT R	FIG-541 59112	1	64.80
65209FJ000	GLASS-REAR QUARTER, R ? IGHT	FIG-652 65210A	1	504.00
65245FJ000	DAM RUBBER-REAR QUAR ? TER	FIG-652 65245	1	10.80
65277FJ000	SEAL-WINDOW REAR QUA ? RTER	FIG-652 65277A	1	4.70
63019FJ000	GLASS-REAR GATE X	FIG-621 63011	1	799.20
65245SC000	DAM RUBBER-REAR QUAR ? TER	FIG-621 65245	1	21.60
57704FJ041	BUMPER-FACE, REAR ✓ cut	FIG-591 57704A	1	594.00
57707FJ080	BRACKET-REAR BUMPER ✓ Nec CORNER, RIGHT	FIG-591 57707AC	1	28.80
57707FJ090	BRACKET-REAR BUMPER ✓ Nec CORNER, LEFT	FIG-591 57707AD	1	28.80
57707FJ160	BRACKET-REAR BUMPER ? SIDE, RIGHT	FIG-591 57707H	1	14.40
57707FJ170	BRACKET-REAR BUMPER ? SIDE, LEFT	FIG-591 57707I	1	14.40
57731FG010I6	COVER-REAR BUMPER ✓ Nec	FIG-591 57731C	1	14.40
57707FJ201	BRACKET-REAR BUMPER, ? LOWER	FIG-591 57707N	2	14.40
91112FJ101	GARNISH-FRONT FENDER ✓ cut , RIGHT	FIG-914 91111	1	180.00
91112FJ121	GARNISH-REAR QUARTER ✓ MS , RIGHT	FIG-914 91111D	1	180.00
		Page-Total		3,338.30

Memo

Grand Total
6,853.00

--

Tel

Estimate

Date 06/27/2017

003 / 003

Name	QUOTATION FOR SKH6710Y	Tel (Home)	
Address		Tel (Office)	
E-Mail		Tel (Portable)	
		Fax	
		Model Name	G33
		Body Model	GP7AKHC
		Vin-Code	JF1GP7KC5CG-009077

Part Number	Part Code Name	Part Code	Q'ty	Price
91112FJ141	GARNISH-SIDE SILL, RI <i>✓ w/</i> GHT	FIG-914 91111W	1	180.00
91036FJ284	DOOR MIRROR UNIT-RIG <i>✓ CRK</i> HT	FIG-912 91031N	1	576.00
91059AJ200	COVER-CAP OUT MIRROR <i>✓ MS</i> , RIGHT	FIG-912 91054D	1	64.80
84401AJ000	LAMP ASSEMBLY-SIDE T <i>✓ CRK</i> URN, MIRROR RIGHT	FIG-912 84401B	1	102.00
91054AJ221	COVER-CAP OUT MIRROR <i>✓ MS</i> , RIGHT LOWER	FIG-912 91054F	1	33.90
91039AJ121	MIRROR-REPAIR, RIGHT <i>?</i>	FIG-912 91039	1	90.00
		Page-Total		1,046.70
		Sub-Total		6,853.00
		Total Tax		6,853.00
		Grand Total		6,853.00

Memo

Grand Total
6,853.00

--

Tel

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0249/2017
DATE : 27-JUN-2017

ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
S(038985)
TEL : 6829 9199/200
FAX : 6829 9248/49
MOTOR CLAIM DEPT

OWNER'S NAME : LIM HAN CHEONG
ADDRESS : APT BLK 439C SENGKANG WEST AVENUE
#12-301
S(793439)
TELEPHONE NO : 97919757

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : D17MTPV01000813
VEHICLE NO : SKH6710Y
MODEL CODE : GP7AKHC
MODEL/YEAR : SUBARU XV 2.0I-S AWD CVT
ENGINE NO : FB20R321624
CHASSIS NO : JF1GP7KC5CG009077
MILEAGE : 160518 KM
DATE IN : 27/06/2017
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH ALI**
ACCIDENT DATE : 21/06/2017

Print Date : 24/05/2018
Print Time : 10:00:43

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKH6710Y

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	TO REPLACE/REPAIR FRT RHS DOOR, FRT RHS FENDER, RR DOOR, RR BUMPER.	5600.00	2240.00
2	ZZ/002	TO RESPRAY FRT RHS FENDER, FRT RHS DOOR, RR RHS DOOR, RR FENDER AND RR BUMPER.	2940.00	2100.00
3	ZZ/003	TRANSFER/BALANCE/RIM	100.00	50.00
4	ZZ/004	TRANSFER FRT RHS AND REAR RHS DOOR MECHANISM.	450.00	400.00
5	ZZ/005	WHEEL ALIGNMENT	250.00	200.00
6	ZZ/006	REMOVE & REFLX CARPET, SEAT TO FACILITATE REPAIRS.	450.00	400.00
7	ZZ/007	REMOVE & INSTALL REAR RHS QUATER GLASS.	230.00	180.00
8	ZZ/008	TO SUPPLY AND INSTALL REVERSE SENSOR 2 EYES	350.00	300.00
9	ZZ/009	TO SUPPLY & INSTALL REAR RHS QUATER GLASS TINTED FILM.	295.00	245.00
10	ZZ/011	TO SUPPLY AND INSTALL RR QUATER GARNISH, SIDE SILL GARNISH AND FRT RHS QUATER GARNISH	190.00	140.00
11	ZZ/012	INSTALL DRIVER SIDE MIRROR ASSY	120.00	70.00
12	ZZ/013	SUPPLY & INSTALL SPORTS RIMS @ \$600.00 AS APPROVED BY SURVEYOR	600.00	600.00 (A)
13	ZZ/014	SUPPLY 1 PC TYRE 225/50/R18	500.00	500.00 (A)
14	ZZ/10	SUNDRIES	150.00	100.00
TOTAL LABOUR CHARGES			12225.00	7525.00

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKH6710Y

S/NO PARTS DESCRIPTION		PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	PNL SD OUT QTR RP5RH	NEED 909400005 51439FJ0429P	864.00	✓		OK
2	FRONT RHS FENDER	57120FJ0509P	198.00	✓		OK
3	BUMPER FACE REAR XV	57704FJ041	594.00	✓		OK
4	BRKT RRH BUMP CORN	57707FJ080	28.80	✓		OK
5	BRKT RLH BUMP CORN	57707FJ090	28.80	✓		OK
6	COVER-REAR BUMPER	57731FG01016	14.40	✓		OK
7	PNL AY DR FRH	60009FJ0019P	648.00	✓		OK
8	PANEL ASSY-REAR DOOR RH WGN	60409FJ0009P	648.00	✓		OK
9	HANDLE OUT DR	61160FJ000TQ	43.20	✓		OK
10	WSTR OUT DR F RH	61280FJ001	126.00	✓		OK
11	WEATHER STRIP-DOOR, REAR OUTER RH	62280FJ000	126.00	✓		OK
12	WEATHER STRIP-FRONT DOOR RH	63511FJ000	119.00	✓		OK
13	RUN CHANNEL DR FRH	63527FJ000	90.00	✓		OK
14	WSTR BODY SD FLG F	63571VA000	90.00	✓		OK
15	LAMP ASSY-SIDE TURN MIRROR RH	84401AJ000	102.00	✓		OK
16	R VIEW MIR UNIT RH	91036FJ284	576.00	✓		OK
17	COVER MIR BODY RH	91054AJ221	33.90	✓		OK
18	COVER CAP REPAIR RH	COLOR-91054AJ200## 91059AJ200	64.80	✓		OK
19	GARNISH-FRONT FENDER RH (SUPP)	91112FJ101	180.00	✓	CUT	OK
20	GARNISH-REAR QUARTER RH	91112FJ121	180.00	✓		OK
21	GARNISH-SIDE SILL RH	USE FJ140 91112FJ141	180.00	✓		OK
SUB TOTAL			4934.90	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)			986.98	0.00	0.00	0.00
GRAND TOTAL			3947.92	0.00	0.00	0.00
OVERALL TOTAL			3947.92			

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIEL LIST FOR ACCIDENT VEHICLE REGN NO SKH6710Y

		DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER			
			NETT	LIST	S/NETT
					S/LIST REMARKS

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SKH6710Y

NETT ITEM 4934.90
LESS 20 % -986.98
NETT AMOUNT 3947.92

LIST ITEM 0.00
LESS 50 % 0.00
LIST AMOUNT 0.00

SPECIAL NETT AMOUNT 0.00

S/LIST ITEM 0.00
LESS 30 % 0.00
S/LIST AMOUNT 0.00

TOTAL LABOUR CHARGES 7525.00
TOTAL SPARE PARTS CHARGES 3947.92

TOTAL CHARGES 11472.92
ADD 7 % GST 803.10

GRAND TOTAL 12276.02



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD			Ref : CS/EGI17012437/Stbe2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985			Date : 16-07-2018	
			Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XE 1866B	Veh. Inspected	SKH 6710Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	DSMFP1701655	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	28/06/2017	
2. Vehicle Particulars & Condition				
Make & Model	SUBARU XV	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	JF1GP7KC5CG009077	Colour	WHITE	
Odometer	160518	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R18	MICHELIN	7 mm	
L/H Front Tyre	225/50 R18	MICHELIN	7 mm	
R/H Rear Tyre	225/50 R18	MICHELIN	7 mm	
L/H Rear Tyre	225/50 R18	MICHELIN	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/06/2017	Inspection Date	29/06/2017	
Survey held at	MOTOR IMAGE ENTERPRISES PTE LTD 19 TOA PAYOH LORONG 8 SINGAPORE 319255			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKH 6710Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	MIRROR-REPAIR, RIGHT	NOT NECESSARY	90.00	-
1	FENDER-COMPLETE-FRONT, RIGHT	DENTED	198.00	198.00
1	PANEL ASSEMBLY-FRONT DOOR, RIGHT	DENTED	648.00	648.00
1	HANDLE-DOOR, OUTER	CUT	43.20	43.20
1	TAPE-FRONT DOOR, RIGHT	NOT NECESSARY	9.00	-
1	TAPE-FRONT DOOR SASH RIGHT	NOT NECESSARY	36.00	-
1	TAPE-FRONT DOOR SASH, REAR RIGHT	NOT NECESSARY	23.40	-
1	WEATHER-STRIP-DOOR, OUT RH	NECESSARY	126.00	126.00
1	LATCH & ACTUATOR ASSEMBLY-FRONT, RIGHT	NOT NECESSARY	252.00	-
1	RRH DOOR	DENTED	648.00	648.00
1	TAPE-REAR DOOR SASH RIGHT	NOT NECESSARY	23.40	-
1	TAPE-REAR DOOR SASH, CENTER RIGHT	NOT NECESSARY	27.00	-
1	TAPE-REAR DOOR SASH, REAR RIGHT	NOT NECESSARY	9.00	-
1	WEATHER STRIP-DOOR, REAR OUTER RIGHT	NECESSARY	126.00	126.00
1	WEATHER STRIP-FRONT DOOR, RIGHT	NECESSARY	119.00	119.00
1	RUN CHANNEL-FRONT DOOR, RIGHT	NECESSARY	90.00	90.00
1	WEATHER STRIP-BODY SIDE, FLANGE FRONT	NECESSARY	90.00	90.00
1	REAR QUARTER COMPLETE-OUTER, RIGHT	NECESSARY	864.00	864.00
1	MUD GUARD, RIGHT RIGHT	TO REPAIR SEE LABOUR	64.80	-
1	GLASS-REAR QUARTER, RIGHT	NOT NECESSARY	504.00	-
1	DAM RUBBER-REAR QUARTER	NOT NECESSARY	10.80	-
1	SEAL-WINDOW REAR QUARTER	NOT NECESSARY	4.70	-
1	GLASS-REAR GATE	NOT NECESSARY	799.20	-
1	DAM RUBBER-REAR QUARTER	NOT NECESSARY	21.60	-
1	BUMPER-FACE, REAR	CUT	594.00	594.00
1	BRACKET-REAR BUMPER CORNER, RIGHT	NECESSARY	28.80	28.80
1	BRACKET, REAR BUMPER CORNER, LEFT	NECESSARY	28.80	28.80
1	BRACKET-REAR BUMPER SIDE, RIGHT	NOT NECESSARY	14.40	-
1	BRACKET-REAR BUMPER SIDE, LEFT	NOT NECESSARY	14.40	-
1	COVER-REAR BUMPER	NECESSARY	14.40	14.40

Report Ref No. CS/EGI17012437/Stbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	BRACKET-REAR BUMPER, LOWER	NOT NECESSARY	14.40	-
1	GARNISH-FRONT FENDER, RIGHT	CUT	180.00	180.00
1	GARNISH-REAR QUARTER, RIGHT	MISSING	180.00	180.00
1	GARNISH-SIDE SILL, RIGHT	CUT	180.00	180.00
1	DOOR MIRROR UNIT-RIGHT	CRACKED	576.00	576.00
1	COVER-CAP OUT MIRROR, RIGHT	MISSING	64.80	64.80
1	LAMP ASSEMBLY-SIDE TURN, MIRROR RIGHT	CRACKED	102.00	102.00
1	COVER-CAP OUT MIRROR, RIGHT LOWER	MISSING	33.90	33.90
	LESS 20% DISCOUNT		-	-986.98
			6,853.00	3,947.92
	<u>SPECIAL NETT ITEMS</u>			
1	SUNDRIES (SN)	NECESSARY	150.00	100.00
			150.00	100.00
	<u>LABOUR</u>			
	INSTALL DRIVER SIDE MIRROR ASSY.		120.00	70.00
	TO REPLACE / REPAIR FRT RHS DOOR, FRT RHS FENDER, RR DOOR, RR BUMPER. INCLUSIVE OF THE REPAIR OF MUD GUARD, RIGHT RIGHT.		5,600.00	2,240.00
	TO RESPRAY FRT RHS FENDER, FRT RHS DOOR, RR RHS DOOR, RR FENDER AND RR BUMPER.		2,940.00	2,100.00
	TRANSFER / BALANCE / RIM.		100.00	50.00
	TRANSFER FRT RHS AND REAR RHS DOOR MECHANISM.		450.00	400.00
	WHEEL ALIGNMENT.		250.00	200.00
	REMOVE & REFIX CARPET, SEAT TO FACILITATE REPAIRS.		450.00	400.00
	REMOVE & INSTALL REAR RHS QUATER GLASS.		230.00	180.00
	TO SUPPLY AND INSTALL REVERSE SENSOR 2 EYES.		350.00	300.00
	TO SUPPLY & INSTALL REAR RHS QUATER GLASS TINTED FILM.		295.00	245.00
	TO SUPPLY AND INSTALL RR QUATER GARNISH, SIDE SILL GARNISH AND FRT RHS QUATER GARNISH.		190.00	140.00
	SUPPLY & INSTALL SPORTS RIM @ \$600.00 AS APPROVED BY SURVEYOR. (ADDITIONAL)		600.00	600.00

Report Ref No. CS/EGI17012437/Stbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SUPPLY 1 PC TYRE 225/50/R18. (ADDITIONAL)		500.00	500.00
			12,075.00	7,425.00
	GRAND TOTAL		19,078.00	11,472.92
RECOMMENDED COST OF REPAIRS				11,472.92

Report Ref No. CS/EGI17012437/Stbe2

YEANG WAI KEEN

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.