

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKH6710Y

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	TO REPLACE/REPAIR FRT RHS DOOR, FRT RHS FENDER, RR DOOR, RR BUMPER.	5600.00	2240.00
2	ZZ/002	TO RESPRAY FRT RHS FENDER , FRT RHS DOOR, RR RHS DOOR, RR FENDER AND RR BUMPER.	2940.00	2100.00
3	ZZ/003	TRANSFER/BALANCE/RIM	100.00	50.00
4	ZZ/004	TRANSFER FRT RHS AND REAR RHS DOOR MECHANISM.	450.00	400.00
5	ZZ/005	WHEEL ALIGNMENT	250.00	200.00
6	ZZ/006	REMOVE & REFIX CARPET, SEAT TO FACILITATE REPAIRS.	450.00	400.00
7	ZZ/007	REMOVE & INSTALL REAR RHS QUATER GLASS.	230.00	180.00
8	ZZ/008	TO SUPPLY AND INSTALL REVERSE SENSOR 2 EYES	350.00	300.00
9	ZZ/009	TO SUPPLY & INSTALL REAR RHS QUATER GLASS TINTED FILM.	295.00	245.00
10	ZZ/011	TO SUPPLY AND INSTALL RR QUATER GARNISH ,SIDE SILL GARNISH AND FRT RHS QUATER GARNISH	190.00	140.00
11	ZZ/012	INSTALL DRIVER SIDE MIRROR ASSY	120.00	70.00
12	ZZ/013	SUPPLY & INSTALL SPORTS RIMS @ \$600.00 AS APPROVED BY SURVEYOR	600.00	600.00 (A)
13	ZZ/014	SUPPLY 1 PC TYRE 225/50/R18	500.00	500.00 (A)
14	ZZ/10	SUNDRIES	150.00	100.00
TOTAL LABOUR CHARGES			12225.00	7525.00