Surveyor : Gwarang	<u>ASSIGNMENT</u> (Of	fice)		
From (Person): Suhara	f FCL		Date/Time	29/6/2017 11-18a
Estimated Cost:	Bill to:			
OD /TP / WS/TP RES / OD RES / EVA /				_
To Inspect Vehicle No: SUC 2453		Insured	: 54C	1337
at Workshop m/s Chunn Mid	<u> </u>	Tel	<u> </u>	54 25119
of u Am't	TVA Park 2A A 03.	-19 Autopoint		
Policy No:	Claim	No:	DI 1	UU 6358MFC4
Sum Insured:	Ехо	ess:		
Make of Veh: (Client's Record)			D.O.A	2/6/2017
CA / REV / REP. / REV 24 HRS				dorsement:
Date/Time: Perso	n Contacted:	<u> </u>		
Date/Time Action/Instruction ()	Estimate			
SMC DUS 3C - CC; AIC	16.25253 Drl			DEA 16/2/201
Sicrsp- which	1763 116/12/02	-j		DUA 14/10/201
				<u> </u>

hd. REF: pct	
	GNMENT
From: Date: 28/6/14/17 Estimated Cost:	Veh No: GHC 2452 C Yr Regn: 11 Nov 2010 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxix Prime Mover /
OD (TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No: SIC2W3C	Make: Hyundoi Sonata c.c 1991 Colour Blue A/C: Insured/Std/NI/NA
at Workshop m/s Chuni Nitur	Colour 3/we A/C: Insured / Std / NI / NA
of	Sp.Reading 145/20 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: KMHET41VMA:A796216
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum insured: Excess:	Steering: Increer / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inforder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: (Nil) S/Rim / STD A/Rim or
	Tyre Size: F: 215/60 R/b
(Policy Condition)	R: !!
Remark: The veh had commenced its N/S O/S repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of hispection.	TOYO/YOKO OF MAXX 15
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent?: Yes or No	R/Bal. (mm R/Bal. mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. mm
Est. Repairs: 12 days Res.: Yes or No	D.O.A. D.O.I. 29-06-17
Lum Sum: % 3 Val.: Yes or No	Survey held at Si3c/m
CA / REV / REP. / 24 HRS Vehicle: IN / OUT	Des. of Damages (Frt / Rear) O/S / N/S / U/C / Rooftop or
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction 3/7/17 email pret to sithara.	
Pls chertippair war	Sin
RECEIVED 1 8 MAY 2019	1 An
Date/Time. File Pass to? : Preli. Report	Days Of Repair: 1⊅ 17¥ 15
	Resurvey No. of Trip: Survey Fee: 170 + 195
2) Add Fee	
	:Interview (\$) Photos (142
Report Format :	: Tech. Invs (\$) Others
Lump (\$1m / 1.B.l: (\$12,000)	:Weekend (\$)
•	Total 5/18 667



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

IRS	ST CAPITAL INSUF	RANCE LTD	Ref : CS/FCI170125	56/Ggh3
	OBINSON ROAD 01 CITY HOUSES	NGAPORE 068877	Date: 29-06-2017	
			Code: FCI2	
1.	en Santa Santa Sa	Policy Particu	lars :- THIRD PARTY CLA	Maria
	Insured Veh.	SHC 133P	Veh. Inspected	SHC 2453C
	Policy No.		Coverage (\$)	0.00
	Claim No.	D17006358MFSH	Excess (\$)	0.00
	Assign From	CWS (SITHARA)	Assign Date	29/06/2017
2.		Vehicle	Particulars & Condition	Fig Supplemental State (Sp. 1998)
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
3.		Co	onditions of Tyres	e de la companya de l
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4.	A THE RESERVE AND THE PROPERTY OF THE PARTY	Desc	cription of Damages	
5.	2000年 · 國內特別	A Section of the sect		
	Accident Date		Inspection Date	29/06/2017
	Survey held at	CHUNNI MOTOR WORK	PTE LTD	
		BLK 10 ANG MO KIO IND #03-19 AMK AUTOPOINT SINGAPORE 568047.	•	
	A TO SERVICE STORY	and the state of t	Remarks	

First Capital Insurance Limited

Company Reg. No. 195000106C GST Reg. No. M2-0001676-9

A FAIRFAX Company

MOTOR SURVEY ASSIGNMENT

Date

28-06-2017

Our Ref No. D17006358MFSH

Accident Date

25-06-2017

Claim Type. Third Party

Insured Vehicle

SHC0133P

Third Party Vehicle. SHC2453C

Survey Location

BLK 10 ANG MO KIO INDUSTRIAL PARK 2AAMK AUTOPOINT #03-19

Contact Person.

LYNN OR IRENE - 65421726

Contact No.

65427162/0

Fax No. 65426039

Survey Type

WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:

Appointed

Surveyor

LKK AUTO CONSULTANTS PTE LTD

Contact Person

NΑ

Fax No. 68416315

Contact Number.

NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc: Workshop

CHUNNI MOTOR WORK

Attention, NIL

Cc: TP Solicitor

NA

TP Solicitor Fax No. NA

Officer Incharge

SITHARA

PTE LTD

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Job Sheet (/	ClaimWS/Surveyor/JobSheet/	(224658) PI	RI Documents Close X		
			PRI Header Details		
Claim No	D17006358MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & CHUNNI I
Workshop Name	CHUNNI MOTOR WORK PTE LTD (Contact Person: LYNN OR IRENE - 65421726)	Survey Location & Contact Details	BLK 10 ANG MO KIO INDUS Mobile: 0 , Phone: 65427 EmailId: CHUNNIMOTOR@	162 , Fax: 65	
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE	ADMIT LIABII	LITY QUANTUM
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC0133P	TP Vehicle No	SHC2453C
PRI Recieved Date	28-06-2017 06:32:03 PM	Surveyor Appointed Date	29-06-2017 11:18:05 AM	Surveyor Accept Date	29-06-2017 1
			Survey Report Upload	<u> </u>	
Surveyor Inspection Date *:		Surveyor Report Date	29-06-2017	Upload Survey Report *:	Choose File
			Vehicle Particulars	·	<u> </u>
Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year •
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			
Multiple Do	ocuments Upload				,
		Upload Multiple	Documents		
File Nam	ie			Action	
Surveyor J	ob Remarks				
Remarks				Save	

Ai Phing (LKKAuto)

From:

Ai Phing (LKKAuto)

Sent:

Monday, 3 July, 2017 3:21 PM

To:

'Claim Workflow System'

Cc: Subject: SITHARA@FIRST-INSURANCE.COM.SG; SUR RE: SURVEY ASSESSMENT - D17006358MFSH/1

Attachments:

SHC 2453C.pdf

Dear Sithara,

Enclosed herewith preliminary advise of vehicle SHC 2453C.

Best Regards,

Ai Phing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Thursday, 29 June, 2017 11:48 AM

To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>

Cc: SITHARA@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D17006358MFSH/1

Dear Sir/Madam,

Thank you for the assignment.

Best Regards,

Ashley Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@first-insurance.com.sg]

Sent: Thursday, 29 June, 2017 11:18 AM To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; SITHARA@FIRST-INSURANCE.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D17006358MFSH/1

Dear Sir/Mdm,



Your Ref: D17006358MFSH

Date: 03-07-2017

Our Ref: CS/FCI17012556/Ggh3

The Motor Claims Department First Capital Insurance Ltd

Without Prejudice

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 2453C

Please be informed that we had conducted the inspection of the above mentioned vehicle on 29-06-2017 at the premises of M/s CHUNNI MOTOR and have the following to report:-

Workshop Estimate Amount	: <u>S\$</u>	27,926.34
Revised Estimate Amount	: <u>S\$</u>	8,697.82
"Check" Items Amount	: <u>S\$</u>	<u>11,746.48</u>
Market Value	: <u>S\$</u>	
LTA Reimbursement Value	: <u>S\$</u>	-
Nett Value	: <u>S\$</u>	<u> </u>

Description of Damage:

The vehicle sustained damages at the front and rear portion.



Yours faithfully

Xing Guo Qiang Automotive Assessor

Text size +

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

3821R

Vehicle Details

Vehicle No.:

SHC2453C

Vehicle to be Exported:

Intended De-registration

27 Jun 2017

Date:

HYUNDAI

Vehicle Make: Vehicle Model:

SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO

Primary Colour:

Manufacturing Year:

2010

Engine No.:

D4EAA905774

Chassis No.:

KMHET41VMAA796216

Maximum Power Output: 110.0 kW (147 bhp)

Open Market Value:

\$15,549.00

Original Registration Date:

11 Nov 2010

First Registration Date:

11 Nov 2010

Transfer Count:

0

Actual ARF Paid:

\$15,549.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

10 Nov 2018

PARF Rebate Amount:

\$10,106.00

Intended COE Rebate Details

COE Expiry Date:

10 Nov 2018

COE Category:

A - Car (1600cc & below)

COE Period(Years):

PQP Paid:

\$25,300.00

COE Rebate Amount:

\$4,338.00

Total Rebate Amount:

\$14,444.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 27 Jun 2017

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer. Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution Copyright © 2017 LTA | Privacy Statement | Terms of Use | Disclaimer | Rate the Website | Rate this e-Service Last updated on 24 Jun 2017 at 08:45 PM Estructed

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:

Vehicle Owner Particulars

Company

(0st of train = 57218.71

Owner ID:

3821R

ARF 65% = 10106.85

- 490.74

Vehicle Details

Vehicle No.:

SHC2453C

Vehicle to be Exported:

Degraction = (57218.71-10,101.85) 1. 96 mms

Intended De-registration

Date:

27 Jun 2017

Vehicle Make:

HYUNDAI

Vehicle Model:

SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO

Primary Colour:

Blue

Manufacturing Year:

2010

Bisk Volue = (440.74 x 17) + 1010685

Engine No.:

D4EAA905774

Chassis No.:

KMHET41VMAA796216

_ 18449.43

Maximum Power Output: 110.0 kW (147 bhp)

Open Market Value:

\$15,549,00

Med role = 18449.43-14444.60

=4K

Original Registration Date:

11 Nov 2010

First Registration Date:

11 Nov 2010

Transfer Count:

0

Actual ARF Paid:

\$15,549.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

10 Nov 2018

PARF Rebate Amount:

\$10,106.00

intended COE Rebate Details

COE Expiry Date:

10 Nov 2018

COE Category:

A - Car (1600cc & below)

COE Period(Years):

POP Paid:

\$25,300.00

COE Rebate Amount:

\$4,338.00

Total Rebate Amount:

\$14,444.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 27 Jun 2017

OK

Eand Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer. Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions. Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2017 LTA | Privacy Statement | Terms of Use | Disclaimer | Rate the Website | Rate this e-Service Last updated on 24 Jun 2017 at 08:45 PM 「五者が一方の光をある魔神はないといいか、からないないは、これをいく

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid.	
	ACCIDENT STATEMENT
Date Of Report	27/06/2017 14:52
Date Of Accident	25/06/2017 17:05
Exact Location Of Accident	PIE (CHANGI) B4 PAYA LEBAR EXIT
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE

SHC133P

Vehicle Registration Number

A Reference from

Insured/Policyholder

Name Of Registered Owner

CITYCAB PTE LTD

Co Reg No

199502839G

Email Address

FLEETSAFETY@CDGTAXI.COM.SG

Mobile Phone No

Alternative Phone No

OFFICE-65508768

Vehicle Particulars

Manufacturer

HYUNDAI

Model

SONATA-2.0 (A)

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No. Please state action to be taken

REPORTING ONLY

Vehicle Category

TAXI

Insurance Company

Name of Insurance Company

FIRST CAPITAL INSURANCE LTD

Type Of Coverage

THIRD PARTY FIRE AND/OR THEFT

Salata Salat

Fleet Policy

YES

Policy Number

D-15072702MFSH

Cover Note Number

Driver

Name of Driver

YOONG LIAN SING

NRIC No

S1051028G 08/04/1952

Date Of Birth Occupation

OUTDOOR

Date Of Driving Pass

07/12/1993

Driving Experience

23 YEARS AND 6 MONTHS

Gender

MALE

Mobile Number

Fax Number

Contact Number

EMail Address

YLIANSING_088@YAHOO.COM

Vehicle Registration Number

SLM119C

Vehicle Make/Model/Colour

MERCEDES

Details Of Properties

Name of Driver

UNKNOWN

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

FRONT AND REAR

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SKC6099E

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

UNKNOWN

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

REAR

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Describe Circumstances of the Accident

CITYCAB PTE LTD CO. REG. NO. 199502839G

Policyholder's Signature / Date &

Time

On. 25/6/2017 @ about 17:05 hrs. my tapi (A) was	
travelling along PIE (Changi) with A passengers. Before	
Paya Lebar exit, the front velocle (B) suddenly	
stopped. I could not stop in time and hit onto	
its rear. When checking the damage, then realized	<u></u>
Veh C x D was involved too. No injury at the	
point of accident.	
	_
	_
·	
	_
Declaration	
We declare the foregoing particulars are true in every respect.	

Driver's Signature (If driver is not the policyholder) / Date

Witnessed by Reporting Centre

Personnel

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT
Date Of Report	27/06/2017 13:38
Date Of Accident	25/06/2017 17:05
Exact Location Of Accident	PIE TWDS CHANGI AIRPORT B4 PAYA LEBAR RD EXIT
Country/State of Loss	SINGAPORE

[DE	ΤA	ILS	3 ()F	ow	N١	/EH	IC	E

Vehicle Registration Number

SHC2453C

Insured/Policyholder

Name Of Registered Owner

COMFORT TRANSPORTATION PTE LTD

199303821R

Co Reg No Email Address

FLEETSAFETY@CDGTAXI.COM.SG

Mobile Phone No

Alternative Phone No

OFFICE-65508768

Vehicle Particulars

Manufacturer HYUNDAI Model SONATA

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

TAXI

Insurance Company

Name of Insurance Company

INDIA INTERNATIONAL INSURANCE PTE LTD

Type Of Coverage

THIRD PARTY FIRE AND/OR THEFT

Fleet Policy

YES

Policy Number

MCOM0016

Cover Note Number

Driver

Name of Driver ANTHONY LEE CHYE CHONG

NRIC No S7323513H
Date Of Birth 14/06/1973
Occupation OUTDOOR
Date Of Driving Pass 04/11/1992

Driving Experience 24 YEARS AND 7 MONTHS

Gender MALE

Mobile Number

Fax Number

Contact Number

EMail Address

ASTARCAR@HOTMAIL.COM

Address

253 12-17 COMPASSVALE STREET

Postcode

540253

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - TAXI DRIVER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION- CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

Was any body injured in the Accident?

NO YES

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

4

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

POLICE STATION NAME [OTHER]

CHANGKAT NPP

Was notice of intended Prosecution given?

If Yes, against whom?

NO

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SHC133P

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

FRT

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Page 2 of 22

Vehicle Registration Number

SLM119G

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

CHIA KOK MENG

NRIC/Passport Number

S7328370A

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

FRT & REAR

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number Email Address

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SKC6099E

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

REAR

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF INJURED PERSON 1

ANTHONY LEE CHYE CHONG

Name

44

Approximate Age Injuries Sustain

NECK, BACK, SHOULDER, HEAD, LEGS

Injured person in which vehicle?

SHC2453C

Were seat belts worn?

YES

Was injured conveyed to hospital by ambulance?

NO

Address

Postcode

Refer to Police Report no: T/20170626/2038	
kortho accident I felt nain en my nock head shoulder lower DACK	and both
ter the accident,I felt pain on my neck,head,shoulder,lower back numb.I have been given 7 days MC.	
Idilibii ildec been given / days ii.e.	•
	-
	· · ·

policyholder's Signature/Date&Time

Driver's Signature(If driver is not the policyholder)

Date & Time 27/06/2017 @ 11:00 Hrs

Alice

Witnessed by Reporting

Centre Personnel

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful</u> and <u>accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that :

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims:
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to coffect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

COMFORT TRANSPORTATION PTE LTD CO. REG. NO. 199303821R

Policyholder's Signature / Date & Driver's S

Sketch Plan


Driver's Signature (If driver is not the policyholder) / Date & Time 27/06/2017 @ 11:00hrs

Witnessed by Reporting Centre

Alice

Refer To The Attachment

PIE TOWARD CHANGI ARPORT.



1.D-9KC-6099-E

2.C-SLM-119-9

- 3. A-SHC-2453-C

4.B-SHC-133-P.

COMFORT TRANSPORTATION PTE LTD CO. REG. NO. 199303821R Anthony Lee Chye Chong S 7323513 H 27/6/17





1 of 3 Report No. T/20170626/2038

Police Station Of Origin: Changkat NPP 109 Tampines Street 11 #01-261 SINGAPORE 521109 Tel No: 1800-7819999

REPORT OF A TRAFFIC ACCIDENT								
	NEMT	ACCI	EEIC	TDA	Α	OE.	COT	DED

Date/Time 26/06/2017	•	ade:	Vide Report No.:	Station Diary No.: 24
Pašaras s		and the state of t		
Name of In	formant:		Address:	
ANTHONY	LEE CH	YE CHONG	APT BLK 253 COMPASSVAL 540253	E STREET #12-17 SINGAPORE
ID Type / II	D No.:		Contact No.:	
NRIC NO /	S732351	3H -	Home/Office ⁻	Mobile: 98583613
Nationality: SINGAPOR		EN	Email:	
Sex:	Age:	Date of Birth:	Type of Informant:	
Male	44	14/06/1973	Driver	
Race:	•	•	Language:	Institution / School Name:
Chinese		•		
Occupation	1:		Driving Licence Information:	
Taxi driver			Class: 3	Date of Expiry:

Gianura gin osma				COMPANY STATES IN MALES TO THE WAY TO STAMME STATES
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 25/06/2017 17:05	Type of Location: Straight Road
Location: Along Road 1 PAN ISLAND EX				
	Airport direction before Pay		- 1	
Weather:	Roa	d Surface:	} F	Road Speed Limit:
Clear	Dry			
Traffic Flow:	Traff	ic Control:) T	raffic Volume:
Type of Collision: Between Moving	Vehicles - Head To Rear		, a	Anyone conveyed by ambulance:

Vagaraja		Naka.	MeYora		
SHC133P	Car			Slightly	0
		'		Damaged	
SHC2453C	Car			Slightly	3
				Damaged	
SKC6099E	Car			Slightly	0
				Damaged	
SLM119G	Car			Slightly	0
				Damaged	





2 of 3 Report No. T/20170626/2038

Police Station Of Origin: Changkat NPP 109 Tampines Street 11 #01-261 SINGAPORE 521109 Tel No: 1800-7819999

CONTINUATION OF REPORT

		and the second s	rangawa at ang kala Marangaya	The transfer that don't are the		en e
Any Pedestrian Ir			(5)		<u> </u>	: NIA
No. of Pedestrian	s Injured: NIL		Use of Ped	iestrian	Cross	ang: NA
Name	ANTHONY LEE CHY	E CHONG	and a second second second second	ID No.	· . · · · · · · · · · · · · · · · · · ·	S7323513H
Related Vehicle	SHC2453C (Car)	- -		Conta	ct No.	98583613
Hospital/Clinic	MOUNT ALVERNIA I	HOSPITAL		Class Driving Licence Expiry	g ce &	Class: 3 Date of Expiry: NIL
Date Treatment	26/06/2017		Date Discl	harge	26/06	6/2017
No. of Days gran	ted Medical Leave	07	Degree of	Injury	Sligh	t
Name	Chia Kok Meng			ID No		S7328370A
Related Vehicle	SLM119G (Car)			Conta	ct No.	NIL
Hospital/Clinic	NIL			Class Drivin Licent Expiry	g ce &	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Disc	harge	NIL	
	ted Medical Leave	NIL	Degree of	Injury	NIL	

Brief Details.

On 25/06/2017 at about 1705hrs, I was in my taxi - SHC2453C, with at least 3 other passengers who were heading to Bedok.

While we were on the first lane on PIE towards Changi Airport before Paya Lebar exit, we noticed that a vehicle ahead stopped, as such, I slowed down the vehicle and came down to a complete stop eventually.

Suddenly, I felt a bang from the rear of my vehicle by SHC133P, the nudge was too strong that it shifted my vehicle forward to the front car (SLM119G). All drivers involved alighted and we confirmed that no one needed any immediate medical attention. A total of 4 vehicles were involved in the accident, SKC6099E followed by SLM119G, then my vehicle and SHC133P.

Traffic police had also attended to the scene. We exchanged our particulars. I felt some aching from my neck to the head and also to my eyes ,lower back to both legs, and also my shoulder area. I see the doctor and was given 7 days MC.





3 of 3

Report No. T/20170626/2038

Police Station Of Origin: Changkat NPP 109 Tampines Street 11 #01-261 SINGAPORE 521109 Tel No: 1800-7819999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:	Signature Of Informant:
G / Staff Sgt TAN YI YI, JEAN	Kathuny
Signature Of Interpreter:	Date/Time:
Not applicable	26/06/2017 13:56
Officer In Charge Of Case:	Classification Of Case:
TP / GIT /	
SI YEO CHUN JIAN	
Contact No.: 65476213	
Authentication Stamp 5N	167
NP168 (表) (本語) () ()	

2,080.00

CHUNNI MOTOR WORK PTE LTD

To survey my les aglian ILLK

REPAIR ESTIMATE*

VEHICLE NO : SHC 2453C

MAKE

DATE: 27.06.2017

TEL: 6542 5119

FAX: 6542 6039 MODEL : HYUNDAI SONATA **FCI** Parts Description/ Labour **Unit Price** Amount Qιγ Type Radiator Grille 🖊 CHA 282.10 \$ Radiator Grille U Moulding / CAP \$ 108.90 Front Bumper Cover / 9C \$ 538.80 Front Bumper Sponge \$ 136.30 Front Bumper Reinforcement / \$ 504.10 Front Bumper Centre Grille 7 S 131.10 59.90 Front Bumper Lip 📈 Front Bumper Bracket Top (LH/RH) 🗶 S 22,40 \$ 44.80 Front Bumper Protector (LH/RH) / \$ \$ 58.40 29.20 Front Bumper Bracket (LH/RH) \$ 40.20 20.10 \$ S Front Bumper Side Bracket X 14.30 \$ 28.60 22.00 Front Bumper Clips 10 pcs / KC \$ Headlamp Support Panel Assy S 1,023.00 Headlamp (LH/RH) UH CA \$ 1,595.80 797.90 Radiator S 814.80 Radiator Fan Blade, Cowling, Motor Assy 7. \$ 651,30 Radiator Bracket \$ 6.20 \$ 12.40 Aircon Condenser \$ 1.089.90 Inter Cooler ? 771.50 \$ Inter Cooler Mounting (2 PCS) ? \$ 24.80 Wiring-ECM 7 3,107.80 \$ 11,046.50 **SUB TOTAL** LESS 20% 2,209.30 DISCOUNTED TOTAL 8,837.20 Front Number Plate / BT 25.00 | Nett Front No Plate Trim Cover / GA S 30.00 |Nett 55.00 Labour Charge 1,000.00 | 600 Panel Beating Spray Painting Charge \$ 200.00 Wiring Charge \$ 50.00 \$ 50.00 Towing Charge 100 S 150.00 Remove/Refix Aircon & Refill Gas Remove/Refix Dashboard \$ 450.00 Remove/Refix Fuse Box S 180.00

TOTAL LABOUR

Qty Parts Description/Labour Boot Lid / bul		, ,,	nit Price	1	Amount
12000.000	Type		Ide x 1300	\$	1,349.50
Boot Lid Rubber - Twi				\$	110.90
Boot Lid Rabbel 5 707				\$	132.10
Boot Lid Lock Lower - B7				S	30.30
Boot Lid Key Lock X ~~		ļ		s	78.20
Boot Lid Sonata Plate / ,		i		\$	43.60
Boot Lid Hyundai Plate				S	24.20
Boot Lid 'H' Emblem				\$	26.10
· · · · · · · · · · · · · · · · · · ·				\$	22.70
Boot Lid CRDI Plate Boot Lid Lamp (LH/RH) TA			220.20	l	
Boot Lid Lamp (LH/KH)		S	230.20	\$	460.40
Boot Lid Trimboard				\$	165.40
Boot Lid Trimboard Clips (11pcs) / MC				\$	11.00
Rear Bumper				\$	578.40
Rear Bumper Reinforcement				\$	483.30
Rear Bumper Clip		_		\$	22.00
Rear Bumper Bracket		S	49.00	\$	98.00
Rear Bumper Sponge ?				S	137.40
Rear Bumper Under Cover				S	185.80
Rear Bumper Protector (LH/RH) / Suk		S	38.00	S	76.00
Tail Lamp (LH/RH) / CFA		\$	344.00	S	688.00
Tail Lamp Quarter Panel (LH/RH) X NN		\$	93.80	\$	187.60
Rear Panel / huc				\$	391.80
Rear Panel Garnish CHA				S	95.80
Spare Tyre Holder				\$	27.60
Spare Tyre Panel ?				\$	863.00
Spare Tyre Panel Cushion 'l				S	200.30
Rear Towing Hook X NN		Ì		\$	135.30
Member Assy-Rear Floor Centre				S	163.60
Member Assy-Rear Floor Centre Panel Assy-Rear Floor Side (LH) Fisherst Bire Is subseq.		1		\$	88,55
Exhaust Pipe Insulator 7				\$	56.10
Exhaust Silencer 7				S	723.00
Exhaust Pipe Hanger				\$	56.10
Rear Fender (LH/RH) X Repair PH?		\$	1,935.90	\$	3,871.80
inear relider filler Limite (Linking)		S	74.10	\$	148.20
Rear Fender Corner Hardboard Cover (LH) X X X X X X X X X				\$	204.30
Rear Fender Air-Duct X WW				\$	49.40
Rear Fender Trim Board (LH/RH) / 1		\$	180.90	\$	361.80
Rear Windscreen Moulding × 5]		\$	60.00
Rear Wiring Assy				\$	1,458.00
SUB TOTAL				S	13,865.55
LESS 20%				s	2,773.11
DISCOUNTED TOTAL				\$	11,092.44
					•
Boot Lid Comfort Logo & Tel No. Sticker / #				S	30.00
Rear Bumper Reverse Sensor / MS				\$	135.70
Rear Bumper Rubber Mat \(\sum_{\text{U}} \)				S	50.00
Rear Fender Comfort Sticker (LH/RH)		S	30.00	S	60.00
Rear Windscreen Sealant &		"	24.44	S	46.00

SHC 2453C

Qty	Parts Description/ Labour	Туре	Unit Price	Amount	↓
	Labour Charge				1
	Panel Beating			\$ 2,600.00	180
	Spray Painting Charge	l l		\$ 1,600.00	
	Wiring Charge			\$ 100.00	2
	Tuff Kote			\$ 150.00	
	Rear Chassis Alignment Charge			\$ 400.00	
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00	٠,
	Remove/Refix Rear Windscreen Glass			\$ 120.00	1
	Remove/Refix Reverse Sensor	1		\$ 120.00	1 '
	Remove/Refix Fuel Tank			\$ 150.00	-
	Remove/Refix Exhaust Pipe			\$ 150.00	1 '
	Remover Carladat 1 pe			150.00	1 '
	TOTAL LABOUR			\$ 5,540.00	1
	TOTAL LABOUR			3 3,340.00	┨
	ESTIMATE TOTAL			\$ 27,926.34	1
	ESTEMATE TOTAL			3 27,920.34	=
		!			
	1000 a	1			
	10 Vous.				
	LIMAN SINA REPARTY.				
	(acceptant in a				
	After repair photos.				
	All for the]			
	Cource Giang - erfout 2			İ	
	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	0			
	10 Days. (umpsum Repair. After repair photos. Gene Giang - erfort 2 28/6/17	1) /			
	1 1	$\lfloor \neg . \rfloor$			
		<i>[50 1.</i>			
	\triangleright	{ ∕ /		}	
	LKK Auto Consultants hence notify	 			
	the Repairer of the following:	[]		1	
	 To resurvey before/after spray painting]	1
	 To display damaged part(s) during resurvey Parts prices are subject to confirmation 	1 1			1
	Third party survey is on a "Without Prejudice"	hasis			1
	 No illegal modification(s) is allowed 	1 1			
	 Supplementary item(s) must be resurveyed is subject to final approval from insurance C 	end			
		empany			
	Acknowledged by Repairer				
	Signature: Date:	[]			
	Cate.	└			
	l .	1 1		_1	1

CHUNNI MOTOR WORK PTE LTD	Po furkers by	Guo Wi

DATE : 27.06.2017 VEHICLENO: SHC 2453C TEL : 6542 5119

MAKE	:		100479113	wat		
MODEL	: HYUNDAI SONATA		: 6542 6039	FCI		
Qe	Pares Description/ Labour	Type	Unit Price	Amount	_	
——————————————————————————————————————	Radiator Grillo CH	}		\$ 282.10		
	Radiator Grille U Moulding - CPA	1	ļ	\$ 108.50		
	Front Bumper Cover - PC	1	ł	5 538.80		
· \	Front Bumper Sponge QVBA			S 136.30		
A, P	Front Bumper Reinforcement BT			\$ 504.10		
	Front Bumper Centre Grille V BR]		S 131.10	<u> </u>	
	Front Bumper Lip X HH			S 59.90	× .	
	Front Bumper Bracket Top (LH/REI) X HAL		S 22.40	S 44.80	×	
,	Front Bumper Protector (LH/RH)		5 29.20	5 58.40		
.9	Front Bumper Bricket (LHVRH) × HH	1	\$ 20.10	S 40.20	*	
	Enne Bromer Side Brocket X M. C	ł	S 14.30	\$ 28.60	×	
	Front Bumper Clips 10 pes - AC BR	ļ		S 22.00	-	
	Headlamp Support Panel Assy 2 1 BR	1		\$ 1,023.00	س	
	Headlamp (LH/RH) W OA PHR BRV	1	5 797.90	1	· ·	
	Radiator & But BT	1		S 814.80		
	Radiator Fan Blade, Cowling, Motor Assy	. }		\$ 651,30		
	Radiator Bracket HM		5 6.20		×	
	Aureon Condenser / Buc.			\$ 1,089,90	<u></u>	
723	Inter Cooler 2 V Buc	1	1	5 771.50	レ	
	inter Cooler Mounting (2 PCS) A HA	MAKO		\$ 24.80	× _	
- "al	Miles Cooler Mounting (21 Co)	3%	3.30km	\$ 3,107.80	×	
		1/6			_	
· ·	8 HA SUB TOTA	, j	7728.00 6182.40	\$ 11,046.50		
	LESS 205	1	1 1 100	\$ 2,209.30	1	
	DISCOUNTED TOTA	.1	1 (182.40	5 8,837.20	1	
ı	DASCOUNTED 101%	-].	, , , ,		1	
W			•			
<i>A</i> .	<u></u> ∰-				1	
1.	by severally BT	ł		S 25.00	Nea -	
•	Front Number Plate	.	1	•	Nett -	
	Front No Plate Trim Cover _ Cot		0.001	3 30,00	11.00	
			55	\$ 55.00	╣	
				3 33,00	-{	
			}	1		
				1		
	Labour Charge	1	1	\$ 1,000.00	Bec	
	Panel Beating	1		5 200,00		
	Spray Painting Charge	1		\$ 30 ,50,00		
	Wiring Charge	1	930/	S 50.00		
	Towing Charge	-	''	S 150.00	1 .	
	Remove/Refix Aircon & Refill Gas			1	1	
	Remove/Refix Dashboard	- L	M	عمومون والأ		
	Remove/Refix Fuse Box	1	H	K S 7180.00	1 20	
•				5 2 404 40	:	
	TOTALLABOU	URC		S 2,089.00	4	

LOYANG

#_.2/_3

29-06-17:09:42 ; Soon Hock Automotive

30-06-17;15:38

LOYANG

2/ 1C

2/ 9

-321.70

8-17;16:19 ; Chunni Motor Works Pte Ltd

Soon Hock

SHC 2453C Unit Price Jagront Type Parts Description/ Labour 1,349.50 r. Duc Boot Lid 110.90 Boot Lid Rubber - Tun Boot Lid Lock Upper > 0.7 2 132.10 2 30,30 Boot Lid Lock Lower - BT \$ 78.20 Book Lid Key Lock X ~~ S 43.60 Boot Lid Sonata Plate / S 24.20 Boot Lid Hyundal Plate 🖊 S 26.10 Boot Lid 'H' Emblem S 22.70 Boot Lid CRDI Plate Boot Lid Lamp (LH/RH) S 230.20 460,40 2 Book Lid Trimboard _ TN \$ 165.40 Boot Lid Trimboard Clips (11pcs) - MC \$ 11,00 £ 578,40 Rear Bumper / Cl Rear Bumpor Reinforcement S 483.30 \$ 22.00 Rear Bumper Clip / Rear Bumper Bracket 98.00 49.00 Rear Bumper Sponge 2/32 137.40 S 185.80 Rest Bumper Under Cover Rear Bumper Protector (LH/RH) / Sel 38,00 76.00 Tail Lamp (LH/RH) / CFA 344.00 688'00 Tail Lamp Quarter Panel (LH/RH) X NN 187,60 93.80 × 391.80 S Rear Panel / Buc Rear Panel Gamish - CHA S 95,80 Spare Tyre Holder 4 V Buc/BR 27,60 Spare Tyre Panel 7 / Buc 863.00 Spare Tyre Panel Cushion 40 200.30 X Rear Towing Hook 🗶 ៷ 135.30 Member Assy-Rear Floor Centre X (Repair. 163.60 Panel Assy-Rear Floor Side (LH) 88.55 Exhaust Pipe Insulator 🦪 🗸 56,10 Exhaust Siloncer TVDT 723,00 Exhaust Pipe Hanger 2 14 37 56.10 Rear Fonder (IHRHIH) X Repair PH \$ 1,935.50 \$ _3,371.30 Rear Fender Inner Lining (LHRH) \$ 148.20 74.10 Rear Fender Corner Hardboard Cover (LH) 🗴 🗥 \$ × 204.30 X NN \$ Rear Fender Air-Duct 49.40 Rear Fender Trim Board (LH/RH) 120.90 2. 361.80 Rear Windscreen Moulding 🗷 🕼 60.00 Rear Wiring Assy 🗶 📈 1,458.00 8998.60 S 13,865.55 SUB TOTAL 7198.88 s 2,773.11 LESS 20% \$ 11,092.44 DISCOUNTED TOTAL Boot Lid Comfort Logo & Tel No. Sticker / ACC 30.00 Nett 1 S Rear Bumper Reverso Sensor / M.S. S 135.70 Nett -Rest Bumper Rubber Mat / U \$ 50.00 Netr 🛩 Rear Fender Comfort Sticker (LH/RH) S 30.00 S 60,00 Nett 1 Rear Windscreen Sealant & BOV LLC S 46,00 Nett -321.20

Page 2.053

LOYANG

.. # _.3/ _ 3

29-06-17:09:42 | Soon Hock Automotive

LOYANG

3/10

6-17;16:19 ;Chunni Motor Works Pte Ltd Soon Hock

3/ 9

Party Description/ Labour	Турс	Unit Price	SHC 2453C
 Labour Charge			
Panel Bearing			\$ 2,600,00
Spray Painting Charge			\$ 1,600,00
, - · · · · · · · · · · · · · · · · · ·			
Wiring Charge			\$ 100.00
Tuff Kote			\$ 150.00
Rear Chassis Alignment Charge			\$ 400.00
Remove/Refix Cushion & Upholstery Rear			\$ 150.00
Remove/Refix Rear Windscreen Glass			580 120.00
Remove/Refix Reverse Sensor			
			\$ 120.00
Remove/Refix Fuel Tank		2310/	\$ 150,00
Remove/Refix Exhaust Pipe		2310/	\$ 150.00
TOTAL LABOUR			6 54000
TOTAL LABOUR			\$ 5,540.00
ESTIMATE TOTAL			\$ 27,926.34
12			16997.98
1000			1
18 Voys.			1/512100
lampson repair.			
After repair photos.		17/	
Charles Calk Dea			
12 10 Days. 1 umpsum Repair. After repair photos. Genc Giang - Erft our		10 cg	Ì
28/6/17			
			}
) (
1			1
]			1
This is an initial astimate based on a visual inspection of the	أمره مردعات	ت حادثاً	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internat	ionale Des Experts En Autom	oblie
FIRS	ST CAPITAL INSUI	RANCE LTD	Ref : CS/FCI1701255	56/Grbe2
	ROBINSON ROAD 01 CITY HOUSES	INGAPORE 068877	Date: 23-05-2018 Code: FCI2	
1.		Policy Particular	s :- THIRD PARTY CLAI	M de la
	Insured Veh.	SHC 133P	Veh. Inspected	SHC 2453C
	Policy No.	D-15072702MFSH	Coverage (\$)	0.00
	Claim No.	D17006358MFSH	Excess (\$)	0.00
	Assign From	SITHARA	Assign Date	29/06/2017
2.		Vehicle Par	ticulars & Condition	
	Make & Model	HYUNDAI SONATA	c.c	1991
	Engine No.	HIDDEN	Year of Reg.	2010
	Chassis No.	KMHET41VMAA796216	Colour	BLUE
	Odometer	145120	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3.		Condi	itions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	MAXXIS	6 mm
	L/H Front Tyre	215/60 R16	MAXXIS	6 mm
	R/H Rear Tyre	215/60 R16	MAXXIS	6 mm
	L/H Rear Tyre	215/60 R16	MAXXIS	6 mm
4.	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Descrip	tion of Damages	
	THE VEHICLE SU			N.
5.		Gener	al Information	
	Accident Date	25/06/2017	Inspection Date	29/06/2017
	Survey held at	CHUNNI MOTOR WORK PTE BLK 10 ANG MO KIO IND. PA		
-		#03-19 AMK AUTOPOINT SINGAPORE 568047.		
5a.∖	Amenia 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	50 15 15 15 15 15 15 15 15 15 15 15 15 15	Remarks	
	B)THE INSPECTION	ISISTENT TO ACCIDENT REPO ON WAS CONDUCTED ON A'W CE TO YOUR INSTRUCTIONS,	ITHOUT PREJUDICE" BAS	
		DECASE OF SHEET HAVE A COMPANY OF A SHEET HA	AND THE RESIDENCE OF THE PARTY	
5b.		Estimate	e Days of Repair	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 2453C

Qty		Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT	OF PARTS			
1	RADIATOR GRILL	E	CRACKED	282.10	282.10
1	RADIATOR GRILL	E U MOULDING	CRACKED	108.90	108.90
1	FRONT BUMPER	COVER	DEFORMED	538.80	538.80
1	FRONT BUMPER	SPONGE	BROKEN	136.30	136.30
1	FRONT BUMPER	REINFORCEMENT	BENT	504.10	504.10
1	FRONT BUMPER	CENTRE GRILLE	BROKEN	131.10	131.10
1	FRONT BUMPER	LIP	NOT NECESSARY	59.90	-
2	FRONT BUMPER	BRACKET TOP (LH/RH) @\$22.40	NOT NECESSARY	44.80	-
2	FRONT BUMPER	PROTECTOR (LH/RH) @\$29.20	NECESSARY	58.40	58.40
2	FRONT BUMPER	BRACKET (LH/RH) @\$20.10	NOT NECESSARY	40.20	-
2	FRONT BUMPER	SIDE BRACKET @\$14.30	NOT NECESSARY	28.60	-
10	FRONT BUMPER	CLIPS	NECESSARY	22.00	22.00
1	HEADLAMP SUPP	PORT PANEL ASSY	BROKEN	1,023.00	1,023.00
2	HEADLAMP (LH/R	H) @\$797.90	N/S CRACKED / O/S BROKEN	1,595.80	1,595.80
1	RADIATOR		BUCKLED / BENT	814.80	814.80
1	RADIATOR FAN B	LADE, COWLING MOTOR ASSY	BROKEN	651.30	651.30
2	RADIATOR BRAC	KET @\$6.20	NOT NECESSARY	12.40	-
1	AIRCON CONDEN	ISER	BUCKLED	1,089.90	1,089.90
1	INTER COOLER		BUCKLED	771.50	771.50
2	INTER COOLER M	OUNTING	NOT NECESSARY	24.80	-
1	WIRING - ECM		NOT NECESSARY	3,107.80	-
1	BOOT LID		BUCKLED	1,349.50	1,349.50
1	BOOT LID RUBBE	R	TWISTED	110.90	110.90
1	BOOT LID LOCK L	JPPER	BENT	132.10	132.10
1	BOOT LID LOCK L	.OWER	BENT	30.30	30.30
1	BOOT LID KEY LO	OCK	NOT NECESSARY	78.20	-
1	BOOT LID SONAT	A PLATE	NECESSARY	43.60	43.60
1	BOOT LID HYUND	AI PLATE	NECESSARY	24.20	24.20
1	BOOT LID 'H' EMB	ILEM	NECESSARY	26.10	26.10
1	BOOT LID CRDI P	LATE	NECESSARY	22.70	22.70



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By: Workshop (\$))	Out Adjusted (\$)
2	BOOT LID LAMP (LH/RH) @\$230.20	SCRATCHED	460.40	460.40
1	BOOT LID TRIMBOARD	TORN	165.40	165.40
11	BOOT LID TRIMBOARD CLIPS	NECESSARY	11.00	11.00
1	REAR BUMPER	DEFORMED	578.40	578.40
1	REAR BUMPER REINFORCEMENT	BROKEN	483.30	483.30
1	REAR BUMPER CLIP	NECESSARY	22.00	22.00
2	REAR BUMPER BRACKET @\$49.00	BROKEN	98.00	98.00
1	REAR BUMPER SPONGE	BROKEN	137.40	137.40
1	REAR BUMPER UNDER COVER	DEFORMED	185.80	185.80
2	REAR BUMPER PROTECTOR (LH/RH) @\$38.00	SCRATCHED	76.00	76.00
2	TAIL LAMP (LH/RH) @\$344.00	CRACKED	688.00	688.00
2	TAIL LAMP QUARTER PANEL (LH/RH) @\$93.80	NOT NECESSARY	187.60	-
1	REAR PANEL	BUCKLED	391.80	391.80
1	REAR PANEL GARNISH	CRACKED	95.80	95.80
1	SPARE TYRE HOLDER	BUCKLED / BROKEN	27.60	27.60
1	SPARE TYRE PANEL	BUCKLED	863.00	863.00
1	SPARE TYRE PANEL CUSHION	TORN	200.30	200.30
1	REAR TOWING HOOK	NOT NECESSARY	135.30	-
1	MEMBER ASSY - REAR FLOOR CENTRE	TO REPAIR SEE LABOUR	163.60	-
1	PANEL ASSY-REAR FLOOR SIDE (LH)	NOT NECESSARY	88.55	-
1	EXHAUST PIPE INSULATOR	BENT	56.10	56.10.
1	EXHAUST SILENCER	DENTED	723.00	723.00
1	EXHAUST PIPE HANGER	SERVICEABLE	56.10	-
2	REAR FENDER (LH/RH) @\$1935.90	O/S DENTED	3,871.80	1,935.90
2	REAR FENDER INNER LINING (LH/RH) @\$74.10	NOT NECESSARY	148.20	-
1	REAR FENDER CORNER HARDBOARD COVER (LH)	NOT NECESSARY	204.30	-
1	REAR FENDER AIR-DUCT	NOT NECESSARY	49.40	-
2	REAR FENDER TRIM BOARD (LH/RH) @\$180.90	SERVICEABLE	361.80	-
1	REAR WINDSCREEN MOULDING	NECESSARY	60.00	60.00
1	REAR WIRING ASSY	NOT NECESSARY	1,458.00	-



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

ty	Description of Parts	Condition	Estimate By Workshop (\$))	
	LESS 20% DISCOUNT		-4,982.41	-3,345.3
			19,929.64	13,381.2
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN)	BENT	25.00	25.
1	FRONT NO PLATE TRIM COVER (SN)	СИТ	30.00	30.
1	BOOT LID COMFORT LOGO & TEL NO. STICKER (SN)	NECESSARY	30.00	30.
1	REAR BUMPER REVERSE SENSOR (SN)	MISSING	135.70	135.
1	REAR BUMPER RUBBER MAT (SN)	DEFORMED	50.00	50.
2	REAR FENDER COMFORT STICKER (LH/RH) @\$30.00 (SN)	NECESSARY	60.00	60.
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.
			376.70	376.
	LABOUR			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF MEMBER ASSY - REAR FLOOR CENTRE.		3,600.00	1,400.
	SPRAY PAINTING CHARGE.		1,800.00	1,400.
	WIRING CHARGE.		150.00	50.
	TOWING CHARGE.	NOT NECESSARY	50.00	
	REMOVE / REFIX AIRCON & REFILL GAS.		150.00	100
	REMOVE / REFIX DASHBOARD.	NOT NECESSARY	450.00	
	REMOVE / REFIX FUSE BOX.	NOT NECESSARY	180.00	
	TUFF KOTE.		150.00	60
ļ	REAR CHASSIS ALIGNMENT CHARGE.	NOT NECESSARY	400.00	
	REMOVE / REFIX CUSHION & UPHOLSTERY REAR.		150.00	60
	REMOVE / REFIX REAR WINDSCREEN GLASS.		120.00	80.
	REMOVE / REFIX REVERSE SENSOR.		120.00	40.
	REMOVE / REFIX FUEL TANK.	NOT NECESSARY	150.00	
	REMOVE / REFIX EXHAUST PIPE.		150.00	50.
			7,620.00	3,240.
	GRAND TOTAL		27,926.34	16,997.





K

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.S.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES: This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. information provided must be as truthful.and.accurate.as.possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate.policy.liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that :

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

& Time

- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

CITYCAB PTE LTD CO. REG. NO. 1995028390

Policyholder's Signature / Date & Time

Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date

Witnessed by Reporting Centre Personnel Address

BLK 64 KALLANG BAHRU

#04-371

Postcode

330064

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - TAXI DRIVER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION- HEAD TO REAR (INSURED HIT TP)

on two care and an entry of the contract of th

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

Was any body injured in the Accident?

NO NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

5

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SHC2453C

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

UNKNOWN

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

FRONT AND REAR

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2