

10/20/2017

ASS. REC. BY:

REF: CS/CTU7012600/R1H302

Special Instruction:

Surveyor
Munir

Ressul

ASSIGNMENT (Office)

From (Person):

Cheng Boon sen

of

CT2

Date/Time 29/6/2017 2:38pm

Estimated Cost:

Bill to:

OD / TP / V / S / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SG68111R

Insured:

at Workshop m/s

Cheng Auto

Tel:

86667775

of

1 Sovn Lee of #06-41

Policy No:

DMPCSN 3017881705

Claim No:

SNM17003777C01

Sum Insured:

Excess:

TISA

Make of Veh:

D.O.A.

27/6/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

29/6/2017 2:50pm

Person Contacted:

munir

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SG68111R-CS2/ATA15002500/R1/3d1

D.O.A. 9/2/2015

Pending estimate, according to repairer. It's
supposed to be a wind screen claim.

Claims@chengauto.com

Rafael

REF:

7332A

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SGG 8111R*

at Workshop m/s *Chhach auto*

of *1, Sun Lee St*

Insured: *CTI/00*

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: *TBA*

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: *44,000*

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: *SGG 8111R* Yr Regn: *2009 / APR*

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *B.M.W 520 I A* c.c. *1995*

Colour: *BLUE* A/C: Insured / Std / NI / NA

Sp. Reading: *189761* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *WANT12046CX 29537*

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: *225/50R17*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. *6* mm R/Bal. *6* mm

L/Bal. *6* mm L/Bal. *6* mm

D.O.A. *27/06/17* D.O.I. *29/06/17*

Survey held at *Chhach auto*

Des. of Damages ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

lump sum \$2750, 4days. (Red: 7524.72:7370)

RECEIVED 23 MAY 2018

Date/Time, File Pass to?

1) *23/5 TYPBT*

Date/Time, File Return to?

2) _____

☐ : Preli. Report

☒ : Final Report

Days Of Repair: *4*

Resurvey No. of Trip: *1*

Survey Fee: _____

Transportation: _____

) S + RS SI

) Photos

) Others

TOTAL

Report Format : *00*

Lump Sum / I.B.I: (\$ *2750*)

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

200

200



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI17012600/R1th3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 29-06-2017		
		Code : CTI		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected	SGG 8111R	
Policy No.	DMPCSN3017881705	Coverage (\$)	0.00	
Claim No.	SNM17D03777C01	Excess (\$)	0.00	
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	29/06/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	27/06/2017	Inspection Date	29/06/2017	
Survey held at	CHENG AUTO BODYWORKS 1 SOON LEE STREET #06-41 PIONEER CENTRE SINGAPORE 627605			
5a. Remarks				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Jun 2017		29 Jun 2017 14:38 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TEIW GUAT CHOO, ID: S1777332A, Tel: +6590049947, Email: NOEMAIL		
Vehicle Reg. No.:	SGG8111R	Date of Loss:	27/06/2017 15:00 - :59
Claim Type:	OD / SNM17D03777C01	Policy/Cover Note No.:	DMPCSN3017881705 (Comprehensive)
		Excess:	S\$0.00
Repairer:	- Not Applicable - (-)		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 10/07/2017]		
Driver/Custodian:	TEIW GUAT CHOO (50 / Female), NRIC: S1777332A, Tel: +6590049947		
Adj Asg. Remarks:	SURVEY REVERT		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAUTO)

From: CLAIMS@CHENGAUTO.COM
Sent: Tuesday, 22 May 2018 3:43 PM
To: Denise Tay (LKKAUTO)
Subject: Re: RE: FW: SGG 8111R OD CHINA TAI PING

Dear Denise,

Claim REF .No. : SNM17D03777C01
CHENG AUTO ref. no. : TEIW GUAT CHOO / SGG8111R
Insured Name : TEIW GUAT CHOO
Policy Number : DMPCSN3017881705
Insurer/Policy Type : CHINA TAIPING INSURANCE / COMPREHENSIVE
Date of Loss : 27/6/2017
Our Vehicle No : SGG8111R
TP Vehicle No : Breakage of Windscreen

We refer to your offer.

We accept the offer S\$2,750.00 & 04 days.

Kindly make an offer in Merimen for our acceptance.

Thank you.

Thanks & Best Regards,
Claims Department



CHENG AUTO BODYWORKS

HP: 8666 7775 | Office-Tel: 6631 0707 | Fax: 6316 2431

Reporting Centre

Address: 5 Soon Lee Street #01-60 Pioneer Point, Singapore 627607

Email: claims@chengauto.com

Workshop

Address: 5 Soon Lee Street #01-62 Pioneer Point, Singapore 627607

Email: cab@chengauto.com

Windscreen

Address: 5 Soon Lee Street #01-41 Pioneer Point, Singapore 627607

Email: windscreen@chengauto.com

Spraypainting

Address: 1 Soon Lee Street #06-41 Pioneer Centre, Singapore 627605

Email: cab@chengauto.com

On 25/4/2018 4:44 PM, Denise Tay (LKKAUTO) wrote:

Dear Sir,

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 12 July, 2017 10:11 AM
To: claims@chengauto.com
Cc: SUR
Subject: SGG 8111R OD CHINA TAI PING
Attachments: index.pdf

Dear Sir,

As spoken, enclosed estimate

As instructed by our client, please proceed to repair the insured vehicle **SGG 8111R (Excess \$TBA/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

SGG8111R (SNM17D03777C01)

OD

Jun 27 2017 3:00PM

[TEIW GUAT CHOO]

Cheng Auto Bodyworks

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 11/07/2017 17:42 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$3700.00) - SGG8111R - Claim Handler: Chong Boon Sen

Approved:3700.00:PLEASE PROCEED TO AUTHORIZE REPAIR.

DOCUMENTS SUMMARY

There are no documents.



**SINGAPORE
POLICE FORCE**



T/20170627/2116

1 of 3

Report No. T/20170627/2116

Police Station Of Origin:
Bukit Panjang South NPP
124 Pending Road #01-00 SINGAPORE
670124
Tel No: 1800-7609999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 27/06/2017 16:43	Vide Report No.: j/20170627/0141	Station Diary No.: 34
--	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: TEIW GUAT CHOO			Address: APT BLK 731 JURONG WEST STREET 72 #09-19 SINGAPORE 640731		
ID Type / ID No.: NRIC NO / S1777332A			Contact No.: Home/Office: Mobile: 90049947		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 50	Date of Birth: 01/11/1966	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Real estate agent			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 27/06/2017 15:10	Type of Location: Straight Road
Location: Along Road 1 PENDING ROAD				
Pending Road towards Bukit Panjang Ring Road right lane Lamp Post Number: 5				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume:
Type of Collision: Moving Vehicle Against - Pedestrian				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGG811R	Car				Slightly Damaged	0



**SINGAPORE
POLICE FORCE**



T/20170627/2116

Police Station Of Origin:
Bukit Panjang South NPP
124 Pending Road #01-00 SINGAPORE
670124
Tel No: 1800-7609999

2 of 3

Report No. T/20170627/2116

CONTINUATION OF REPORT

Brief Details.

On 27/06/2017 at about 1510, I was driving my vehicle SGG8111R along Pending Road towards Bukit Panjang Ring Road right lane. I could not remember the traffic light was what color. Suddenly, I felt an impact at the front portion of my vehicle. I then realized hit onto a pedestrian who was crossing the road. I immediately got off and render assistance to the said pedestrian. I also called the police at 1513hrs.

Subsequently police and ambulance came to the scene. The Traffic police advised to me lodge a police report. The pedestrian was conveyed to hospital. There is no in car camera installed inside my vehicle.



SINGAPORE
POLICE FORCE



T/20170627/2116

3 of 3

Police Station Of Origin:
Bukit Panjang South NPP
124 Pending Road #01-00 SINGAPORE
670124
Tel No: 1800-7609999

Report No. T/20170627/2116

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

Sgt QUEK JUN CAI

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Sr Staff Sgt MOHAMMAD ABDILLAH BIN PALIL

Contact No.: 65476246

Authentication Stamp

NP168

Singapore Police Force

Signature Of Informant:

Date/Time:

27/06/2017 16:43

Classification Of Case:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/06/2017 16:17
Date Of Accident	27/06/2017 15:10
Exact Location Of Accident	ALONG PENDING ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGG8111R
Insured/Policyholder	
Name Of Registered Owner	TEIW GUAT CHOO
NRIC No	S1777332A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90049947
Alternative Phone No	OFFICE-90049947

Vehicle Particulars

Manufacturer	BMW
Model	520i-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3017881705
Cover Note Number	

Driver

Name of Driver	TEIW GUAT CHOO
NRIC No	S1777332A
Date Of Birth	01/11/1966
Occupation	INDOOR
Date Of Driving Pass	13/11/2001
Driving Experience	15 YEARS AND 7 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-90049947
Fax Number	
Contact Number	OFFICE-90049947
Email Address	NOEMAIL

Address
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured. OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 Vehicle -
 Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLIDED INTO PEDESTRAIN
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? YES
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name BUKIT PANJANG SOUTH NEIGHBOURHOOD POLICE POST
 Police Station Address ROAD: BLK 124 PENDING ROAD , POSTCODE: 670124 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-7609999 - FAX NO: 67636614
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number PEDESTRAIN
 Vehicle Make/Model/Colour
 Details Of Properties
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number
 Email Address

DETAILS OF INJURED PERSON 1

Name

Approximate Age

Injuries Sustain

Injured person in which vehicle?

PEDESTRAIN

Were seat belts worn?

Was injured conveyed to hospital by ambulance?

Address

Postcode

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in the accident (all insurer(s) who have insured vehicle(s) involved in the accident shall be collectively referred to as the "Insurers"), the Insurers' law firms/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law firms/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law firms/law firms) which may be based outside of Singapore, for one or more of the above Purposes.

x 

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

Sketch Plan



I/we declare the foregoing particulars are true in every respect.

- Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Certificate of Insurance



中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Cat. Reg. No. 203203940

Model
K 5M
AN64334
Cov. Type: C

MOTOR PRIVATE CAR

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 158)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1980
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1958 (Malaysia)

ORIGINAL

CERTIFICATE No.	00000000000000000000	Engine No. J02015504662086
		Chassis No. J02015504662086
1. Motor Mark and Registration Name of vehicle	SUGR1128	ANTOSAFE
2. Name of Policyholder	MR TETU GUAT CHOO	
3. Effective date of the Commencement of insurance for the purposes of the Registration Certificate of Endowment	20 April 2017	Named Driver's Ex Sect. 1 \$5750.00 Additional Ex Other than Named Drivers: Ex Sect. 1 - Age < 25 \$11,000.00 Ex Sect. 1 - Age > 25 \$1500.00 " Age as at date of accident Ex ON WINDSCREEN \$1100.00
4. Date of Expiry of Insurance	19 April 2018	
5. Persons or Classes of Persons entitled to drive?		
(a) The Policyholder.		
(b) Any other person who is driving on the Policyholder's order or with his permission.		
Provided that the person driving is permitted in accordance with the licensing or other law or regulations to drive the motor vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the motor vehicle.		
6. Limitations on use?		
Use for social, domestic and pleasure purposes and for the Policyholder's business. The policy does not cover use for hire or reward tuition driving test racing pace-making, reliability trial, speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the motor trade.		
Excess whichever is applicable for losses occurring outside Singapore (Constructive total loss/theft) will be doubled.		
One time waiver of Excess for the first \$11,000 will apply to the insured and named drivers in the event of one Damage Claim at our Authorized workshops for each Policy Year.		
NOTE: PURCHASE CO. : UNITED OVERSEAS BANK LIMITED AS HP OWNER "Limitations provided irrespective by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 158) and Section 95 of the Road Transport Act 1987 (Malaysia), are not to be included under these headings"		

I/We hereby Certify that the policy in which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 158) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please see reverse



Issued By: YETTA LIM (SINGAPORE) PTE. LTD.
Authorized Signatory

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

[Signature]
Authorized Signatory

3 Anson Road #16-00 Springhill Tower Singapore 079906 Tel: 6349-6111 Fax: 6226-3602 Website: www.tp.cntaiiping.com

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 7332A

Vehicle Details

Vehicle No.: SGG8111R

Vehicle to be Exported: No

Intended De-registration Date: 30 Jun 2017

Vehicle Make: B.M.W.

Vehicle Model: 520I AUTO ABS AIRBAG 2WD XENON HEADLAMP

Primary Colour: Blue

Manufacturing Year: 2008

Engine No.: A020I354N46B20BE

Chassis No.: WBANT12040CX29937

Maximum Power Output: 115.0 kW (154 bhp)

Open Market Value: \$47,727.00

Original Registration Date: 20 Apr 2009

First Registration Date: 20 Apr 2009

Transfer Count: 0

Actual ARF Paid: \$47,727.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 19 Apr 2019

PARF Rebate Amount: \$26,249.00

Intended COE Rebate Details

COE Expiry Date: 19 Apr 2019

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$7,326.00

COE Rebate Amount: \$1,320.00

Total Rebate Amount: \$27,569.00

The information contained herein is correct as at 30 Jun 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

Last updated on 24 Jun 2017 at 08:45 PM

Cheng Auto Bodyworks (Co.Reg.No:53315238X)1 Soon Lee Street, #06-41, Pioneer Centre
Singapore 627605

Tel: 6631 0707 Fax: 6316 2431 Email: chengauto@tlsgroup.com.sg

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type: OD (OWN DAMAGE)
Policy No: DMPCSN3017881705
Vehicle Reg. No.: SGG8111R
Driver Age/Info: 50 / FEMALE
TP Injury Involved? YES
Insured/Claimant: TEIW GUAT CHOO
Driver: TEIW GUAT CHOO

Ref. No:
Date of Loss: 27/06/2017
Driveable?
Party At Fault: UNKNOWN
Third Party Involved? YES
Contact No: +6590049947

Make/Model: BMW 520I, 2.0 (A)
Vehicle Colour: BLUE
Engine No: A020I354N46B20BE
Odometer: 10000 KM

Vehicle Reg. Date: 20/04/2009
Chassis No: WBANT12040CX29937

Paint Type:
Total Loss? NO
Est. Duration of Repair (day) 7

Present Location: CHENG AUTO BODYWORKS (HQ)

COST OF CLAIMS

	Amount
Parts	8,685.50
Miscellaneous Items	564.90
Labour	1,024.32
Paintwork Labour	0.00
Towing	0.00

Nett Amount (S\$) 10,274.72

This claim is handled by: MURUGESAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Jun 2017)
 Parts: 143 BMW 520i 2.0 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)

Print Code: Cheng Auto Bodyworks/SGG8111R/30/06/2017 18:14

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*AIR GUIDE TRIM	0.00	0.00	*140.00 F XSVL
2	1	NA	*BONNET	0.00	0.00	*1,500.00 F VBT
3	1	NA	*BONNET SPRING	0.00	0.00	*40.00 F XSVL
4	1	NA	*FRONT BUMPER COVER	0.00	0.00	*900.00 F XSVL
5	1	NA	*FRONT BUMPER SUPPORT	0.00	0.00	*450.00 F XSVL
6	1	NA	*FRT BUMPER GRILLE	0.00	0.00	*55.00 F XSVL
7	1	NA	*FRT BUMPER MNTG KIT	0.00	0.00	*15.00 F XSVL
8	1	NA	*GRILLE BADGE	0.00	0.00	*65.00 F XSVL
9	1	NA	*L/BONNET HINGE	0.00	0.00	*75.00 F XSVL
10	1	NA	*L/F BONNET STRUT	0.00	0.00	*60.00 F XSVL
11	1	NA	*L/F BUMPER BRACKET	0.00	0.00	*25.00 F XSVL
12	1	NA	*L/F GRILLE	0.00	0.00	*120.00 F XSVL
13	1	NA	*L/F WIPER ARM	0.00	0.00	*80.00 F XSVL
14	1	NA	*LEFT HEADLAMP ASSY	0.00	0.00	*1,250.00 F XSVL
15	1	NA	*R/BONNET HINGE	0.00	0.00	*75.00 F XSVL
16	1	NA	*R/BONNET LOCK	0.00	0.00	*120.00 F XSVL
17	1	NA	*R/F BONNET STRUT	0.00	0.00	*60.00 F XSVL
18	1	NA	*R/F BUMPER BRACKET	0.00	0.00	*25.00 F XSVL
19	1	NA	*R/F GRILLE	0.00	0.00	*120.00 F XSVL
20	1	NA	*R/F WING	0.00	0.00	*400.00 F XSVL
21	1	NA	*R/F WIPER ARM	0.00	0.00	*180.00 F XSVL
22	1	NA	*R/FRONT SCREEN MLDG	0.00	0.00	*35.00 F XSVL
23	1	NA	*RAIN-LIGHT SENSOR	0.00	0.00	*90.00 F XSVL
24	1	NA	*RIGHT HEADLAMP ASSY	0.00	0.00	*1,250.00 F XSVL
25	1	NA	*SOUND INSULATION	0.00	0.00	*190.00 F XSVL
26	1	NA	*SPECIALIST AUDATEX FEES	0	0.00	*42.00 FS V
27	1	NA	*SPECIALIST FRT NO. PLATE	0	0.00	*45.00 FS VBT
28	1	NA	*SPECIALIST WINDSCREEN SEALANT	0	0.00	*25.00 FS VBT
29	1	NA	*SUNDRY PARTS	0	0.00	*100.00 FS VBT
30	1	NA	*WINDSCREEN	0.00	0.00	*750.00 F VBT

F=Franchise part, S=SpaNett.

Sub Total (\$\$)	8,282.00
+ Margin on L,N Items 5.00% (\$\$)	403.50
Total Parts (\$\$)	8,685.50

Cheng Auto Bodyworks/SGG8111R/30/06/2017 18:14. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

REPAIR DETAILS**Reference**

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 28 Dec 2017)
Parts: 143 **BMW 520i 2.0 (A)** (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Cheng Auto Bodyworks/SGG8111R/28/12/2017 09:38
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Windscreen Bond Kit	0.00	0.00	131.85 - net
2	1		*Cleaner R1 frt scrn	0.00	0.00	47.25 - net
3	10		*Front screen clip	0.00	0.00	16.50 - net
4	1		*Info label airbag	0.00	0.00	23.25 x SVC
5	4		*Windscreen buffer	0.00	0.00	6.40 ✓ net
6	2		*Windscreen buffer	0.00	0.00	2.90 ✓ net
7	1		*Front screen cover	0.00	0.00	39.35 x SVC
8	1		*Lwr windscreen seal	0.00	0.00	82.80 ✓ net
9	1		*Anti-misting sensor	0.00	0.00	224.75 x SVC
Sub Total (\$\$)						0.00
+ Margin on L,N Items 5.00% (\$\$)						0.00
Total Parts (\$\$)						0.00

Cheng Auto Bodyworks/SGG8111R/28/12/2017 09:38. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 GST 7%

564.90

Sub Total (S\$)

564.90

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 Total Paint Labour

New

317.40

2 Total Paint Materials

New

223.92

3 Total Panel/Mechanical Labour

New

483.00

Gross Labour Cost (S\$)

1,024.32

Cheng Auto Bodyworks/SGG8111R/30/06/2017 18:14. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

**CHINA TAIPING
INSURANCE (S) PTE LTD
3 ANSON ROAD
#15-02 SPRINGLEAF
TOWER**

079909

**Claim Reference: SNM17D03777C01
Assessment Number: GR000070
Version: CHENGABS/1
Date Calculated: 04/07/2017 04:25**

**Full Report - V1
Registration: SGG8111R
Printed: 04/07/2017 11:29**

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Mr K.K Lau	Date of Incident:	27/06/2017
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:	SNM17D03777C01	Estimated Repair Time:	
Policy Number:	DMPCSN3017881705	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	BMW
Model:	5 Series
Sub Model:	520 I
Model Sheet Number:	145 01
Registration:	SGG8111R
Registration Month:	
Registration Year:	
VIN Number:	WBANT12040CX29937
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

Model Specs

FROM 11/2008	AIR CON AUTOMATIC
DIP/FOLD MIRROR	RADIO BUSINESS CD
XENON HEADLAMPS	HEADLAMP WASHERS
DAKOTA LEATHER TRIM	ELEC/SEAT ADJ MEMORY
FRT/RR DRINK HOLDER	TRIM POPLAR WOOD
DIP REAR VIEW MIRROR	2.0 LTR 125 KW
6-SPEED AUTOMATIC	TYRES 225/55 WR 16
WHEELS 7J X 16 ALLOY	4-DOOR
PARK DISTANCE CONT	CHROME LINE
SPEED CRUISE ONTROL	TWO COAT METALLIC

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	30/06/2017
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:	Tread Depth RHF:	
Tread Depth LHF:	Tread Depth RHR:	
Tread Depth LHR:	Direction of Impact:	
Damage Areas:		

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: SNM17D03777C01

Assessment Number: GR000070



Version: CHENGABS/1

Date Calculated: 04/07/2017 04:25

Full Report - V1

Registration: SGG8111R

Printed: 04/07/2017 11:29

**Addresses****Cost Summary**

Total Labour	\$800.40
Total Paint/Material	\$223.92
Total Parts	\$9,176.99
Total of Additional Costs	\$112.00
Excess:	TBA
Grand Total Exc GST:	\$10,313.31
0 % GST:	\$0.00
Grand Total Inc GST:	\$10,313.31

Repair Information**LABOUR**

Time Basis 12 WU = 1 HR. Price/CL 1 = \$46.00/HR
Price/Dent = \$46.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
41 35 000)	R + R R/F WING INCLUDES: R + R BUMPER, INDICATOR AND WHEELHOUSE COVER DOES NOT INCLUDE: R + R SILL MOULDING	17.0	65.17
51 23 600	R + R RIGHT BONNET LOCK	3.0	11.50
51 11 551	R + R FRONT BUMPER CARRIER	3.0	11.50
51 11 592	RENEW FRONT BUMPER COVER (FRONT BUMPER REMOVED)	9.0	34.50
61 67 802	HEADLIGHT WASHER UNIT - SUPPLEMENTARY OPERATION INCLUDES: REMOVE/REFIT WASHER NOZZLES	5.0	19.17
66 20 610	ADD/WORK PARK DISTANCE CONTROL	4.0	15.33
51 11 701	RENEW L/F BUMPER BRACKET (REMOVED)	1.0	3.83
51 11 701	RENEW R/F BUMPER BRACKET (REMOVED)	1.0	3.83
63 12 826)	R + R BOTH HEADLAMPS	8.0	30.67
63 12 524	RENEW L/HEADLAMP (REMOVED)	3.0	11.50
63 12 524	RENEW R/HEADLAMP (REMOVED)	3.0	11.50
41 61 600	R + R BONNET	4.0	15.33
41 61 501	REPLACE BONNET (WITH BONNET REMOVED)	6.0	23.00
51 23 504)	ADJUST BONNET LOCK	2.0	7.67
41 61 545)	RENEW L/BONNET HINGE	1.0	3.83
41 61 545)	RENEW R/BONNET HINGE	1.0	3.83
41 61 544)	RENEW BONNET HINGE (ADD/WORK)	1.0	3.83
61 61 602)	RENEW L/WIPER ARM (REMOVED)	1.0	3.83
61 61 602)	RENEW R/WIPER ARM (REMOVED)	1.0	3.83

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: SNM17D03777C01
 Assessment Number: GR000070
 Version: CHENGABS/1
 Date Calculated: 04/07/2017 04:25

Full Report - V1
 Registration: SGG8111R
 Printed: 04/07/2017 11:29

51 31 511	RENEW WINDSCREEN	39.0	149.50
64 11 971	ADD/WORK FOR FITTING SENSOR	1.0	3.83
61 35 996	ADD/WORK FOR RAIN-/LIGHT SENSOR	5.0	19.17
51 71 947	R + R RIGHT SILL RAIL	7.0	26.83
LABOUR COST		126.0	
Total Work Units		0.0HRS	0.00
Corrosion Protection External Labour		0.0HRS	0.00
Corrosion Protection Internal Labour		10.5HRS	\$483.00
Sub Total		6.9HRS	\$317.40
Paint Labour		17.4HRS	\$800.40
Total Labour			

NOTE TIME BASIS = 12 WU / HOUR

Time Basis 10 WU = 1 HR. Price = \$46.00/HR
 WU Cost Price (\$)

PAINT WORK			
Guide Number	Description		
	- SPEED CRUISE ONTROL		
	- TWO COAT METALLIC		
471	BONNET NEW PART PAINTING	31.0	
742	R/F WING NEW PART PAINTING	10.0	
283	FRONT BUMPER NEW PART PAINT K1R	14.0	
LABOUR COST - PAINT		55.0	
TIME(PAINT)		9.0	
Preparation Main Work Metal		5.0	
Preparation Comp. Work Plastic		0.0	
Preparation Work Multi Layer Paint		69.0	
Total Work Units (10WU/HR)		6.9HRS	\$317.40
Total Paintwork Labour			Cost Price
MATERIAL COST - PAINT			\$127.45
New Part Painting			\$69.37
New Part Painting - Plastic K1R			\$18.10
Material-Const Main Work Metal			\$9.00
Material-Const Comp. Work Plastic			\$223.92
Total Excluding Pearlescent Uplift			\$0.00
Pearlescent Uplift @ 0.0%			\$223.92
Total Paint Material Cost			

PARTS

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
283	1	FRONT BUMPER COVER	51 11 7 178 079		0%	900.00*
303	1	FRT BUMPER GRILLE	51 11 7 178 115		0%	55.00*
317	1	L/F BUMPER BRACKET	51 11 7 178 077		0%	25.00*
318	1	R/F BUMPER BRACKET	51 11 7 178 078		0%	25.00*
336	1	FRONT BUMPER SUPPORT	51 11 7 178 080		0%	450.00*
351	1	FRT BUMPER MNTG KIT	USE SINGLE PARTS		0%	15.00*
415	1	L/F GRILLE	51 13 7 027 061		0%	120.00*
416	1	R/F GRILLE	51 13 7 027 062		0%	120.00*
431	1	GRILLE BADGE	51 14 8 132 375		0%	65.00*
471	1	BONNET	41 61 7 111 385		0%	1,500.00*
475	1	L/BONNET HINGE	41 61 7 120 275		0%	75.00*
476	1	R/BONNET HINGE	41 61 7 120 276		0%	75.00*
481	1	SOUND INSULATION	51 48 7 148 208		0%	190.00*
497	1	L/F BONNET STRUT	51 23 7 008 745		0%	60.00*

Price Valid: 01/06/2017

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: SNM17D03777C01

Assessment Number: GR000070

Version: CHENGABS/1

Date Calculated: 04/07/2017 04:25

Full Report - V1

Registration: SGG8111R

Printed: 04/07/2017 11:29

498	1	R/F BONNET STRUT	51 23 7 008 745	0%	60.00*	X
504	1	R/BONNET LOCK	51 23 7 008 755	0%	120.00*	X
561	1	LEFT HEADLAMP ASSY	63 12 7 177 753	0%	1,250.00*	X
562	1	RIGHT HEADLAMP ASSY	63 12 7 177 754	0%	1,250.00*	X
742	1	R/F WING	41 35 7 111 430	0%	400.00*	X
1392	1	AIR GUIDE TRIM	51 71 7 027 083	0%	140.00*	X
1401	1	WINDSCREEN	51 31 7 177 297	0%	750.00	CE
1411	1	WINDSCREEN BOND KIT	83 19 2 289 285	0%	131.55	ne
1414	1	CLEANER R1 FRT SCR	83 19 2 289 286	0%	47.25	ne
1415	10	FRONT SCREEN CLIP	51 31 7 064 098	0%	16.50	ne
1417	1	INFO LABEL AIRBAG	71 21 2 122 334	0%	23.25	ne
1419	4	WINDSCREEN BUFFER	51 31 1 925 433	0%	6.40	ne
1420	2	WINDSCREEN BUFFER	51 31 7 061 285	0%	2.90	ne
1423	1	FRONT SCREEN COVER	51 31 7 166 841	0%	39.35	ne
1424	1	LWR WINDSCREEN SEAL	51 48 7 009 037	0%	82.80	ne
1426	1	R/FRONT SCREEN MLDG	51 31 7 045 448	0%	35.00	ne
1447	1	RAIN-/LIGHT SENSOR	61 35 9 254 026	0%	90.00*	X
1449	1	ANTI MISTING SENSOR	64 11 6 928 326	0%	224.75	X
1453	1	L/F WIPER ARM	61 61 7 198 597	0%	80.00*	X
1454	1	R/F WIPER ARM	61 61 7 185 366	0%	180.00*	X
1000	1	BONNET SPRING	Renew	0%	40.00*	X
f: OEM Parts				Sub Total	\$8,644.75	
g: Original				Mark Up From Cost (5 %)	\$432.24	
h: Secondhand				Sundry Parts (Fixed)	\$100.00	
p: Parallel				Total Parts	\$9,176.99	
x: Exchange						

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras	Description	Betterment	Price
	AUDATEX FEE SPECIALIST	0%	\$42.00
	W/SCREEN SEALANT SPECIALIST		\$25.00
	FRT NO. PLATE SPECIALIST	0%	\$45.00
	Total Extras		\$112.00

Final Calculation

Total Parts	\$9,176.99
Labour	
Total Panel/Mechanical	\$483.00
Total Paintwork	\$317.40
Total Labour	\$800.40
Additional Costs	
Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$112.00
Total of Additional Costs	\$223.92
Total Paint/Material Costs	\$10,313.31
Grand Total Excludes GST	\$0.00
GST @ 0 %	\$10,313.31
Grand Total Includes GST	

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: SNM17D03777C01

Assessment Number: GR000070

Version: CHENGABS/1

Date Calculated: 04/07/2017 04:25

Full Report - V1

Registration: SGG8111R

Printed: 04/07/2017 11:29

Assessment Notes

Person
Hp 90010068

4 days

W3

29/06/17 @ 1710

EXCESS: TPA

Revers

Reg after repair

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**CHINA TAIPING
INSURANCE (S) PTE LTD
3 ANSON ROAD
#15-02 SPRINGLEAF
TOWER
079909**

Claim Reference:
Assessment Number: GR000070
Version: CHINATAI/8
Date Calculated: 05/01/2018 09:05

Full Report - V1
Registration: SGG8111R
Printed: 05/01/2018 17:11

Summary Information

Claim			
Location:	Singapore (SG)	Currency:	SGD
Printed by:	Mr K.K Lau	Date of Incident:	27/06/2017
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	DMPCSN3017881705	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle		Model Specs	
Manufacturer:	BMW	FROM 11/2008	AIR CON AUTOMATIC
Model:	5 Series	DIP/FOLD MIRROR	RADIO BUSINESS CD
Sub Model:	520 I	XENON HEADLAMPS	HEADLAMP WASHERS
Model Sheet Number:	145 01	DAKOTA LEATHER TRIM	ELEC/SEAT ADJ MEMORY
Registration:	SGG8111R	FRT/RR DRINK HOLDER	TRIM POPLAR WOOD
Registration Month:		DIP REAR VIEW MIRROR	2.0 LTR 125 KW
Registration Year:		6-SPEED AUTOMATIC	TYRES 225/55 WR 16
VIN Number:	WBANT12040CX29937	WHEELS 7J X 16 ALLOY	4-DOOR
Odometer:	Not Known	PARK DISTANCE CONT	CHROME LINE
Colour:		SPEED CRUISE ONTROL	TWO COAT METALLIC
Engine Number:			
Fuel Level:	%		

Vehicle Condition

Vehicle Status		
Pre-Accident Condition:		Severity of Impact:
Steering:		Vehicle Status on Inspection:
		Date of Inspection:
Brakes Pedal Travel:		30/06/2017
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		Tread Depth RHF:
Tread Depth LHF:		Tread Depth RHR:
Tread Depth LHR:		Direction of Impact:
Damage Areas:		

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference:

Assessment Number: GR000070



Version: CHINATAI/8

Date Calculated: 05/01/2018 09:05

Full Report - V1

Registration: SGG8111R

Printed: 05/01/2018 17:11



Addresses

Cost Summary

Total Labour	\$410.17
Total Paint/Material	\$125.94
Total Parts	\$2,801.02
Total of Additional Costs	\$112.00
Excess:	TBA
Grand Total Exc GST:	\$3,449.13
7 % GST:	\$241.44
Grand Total Inc GST:	\$3,690.57

Repair Information

LABOUR

Time Basis 12 WU = 1 HR. Price/CL 1 = \$46.00/HR
Price/Dent = \$46.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
NO NUMBER	ADD/TIME FOR MAIN WORK	2.0	7.67
41 61 600	R + R BONNET	4.0	15.33
41 61 501	REPLACE BONNET (WITH BONNET REMOVED)	6.0	23.00
51 23 504)	ADJUST BONNET LOCK	2.0	7.67
51 31 511	RENEW WINDSCREEN	39.0	149.50
64 11 971	ADD/WORK FOR FITTING SENSOR	1.0	3.83
61 35 996	ADD/WORK FOR RAIN-/LIGHT SENSOR	5.0	19.17
LABOUR COST		59.0	
Total Work Units		0.0HRS	0.00
Corrosion Protection External Labour		0.0HRS	0.00
Corrosion Protection Internal Labour		4.9HRS	\$226.17
Sub Total		4.0HRS	\$184.00
Paint Labour		8.9HRS	\$410.17
Total Labour			

NOTE TIME BASIS = 12 WU / HOUR

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$46.00/HR
WU Cost Price (\$)

Guide Number	Description	WU	Cost Price (\$)
471	- SPEED CRUISE ONTROL - TWO COAT METALLIC BONNET NEW PART PAINTING	31.0	
LABOUR COST - PAINT		31.0	
TIME(PAINT)			

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference:
Assessment Number: GR000070
Version: CHINATAI/8
Date Calculated: 05/01/2018 09:05

Full Report - V1
Registration: SGG8111R
Printed: 05/01/2018 17:11

Preparation Main Work Metal	9.0	
Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	40.0	
Total Paintwork Labour	4.0HRS	\$184.00
MATERIAL COST - PAINT		Cost Price
New Part Painting		\$107.84
Material-Const Main Work Metal		\$18.10
Total Excluding Pearlescent Uplift		\$125.94
Pearlescent Uplift @ 0.0%		\$0.00
Total Paint Material Cost		\$125.94

PARTS

				Price Valid: 01/12/2017	
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
1449	1	ANTI MISTING SENSOR	64 11 6 928 326		0% 0.00F
471	1	BONNET	41 61 7 111 385		0% 1,500.00*
1414	1	CLEANER R1 FRT SCRIN	83 19 2 289 286		0% 47.25
1415	10	FRONT SCREEN CLIP	51 31 7 064 098		0% 16.50
1423	1	FRONT SCREEN COVER	51 31 7 166 841		0% 0.00F
1417	1	INFO LABEL AIRBAG	71 21 2 122 334		0% 0.00F
1424	1	LWR WINDSCREEN SEAL	51 48 7 009 037		0% 82.80
1426	1	R/FRONT SCREEN MLDG	51 31 7 045 448		0% 35.00*
1448	1	RAIN-/LIGHT SENS OPT	61 35 9 248 398		0% 0.00F
1401	1	WINDSCREEN	51 31 7 177 297		0% 750.00*
1411	1	WINDSCREEN BOND KIT	83 19 2 289 285		0% 131.55
1419	4	WINDSCREEN BUFFER	51 31 1 925 433		0% 6.40
1420	2	WINDSCREEN BUFFER	51 31 7 061 285		0% 2.90
f: OEM Parts				Saving	\$330.65
g: Original				Sub Total	\$2,572.40
h: Secondhand				Mark Up From Cost (5 %)	\$128.62
p: Parallel				Sundry Parts (Fixed)	\$100.00
x: Exchange				Total Parts	\$2,801.02

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras	Description	Betterment	Price
	AUDATEX FEE SPECIALIST	0%	\$42.00
	W/SCREEN SEALANT SPECIALIST		\$25.00
	FRT NO. PLATE SPECIALIST	0%	\$45.00
	Total Extras		\$112.00

Final Calculation

Total Parts		\$2,801.02
Labour		
Total Panel/Mechanical	\$226.17	
Total Paintwork	\$184.00	
Total Labour		\$410.17
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$112.00	
Total of Additional Costs		\$112.00
Total Paint/Material Costs		\$125.94
Grand Total Excludes GST		\$3,449.13

CHINA TAIPING INSURANCE (S) PTE LTD

Full Report - V1

Claim Reference:

Assessment Number: GR000070

Version: CHINATAI/8

Date Calculated: 05/01/2018 09:05

Registration: SGG8111R
Printed: 05/01/2018 17:11

GST @ 7 %

Grand Total Includes GST

\$241.44

\$3,690.57

Assessment Notes

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed
Main	30 Jun 2017 17:17 Sendback Est	30 Jun 2017 18:14 S\$10,274.72	03 Jul 2017 13:29 Edit Adj Rpt	S\$2,750.00 Edit Estimates	S\$2,750.00 View Rpt	
Supp #1	27 Dec 2017 14:46	28 Dec 2017 09:38 S\$0.00	28 Dec 2017 09:38			(Combined)
						Pending for Survey Report Cancel Case
						Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: TEIW GUAT CHOO , ID: S1777332A, Tel: +6590049947, Email: NOEMAIL									
Vehicle Reg. No.: SGG8111R		Date of Loss:	27/06/2017 15:00 - :59 [98 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type: OD / SNM17D03777C01		Policy/Cover Note No.:	DMPCSN3017881705 (Comprehensive)						
		Excess:	S\$0.00						
Repairer: Cheng Auto Bodyworks (HQ) 5 Soon Lee Street #01-62 Pioneer Point, 627607 Pioneer - Tel: 6631 0707									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 12/07/2017]									
Driver/Custodian: TEIW GUAT CHOO (50 / Female), NRIC: S1777332A, Tel: +6590049947									
Adj Asg. Remarks: survey revert.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• CHINA_TAIPIING (11/07/2017): Alert - Adj Mandate Approved (S\$3700.00) - SGG8111R - Claim Handler: Chong Boon ...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SGG8111R (SNM17D03777C01)

OD

Jun 27 2017 3:00PM

[TEIW GUAT CHOO]

Cheng Auto Bodyworks

View View in Browser

Upload Documents
Upload Photos
Compose New Letter

1 per page 1 ☒

Assessment Reports			Thumbnail	Print
No	Finalized On	Cheng Auto Bodyworks (HQ)		
1	30/06/17 18:14	Repairer Estimates	Load HTM	
2	28/12/17 09:38	Repairer Estimates Suppl. #1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/07/17 09:07	Adjuster Immediate Advice	Load HTM	

3 per page 3 ☒

Photos/Images			Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		
1	23/05/18 10:20	Reinspection Photo	Load PDF	
2	23/05/18 10:20	General View	Load PDF	

1 per page 1 ☒

Documentation			Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		
1	10/07/17 09:09	AUDATEX	Load PDF	
2	10/07/17 09:29	ESTIMATE MARKING	Load PDF	

Linked Accident Report Documents

View View in Browser

1 per page 1 ☒

Assessment Reports			Thumbnail	Print
No	Finalized On	Cheng Auto Bodyworks (HQ)		
1	29/06/17 11:41	Accident Statement	Load HTM	
2	08/07/17 11:46	Addendum Sheet	Load JPG	☒
3	08/07/17 11:46	Accident Statement Addm. #1	Load HTM	

3 per page 3 ☒

Photos/Images			Thumbnail	Print
No	Finalized On	Cheng Auto Bodyworks (HQ)		
1	29/06/17 10:51	Accident Photo	Load JPG	☒
2	29/06/17 10:51	Driving License	Load JPG	☒
3	29/06/17 10:51	Police Report	Load JPG	☒
4	29/06/17 10:51	Police Report	Load JPG	☒
5	29/06/17 10:51	Police Report	Load JPG	☒
6	29/06/17 11:41	Accident Photo	Load JPG	☒
7	29/06/17 11:41	Accident Photo	Load JPG	☒
8	29/06/17 11:41	Accident Photo	Load JPG	☒
9	29/06/17 11:41	Accident Photo	Load JPG	☒
10	29/06/17 11:41	Accident Photo	Load JPG	☒
11	29/06/17 11:41	Accident Photo	Load JPG	☒
12	29/06/17 11:41	Accident Photo	Load JPG	☒

1 per page 1 ☒

Documentation			Thumbnail	Print
No	Finalized On	Cheng Auto Bodyworks (HQ)		
1	29/06/17 10:51	Accident Sketch Plan	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On		Thumbnail	Print
2	29/06/17 10:51	Cheng Auto Bodyworks (HQ) Accident Sketch Plan	 Load JPG	☒
3	29/06/17 10:51	Certificate of Insurance	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT117012600/R1TH3E2
Date: 28/05/2018

REFERENCE

Insured/Claimant: TEIW GUAT CHOO Policy No: DMPCSN3017881705
Date of Loss: 27/06/2017 Nature of Claim: OD Claim No: SNM17D03777C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGG8111R** Engine No: A020I354N46B20BE
Make & Model: BMW 520I, 2.0 (A) Chassis No: WBANT12040CX29937
Reg. Date: 20/04/2009 (Man. Year: 2008) Odometer: 189761 km
Colour: Blue
Engine Capacity: 1995 cc
Market Value/New Car Price: S\$44,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

	Repairer's	Adjuster's	Difference	Diff %
COST OF CLAIMS				
Parts	8,685.50	2,913.02	5,772.48	66.46
Miscellaneous Items	564.90	0.00	564.90	100.00
Labour	1,024.32	536.11	488.21	47.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,274.72	3,449.13	6,825.59	66.43
Approved Total (Overridden) (S\$)		2,750.00		
(S\$)	10,274.72	2,750.00	7,524.72	73.24
+ GST 0.00/7.00% (S\$)	0.00	192.50	-192.50	
Nett Amount (S\$)	10,274.72	2,942.50	7,332.22	71.36

INSPECTION

Date of Assignment: 03/07/2017 Present Location:
Date Inspected: 29/06/2017 Inspected At:

Cheng Auto Bodyworks (HQ)
1 Soon Lee Street, #06-41, Pioneer Centre
Singapore 627605

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 May 2018)
 Parts: 143 BMW 520I 2.0 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SGG8111R)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*AIR GUIDE TRIM	Serviceable	140.00 F	*- F
2	1	NA	*BONNET	Bent	1,500.00 F	*1,500.00 F
3	1	NA	*BONNET SPRING	Serviceable	40.00 F	*- F
4	1	NA	*FRONT BUMPER COVER	Repair	900.00 F	*- F
5	1	NA	*FRONT BUMPER SUPPORT	Serviceable	450.00 F	*- F
6	1	NA	*FRT BUMPER GRILLE	Serviceable	55.00 F	*- F
7	1	NA	*FRT BUMPER MNTG KIT	Serviceable	15.00 F	*- F
8	1	NA	*GRILLE BADGE	Serviceable	65.00 F	*- F
9	1	NA	*L/BONNET HINGE	Serviceable	75.00 F	*- F
10	1	NA	*L/F BONNET STRUT	Serviceable	60.00 F	*- F
11	1	NA	*L/F BUMPER BRACKET	Serviceable	25.00 F	*- F
12	1	NA	*L/F GRILLE	Serviceable	120.00 F	*- F
13	1	NA	*L/F WIPER ARM	Serviceable	80.00 F	*- F
14	1	NA	*LEFT HEADLAMP ASSY	Serviceable	1,250.00 F	*- F
15	1	NA	*R/BONNET HINGE	Serviceable	75.00 F	*- F
16	1	NA	*R/BONNET LOCK	Serviceable	120.00 F	*- F
17	1	NA	*R/F BONNET STRUT	Serviceable	60.00 F	*- F
18	1	NA	*R/F BUMPER BRACKET	Serviceable	25.00 F	*- F
19	1	NA	*R/F GRILLE	Serviceable	120.00 F	*- F
20	1	NA	*R/F WING	Serviceable	400.00 F	*- F
21	1	NA	*R/F WIPER ARM	Serviceable	180.00 F	*- F
22	1	NA	*R/FRONT SCREEN MLDG	Necessary	35.00 F	*35.00 F
23	1	NA	*RAIN-/LIGHT SENSOR	Serviceable	90.00 F	*- F
24	1	NA	*RIGHT HEADLAMP ASSY	Serviceable	1,250.00 F	*- F
25	1	NA	*SOUND INSULATION	Serviceable	190.00 F	*- F
26	1	NA	*SPECIALIST AUDATEX FEES		42.00 FS	*42.00 FS
27	1	NA	*SPECIALIST FRT NO. PLATE	Bent	45.00 FS	*45.00 FS
28	1	NA	*SPECIALIST WINDSCREEN SEALANT	Necessary	25.00 FS	*25.00 FS
29	1	NA	*SUNDRY PARTS	Necessary	100.00 FS	*100.00 FS
30	1	NA	*WINDSCREEN	Cracked	750.00 F	*750.00 F
Supplementary #1						
31	1		*Windscreen Bond Kit	Necessary	-	*131.55 F
32	1		*Cleaner R1 frt scrn	Necessary	-	*47.25 F
33	10		*Front screen clip	Necessary	-	*16.50 F
34	1		*Info label airbag	Serviceable	-	*- F
35	4		*Windscreen buffer	Necessary	-	*6.40 F
36	2		*Windscreen buffer	Necessary	-	*2.90 F
37	1		*Front screen cover	Serviceable	-	*- F
38	1		*Lwr windscreen seal	Necessary	-	*82.80 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*Anti-misting sensor	Serviceable	-	*- F
F=Franchise part. S=SpcNett.						
				Sub Total (S\$)	8,282.00	2,784.40
+ Margin on L,N Items 5.00/5.00% (S\$)					403.50	128.62
				Total Parts (S\$)	8,685.50	2,913.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	GST 7%	564.90	0.00
Sub Total (S\$)			564.90	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	Total Paint Labour	New	317.40	184.00
2	Total Paint Materials	New	223.92	125.94
3	Total Panel/Mechanical Labour	New	483.00	226.17
Gross Labour Cost (S\$)			1,024.32	536.11

Report was unsubmitted during this print-out.

< END OF ESTIMATES >