

TRANS-CAB AUTO SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

Co./GST Reg. No. 201019626G

SHB 7547M*Not Authenticated*
61 Sep 8 1000

Vehicle No.:

Chassis No.:

Date of Accident:

Vehicle Make:

Vehicle Model:

Third Party Insurer:

SHB 7547M

KL1LA69RJBB091501

22.6.2017

CHEVROLET

CHEVROLET EPICA 2.0

Atty

PART	LIST
1 Front Fender LH	\$ R 837.60
1 Front Fender Liner LH	\$ S 47.00
1 Front Door LH	\$ R 1,133.00
1 Front Door Outer Moulding LH	\$ S 220.00
1 Front Door Outer Handle LH	\$ S 125.00
1 Front Door Handle Support LH	\$ S 3.00
1 Front Door outer handle inner seal LH	\$ S 89.15
1 Front Door outer key lock LH	\$ S 25.00
1 Front Door Hinge Upper LH	\$ R 65.00
1 Front Door Hinge Lower LH	\$ R 65.00
1 Front Door inner lock LH	\$ S 586.00
1 Front Door Inner Lock Latch LH	\$ S 206.00
1 Front Door Check / Arrestor LH	\$ S 67.50
1 Front Door Weatherstrip LH	\$ S 138.79
1 Front Door glass channel weatherstrip LH	\$ S 160.00
1 Front Door inner trim board LH	\$ S 455.69
1 Front Door window glass LH	\$ S 456.12
1 Front Door Power Window Motor (Master) LH	\$ S 284.97
1 Front Door power window motor switch	\$ S 145.00
1 Front Door Window Regulator Gear LH	\$ S 84.58
1 Front Side View Mirror LH	\$ S 939.00
1 Side Rocker Panel Garnish LH	\$ S 236.40
1 Side Rocker Panel Outer LH	\$ R 433.26
1 Centre pillar outer LH	\$ R 446.00
1 Centre pillar inner LH	\$ R 460.00
1 Rear Door LH	\$ R 1,133.00
1 Rear Door inner lock LH	\$ S 425.00
1 Rear Door check / arrestor LH	\$ S 65.00
1 Rear Door lock striker / latch LH	\$ S 120.00
1 Rear Door outer weatherstrip moulding LH	\$ S 85.00

1	Rear Door outer handle LH	\$	60.00	} X
1	Rear Door outer handle - rubber seal LH	\$	25.00	
1	Rear Door inner opening handle LH	\$	45.50	
1	Rear Door inner trim board LH	\$	455.69	
1	Rear Door kicking plate / step garnish LH	\$	63.25	
1	Rear Door window glass channel weatherstrip LH	\$	143.25	
1	Rear Door window glass channel holder LH	\$	205.60	
1	Rear Door channel weatherstrip / felt LH	\$	89.50	
1	Rear Door interior light switch LH	\$	139.20	
1	Rear Door power window motor (master) LH	\$	274.97	
1	Rear Door regulator gear LH	\$	55.30	
1	Rear Door regulator handle LH	\$	65.30	
1	Rear Fender LH	\$	1,145.00	
1	Rear Fender Inner Cowling LH	\$	76.60	
1	Rear Tail Lamp LH	\$	479.30	
1	Rear Bumper	\$	1,202.00	
1	Rear Bumper Side Retainer LH	\$	68.76	
1	Rear Bumper Reflectors LH	\$	119.74	

TOTAL	\$	14,251.02
10%	\$	1,425.10
	\$	12,825.92

Specical Nett

1 Set	Front Fender Liner Clip	\$	30.00	} X
1Set	Rear Bumper Parking Sensor	\$	300.00	
1 Set	Rear Bumper Fastener Clip	\$	30.00	
1 Set	Rear Fender Liner Clip	\$	30.00	
1	Door Sticker "Trans-cab"	\$	80.00	
1	Door Sticker "6555-3333"	\$	80.00	
1set	Side Rocker Panel Garnish Clip LH	\$	60.00	
1	Front Tyre LH	\$	360.00	
1	Front Wheel Rim LH	\$	254.00	
1	Hub Cup Rim Front LH	\$	35.00	
1	Rear Tyre LH	\$	360.00	
1	Rear Wheel Rim LH	\$	254.00	
1	Hub Cup Rim RR LH	\$	35.00	

TOTAL	\$	1,908.00
--------------	-----------	-----------------

TOTAL PARTS	\$	14,733.92
--------------------	-----------	------------------

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of Parts,
Adjust And Realign The Same

\$ 2,800.00

1501

To Rust-Proofing Of The Affected Areas.	\$	220.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
Putty and Spray Painting Of The Affected Portion.	\$	2,800.00	269
To Check Electrical Lighting Concerned.	\$	170.00	29
To check steering geometry and computer wheel alignment	\$	220.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00	X

TOTAL	\$	6,720.00
--------------	-----------	-----------------

Over All Total	\$	21,453.92
-----------------------	-----------	------------------

REPAIR DAYS**10-DAYS**

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: