

22/03/2011

ASS. REC. BY:

REF:

CS/PC47012908/Gcd3n2

Special Instruction:

Surveyor:

Cuo Bichong

ASSIGNMENT (Office)

From (Person):

S. B. R. A. M.

of

PC1

Date/Time:

4/7/2017 9.40am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLM8353T

Insured:

SNC 75514

at Workshop m/s

Carlife Auto

Tel:

62733810

of

Blk 1002 Bukit Merah Lane S #01-75

Policy No:

Claim No:

D17006524MK54

Sum Insured:

Excess:

Make of Veh:

D.O.A.

30/6/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

wp

5/7/2017 @ after 12pm

H.O.D. Endorsement:

Date/Time:

4/7/2017 9.53am

Person Contacted:

May

Vehicle IN / OUT

Date/Time

Action/Instruction

(✓)

Estimate

SLM8353T-X

SNC75514-X

08/11/13

AS S. REC. BY: XhdREF: FCI

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Car life

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 2053.36 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLM8353TYr Regn: 13 Apr 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hondac.c. 1496Colour: Red

A/C: Insured / Std / NI / NA

Sp. Reading: 13491

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RU31210518Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 215/60R16R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 8 mmR/Bal. 8 mmL/Bal. 8 mmL/Bal. 8 mm

D.O.A. _____

D.O.I. 05-07-17Survey held at W/S4:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Transit \$ 2053.3609/07/19 Mr Tan Carlite confirm amount \$ 2053-36 194 GST
(Red 5509.36, 72%)

RECEIVED 09 JUL 2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4Resurvey No. of Trip: 2+1

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

Survey Fee: 150Transportation: 50S + RS, SI 50+50+50Photos 43

Others _____

TOTAL

393Report Format: TPLump Sum / I.B.I. (\$ 2053.36)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17012908/Ggh3		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 04-07-2017		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7551U	Veh. Inspected	SLM 8353T	
Policy No.		Coverage (\$)	0.00	
Claim No.	D17006524MFSH	Excess (\$)	0.00	
Assign From	CWS (SITHARA)	Assign Date	04/07/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	30/06/2017	Inspection Date	05/07/2017	
Survey held at	CAR LIFE AUTO ENGINEERING SERVICES BLK 1002 BUKIT MERAH LANE 3 # 01-75 SINGAPORE 159719			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

MOTOR SURVEY ASSIGNMENT

Date	03-07-2017	Our Ref No. D17006524MFSH
Accident Date	30-06-2017	Claim Type. Third Party
Insured Vehicle	SHC7551U	Third Party Vehicle. SLM8353T
Survey Location	BLK 1002 BUKIT MERAH LANE 3 # 01-75	
Contact Person.	TAN	
Contact No.	62733810/ 62787522	Fax No. 62787522
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CAR LIFE AUTO ENGINEERING SERVICES	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/224887)



PRI Documents



Close X

PRI Header Details

Claim No	D17006524MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & CAR LIFE SERVICES
Workshop Name	CAR LIFE AUTO ENGINEERING SERVICES (Contact Person : TAN)	Survey Location & Contact Details	BLK 1002 BUKIT MERAH LANE 3 # 01-75 Mobile: 62787522 , Phone: 62733810 , Fax: 6278752; EmailId: AUTOLIFE_SIN@YAHOO.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC7551U	TP Vehicle No	SLM8353T
PRI Recieved Date	03-07-2017 09:59:06 PM	Surveyor Appointed Date	04-07-2017 09:40:03 AM	Surveyor Accept Date	04-07-2017 0

Survey Report Upload

Surveyor Inspection Date *		Surveyor Report Date	04-07-2017	Upload Survey Report *	Choose File
----------------------------	--	----------------------	------------	------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Ai Phing (LKKAUTO)

From: Ai Phing (LKKAUTO)
Sent: Monday, 10 July, 2017 5:15 PM
To: 'Claim Workflow System'
Cc: SITHARA@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17006524MFSH/1

Dear Sithara,

Please be informed that we have inspected the vehicle SLM 8353T on 05-07-2017.
We are pending estimate from repairer.

Best Regards,

Ai Phing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 4 July, 2017 9:54 AM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: SITHARA@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17006524MFSH/1

Dear Sir/Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Ashley Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Tuesday, 4 July, 2017 9:40 AM
To: ASSIGNMENTS@LKKAUTO.COM

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	8875M
Vehicle Details	
Vehicle No.:	SLM8353T
Vehicle to be Exported:	No
Intended De-registration Date:	13 Jun 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL HYBRID 1.5X A
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	LEB5910529
Chassis No.:	RU31210518
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$26,734.00
Original Registration Date:	13 Apr 2017
First Registration Date:	13 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Apr 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	12 Apr 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$54,000.00
COE Rebate Amount:	\$47,691.00
Total Rebate Amount:	\$51,441.00

The information contained herein is correct as at 13 Jun 2018

OK

CAR LIFE AUTO ENGINEERING SERVICES

Mailing address: 20, BINCHANG RISE SINGAPORE 579887
 W/shop address: BLK 1002 BUKIT MERAH LANE 3 # 01-75 SINGAPORE 159719
 E-mail : autolife_sin@yahoo.com.sg
 Tel: 6273 3810 Fax: 6278 7522

Date : 05-Jul-17

Address : ENERGY PRODUCTS PTE LTD
 21 BUKIT BATOK CRESCENT
 # 17-74 WCEGA TOWER
 SINGAPORE 658065

Reference : TP 1116/07/17
 Vehicle No : SLM 8353T
 Make/Model : HONDA VEZEL
 Insurance Co. : NTUC

RE : QUOTATION FOR REPAIRS TO SLM 8353T FOR THIRD PARTY CLAIMS.

PARTS REQUIRED	QTY	AMT \$
1) FRONT BUMPER / <i>re</i>	1	\$ 1,085.00 <i>727.5</i>
2) FRONT BUMPER RETAINER <i>LH- re.</i>	2	\$ 46.00 <i>23</i>
3) FRONT BUMPER BEAM <i>X nn</i>	1	\$ 321.00 <i>X</i>
4) FRONT LOWER BUMPER / <i>re</i>	1	\$ 381.00 <i>=</i>
5) FRONT BUMPER LOWER SPLASH GUARD <i>- re</i>	1	\$ 220.00 <i>=</i>
6) BUMPER CLIPS / <i>mc</i>	10	\$ 38.00 <i>=</i>
7) BUMPER LOWER CLIPS/ LIP CLIPS <i>- mc</i>	20	\$ 76.00 <i>=</i>
8) FOG LAMP / <i>CRA</i>	1	\$ 427.70 <i>727.7</i>
9) FOG LAMP GARNISH / <i>re.</i>	1	\$ 65.00 <i>45</i>
10) FENDER <i>X repair.</i>	1	\$ 580.00 <i>X</i>
11) FENDER COWLING <i>X na</i>	1	\$ 135.00 <i>X</i>
12) FENDER GARNISH / <i>re</i>	1	\$ 195.00 <i>153</i>
13) FENDER GARNISH CLIPS / <i>mc.</i>	10	\$ 38.00 <i>=</i>
14) FRONT GRILLE ASSY <i>X</i>	1	\$ 1,150.00 <i>X</i>
15) FRONT GRILLE CLIPS <i>X</i>	6	\$ 3.80 <i>X</i>
16) HEADLAMP <i>X</i>	1	\$ 1,859.40 <i>X</i>
17) HEADLAMP BRACKET <i>X</i>	1	\$ 45.00 <i>X</i>
LIST PRICE TOTAL		\$ 6,665.90 <i>2029.2</i>
LESS DISCOUNT 20%		\$ 1,333.18
LIST PRICE TOTAL AFTER LESS		\$ 5,332.72 <i>1623.36</i>
TOTAL PARTS COST		\$ 5,332.72

LABOUR AND MISCELLANEOUS CHARGES

1)	TO REMOVE & REPLACE FRONT BUMPER, HEADLAMP, FENDER & TO PANEL BEAT & ALIGN.	\$ 1,000.00 <i>200</i> (5 DAYS)
2)	TO PUTTY & SPRAY PAINT FRONT BUMPER, LOWER BUMPER, FENDER & OTHER AFFECTED AREA.	\$ 800.00 <i>200</i> (4 PANELS)
3)	TO CHECK & RECTIFY WIRING & FOCUS HEADLAMP.	\$ 80.00 <i>30</i>

ATT: GUO QIANG

5)

TUFF KOTE RUST PROOFING

\$ 350.00

X NN

LABOUR TOTAL

\$ 2,230.00

TOTAL ESTIMATED REPAIR COST

\$ 7,562.72

2053.36

4 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17012908/Gcd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 09-07-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7551U	Veh. Inspected	SLM 8353T	
Policy No.	D-15072702MFSH	Coverage (\$)	0.00	
Claim No.	D17006524MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	04/07/2017	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	RU31210518	Colour	RED	
Odometer	13491	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	MICHELIN	8 mm	
L/H Front Tyre	215/60 R16	MICHELIN	8 mm	
R/H Rear Tyre	215/60 R16	MICHELIN	8 mm	
L/H Rear Tyre	215/60 R16	MICHELIN	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/06/2017	Inspection Date	05/07/2017	
Survey held at	CAR LIFE AUTO ENGINEERING SERVICES BLK 1002 BUKIT MERAH LANE 3 # 01-75 SINGAPORE 159719			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 8353T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DEFORMED	1,085.00	727.50
2	FRONT BUMPER RETAINER	N/S DEFORMED	46.00	23.00
1	FRONT BUMPER BEAM	NOT NECESSARY	321.00	-
1	FRONT LOWER BUMPER	DEFORMED	381.00	381.00
1	FRONT BUMPER LOWER SPLASH GUARD	DEFORMED	220.00	220.00
10	BUMPER CLIPS	NECESSARY	38.00	38.00
20	BUMPER LOWER CLIPS/LIP CLIPS	NECESSARY	76.00	76.00
1	FOG LAMP	CRACKED	427.70	327.70
1	FOG LAMP GARNISH	DEFORMED	65.00	45.00
1	FENDER	TO REPAIR SEE LABOUR	580.00	-
1	FENDER COWLING	NOT NECESSARY	135.00	-
1	FENDER GARNISH	DEFORMED	195.00	153.00
10	FENDER GARNISH CLIPS	NECESSARY	38.00	38.00
1	FRONT GRILLE ASSY	NOT NECESSARY	1,150.00	-
6	FRONT GRILLE CLIPS	NOT NECESSARY	3.80	-
1	HEADLAMP	NOT NECESSARY	1,859.40	-
1	HEADLAMP BRACKET	NOT NECESSARY	45.00	-
	LESS 20% DISCOUNT		-1,333.18	-405.84
			5,332.72	1,623.36
LABOUR				
	TO REMOVE & REPLACE FRONT BUMPER, HEADLAMP, FENDER & TO PANEL BEAT & ALIGN.		1,000.00	200.00
	TO PUTTY & SPRAY PAINT FRONT BUMPER, LOWER BUMPER, FENDER & OTHER AFFECTED AREA.		800.00	200.00
	TO CHECK & RECTIFY WIRING & FOCUS HEADLAMP.		80.00	30.00
	TUFF KOTE RUST PROOFING.	NOT NECESSARY	350.00	-
			2,230.00	430.00
GRAND TOTAL			7,562.72	2,053.36
RECOMMENDED COST OF REPAIRS				2,053.36

Report Ref No. CS/FCI17012908/Gcd3n2



Report Ref No. CS/FCI17012908/Gcd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever in contract or tort is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part does so at his or her own risk.