

VEHICLE NO : FBH 1743S

Yamaha R15 V2

Nett items

1	IU unit	160.00	500 ✓
2	Body decal sticker - 1 set	200.00	1000 ✓
3	Towing fee	40.00	✓
4	Remove & replace necessary parts, align & etc	320.00	250
5	Remove & replace fork tube & top up fork oil	150.00	80
6	Putty & touch up paint work & decal body sticker labour	450.00	300

Sub-Total 1,320.00

Nett Total 4,966.80

930
+ 200 = 1130

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion
Thank you

SG 98 MOTOR PTE LTD

LS

Paul
Hp 90010068
4 days
L/S
07/07/17 @ 1325

1803.60
1130.00
2933.60
20%
2346.88
43-21350
4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____