

ASS. REC. BY:

REF:

CS/AWA17013216 / TQh372

Special Instruction:

Surveyor: Tadfish

ASSIGNMENT (Office)

From (Person): Stella Goh

of ANA

Date/Time: 7/7/2017 4.57pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD  / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLG1142K

Insured: SFC 357J

at Workshop no: Performance Motors

Tel: 63190174

of 203 Alexandra Road

Policy No: AM WSB 0021661604

Claim No: NSV1700802/SG

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_  
(Client's Record)

D.G.A. 6/7/2017

CA / REV / REP. / REV 24 HRS rup

14/7/2017 @ 10am

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 7/7/2017 5pm

Person Contacted: online

Vehicle-IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLG1142K-1
	SFC 357J - CU/VAL1700 0486/CU
<u>28/12/17 @ 5.12pm</u>	<u>confirmed with Caroline final fig @ 10297.30, 7 days.</u> <u>(Red @ 2214.10, 21%)</u>

DA - 24/12/2016

Taufik

REF: ANA

ASSIGNMENT

From: Date: 14/7/2017

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLQ 1142K

at Workshop m/s Performance

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: Enthusian

100% owner using

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS (wp)

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLQ 1142K. Yr Regn: 2017, June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW X3 cc 1997

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 1173 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WBSAWY920800W22508

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/50R18

R: 7

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal: 6 mm Rear R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. D.O.I. 14/7/17

Survey held at PML

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 29 DEC 2017

Date/Time, File Pass to? [ ] : Preli. Report

1) 29/12/17 [ ] : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee: [ ] Site Insp (\$ ) S + RS \$

[ ] Interview (\$ ) Photos

[ ] Tech. Invs (\$ ) Others

[ ] Weekend (\$ )

TOTAL

Large empty box for stamp or signature, with '250' written at the bottom.

Report Format : Te

Lump Sum / I.B.I. (\$) 10277.30



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ALLIED WORLD ASSURANCE COMPANY LTD		Ref : CS/AWA17013216/T1qh3	
(SINGAPORE BRANCH) 60 ANSON ROAD ,#08-01 (9th FLOOR) MAPLETREE ANSON SINGAPORE 079914		Date : 07-07-2017	
		Code : AWA	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SFC 357J	Veh. Inspected	SLQ 1142K
Policy No.	AVHWSB0021661604	Coverage (\$)	0.00
Claim No.	NSV1700802/SG	Excess (\$)	0.00
Assign From	STELLA GOH	Assign Date	07/07/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	06/07/2017	Inspection Date	14/07/2017
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

## Survey Department Check List (Case Handler)

Reference No. : C31AWA19013216 F11ah3  
 Policy Type: OD (TP) / TP RES / TL / EVA

SLB 1142K

Case Handler

Typist

**Admin** (Ashley): Case handler to make sure all information created by the assignment team are **ACCURATE**.

**(1) Office Assign Form**

	Y-Date	N-Date	Y-Date	N-Date
C Reference No.	✓			
C Customer Code	✓			
N Assign From	✓			
C Assign Date	✓			
C Veh No (Inspected)	✓			
C Veh No (Insured)	✓			
C D.O.A	✓			
C Policy No	✓			
C Claim No	✓			
C Insurance Authorisation (CA /REV/REP)	✓			
C Report Type	✓			
C Weekend Charges	✓			
N Survey held at/Repairer	✓			
C Excess				

**Surveyor** (Taukiah): Case handler to make sure the surveyor completed all required information.

**(1) Assignment Form**

C Vehicle No	✓	
C Regn Month/Year	✓	
N Vehicle Type	✓	
N Make & Model	✓	
C Engine Capacity. (C.C)	✓	
N Colour	✓	
C Odometer. (Sp.Reading)	✓	
C Chassis No	✓	
N General Condition	✓	
N Steering	✓	
N Brake	✓	
N Modification (Modi)	✓	
C Tyre Size	✓	
N Tyre Make	✓	
C Tyre Balance	✓	
C Date of Inspection	✓	
N Survey held	✓	
N Des.of Damages	✓	

**(2) System - (Views/Merimen)**

C Damaged Vehicle Photographs Uploaded	✓			
--	---	--	--	--

**(3) Workshop Estimate/Assignment Form**

N ALL Parts condition	✓	
C Market Value for OD cases		
C Estimate Repair Cost for PRI (RSI, TMI, MSIG)		
C Days of repair	✓	
C Finalised Amount		
C Re-inspection Cases to Finalize within 5 Days		

**(4) System - (Views/Merimen)**

C Resurvey photo Uploaded	✓			
---------------------------	---	--	--	--

Check By: [Signature] 28/12/12  
 Case Handler                      Date

**Ashley Chong (LKK Auto)**

---

**From:** Goh, Stella <stella.goh@awac.com> on behalf of Motorsurvey <Motorsurvey@awac.com>  
**Sent:** Friday, 7 July, 2017 4:57 PM  
**To:** SUR (sur@lkkauto.com)  
**Cc:** LKK (assignments@lkkauto.com); PBSP (pml-pbsp@simedarby.com.sg)  
**Subject:** TP Survey assignment for SLQ 1142K DOA: 06.07.2017 Our ref: NSV1700802/SG

The above captioned accident refers.

Pursuant to the Practice Directions Amendment No. 1 of 2016 which was effective on 1 April 2016, we like to advise that the third party claimant and us do have consensus in the appointment of **Mr Mohamad Taufikh / Mr Mohammed Rasul**, as the Single Joint Expert to conduct the pre-repair survey of the third party claimant's vehicle.

Please conduct "THIRD PARTY" survey on without prejudice basis. The information as are follows:

3 <sup>rd</sup> Party Vehicle	:	SLQ 1142 K
Insured Vehicle	:	SFC 357 J
Policy Number	:	AVHWSB0021661604
Name of Workshop	:	Performance Motor Limited
Contact Number	:	6319 0174
Person to Contact	:	Caroline
Estimated Cost of repairs	:	\$ 12,714.06

Regards,  
Claims Division

Copy to Performance Motor Limited via Email

Note -

- ( X )
1. This is to keep you informed that we have appointed surveyors to conduct inspection to your client's damaged vehicle on a without prejudice basis.
  2. **Please keep our motor surveyor and us informed so as to enable the surveyor to conduct a post repair inspection once your client's vehicle has been repaired and before returning the repaired vehicle to your customer.**
  3. Please quantify your client's claim with all relevant supporting documents once your client's vehicle has been repaired.
  4. Please do not construe this appointment of surveyor and our above request as an admission of liability.

---

The information contained in this e-mail and any attachments hereto is confidential. If you are not the intended recipient, you must not use or disseminate any of this information. If you have received this e-mail in error, please immediately notify the sender by reply e-mail and permanently delete the original e-mail (and any attachments hereto) and any copies or printouts thereof. Although this e-mail and any attachments

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Thursday, 28 December, 2017 5:12 PM  
**To:** PBSP; Taufikh (LKKAuto); SUR; CS A Team  
**Subject:** RE: FINAL REPORT / SLQ1142K

Dear Caroline,

Confirm final fig \$10,297.30 before GST and 7 repair days.

Wishes you a Happy New Year 2018

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: PBSP [<mailto:pml-pbsp@sime-darby.com.sg>]

Sent: Monday, 18 December, 2017 4:05 PM

To: Taufikh (LKKAuto) <[Taufikh@lkkauto.com](mailto:Taufikh@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>; CS A Team <[cs-a@lkkauto.com](mailto:cs-a@lkkauto.com)>

Subject: FINAL REPORT / SLQ1142K

Dear Taufikh

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 5,811.00

Total Parts : 4,486.30

Total Labour & Parts : 10,297.30

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	06/07/2017 17:31
Date Of Accident	06/07/2017 07:55
Exact Location Of Accident	UPP THOMSON RD RIGHT AFTER SLE FLYOVER
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLQ1142K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	NG MENG HUEH ILINI
NRIC No	S7325679H
Email Address	ILINI_NG@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-96204913
Alternative Phone No	OFFICE-98788839

### Vehicle Particulars

Manufacturer	BMW
Model	X3
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	C0073212
Cover Note Number	

### Driver

Name of Driver	NG MENG HUEH ILINI
NRIC No	S7325679H
Date Of Birth	22/07/1973
Occupation	INDOOR
Date Of Driving Pass	25/05/1995
Driving Experience	22 YEARS AND 1 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-96204913
Fax Number	
Contact Number	OFFICE-98788839
Email Address	ILINI_NG@HOTMAIL.COM

Address	221 QUEENSWAY #05-01
Postcode	276750
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACH.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFC357J
Vehicle Make/Model/Colour	HONDA BLUE
Details Of Properties	
Name of Driver	THINAGHAREN RAJA THEVAR
NRIC/Passport Number	S9020458J
Contact Number	81236190
Address	
Postcode	
Insurance Company Name	ALLIED WORLD ASSURANCE COMPANY, LTD
Nature Of Damage	
No. Of Passenger (Including Driver)	1

#### Details of Witness

Name	
Phone Number	
Email Address	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

*[Handwritten Signature]*  
3:30 pm  
6th July 2017  
Policyholder's Signature / Date & Time

\_\_\_\_\_  
Driver's Signature (If driver is not the policyholder) / Date & Time

*[Handwritten Signature]*  
Witnessed by Reporting Centre Personnel

**Sketch Plan**



Sketch Plan Pg. 2

Describe Circumstances of the Accident

Stopped at Traffic light, right below SLE Flyover, along Upper Thomson Road. After lights are Green, proceeded forward. Moved passed Traffic junction and after SLE Flyover, ~~the~~ Traffic is very slow and came to a stop along Upper Thomson Road. Was getting ready to move after the van in front starts to move and was hit at rear by SFC 357J, Blue Honda, driven by army personnel, Mr Thiragharen Raja Thevar, S902045BJ. He admitted his fault as he was distracted and was trying to hit "some bug" on his leg and hit me. Photos were taken & exchanged IC & contact details. No injuries. Video from BMW is available.

Declaration

I/We declare the foregoing particulars are true in every respect.

  
6 July 2017  
Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel

14.07.2017 @ 10.00am

Survey only

Relative to convert OD -19/7/17

waiting

BMW Dealer

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159942  
Tel: 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax: 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel: 63190888 (AfterSales)  
Fax: 63449773

316, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel: 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax: 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## E S T I M A T E

07 JUL 2017

Estimate No. : b1 43335	Page No. : 1 of 2
Date Estimated : 07/07/2017	
Prepared By : <u>Inthiran A/L Thurasamy</u>	

**- ESTIMATE REPAIR FOR -**  
NG MENG HUEH ILINI (HUANG MINGHUI ILINI)  
221 QUEENSWAY  
#05-01  
  
SINGAPORE 276750

**- ACCOUNT - 705**  
Allied World Assurance Company, Ltd SG br  
60 Anson Road  
#09-01 Mapletree Anson  
Singapore 079914

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ1142K	0W22508	28/06/2017	X3 sDrive20	0

DESCRIPTION	VALUE
Replace trunk lid, rear bumper and remove attachments etc including knock on accident dent	2125 / 2,550.00
Spray rear bumper, trunk lid	1805 / 2,006.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 / 177.00
To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.	451 / 531.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150 / 177.00
To carry out body cavity preservation. (Per panel).	100 / 118.00
Sundries.	net ? / 150.00
<b>Total Labour 1: 5,709.00</b>	

DESCRIPTION	QTY	PRIC	VALUE
BOOTLID	1	1,763.15	dd / 1,763.15
RR BUMPER CARRIER ECE	1	720.05	bt / 720.05
Gasket rear carrier	2	4.90	? / 9.80
FLAP TOWING EYE REAR	1	36.10	mt / 36.10
RR LH BUMPER MIDDLE MOUNTING	1	141.65	? / 141.65
RR RH BUMPER MIDDLE MOUNTING	1	141.65	? / 141.65
RR BUMPER LH MOUNT	1	197.45	? / 197.45
RR BUMPER RH MOUNT	1	197.45	? / 197.45
COVER MIDDLE BOTTOM	1	67.00	? / 67.00
CLADDING BUMPER REAR (PDC/SCHWARZ)	1	192.55	de / 192.55
REAR BUMPER PANEL PRIMED (PDC)	1	1,375.10	de / 1,375.10

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : **b1 43335** Page No. : 2 of 2  
Date Estimated : **07/07/2017**  
Prepared By : **Wong Yit Loong**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ1142K	0W22508	28/06/2017	X3 sDrive20	0

DESCRIPTION	QTY	PRIC	VALUE
EMBLEM GROMMET	✓ 4	0.80	1.60
TRUNK LID BADGE BMW	1	59.00	59.00
MODEL LETTERING X3	1	61.05	61.05
DECOUPLING RING PDC TORQUE CONVERTE	4	4.95	19.80
BUMPER PDC SENSOR (300 ALPINWEISS)	2	363.05	726.10
BUMPER PDC SENSOR (SCHWARZ)	2	231.10	462.20
Total Parts :			<b>6,173.30</b>

Claims OD / 3<sup>rd</sup> Party / Uninsured losses / Direct Settlement

Regn No. 14/2/17C 10.5 Claim No. 177/17  
 Name Tanjim Sign [Signature]  
 Tel No 97495749 Authorized Yes/No Yes  
 Time 7 days  
 Email tanjim@insuranc.com  
 Insurer [Signature]

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*[Handwritten Signature]*  
17/7/17

Labour 1	:	5,709.00
Parts	:	6,173.30
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	831.76
<b>Grand Total</b>	:	<b>12,714.06</b>

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*  
 \*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

13020.20

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## FINAL REPORT

Estimate No. : b1 43335  
Date Estimated : 07/07/2017  
Prepared By : Wong Yit Loong

Page No. :

**REPAIR FOR -**

NG MENG HUEH ILINI (HUANG MINGHUI ILINI)  
221 QUEENSWAY  
#05-01

SINGAPORE 276750

**- ACCOUNT - 705**

Allied World Assurance Company, Ltd SG br:  
60 Anson Road  
#09-01 Mapletree Anson  
Singapore 079914

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SLQ1142K	0W22508	28/06/2017	X3 sDrive20	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace boot lid and attachments, rear bumper and attachments, third stoplamp include knocking out dents caused by the accident	2125.00		2,125.00	
To spray paint rear bumper and boot lid	1805.00		1,805.00	
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00	
To transfer lock mechanism from old to new boot lid include conducting checks on new boot lid central locking system for proper function.	451.00		451.00	
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150.00		150.00	
To carry out body cavity preservation, (Per panel).	100.00		100.00	
# To remove and install rear windscreen glass to facilitate repairs include conducting checks for proper function	649.00		649.00	CR new
# To remove and install boot compartment carpet and garnish to facilitate repairs	231.00		231.00	CR new
Sundries	150.00		150.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
BOOTLID	1,763.15	1.00		1,763.15
# EXPANDING NUT *	1.00	2.00		2.00
RR BUMPER CARRIER ECE	720.05	1.00		720.05
FLAP TOWING EYE REAR	36.10	1.00		36.10
CLADDING BUMPER REAR (PDC/SCHWARZ)	192.55	1.00		192.55
REAR BUMPER PANEL PRIMED (PDC)	1,375.10	1.00		1,375.10
EMBLEM GROMMET	0.80	2.00		1.60

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



## FINAL REPORT

MODEL LETTERING X3	61.05	1.00	61.05
# TRUNK LID BADGE *	67.80	1.00	67.80
# EXPANDING RIVET *	1.35	10.00	13.50 <i>As new</i>
# THIRD STOPLAMP *	233.60	1.00	233.60 <i>As dis</i>
DECOUPLING RING PDC TORQUE CONVERTE	4.95	4.00	19.80

### # SUPPLEMENTARY ITEMS

Total Labour :	5,811.00
Total Parts :	4,486.30
Total Labour & Parts :	10,297.30
Deduction for Excess :	0.00
Total Repair Costs less Excess:	10,297.30
GST @7%:	720.81
Grand Total :	11,018.11

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



## SUPPLEMENTARY

Estimate No. : b1 43335  
Date Estimated : 07/07/2017  
Prepared By : Wong Yit Loong

Page No. :

REPAIR FOR -  
NG MENG HUEH ILINI (HUANG MINGHUI ILINI)  
221 QUEENSWAY  
#05-01

- ACCOUNT - 705  
Allied World Assurance Company, Ltd SG br.  
60 Anson Road  
#09-01 Mapletree Anson  
Singapore 079914

SINGAPORE 276750

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SLQ1142K	0W22508	28/06/2017	X3 sDrive20	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
# To remove and install rear windscreen glass to facilitate repairs include conducting checks for proper function	649.00		649.00	LA ✓
# To remove and install boot compartment carpet and garnish to facilitate repairs	231.00		231.00	LA ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING NUT *	1.00	2.00		2.00 nec ✓
# TRUNK LID BADGE *	67.80	1.00		67.80 repeated
# EXPANDING RIVET *	1.35	10.00		13.50 nec ✓
# THIRD STOPLAMP *	233.60	1.00		233.60 DR ✓

Total Labour : 880.00  
Total Parts : 316.90  
Total Labour & Parts : 1,196.90



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD

Ref : CS/AWA17013216/T1qh3n2

(SINGAPORE BRANCH)  
60 ANSON ROAD #08-01 (8th FLOOR)  
MAPLETREE ANSON  
SINGAPORE 079914

Date : 05-01-2018



Code : AWA

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SFC 357J	Veh. Inspected	SLQ 1142K
Policy No.	AVHWSB0021661604	Coverage (\$)	0.00
Claim No.	NSV1700802/SG	Excess (\$)	0.00
Assign From	STELLA GOH	Assign Date	07/07/2017

## 2. Vehicle Particulars & Condition

Make & Model	BMW X3	c.c	1997
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WBAWY920800W22508	Colour	WHITE
Odometer	1173	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/50 R18	PIRELLI	6 mm
L/H Front Tyre	245/50 R18	PIRELLI	6 mm
R/H Rear Tyre	245/50 R18	PIRELLI	6 mm
L/H Rear Tyre	245/50 R18	PIRELLI	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

## 5. General Information

Accident Date	06/07/2017	Inspection Date	14/07/2017
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 1142K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	SUNDRIES (SN)	NECESSARY	150.00	150.00
1	BOOTLID (SN)	DENTED	1,763.15	1,763.15
1	RR BUMPER CARRIER ECE (SN)	BENT	720.05	720.05
2	GASKET REAR CARRIER (SN)	NOT NECESSARY	9.80	-
1	FLAP TOWING EYE REAR (SN)	CUT	36.10	36.10
1	RR LH BUMPER MIDDLE MOUNTING (SN)	NOT NECESSARY	141.65	-
1	RR RH BUMPER MIDDLE MOUNTING (SN)	NOT NECESSARY	141.65	-
1	RR BUMPER LH MOUNT (SN)	NOT NECESSARY	197.45	-
1	RR BUMPER RH MOUNT (SN)	NOT NECESSARY	197.45	-
1	COVER MIDDLE BOTTOM (SN)	NOT NECESSARY	67.00	-
1	CLADDING BUMPER REAR (PDC/SCHWARZ)(SN)	DEFORMED	192.55	192.55
1	REAR BUMPER PANEL PRIMED (PDC)(SN)	DEFORMED	1,375.10	1,375.10
4	EMBLEM GRIMMET (SN)	NECESSARY (2 PCS ONLY)	3.20	1.60
1	TRUNK LID BADGE BMW (SN)	NECESSARY	67.80	67.80
1	MODEL LETTERING X3 (SN)	NECESSARY	61.05	61.05
4	DECOUPLING RING PDC TORQUE CONVERTE (SN)	NECESSARY	19.80	19.80
2	BUMPER PDC SENSOR (300 ALPINWEISS)(SN)	NOT NECESSARY	726.10	-
2	BUMPER PDC SENSOR (SCHWARZ)(SN)	NOT NECESSARY	462.20	-
2	EXPANDING NUT (ADDITIONAL)(SN)	NECESSARY	2.00	2.00
10	EXPANDING RIVET (ADDITIONAL)(SN)	NECESSARY	13.50	13.50
1	THIRD STOPLAMP (ADDITIONAL)(SN)	DISTORTED	233.60	233.60
			6,581.20	4,636.30
<b><u>LABOUR</u></b>				
REPLACE TRUNK LID, REAR BUMPER AND REMOVE ATTACHMENTS ETC INCLUDING KNOCK ON ACCIDENT DENT.			2,550.00	2,125.00
SPRAY REAR BUMPER, TRUNK LID.			2,006.00	1,805.00
TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION.			177.00	150.00
TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECKS ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION.			531.00	451.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE OLD PDC ASSEMBLY,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION.		177.00	150.00
	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL).		118.00	100.00
	TO RMEOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE REPAIRS INCLUDE CONDUCTING CHECKS FOR PROPER FUNCTION (ADDITIONAL).		649.00	649.00
	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS (ADDITIONAL).		231.00	231.00
			6,439.00	5,661.00
<b>GRAND TOTAL</b>			<b>13,020.20</b>	<b>10,297.30</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>10,297.30</b>

Report Ref No. CS/AWA17013216/T1qh3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.