

AUTO BEST MOTOR SERVICES

Block 3006 Ubi Road 1 #01-362 Singapore 408700

Registration No: 37684500K

Tel: 6745 6932 / 6746 8978 Fax: 6745 8669

20TH JULY 2018

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

RE: ACCIDENT INVOLVING SGB1717R ON 04/07/2017

Attn: Officer-In-Charge

Dear Sir/Madam,

We are please to submit a repair estimate for the damaged vehicle SGB1717R as follows:

Nett Item(s)

01 pc Front bumper
01 pc Front bumper side bracket RH
01 pc Front fender RH
01 pc Front fender inner liner RH
01 pc Front wheel cap RH

\$ 1358.00

\$ 68.60

\$ 859.89

\$ 162.09

\$ 65

\$ 2513.58

Less 10%

\$ 251.38

Nett Total

\$ 2262.20

Special Nett Item(s)

01 set Front bumper clip
01 set Front fender inner liner clip RH
01 set Front wheel rim RH

\$ 48.00

\$ 38.00

\$ 550.00

Labour and Miscellaneous

To check wiring for proper function.

\$ 30.00

To remove & refit front bumper sensor to facilitate repairs.

\$ 40.00

To transfer RH front wheel rim & conduct wheel balancing.

\$ 35.00

To conduct wheel alignment.

\$ 60.00

Balance C/forward

\$ 3063.20

AUTO BEST MOTOR SERVICES

Block 3006 Ubi Road 1 #01-362 Singapore 408700

Registration No: 37684500K

Tel: 6745 6932 / 6746 8978 Fax: 6745 8669

	Balance B/forward	\$ 3063.20
To re-set & re-programme ECU.		\$ NIL
To replace, repair, straighten & re-align all damaged parts.		\$ 400.00
To spray paint on all affected areas.		\$ 600.00
	Grand Total	<u>\$ 4063.20</u>

Please kindly contact me & send your surveyor down to survey the damaged vehicle the soonest possible.

Thank you and regards.

AUTO BEST MOTOR SERVICES

