

ASS. REC. BY:

Rasyul

REF:

CS/MSH17013395/R1rb 91

Special Instruction:

SURVEYOR

Maimun

ASSIGNMENT (Office)

From (Person):

Catherine Tina

of

MSH

Date/Time:

11/07/2007 3:21pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PA 4867U

Insured:

GW 8076A

at Workshop m/s

MOWA

Tel:

6272 3892

of

15 Tanjong Road

Policy No:

27797078TMV

Claim No:

521817

Sum Insured:

Excess:

Make of Veh:

D.O.A

03072017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

11/07/2007 3:29pm

Person Contacted:

ERIC

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

PA 4867U x

GW 8076A x

Sent peli through nenen

TOTAL

	
N/S	O/S
	

Survey Department Check List (Case Handler)

Reference No. : CG/MSA/17013395/Rib
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (Catherine): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code	✓			
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (Rasul): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By:

Rasul 30/1/18

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/21



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17013395/R1rb		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 11-07-2017		
		Code : MSG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GW 8076A	Veh. Inspected	PA 4867U	
Policy No.	27797078TMV	Coverage (\$)	0.00	
Claim No.	521817	Excess (\$)	0.00	
Assign From	MERIMEN (CATHERINE THIA)	Assign Date	11/07/2017	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	03/07/2017	Inspection Date		
Survey held at	MOVA AUTOMOTIVE PTE LTD 15 FAN YONG ROAD SINGAPORE 629792			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Jul 2017		11 Jul 2017 15:22 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	KOH PIA TENG, ID: S09070988, Tel: +6597721464, Email: NOEMAIL								
Main Claimant:	ASIA PACIFIC ALUMINIUM, Co. Reg. No.: 53175022A								
Vehicle Reg. No.:	PA4867U	Date of Loss:	03/07/2017 04:00 - :59						
Claim Type:	TP / 521817	Policy/Cover Note No.:	27797078TMV (Third Party Only) Coverage: 11/11/2016 - 10/11/2017						
Vehicle Reg. No. (Insured):	GW8076A	Policy No. (Claimant):							
		Excess:							
Repairer:	Mova Automotive Pte Ltd (Bukit Merah) No. 22 Jalan Kilang, #03-01, Mova Building, 159419 Bukit Merah - Tel: 62723892/64763333								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 12/07/2017]								
Driver/Custodian (Insured):	KOH PIA TENG (73 / Male), NRIC: S09070988, Tel: +6597721464								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Catherine Thia Shi Yi

Date: 14 Aug 2017

Preliminary Advice

Insured Vehicle No	: GW8076A	Accident Date	: 03/07/2017
TP Vehicle No	: PA4867U	Assignment Date	: 11/07/2017
Make	: MERCEDES-BENZ VITO 115	Est. Duration of Repair	: 3.00
Date of Inspection	: 03/08/2017		
Inspection At	: MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH) NO. 22 JALAN KILANG, #03-01, MOVA BUILDING SINGAPORE 159419		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,690.20
Revised Amount	:S\$	1,753.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,753.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.



Text size - +

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Business

Owner ID: 5022A

Vehicle Details

Vehicle No.: PA4667U

Vehicle to be
Exported: YesIntended De-
registration Date: 06 Jul 2017

Vehicle Make: MERCEDES BENZ

Vehicle Model: VITO 115L AT

Primary Colour: Silver

Manufacturing Year: 2004

Engine No.: 64698250078209

Chassis No.: WDF63970323082334

Maximum Power
Output: -

Open Market Value: \$43,751.00

Original Registration
Date: 15 Oct 2004First Registration
Date: 15 Oct 2004

Transfer Count: 2

Actual ARF Paid: \$2,188.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry
Date:PARF Rebate
Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 31 Jul 2019

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 5

POP Paid: \$20,383.00

COE Rebate Amount: \$8,427.00

**Total Rebate
Amount: \$8,427.00**

REPUBLIC OF SINGAPORE
DRIVING LICENCE



Licence Number: **S1178908J**
Name: **WONG AN SZE**
Birth Date: **21 Feb 1956**
Issue Date: **24 Dec 2003**


001061327K

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S1178908J**



Name: **WONG AN SZE**
王安慈
Race: **CHINESE**
Date of Birth: **21-02-1956** Sex: **M**
Country of Birth: **SINGAPORE**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

	PASS DATE
Class 2B Motorcycles not exceeding 200 cc	10 Nov 1976
Class 2A Motorcycles between 201 cc and 400 cc	10 Nov 1976
Class 2 Motorcycles exceeding 400 cc	10 Nov 1976
Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	30 Oct 1973

9011
1089


Licence No: S1178908J

NP 428A


2591661



NRIC No: **S1178908J**
Blood Group: **O+** Date of Issue: **10-03-1995**
APT BLK 630 JURONG WEST STREET 65 #09-412
SINGAPORE 640630
NRIC No: **S1178908J** Date: **07/01/2010** No: **6416414**

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

MOTOR @ INCOME.COM.SG

ACCIDENT STATEMENT

Date Of Report	05/07/2017 15:20
Date Of Accident	03/07/2017 04:00
Exact Location Of Accident	BLK 724A JURONG WEST ST 72 OPEN CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	PA4867U
Insured/Policyholder	
Name Of Registered Owner	ASIA PACIFIC ALUMINIUM
Co Reg No	53175022A
Email Address	SAMUELWONG@ASIAPACIFICALUMINIUM.COM
Mobile Phone No	(LOCAL) +65-90111089
Alternative Phone No	OFFICE-90111089

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	VITO 115-2.1 D (A)
Exact Purpose for which vehicle was being used at time of accident	COMPANY USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5063300313-03
Cover Note Number	15/10/2016 - 14/10/2017

Driver

Name of Driver	WONG AN SZE
NRIC No	S1178908J
Date Of Birth	21/02/1956
Occupation	INDOOR
Date Of Driving Pass	30/10/1973
Driving Experience	43 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90111089
Fax Number	
Contact Number	
Email Address	SAMUELWONG@ASIAPACIFICALUMINIUM.COM

Address	BLK 630 JURONG WEST ST 65 #09-412
Postcode	640630
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

MY VEHICLE WAS PARKED ALONG BLK 724A JURONG WEST ST 72 OPEN CARPARK ON 02/07/2017 (SUN) @ EVENING. EVERYTHING WAS FINE AND INTACT WHEN I LOCKED AND LEFT MY VEHICLE. ON 03/07/2017 (MON) @ 0400HRS, WHILE I WAS ASLEEP, SOMEONE CALLED ME ON MY MOBILE NUMBER AND INFORMED THAT VEHICLE B HAD HIT ONTO MY REAR PORTION AS VEHICLE B WAS INTENDING TO DRIVE OUT FROM HIS SAID CARPARK LOT. VEHICLE B FRONT LEFT MIRROR BRACKET HIT ONTO MY VEHICLE REAR PORTION, NO ONE WAS INJURED. THERE IS ONE INDEPENDANT WITNESS WHOM CAN BE REACHED AT MOBILE 8446-2188.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GW8076A
Vehicle Make/Model/Colour	LORRY
Details Of Properties	FRONT LEFT MIRROR BRACKET
Name of Driver	KOH PIA TENG
NRIC/Passport Number	S0907098B
Contact Number	97721464
Address	BLK 733 JURONG WEST ST 73 #02-26
Postcode	640733
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Details of Witness

Name	
Phone Number	84462188

Sketch Plan Pg. 1

NTUC Income Motor Service Centre

Vehicle No.

Report Date: 7/5/2017 Start Time: 3:35 PM

Report No: MT2

D.O.A.

Make / Model

Reporting Type

End Time

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



7/5/2017 15:35

7/5/2017 15:35

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

BLK 724A JURONG WEST ST 72 OPEN CARPARK					
Vehicle A: PA4887U		Vehicle B: GW8076A			

Sketch Plan Pg. 2

Describe Circumstances of the Accident

MY VEHICLE WAS PARKED ALONG BLK 724A JURONG WEST ST 72 OPEN CARPARK ON 02/07/2017 (SUN) @ EVENING. EVERYTHING WAS FINE AND INTACT WHEN I LOCKED AND LEFT MY VEHICLE. ON 03/07/2017 (MON) @ 0400HRS, WHILE I WAS ASLEEP, SOMEONE CALLED ME ON MY MOBILE NUMBER AND INFORMED THAT VEHICLE B HAD HIT ONTO MY REAR PORTION AS VEHICLE B WAS INTENDING TO DRIVE OUT FROM HIS SAID CARPARK LOT. VEHICLE B FRONT LEFT MIRROR BRACKET HIT ONTO MY VEHICLE REAR PORTION. NO ONE WAS INJURED. THERE IS ONE INDEPENDANT WITNESS WHOM CAN BE REACHED AT MOBILE 5446-2188.

Declaration

We declare the foregoing particulars are true in every respect.



7/5/2017 15:35

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

7/5/2017 15:35

Witnessed by Reporting Centre Personnel

Celine Fong (LKKAUTO)

From: Celine Fong (LKKAUTO)
Sent: Monday, 29 January 2018 3:57 PM
To: 'Samuel'; Rasul (LKKAUTO)
Cc: SUR
Subject: RE: Finalise PA4867U Mercedes Vito TP MSIG

Dear Samuel,

Confirm repair cost \$1,883.00 and 3 repair days.

Best Regards,

Celine Fong

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: celinefong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Samuel [<mailto:samuel@nova.com.sg>]
Sent: Monday, 29 January 2018 3:50 PM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: Finalise PA4867U Mercedes Vito TP MSIG

Dear Rasul,

Please kindly revert regarding the COR and number of working day.

Thanks!

Best Regards,
Samuel Ng

From: Samuel [<mailto:samuel@nova.com.sg>]
Sent: 09 January 2018 09:19
To: 'Rasul (LKKAUTO)'
Cc: 'sur@lkkauto.com'
Subject: FW: Finalise PA4867U Mercedes Vito TP MSIG

Dear Rasul,

Please kindly revert regarding the COR and number of working day.

Thanks!

Best Regards,
Samuel Ng



Main Office
 Mova Building
 No. 22, Jalan Kilang
 Singapore 159411
 Tel: (65) 6476 3331
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept
 Block 1008
 Bukit Merah Lane 3
 #01-04/06/08/9
 Singapore 15972

Tel: (65) 6272 3891
 Fax: (65) 6270 8314
 Co. Reg. 198904033C
 GST Reg. M2-0088564-

Estimate

10/07/2017

MSIG INSURANCE (S) PTE LTD (SGX CENTRE)
 16, RAFFLES QUAY
 #24-01 HONG LEONG BUILDING
 SINGAPORE 048581.

Attention :- XA013

Page # :- 1

Veh # :- PA4867U

Veh Model :- MERCEDES BENZ VITO

Estimate# :- CK416056

Claim # :-

ACC. Date :- 03/07/17

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

LIST ITEMS :

1.	REAR WINDSCREEN	1	PC	800.00	800.00
2.	REAR WIPER COVER	1	PC	25.00	25.00
3.	REAR WIPER ARM	1	PC	20.00	20.00
4.	TAILGATE	1	PC	2,500.00	2,500.00
5.	TAILGATE LOGO	1	PC	70.00	70.00
6.	TAILGATE GARNISH	1	PC		
7.	TAILGATE EMBLEM (VITO)	1	PC	55.00	55.00
8.	REAR BUMPER CENTER	1	PC	780.00	780.00
9.	REAR BUMPER LH	1	PC	250.00	250.00
10.	REAR BUMPER RH	1	PC	250.00	250.00
11.	REAR BUMPER REFLECTOR LH	1	PC	28.00	28.00

LIST TOTAL S\$

10% DISCOUNT S\$

4,778.00

-477.80

4,300.20

SPECIAL NET ITEMS :

1.	REAR WINDSCREEN SEALANT	1	PC	40.00	40.00
2.	REAR WINDSCREEN STICKER	1	PC	400.00	400.00
3.	STICKER (70KM/H)	1	PC	150.00	150.00
4.	REAR REVERSE SENSOR	1	PC	200.00	200.00

SPECIAL NET TOTAL S\$

790.00

LABOUR :

TO KNOCK AND STRAIGHTEN REAR END PANEL.
 REMOVE AND REPLACE ACCIDENT DAMAGED PARTS.
 TO REALIGN ALL CONNECTION

150 700.00

TO SPRAY ON REAR BUMPER, REAR BUMPER LH & RH
 TAILGATE

250 600.00

REMOVE AND REPLACE TAILGATE MECHANISM AND
 CHECK LOCKING SYSTEM

60 80.00

TO REMOVE AND REFIX REAR WINDSCREEN, IN ORDER
 TO CHECK WATER LEAKAGE

120.00

TO REMOVE AND REPLACE REVERSE SENSOR AND
 CHECK FUNCTION

X 100.00

LABOUR TOTAL S\$

1,500.00

Parts 1070.00
 - 10% 107.00
 963.00
 S/net 340.00
 Labour 580.00
 1543.00

P/P \$1,583.00



Main Office
Mova Building
No. 22, Jalan Kilang
Singapore 159411
Tel: (65) 6476 3331
Fax: (65) 6271 589
www.mova.com.sg

Workshop Dept
Block 1008
Bukit Merah Lane 3
#01-04/06/08/9
Singapore 15972
Tel: (65) 6272 3891
Fax: (65) 6270 8314
Co. Reg. 198904033C
GST Reg. M2-00888644

Estimate

10/07/2017

MSIG INSURANCE (S) PTE LTD (SGX CENTRE)
16, RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581.

Attention :- XA013

Page # :- 1 128746
Veh # :- PA4867U
Veh Model :- MERCEDES BENZ VITO
Estimate# :- CK416056
Claim # :-
ACC. Date :- 03/07/17
Terms :- C.O.D Days
Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$

6,690.20

GST @ 7 %

468.31

AMOUNT DUE S\$

7,158.51

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 9000068
3 days
P/P
03/08/17 @ 1645
Rang after repair



Automotive Pte Ltd



Main Office

Mova Building
No. 22, Jalan Kilang
Singapore 159411
Tel : (65) 6476 3331
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept

Block 100B
Bukit Merah Lane 3
#01-04/06/08/9-
Singapore 159721
Tel : (65) 6272 3891
Fax : (65) 6270 8311
Co. Reg. 1989040330
GST Reg. M2-00888641

Estimate

10/07/2017

MSIG INSURANCE (S) PTE LTD (SGX CENTRE)
16, RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581.

Attention :- XA013

Page # :- 1

Veh # :- PA4867U

Veh Model :- MERCEDES BENZ VITO

Estimate# :- CK416056

Claim # :-

ACC. Date :- 03/07/17

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR WINDSCREEN	1 PC	800.00	800.00
2.	REAR WIPER COVER	1 PC	25.00	25.00
3.	REAR WIPER ARM	1 PC	20.00	20.00
4.	TAILGATE	1 PC	2,500.00	2,500.00
5.	TAILGATE LOGO	1 PC	70.00	70.00
6.	TAILGATE GARNISH	1 PC		
7.	TAILGATE EMBLEM (VITO)	1 PC	55.00	55.00
8.	REAR BUMPER CENTER	1 PC	780.00	780.00
9.	REAR BUMPER LH	1 PC	250.00	250.00
10.	REAR BUMPER RH	1 PC	250.00	250.00
11.	REAR BUMPER REFLECTOR LH	1 PC	28.00	28.00
LIST TOTAL S\$				4,778.00
10% DISCOUNT S\$				-477.80
				4,300.20
SPECIAL NET ITEMS :				
1.	REAR WINDSCREEN SEALANT	1 PC	40.00	40.00
2.	REAR WINDSCREEN STICKER	1 PC	400.00	400.00
3.	STICKER (70KM/H)	1 PC	150.00	150.00
4.	REAR REVERSE SENSOR	1 PC	200.00	200.00
SPECIAL NET TOTAL S\$				790.00
LABOUR :				
TO KNOCK AND STRAIGHTEN REAR END PANEL. REMOVE AND REPLACE ACCIDENT DAMAGED PARTS. TO REALIGN ALL CONNECTION				150 700.00
TO SPRAY ON REAR BUMPER, REAR BUMPER LH & RH TAILGATE				250 600.00
REMOVE AND REPLACE TAILGATE MECHANISM AND CHECK LOCKING SYSTEM				60 60.00
TO REMOVE AND REFIX REAR WINDSCREEN, IN ORDER TO CHECK WATER LEAKAGE				120.00
TO REMOVE AND REPLACE REVERSE SENSOR AND CHECK FUNCTION				11 X 100.00
LABOUR TOTAL S\$				1,600.00



Estimate

10/07/2017

MSIG INSURANCE (S) PTE LTD (SGX CENTRE)
16, RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581.

Attention :- XA013

Page # :- 1 128746
Veh # :- PA4867U
Veh Model :- MERCEDES BENZ VITO
Estimate# :- CK416056
Claim # :-
ACC. Date :- 03/07/17
Terms :- C.O.D Days
Remarks :-

Main Office
Mova Building
No. 22, Jalan Klang
Singapore 15941
Tel : (65) 6476 333
Fax : (65) 6271 589
www.mova.com.sg

Workshop Dept
Block 1008
Bukit Merah Lane 3
#01-04/06/08/9
Singapore 15972
Tel : (65) 6272 389
Fax : (65) 6270 831
Co. Reg. 19890403K
GST Reg. M2-0088854-

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S	6780.20
AMOUNT S\$	6,690.20
GST @ 7 %	468.31
AMOUNT DUE S\$	7,158.51

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul
Hp 90010068
3 days
P/P
03/08/17 @ 1645
Rang after repair
16/8/17

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Jul 2017		11 Jul 2017 15:22 Edit Adj Rpt	S\$1,883.00 Edit Estimates	S\$1,883.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	KOH PIA TENG, ID: S0907098B, Tel: +6597721464, Email: NOEMAIL	
Main Claimant:	ASIA PACIFIC ALUMINIUM, Co. Reg. No.: 53175022A	
Vehicle Reg. No.:	PA4867U	Date of Loss: 03/07/2017 04:00 - :59
Claim Type:	TP / 521817	Policy/Cover Note No.: 27797078TMV (Third Party Only) Coverage: 11/11/2016 - 10/11/2017
Vehicle Reg. No. (Insured):	GW8076A	Policy No. (Claimant):
		Excess:
Repairer:	Mova Automotive Pte Ltd (Bukit Merah) No. 22 Jalan Kilang, #07-01, Mova Building, 159419 Bukit Merah - Tel: 62723892/64763333	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 10/08/2017]	
Driver/Custodian (Insured):	KOH PIA TENG (73 / Male), NRIC: S0907098B, Tel: +6597721464	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

*PA4867U (521817)
[GW8076A]
TP
ASIA PACIFIC ALUMINIUM
Jul 3 2017 4:00AM
[KOH PIA TENG]
Mova Automotive Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
View
[View in Browser](#)

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	11/07/17 15:22	Accident Statement From: SC - Reg. No: GW8076A, Claimant: KOH PIA TENG	 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/08/17 18:13	Adjuster Immediate Advice	 Load HTM	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/01/18 17:27	General View	 Load JPG	☒
2	29/01/18 17:27	General View	 Load JPG	☒
3	29/01/18 17:27	General View	 Load JPG	☒
4	29/01/18 17:27	General View	 Load JPG	☒
5	29/01/18 17:27	General View	 Load JPG	☒
6	29/01/18 17:27	General View	 Load JPG	☒
7	29/01/18 17:27	General View	 Load JPG	☒
8	29/01/18 17:27	General View	 Load JPG	☒
9	29/01/18 17:27	General View	 Load JPG	☒
10	29/01/18 17:27	General View	 Load JPG	☒
11	29/01/18 17:27	General View	 Load JPG	☒
12	29/01/18 17:27	General View	 Load JPG	☒
13	29/01/18 17:27	General View	 Load JPG	☒
14	29/01/18 17:27	General View	 Load JPG	☒
15	29/01/18 17:27	General View	 Load JPG	☒
16	29/01/18 17:27	General View	 Load JPG	☒
17	29/01/18 17:27	General View	 Load JPG	☒
18	29/01/18 17:27	General View	 Load JPG	☒
19	29/01/18 17:27	General View	 Load JPG	☒
20	29/01/18 17:27	General View	 Load JPG	☒
21	29/01/18 17:27	General View	 Load JPG	☒
22	29/01/18 17:27	General View	 Load JPG	☒
23	29/01/18 17:27	General View	 Load JPG	☒
24	29/01/18 17:27	Photo After Spray	 Load JPG	☒
25	29/01/18 17:27	Photo After Spray	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	11/07/17 15:22	TP PA4867U GIA REPORT From: SC - Reg. No: GW8076A, Claimant: KOH PIA TENG	 Load PDF	
2	11/07/17 15:26	ESTIMATE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17013395/R1RBQ2

Date: 01/02/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 27797078TMV

Claimant Vehicle No: PA4867U

Insured Vehicle No: GW8076A

Date of Loss: 03/07/2017

Nature of Claim: TP

Claim No: 521817

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: PA4867U

Make & Model: MERCEDES-BENZ VITO 115, 2.1 D (A)

Engine No: 64698250078209

Reg. Date: 15/10/2004 (Man. Year: 2004)

Chassis No: WDF63970323082334

Colour: Grey

Odometer: 251537 km

Engine Capacity: 2148 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60 R16

Rear Tyre Size: 225/60 R16

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,180.20	1,303.00	3,877.20	74.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	580.00	1,020.00	63.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,780.20	1,883.00	4,897.20	72.23
+ GST 7.00/7.00% (S\$)	474.61	131.81	342.80	72.23
Nett Amount (S\$)	7,254.81	2,014.81	5,240.00	72.23

INSPECTION

Date of Assignment: 11/07/2017

Date Inspected: 03/08/2017 Inspected At:

Mova Automotive Pte Ltd (Bukit Merah)
No. 22 Jalan Kilang, #03-01, Mova Building
Singapore 159419

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 01 Feb 2018)	
Parts:	N/A	MERCEDES-BENZ VITO 115 2.1 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PA4867U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN	Broken	800.00 FL	*800.00 FL
2	1		*REAR WIPER COVE	Cracked	25.00 FL	*25.00 FL
3	1		*REAR WIPER ARM	Scratched	120.00 FL	*120.00 FL
4	1		*TAILGATE	Repair	2,500.00 FL	*- FL
5	1		*TAILGATE LOGO	Necessary	70.00 FL	*70.00 FL
6	1		*TAILGATE GARNISH (NPA)	Not Necessary	0.00 FL	*- FL
7	1		*TAILGATE EMBLEM (VITO)	Necessary	55.00 FL	*55.00 FL
8	1		*REAR BUMPER CENTER	Serviceable	780.00 FL	*- FL
9	1		*REAR BUMPER LH	Serviceable	250.00 FL	*- FL
10	1		*REAR BUMPER RH	Serviceable	250.00 FL	*- FL
11	1		*REAR BUMPER REFLECTOR LH	Serviceable	28.00 FL	*- FL
12	1		*REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
13	1		*REAR WINDSCREEN STICKER	Necessary	400.00 FS	*150.00 FS
14	1		*STICKER (70KM/H)	Necessary	150.00 FS	*150.00 FS
15	1		*REAR REVERSE SENSOR	Serviceable	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,668.00	1,410.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	487.80	107.00
Total Parts (\$\$)	5,180.20	1,303.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCK AND STRAIGHTEN REAR END PANEL.REMOVE AND REPLACE ACCIDENT DAMAGED PARTS.TO REALIGN ALL CONNECTION	New	700.00	150.00
2	TO SPRAY ON REAR BUMPER ,REAR BUMPER LH & RH TAILGATE	New	600.00	250.00
3	REMOVE AND REPLACE TAILGATE MECHANISM AND CHECK LOCKING SYSTEM	New	80.00	60.00
4	TO REMOVE AND REFIX REAR WINDSCREEN ,IN ORDER TO CHECK WATER LEAKAGE	New	120.00	120.00
5	TO REMOVE AND REPLACE REVERSE SENSOR AND CHECK FUNCTION	New	100.00	0.00
Gross Labour Cost (S\$)			1,600.00	580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >