

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5003Z -

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

*Not Authorised**L1Ln @ 2500***AAD1707-067****SHC5003Z - CANDY**

VF1ABL15AUC275212

RENAULT

LATITUDE

06.07.2017

*China Taiping***PART****LIST**

1	1	BUMPER COVER FRT	\$	<i>Bu</i>	1,259.42	✓
2	1	BUMPER RETAINER FRT LH	\$	<i>Sn</i>	151.41	X
3	1	BUMPER BRACKET FRT LH	\$	<i>R</i>	181.75	X
4	1	BUMPER UNDERTRAY FRT	\$	<i>Sn</i>	472.83	X
5	1	BUMPER GRILLE LOWER FRT	\$	<i>Sn</i>	266.80	} X
6	1	BUMPER FOG LAMP GRILLE LH	\$	<i>Sn</i>	207.22	
7	1	BUMPER SPOILER FRT	\$	<i>Sn</i>	181.75	
8	1	BUMPER BEAM FRT	\$	<i>R</i>	914.08	
9	1	RADAIOR GRILLE	\$	<i>Sn</i>	1,707.78	
10	1	RADAIOR GRILLE BADGE 'RENAULT'	\$	<i>Sn</i>	225.36	
11	1	RADAIOR GRILLE FRAME	\$	<i>Sn</i>	1,353.75	
12	1	FRAME FULL SUPPORT PANEL	\$	<i>Sn</i>	615.90	} X
13	1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i>	89.79	
14	1	HEADLAMP LH	\$	<i>Right</i>	1,184.43	✓
15	1	HEADLAMP PANEL FRT LH	\$	<i>R</i>	152.15	X
16	1	AIR CLEANER LOWER	\$	<i>Sn</i>	352.64	X
17	1	AIR CLEANER HOSE	\$	<i>Sn</i>	76.14	X
18	1	FENDER PANEL FRT LH	\$	<i>R</i>	783.83	X
19	1	WHEELARCH FRT LH	\$	<i>Sn</i>	278.84	X
20	1	ROCKER PANEL OUTER LH	\$	<i>R</i>	987.49	X
21	1	DOOR PANEL FRT LH	\$	<i>R</i>	2,844.66	X
22	1	DOOR MIRROR LH	\$	<i>Sn</i>	1,483.40	X
23	1	DOOR MIRROR GLASS LH	\$	<i>Sn</i>	148.20	X
24	1	DOOR MIRROR BACK COVER LH	\$	<i>Sn</i>	218.46	X
25	1	DOOR HINGE UPPER LH	\$	<i>R</i>	274.50	X
26	1	DOOR HINGE LOWER LH	\$	<i>R</i>	300.55	X

TOTAL	\$	16,713.14
10%	\$	1,671.31
	\$	15,041.83

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5003Z -**AAD1707-067****Specical Nett**

1	1SET	WHEELARCH CLIP FRT LH	\$	nn	66.00	X
2	1SET	FRONT BUMPER CLIP	\$	nn	66.00	✓
3	1	RIM LH FRT	\$	nn	385.00	X
4	1	TYRE LH FRT	\$	nn	330.00	X
5	1	DOOR STICKER "Trans-cab"	\$	nn	80.00	X
6	1	DOOR STICKER "Classic"	\$	nn	30.00	X
7	1	DOOR STICKER "6555-3333"	\$	nn	80.00	X
8	2	Rear Windscreen Sealant	\$	nn	100.00	X
9	1	Rear Windscreen Inner Sponge Seal	\$	nn	150.00	X
10	1SET	WHEELARCH CLIP RR	\$	nn	15.00	X
11	1	RIM LH RR	\$	nn	385.00	X
12	1	TYRE LH RR	\$	nn	330.00	X
13	1SET	WHEELARCH CLIP RR LH	\$	nn	66.00	X
14	1	FENDER FINISHER COVER CLIP REAR LH	\$	nn	20.00	X
15	1SET	REAR BUMPER CLIP	\$	nn	66.00	X
16	1SET	BUMPER RETAINER LH CLIP RR	\$	nn	20.00	X

TOTAL	\$	2,189.00
TOTAL PARTS	\$	17,230.83

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 2,800.00 400

To Check Electrical Lighting Concerned.

\$ 170.00 200

Putty and spray painting of the affected portion.

\$ 3,000.00 400

To transfer of rear fender fittings, attachment and perform water seepage test.

\$ nn 380.00 X

To check steering geometry and computer wheel alignment

\$ nn 220.00 X

Towing fees

\$ nn 120.00 X

To rust-proofing of the affected areas.

\$ nn 170.00 X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1707-067**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5003Z -

To Remove And Refit Rear W/Screen Glass To
Facilitate Bodywork Repair.

\$ *nn* 170.00 X

To transfer of door fittings, attachment and
perform water seepage test.

\$ *nn* 170.00 X

TOTAL	\$	7,200.00
Over All Total	\$	24,430.83

(PARTS BY PARTS) Repair Days**10 Days***2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: