


Accident involving RD 6227 P & SKV 5261 J & SJB 6193 H along 49 Jalan Pemimpin on 07/07/17.

From: Hassim, Mohd Fitri

To: assignments, Admin A

Cc: Tan, Lily (AIG), Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Leong, Kah Yin, Lim, Sheng Yang, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran

Sent: Wednesday, 12 July, 2017 10:14:36 AM

Attachments:  11072017144514.pdf

Hi,

Please refer to the enclosed request from **Soon Hock Motor Pte Ltd**

Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Thanks

Mohd Fitri Bin Hassim

AIG

Express Claims Adjuster II

FNOL-Singapore Windscreen | AIG Shared Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 14, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia

Tel: 8001206556 Ext: 1012117

MohdFitri.Hassim@aig.com | www.aig.com

12-07-2017 @ 1022am
Chris Verin
Kenneth

IMPORTANT NOTICE

The information in this email (and any attachments hereto) is confidential and may be protected by legal privileges and work product immunities. If you are not the intended recipient, you must not use or disseminate the information. Receipt by anyone other than the intended recipient is not a waiver of any attorney-client or work product privilege. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE

IMPORTANT NOTE : Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : _____ Vehicle Registration No : SKV 52613
Name(as shown in NRIC): _____
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
NRIC/Passport No : _____
Address : _____
Contact (Tel) : _____ (H/P) : _____
(Email) : _____
Date of Accident : 07/07/17 Time of Accident : _____
Place of Accident : _____
Insurance Company : MG

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

* "THIRD PARTY VEHICLE SHOULD BE RD 6227P. THAT'S ALL" *

Signature of Vehicle Owner / Driver

Date:

GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE

IMPORTANT NOTE : Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : _____ Vehicle Registration No : SKV 52613
Name(as shown in NRIC): _____
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
NRIC/Passport No : _____
Address : _____
Contact (Tel) : _____ (H/P) : _____
(Email) : _____
Date of Accident : 07/07/17 Time of Accident : _____
Place of Accident : _____
Insurance Company : MG

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

* "THIRD PARTY VEHICLE SHOULD BE RD 6227P. THAT'S ALL" *

Signature of Vehicle Owner / Driver

Date: 17/7/17

10 Anson Road #06-16 International Plaza Singapore 079903 Phone : + 65 6224 0010 Fax : +65 6224 0030
Operating Hours : Monday to Friday 9am to 5pm

Vic (LKKAuto)

From: Tan, Bennie-WZ <Bennie-WZ.Tan@aig.com>
Sent: Monday, 8 October, 2018 2:42 PM
To: Vic (LKKAuto)
Cc: Admin A
Subject: RE: <SEEK MANDATE> Your Ref: 5030539595SG_ACCIDENT INVOLVING VEHICLES SKV 5261J (OI) / RD 6227P (TP) / OTHERS ON 07/07/2017

Hi Vic

Referring to your email.

Please find our responses to the damages below:

1. Rear Boot – **Repair** 4, 5, 13
2. Rear Fender Air Duct – **Photo?** 42-44
3. Set Rear Fender Shield Clips – **Not Necessary** -15
4. Rear Stabilizer bar – **Not Damaged** -41
5. Rear Crossmember – **Not Damaged** - 34, 32, 33
6. ABS Sensor – **Not Damaged** - SHORT CIRCUIT.
7. Front Number Plate Screw – **X** NAC SPECIAL SCREW.
8. Rear Number Plate – **X**
9. Rear Number Plate Screw – **X** } NAC TO REPLACE BOTH REAR BOOT.
10. Rear Tyre Hub Cap – **Not Damaged** 10-12.
11. Towing Charges – **Towing Slip?**

est Regards

Bennie Tan
AIG
Senior Complex Claims Examiner
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1718 | Fax +(65) 6835 7416

Bennie-WZ.Tan@aig.com | www.aig.com.sg

From: Vic (LKKAuto) [mailto:vicalpeh@lkkauto.com]
Sent: Monday, September 10, 2018 9:33 AM
To: Tan, Bennie-WZ
Cc: Admin A; Vic (LKKAuto)
Subject: RE: <SEEK MANDATE> Your Ref: 5030539595SG_ACCIDENT INVOLVING VEHICLES SKV 5261J (OI) / RD 6227P (TP) / OTHERS ON 07/07/2017

Dear Bennie,

Jia Le (LKK Auto)

From: Jia Le (LKK Auto)
Sent: Monday, 6 January 2020 2:49 PM
To: Soon Hock Motor
Subject: RE: Your Ref: RD 6227P_ACCIDENT INVOLVING VEHICLES SKV 526J / RD 6227P / OTHERS ON 07/07/2017

WITHOUT PREJUDICE

Dear Sirs/Mdm,

ACCIDENT INVOLVING SKV 5261J & RD 6227P ON 07/07/2017

We refer to the above matter.

We regret to inform you that our principal maintained settlement at a global sum of **\$10,720.00(all-in).**

Please re-consider our offer.

Thank you.

"Wishing you a Happiness and Prosperity New Year"

Best Regards,

Chan Jia Le | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Soon Hock Motor [mailto:soonhockmotor@gmail.com]

Sent: Friday, 3 January 2020 9:31 AM

To: Jia Le (LKK Auto)

Subject: Re: Your Ref: RD 6227P_ACCIDENT INVOLVING VEHICLES SKV 526J / RD 6227P / OTHERS ON 07/07/2017

Your Ref : SKV 526 J (AIG)

Our Ref : MTP/4968/2017

WITHOUT PREJUDICE

Dear Jia Le,

Your email below refers.

We appreciate your effort in trying to settle this matter amicably but your offer is not acceptable.

We put on record that our client's taxi number RD 6227 P was surveyed by your surveyor, Kenneth Kong (Single Joint Expert) in compliance with the new protocol.

To resolve this matter amicably, we are prepared to compromise and counter offer settlement at a global sum of \$13,500.00.

Kindly review this matter and let us hear from you soon.

Thank you and have a nice day ahead !

Best Regards
William
Claims Department

Soon Hock Motor Pte Ltd
10 Ang Mo Kio Industrial Park 2A
#01-05/06 AMK AutoPoint
Singapore 568047

Tel : 6483-6016
Fax : 6483-6015

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.
It may contain confidential and/or legally privileged information.
If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.
Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.



Save the trees - Do you really need to print this e-mail?

On Tue, Nov 12, 2019 at 3:19 PM Jia Le (LKK Auto) <JiaLe@lkkauto.com> wrote:

WITHOUT PREJUDICE

Dear Sirs/Mdm,

ACCIDENT INVOLVING SKV 5261J & RD 6227P ON 07/07/2017

We refer to the above matter.

We propose settlement at a global sum of **\$10,720.00(all-in).**

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Chan Jia Le | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Vic (LKKAuto)

Sent: Tuesday, 12 December, 2017 9:48 AM

To: soonhockmotor@gmail.com

Cc: Admin A; Asher Sng (LKKAuto); Vic (LKKAuto)

Subject: RE: Your Ref: RD 6227P_ACCIDENT INVOLVING VEHICLES SKV 526J / RD 6227P / OTHERS ON 07/07/2017

Without Prejudice

Dear William,

We refer further to our below email and to our telephone conversation earlier.

As discussed, we had just received the LOD and documents. We would also like to request for a copy of the CCTV Footage and the statement to support for the Loss of Revenue for our principal's mandate approval.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contains confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Vic (LKKAuto)

Sent: Monday, 20 November, 2017 9:00 AM

To: soonhockmotor@gmail.com

Cc: Admin A; Vic (LKKAuto); Asher Sng (LKKAuto)

Subject: Your Ref: RD 6227P_ACCIDENT INVOLVING VEHICLES SKV 526J / RD 6227P / OTHERS ON 07/07/2017

Your Ref: RD 6227P Without Prejudice

Our Ref: CC4/AIG17013521

Dear William,

ACCIDENT INVOLVING VEHICLES SKV 526J / RD 6227P / OTHERS ON 07/07/2017

We refer to the above matter.

We would like to request for a copy of your client's CCTV footage as our principal is requesting for the same copy.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contains confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

View Received Message

This mail is associated with :

***RD6227P (5030539595SG)
[SKV5261J]**

TP
HDT SINGAPORE TAXI TE LTD
Jul 7 2017 12:00AM
[Ang Pau Ju Jasmine]
Soon Hock Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 12/11/2019 14:09 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$10720.00) - RD6227P - Claim Handler: Tan, Bennie-WZ

Approved:10720,00:Pls do your utmost to negotiate at best from: \$10.5k to \$10,720 (All-in) Subj to Final Repair Bill, GIA/LTA Search Bill in order

DOCUMENTS SUMMARY

There are no documents.



SOON HOCK MOTOR PTE LTD

Our Ref : MTP/4968/2017

Your Ref : CC4/AIG17013521

Date :

-7 FEB 2020

M/s LKK Auto Consultants Pte Ltd
Blk 51 Paya Ubi Industrial Park
#02-25
Ubi Avenue 1
Singapore 408933

WITHOUT PREJUDICE

Attention : Vic Alpeh
Case Handler

Dear Vic,

**ACCIDENT INVOLVING RD 6227 P & SKV 526 J ALONG OUTSIDE OF 49 JALAN
PEMIMPIN ON 07-07-2017**

Your email of 04-01-2020 refers.

Strictly on a without prejudice basis and without any admission of liability, we confirm settlement for our client's property damage claim (Cost of repair, GIA search fee and the Loss of Revenue during the period of repair) at a global sum of \$10,720.00.

Please note that the settlement reached is strictly for the aforesaid property damage claim only and is without prejudice to the driver of RD 6227 P, Ng Seong Chee Stewart's rights to claim damage for his injury against your principals, M/s AIG Asia Pacific Insurance Pte Ltd and /or their insured, if any.

As requested, we return the attached Release Voucher duly executed for your onward transmission.

Kindly expedite payment and forward us your cheque for the sum of **\$10,720.00** made in favour of **M/s Soon Hock Motor Pte Ltd** as soon as possible.

Thank you.

Yours faithfully,

For **SOON HOCK MOTOR PTE LTD**

Claims Department

Enc

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Jul 2017 Edit Reg		12 Jul 2017 00:00 Edit Adj Rpt	S\$11,300.00 Edit Estimates	S\$11,300.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	Ang Pau Ju Jasmine, ID: S1788056Z, Tel: +6596943366		
Main Claimant:	HDT SINGAPORE TAXI TE LTD, Co. Reg. No.: 201609494H		
Vehicle Reg. No.:	RD6227P	Date of Loss:	07/07/2017 00:00 - :59 [6 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 5030539595SG	Policy/Cover Note No.:	2100430219 (Comprehensive)
Vehicle Reg. No. (Insured):	SKV5261J	Policy No. (Claimant):	5091754572
		Excess:	
Repairer:	Soon Hock Motor Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 21/07/2017]		
Driver/Custodian (Insured):	ANG TECK CHIA (), NRIC: S0287680I Email:		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (06/01/2020): Alert - Adj Mandate Maintained - RD6227P - Claim Handler: Tan, Bennie-WZ
- AIG_SG_EXPRESS (12/11/2019): Alert - Adj Mandate Approved (S\$10720.00) - RD6227P - Claim Handler: Tan, Bennie...
- AIG_SG_EXPRESS (08/10/2018): Alert - Adj Mandate Maintained - RD6227P - Claim Handler: Tan, Bennie-WZ
- AIG_SG_EXPRESS (16/05/2018): Alert - Adj Mandate Maintained - RD6227P - Claim Handler: Tan, Bennie-WZ

ALL ASSOCIATED TASKS


































[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*RD6227P (5030539595SG)
[SKV5261J]
TP
HDT SINGAPORE TAXI TE LTD
Jul 7 2017 12:00AM
[Ang Pau Ju Jasmine]
Soon Hock Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser ▼	
Letters/Correspondences			1 per page ▼ <input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	1	Edit
Assessment Reports			1 per page ▼ <input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	13/07/17 15:13	Accident Statement From: OD - Reg. No: SKV5261J, Claimant: ANG PAU JU JASMINE	1	Load HTM
Photos/Images			3 per page ▼ <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	08/12/17 11:41	Odometer Reading	1	Load JPG <input checked="" type="checkbox"/>
2	08/12/17 11:41	Chassis Number	1	Load JPG <input checked="" type="checkbox"/>
3	08/12/17 11:41	General View	1	Load JPG <input checked="" type="checkbox"/>
4	08/12/17 11:41	General View	1	Load JPG <input checked="" type="checkbox"/>
5	08/12/17 11:41	General View	1	Load JPG <input checked="" type="checkbox"/>
6	08/12/17 11:41	General View	1	Load JPG <input checked="" type="checkbox"/>
7	08/12/17 11:41	General View	1	Load JPG <input checked="" type="checkbox"/>
8	08/12/17 11:41	General View	1	Load JPG <input checked="" type="checkbox"/>
9	08/12/17 11:41	General View	1	Load JPG <input checked="" type="checkbox"/>
10	08/12/17 11:41	General View	1	Load JPG <input checked="" type="checkbox"/>
11	08/12/17 11:41	General View	1	Load JPG <input checked="" type="checkbox"/>
12	08/12/17 11:41	General View	1	Load JPG <input checked="" type="checkbox"/>
13	08/12/17 11:41	General View	1	Load JPG <input checked="" type="checkbox"/>
14	08/12/17 11:41	General View	1	Load JPG <input checked="" type="checkbox"/>
15	08/12/17 11:41	General View	1	Load JPG <input checked="" type="checkbox"/>
16	08/12/17 11:41	General View	1	Load JPG <input checked="" type="checkbox"/>
17	08/12/17 11:41	General View	1	Load JPG <input checked="" type="checkbox"/>
18	08/12/17 11:41	General View	1	Load JPG <input checked="" type="checkbox"/>
19	08/12/17 11:41	General View	1	Load JPG <input checked="" type="checkbox"/>
20	08/12/17 11:41	General View	1	Load JPG <input checked="" type="checkbox"/>
21	08/12/17 11:41	General View	1	Load JPG <input checked="" type="checkbox"/>
22	08/12/17 11:41	General View	1	Load JPG <input checked="" type="checkbox"/>
23	08/12/17 11:41	General View	1	Load JPG <input checked="" type="checkbox"/>
24	08/12/17 11:41	General View	1	Load JPG <input checked="" type="checkbox"/>
25	08/12/17 11:41	General View	1	Load JPG <input checked="" type="checkbox"/>
26	08/12/17 11:41	General View	1	Load JPG <input checked="" type="checkbox"/>
27	08/12/17 11:41	General View	1	Load JPG <input checked="" type="checkbox"/>
28	08/12/17 11:41	General View	1	Load JPG <input checked="" type="checkbox"/>

Letters/Correspondences			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
29	08/12/17 11:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
30	08/12/17 11:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
31	08/12/17 11:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
32	08/12/17 11:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
33	08/12/17 11:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	08/12/17 11:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	08/12/17 11:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	08/12/17 11:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	08/12/17 11:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	08/12/17 11:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	08/12/17 11:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	08/12/17 11:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	08/10/19 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	08/10/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	08/10/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	08/10/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	08/10/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	08/10/19 11:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
47	08/10/19 11:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
48	08/10/19 11:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
49	08/10/19 11:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
50	08/10/19 11:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/07/17 16:33	EMAIL FROM AIG DD 12072017	 Load PDF	
2	12/07/17 16:33	TP GIA REPORT	 Load PDF	
3	13/07/17 16:57	TP ESTIMATE- MARKED	 Load PDF	
4	14/07/17 14:30	EMAIL TO OI	 Load PDF	
5	23/04/18 12:12	GIA SEARCH	 Load PDF	
6	05/11/19 10:51	TOWING INVOICE	 Load PDF	
7	10/01/20 16:38	EMAIL TO WKSP DATED 060120	 Load PDF	
8	28/02/20 09:32	LOD	 Load PDF	
9	28/02/20 09:32	Authorisation to Act	 Load PDF	
10	28/02/20 09:32	Release Voucher	 Load PDF	
11	28/02/20 09:32	WORKSHOP INVOICE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKV5261J (Insd veh)	Model:	BYD E6Y (A)
	RD6227P (TP veh)		
Date of Accident:	07/07/2017		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Repair Estimate	: \$			25,996.23
Final Repair Cost	: \$			10,720.00
Loss of Use	: \$			18.00 days at \$100.00 per day
Rental (if any)	: \$			days
LTA / GIA Search Fee	: \$			
Others:	: \$			
	: \$			
Final Settlement Sum (GLOBAL SUM)	: \$			10,720.00
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)				
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	Soon Hock Motor Pte Ltd	: \$	10,720.00
2)		: \$	
3)		: \$	

NUR SHAQILAH BTE ABDOL WAHAB

28 Feb
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG17013521/KDS3S2
 Date: 28/02/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100430219
 Claimant Vehicle No: RD6227P Insured Vehicle No: SKV5261J
 Date of Loss: 07/07/2017 Nature of Claim: TP Claim No: 5030539595SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: RD6227P Engine No: HIDDEN
 Make & Model: BYD E6Y, (A) Chassis No: LC0CE4DB6H1012683
 Reg. Date: 01/01/2017 (Man. Year: 2017) Odometer: 20 km
 Colour: Green
 Engine Capacity: 0 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/65R17 Rear Tyre Size: 225/65R17
 Front Left Side: Maxxis 10 mm Rear Left Side: Maxxis 10 mm
 Front Right Side: Maxxis 10 mm Rear Right Side: Maxxis 10 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,276.23	10,740.05	9,536.18	47.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,720.00	3,480.00	2,240.00	39.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,996.23	14,220.05	11,776.18	45.30
Approved Total (Overridden) (S\$)		11,300.00		
Nett Amount (S\$)	25,996.23	11,300.00	14,696.23	56.53
+ Loss of Use (18.0 x S\$100.00/day) (S\$)		1,800.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		13,102.00		
Global Sum Settlement (S\$)		10,720.00		

INSPECTION

Date of Assignment: 12/07/2017
 Date Inspected: 12/07/2017 Inspected At: Soon Hock Motor Pte Ltd (HQ)
 Blk 10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK
 Autopoint
 Singapore 568047
 Estimated Period of Repair: 12.0 days

Adjuster: KENNETH KONG**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	1,262.64 FL	*1,262.64 FL
2	1		*FRONT BUMPER LAMP (LH)	Serviceable	762.10 FL	*- FL
3	1		*FRONT BUMPER SIDE GRILLE (LH)	Serviceable	48.36 FL	*- FL
4	1		*FRONT BUMPER CENTRE GRILLE	Serviceable	214.32 FL	*- FL
5	1		*FRONT BUMPER SIDE BRACKET (LH)	Distorted	28.56 FL	*28.56 FL
6	1		*FRONT BUMPER REINFORCEMENT	Repair	631.32 FL	*- FL
7	1		*FRONT HEADLAMP (LH)	Serviceable	1,388.40 FL	*- FL
8	1		*FRONT HEADLAMP PANEL	Repair	1,080.60 FL	*- FL
9	1		*FRONT GRILLE	Distorted	1,531.80 FL	*1,531.80 FL
10	1		*SET FRONT GRILLE CLIPS	Necessary	30.00 FL	*30.00 FL
11	1		*FRONT BONNET	Repair	1,631.21 FL	*- FL
12	1		*FRONT FENDER (LH)	Repair	742.80 FL	*- FL
13	1		*FRONT AIRCON CONDENSOR	Serviceable	825.22 FL	*- FL
14	1		*FRONT RADIATOR	Serviceable	1,020.24 FL	*- FL
15	1		*REAR BUMPER	Buckled	996.72 FL	*996.72 FL
16	1		*REAR BUMPER SIDE BRACKET (RH)	Distorted	33.96 FL	*33.96 FL
17	1		*REAR BUMPER TOP BRACKET (RH)	Repair	34.78 FL	*- FL
18	1		*REAR BUMPER SIDE REFLECTOR (RH)	Broken	38.40 FL	*38.40 FL
19	1		*REAR BUMPER REINFORCEMENT	Bent	605.22 FL	*605.22 FL
20	1		*REAR BUMPER REINFORCEMENT BRACKET (RH)	Repair	180.00 FL	*- FL
21	1		*REAR BUMPER CENTRE GRILLE	Serviceable	199.30 FL	*- FL
22	1		*REAR BUMPER SIDE BRACKET (RH)	Serviceable	28.30 FL	*- FL
23	1		*REAR LAMP (RH)	Broken	678.72 FL	*678.72 FL
24	1		*SET REAR LAMP CLIPS	Necessary	30.00 FL	*30.00 FL
25	1		*REAR LAMP QUARTER PANEL	Repair	117.50 FL	*- FL
26	1		*REAR PANEL	Repair	1,151.95 FL	*- FL
27	1		*REAR BOOT	Bent	1,672.61 FL	*1,672.61 FL
28	1		*REAR FENDER (RH)	Serviceable	39.36 FL	*- FL
29	1		*REAR FENDER AIR DUCT (RH)	Distorted	188.75 FL	*188.75 FL
30	1		*REAR FENDER SHIELD (RH)		0.00 FL	*- FL
31	1		*SET REAR FENDER SHIELD CLIPS	Necessary	30.00 FL	*30.00 FL
32	1		*REAR FENDER INNER PANEL (RH) (NPA)	Repair	0.00 FL	*- FL
33	1		*REAR SHOCK ABSORBER (RH)	Bent	479.28 FL	*479.28 FL
34	1		*REAR UPPER ARM (RH)	Distorted	150.10 FL	*150.10 FL
35	1		*REAR LOWER ARM (RH)	Bent	245.22 FL	*245.22 FL
36	1		*REAR KNUCKLE ARM (RH)	Bent	344.88 FL	*344.88 FL
37	1		*REAR WHEEL BEARING ING & HUB (RH)	Necessary	240.84 FL	*240.84 FL
38	1		*REAR STABILIZER BAR	Bent	245.52 FL	*245.52 FL
39	1		*REAR STABILIZER LINK (RH)	Distorted	40.59 FL	*40.59 FL
40	1		*REAR CROSSMEMBER	Buckled	1,428.00 FL	*1,428.00 FL
41	1		*ABS SENSOR	Shorted	253.80 FL	*253.80 FL
42	1		*FRONT NUMBER PLATE	Bent	40.00 FS	*40.00 FS
43	1		*FRONT NUMBER PLATE SCREW	Necessary	30.00 FS	*30.00 FS
44	1		*REAR NUMBER PLATE	Necessary	40.00 FS	*40.00 FS
45	1		*REAR NUMBER PLATE SCREW	Necessary	30.00 FS	*30.00 FS
46	1		*SET FRONT PARKING SENSOR	Serviceable	450.00 FS	*- FS
47	1		*SET REAR PARKING SENSOR	Dented	450.00 FS	*450.00 FS
48	1		*REAR TYRE (RH)	Punctured	380.00 FS	*380.00 FS
49	1		*REAR TYRE RIM (RH)	Dented	190.00 FS	*190.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*REAR TYRE HUB CAP	Dented	80.00 FS	*80.00 FS
F=Franchise part, S=SpcNett, L=ListItemDisc.						
Sub Total (\$\$)					22,341.37	11,795.61
- List Item Discount on L Items 10.00/10.00% (\$\$)					2,065.14	1,055.56
Total Parts (\$\$)					20,276.23	10,740.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING.	New	2,000.00	1,400.00
2	SPRAY PAINTING CHARGES.	New	1,600.00	1,200.00
3	WIRING CHARGES.	New	40.00	40.00
4	DASHBOARD WIRING DIAGNOSTIC.	New	200.00	0.00
5	ALIGNMENT CHARGES.	New	200.00	80.00
6	TOWING CHARGES.	New	150.00	50.00
7	TUFF KOTE.	New	180.00	90.00
8	REFILL AIRCON GAS.	New	150.00	0.00
9	REMOVE / REFIX REAR WINDSCREEN GLASS.	New	150.00	120.00
10	REMOVE / REFIX REAR FENDER QUARTER GLASS.	New	120.00	60.00
11	REMOVE / REFIX FRONT & REAR PARKING SENSOR.	New	300.00	120.00
12	REMOVE / REFIX REAR UNDERCARRIAGE.	New	480.00	200.00
13	REMOVE / REFIX CUSHION SEAT & UPHOLSTERY.	New	150.00	120.00
Gross Labour Cost (\$\$)			5,720.00	3,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >