

ASS. REC. BY:

REF:

CS/MSH17013573/TTh302

Special Instruction:

Surveyor

Rahmah

ASSIGNMENT (Office)

From (Person):

Ganeng

of

MSCG

Date/Time 13/1/2017 11:07AM

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

JRW 2691

Insured:

GJY8700K

at Workshop m/s

ASPHORN

Tel:

65150770

of

Blk 56 Toh Guan Road East #01-35

Policy No:

MSD/LPCP/16-002198-00

Claim No:

MSC/V17-000967

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 21/6/2017

CA / REV / REP. / REV 24 HRS (wp)

Date/Time: 13/1/2017 11:15AM

Person Contacted:

mr kee

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

repairer arrange survey on 14/1/2017

JRW 2691-X

GJY8700K-004/E 16012072/Tiya3

DUA 21/9/2016

Part by Part \$3740.60 (Red: 1899.40 ; 33%)

Tanji

REF: MSCG

# ASSIGNMENT

From:

Date: 14/7/2017

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: JRW 2691

at Workshop m/s A S Phawn

of

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS <sup>up</sup>

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: JRW 2691 Yr Regn: 1

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha CC 155 c.c.

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 91133 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 70/90R17

R: 80/90R17-

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxis

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. mm L/Bal. mm

D.O.A. D.O.I. 14/7/17.

Survey held at

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

v/b will pass GIA & estimate later.

RECEIVED 02 FEB 2018

Date/Time, File Pass to?

1/22 Typist

Date/Time, File Return to?

2)

☐ : Preli. Report

☒ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

TOTAL

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format: TP

Lump Sum / I.B.I: (\$ 3740.60 )

200

10

210



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17013573/T1th3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 13-07-2017	
		Code : MSG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SJY 8700K	Veh. Inspected	JRW 2691
Policy No.	MSD/VPCP/16-002198-00	Coverage (\$)	0.00
Claim No.	MSC/V/17-000967	Excess (\$)	0.00
Assign From	MERIMEN (ELAINE NGU)	Assign Date	13/07/2017
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	c.c 0		
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	Colour		
Odometer	-	Steering	
Brakes	Modification		
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	21/06/2017	Inspection Date	14/07/2017
Survey held at	A.S. PHOON PTE LTD BLK 36 TOH GUAN ROAD EAST #01-35 SINGAPORE 608580		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Jun 2017		13 Jul 2017 11:07 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

#### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	HITACHI CAPITAL ASIA PACIFIC PTE LTD, Co. Reg. No.: 199400399N		
Main Claimant:	LIAN TEAK YONG, ID: 841127015987		
Vehicle Reg. No.:	JRW2691	Date of Loss:	21/06/2017 17:00 - :59
Claim Type:	TP / MSC/V/17-000967	Policy/Cover Note No.:	MSD/VPCP/16-002198-00 (Comprehensive) Coverage: 11/10/2016 - 10/10/2017
Vehicle Reg. No. (Insured):	SJY8700K	Policy No. (Claimant):	
		Excess:	S\$750.00
Repairer:	A S Phoon Pte Ltd (toh Guan ) (HQ) BLK 36 TOH GUAN ROAD EAST ENTERPRISE HUB #01-35, 408701 Jurong Island - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 14/07/2017]		
Driver/Custodian (Insured):	TAKAMASA YASUTAKE (), NRIC: G5951124L, Tel: +6596545460		

[View All](#)   [Compose Case Mail](#)

#### ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)   [Search Tasks](#)   [Create New Task](#)   [Complete](#)

#### ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



# SINGAPORE POLICE FORCE

Police Station Of Origin:  
Clementi N.P.C  
20 Clementi Avenue 5 SINGAPORE 129858  
Tel No: 1800-8729999

Certified True Copy  
pursuant to Sec. 78 of the  
Evidence Act, Cap 97.

T/20170621/2171

1 of 3

Report No. T/20170621/2171

Suriati Bte Buang (MX)  
Traffic Police  
Date : 12 JUL 2017

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 21/06/2017 21:09	Vide Report No.:	Station Diary No.: 177
--	------------------	---------------------------

### Informant's Particulars

Name of Informant: TAKAMASA YASUTAKE	Address: APT BLK 6 ALEXANDRA VIEW #43-01 THE METROPOLITAN CONDOMINIUM SINGAPORE 158746
ID Type / ID No.: FIN NO / G5951124L	Contact No.: Home/Office: Mobile: 96545460
Nationality: JAPANESE	Email:
Sex: Male Age: 49 Date of Birth: 16/11/1967	Type of Informant: Driver
Race: Others	Language: English Institution / School Name:
Occupation: Chemical engineer (general)	Driving Licence Information: Class: 2B, 2A, 3 Date of Expiry: 27/06/2021

### General Information of the Accident

General Information of the Accident				
Type of Accident:	Non-Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 21/06/2017 17:55	Type of Location: Straight Road
Location: Along Road 1 TUAS WEST ROAD				
Along Tuas West Road towards the direction of AYE, in front of 118 Pioneer Road.				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

### Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
JRW2691	Motorcycle	YAMAHA	135LC	White	Slightly Damaged	0
SJY8700K	Car	TOYOTA	Altis	Blue	Slightly Damaged	0

### Details of Person Involved

Any Pedestrian Involved: No	Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL	



**SINGAPORE  
POLICE FORCE**



T/20170621/2171

2 of 3

Police Station Of Origin:

Clementi N.P.C

20 Clementi Avenue 5 SINGAPORE 129858

Tel No: 1800-8729999

Report No. T/20170621/2171

**CONTINUATION OF REPORT**

<b>Driver</b>		<b>ID No.</b>		<b>G5951124L</b>	
<b>Name</b>	<b>TAKAMASA YASUTAKE</b>			<b>Contact No.</b>	<b>96545460</b>
<b>Related Vehicle</b>	<b>SJY8700K (Car)</b>			<b>Class of Driving Licence &amp; Expiry Date</b>	<b>Class: 2B,2A,3 Date of Expiry: 27/06/2021</b>
<b>Hospital/Clinic</b>	<b>NIL</b>			<b>Date Treatment</b>	<b>NIL</b>
<b>Date Discharge</b>			<b>NIL</b>		
<b>No. of Days granted Medical Leave</b>			<b>NIL</b>		
<b>Degree of Injury</b>			<b>NIL</b>		
<b>Rider</b>					
<b>Name</b>	<b>LIAN TEAK WEI</b>			<b>ID No.</b>	<b>NIL</b>
<b>Related Vehicle</b>	<b>NIL</b>			<b>Contact No.</b>	<b>86731139</b>
<b>Hospital/Clinic</b>	<b>NIL</b>			<b>Class of Driving Licence &amp; Expiry Date</b>	<b>Class: NIL Date of Expiry: NIL</b>
<b>Date Treatment</b>			<b>NIL</b>		
<b>Date Discharge</b>			<b>NIL</b>		
<b>No. of Days granted Medical Leave</b>			<b>NIL</b>		
<b>Degree of Injury</b>			<b>NIL</b>		

**Brief Details.**

On 21.06.2017 at about 1755hrs, while I was driving my rental vehicle of reg no. SJY8700K along Tuas West Road towards the direction of AYE, I involved in a road traffic accident in front of 118 Pioneer Road.

2. At that juncture, the road towards AYE was jammed, thus I decided to make an U-turn and to travel on the opposite direction. In the midst of doing that, I slowly made the right turn and suddenly a oncoming motorcycle of reg no. JRW2691 came forward and its front portion hit onto my vehicle's front right side portion.

3. After the accident, we exchanged our particulars and no ambulance came thus no one was being conveyed to the hospital as the rider only sustained minor scratch marks on his elbows.

4. Attached is the sketch plan that was drawn by myself.

Certified True Copy  
pursuant to Sec. 78 of the  
Evidence Act, Cap 97.

Surint. Bte. Buang (MX)  
Traffic Police

Date: 12 JUL 2017





**SINGAPORE  
POLICE FORCE**



T/20170621/2171

3 of 3

Police Station Of Origin:  
Clementi N.P.C  
20 Clementi Avenue 5 SINGAPORE 129858  
Tel No: 1800-8729999

Report No. T/20170621/2171

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

Certified True Copy  
pursuant to Sec. 78 of the  
Evidence Act, Cap 97.

.....  
Serial: 810 040 (MX)  
Traffic Police  
Date: 12 JUL 2017

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:  
D /  
Sr Staff Sgt LOH WEE CHOON

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / AEIT /  
Sgt YEO KIA HUAT  
Contact No.: 65476325

Authentication Stamp  
NP168

Signature Of Informant:

Date/Time:  
21/06/2017 21:09

Classification Of Case:

07/JUL/2017/FRI 17:46

FAX No.

P. 001/005

17-967  
EN

**TAN CHIN HOE & CO**  
ADVOCATES & SOLICITORS  
GST No. & UEN: 53131160X

24 Raffles Place  
#24-01 Clifford Centre  
Singapore 048621

Tel: 6538 2687  
Facsimile: 6538 0287  
Email: info@tanchinhoe.com.sg

Your Ref:

Our Ref:

RT/265/2017/sn



7 July 2017

MSIG Insurance (Singapore) Pte Ltd  
4 Shenton Way  
#23-01 SGX Centre 2  
Singapore 068807

FAX NO: 68277800

BY HAND

NON-INJURY CLAIM

Attn: Claims Department

Dear Sirs

**ACCIDENT INVOLVING JRW2691 AND SJY8700K ON 21 JUNE 2017**

1. We act for Mr Lian Teak Yong and are instructed to claim damages against your insured in connection with a road traffic accident on 21 June 2017 at Tuas West Road involving our client's motorcycle no. JRW2691 and your insured's vehicle registration number SJY8700K.
2. We are instructed that the accident was caused by your insured's negligent driving and/or management of his vehicle. As a result of the accident, our client's motorcycle was damaged and our client has been put to loss and expense.
3. We will revert with our client's quantification shortly.
4. In the meantime, our client's motorcycle is at the premises of A S Phoon Pte Ltd at Blk 36 Toh Guan Road East #01-35 Singapore 608580. Please contact Mr Kee at 65150770 for an appointment to survey the motorcycle within 2 days, failing which A S Phoon Pte Ltd will proceed to carry out the repairs.
5. We also enclose a copy of our client's rider's traffic police report for your attention.
6. Please let us have a copy of your insured driver's accident statement/traffic police report, if any.

Yours faithfully

Richard Tan

cc

1.

Hitachi Capital Asia Pacific Pte Ltd  
111 Somerset Road  
#11-05 Tripleone Somerset  
Singapore 238164



2. A S Phoon Pte Ltd  
(Fax No. 65150779) Please liaise directly with our client your repair cost. If you do not hear from the insurance company within the next 2 days, you ought to have our client's motorcycle surveyed by an independent surveyor prior to carrying out the repairs.



# SINGAPORE POLICE FORCE



T/20170622/2141

1 of 3

Report No. T/20170622/2141

Police Station Of Origin:

Nanyang N.P.C

2 Jurong West Avenue 5 SINGAPORE

649482

Tel No: 1800-7929999

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:  
22/06/2017 18:10

Vide Report No.:

Station Diary No.:  
124

### Informant's Particulars

Name of Informant:

LIAN TEAK WEI

Address:

ID Type / ID No.:

FIN NO / G2246890P

Contact No.:

Mobile: 86731139

Home/Office:

Email:

Nationality:

MALAYSIAN

Sex:

Male

Age:

27

Date of Birth:

20/10/1989

Type of Informant:

Driver

Language:

Institution / School Name:

Race:

Chinese

Occupation:

Machinery mechanic (general)

Driving Licence Information:

Class:

Date of Expiry:

### General Information of the Accident

Type of  
Accident:

Injury  
Attended by Police

Drink  
Drive:  
No

Date/Time of  
Accident:  
21/06/2017 18:00

Type of Location:  
Straight Road

Location:

Along Road 1

TUAS WEST ROAD

Tuas West Road towards Tuas Checkpoint

Weather:

Clear

Road Surface:

Dry

Road Speed Limit:

Traffic Flow:

Traffic Control:

Traffic Volume:

Heavy

Type of Collision:

Between Moving Vehicles - Head To Side

Anyone conveyed by  
ambulance:

No

### Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
JRW2691	Motorcycle				Seriously Damaged	0
SJY8700K	Car				Seriously Damaged	0

### Details of Person Involved

Any Pedestrian Involved: No

No. of Pedestrians Injured: NIL

Use of Pedestrian Crossing: NA

**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Nanyang N.P.C  
2 Jurong West Avenue 5 SINGAPORE  
649482  
Tel No: 1800-7929999



T/20170622/2141

2 of 3

Report No. T/20170622/2141

## CONTINUATION OF REPORT

Driver		ID No.	G2246690P
Name	LIAN TEAK WEI		Contact No.
Related Vehicle	JRW2691 (Motorcycle)		86731139
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL		Class of Driving Licence & Expiry Date
		Class: NIL Date of Expiry: NIL	
Date Treatment	22/06/2017	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	NIL

**Brief Details.**

On 21/06/17 at about 1800hrs, I was riding my motorcycle bearing registration number JRW2691 along Tuas West Rd heading towards Tuas Checkpoint. I was at the right lane and was going to change to left lane to turn left towards the slip road to Tuas Checkpoint along AYE. A vehicle bearing registration number SJY8700K was on the left lane and as I was about to change to the left lane which overtaking him, he did a sudden illegal U turn and I knock to the driver side door. I then fell down from my bike and suffer lower back and palm injuries. I was then instructed by my company to lodge a police report. I am lodging this report to claim insurance and to report an accident that occurred.

**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Nanyang N.P.C  
2 Jurong West Avenue 5 SINGAPORE  
649482  
Tel No: 1800-7929999



T/20170622/2141

3 of 3

Report No. T/20170622/2141

**CONTINUATION OF REPORT****Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J/

Sgt WONG JUN WEI, DANIEL

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Staff Sgt RAZIZ BIN TAHAR

Contact No.: 65476200

Signature Of Informant:

Date/Time:

22/06/2017 18:10

Classification Of Case:

Authentication Stamp

NR468



Signature:

SN 137



潘發展私人有限公司

A. S. PHOON PTE LTD

as as one else

Head Office  
Ubi  
Toh Guan  
Website

399, Changi Road Singapore 410846 Tel (65) 6747 0770 Fax (65) 6841 1263  
Bik 3007 #01-432/436 Ubi Road 1, Singapore 408701 Tel (65) 6744 0770 Fax (65) 6742 0250  
Bik 36 Toh Guan Road East #01-35 Singapore 608580 Tel (65) 6515 0770 Fax (65) 6515 0779  
www.asphoon.com Email Enquiry@asphoon.com Co Reg No: 197701213H

JRW2691 YAMAHA LC135MN REPAIR ESTIMATE

NO	DESCRIPTION	AMOUNT (SGD)
1	FRONT WHEEL ASSY	\$320.00 <i>bt</i>
2	FRONT WHEEL AXLE	\$22.00 <i>bt</i>
3	FRONT WHEEL BEARING X 2	\$40.00 <i>Xm</i>
4	RUST COVER X 2	\$16.00 <i>Xm</i>
5	FRONT FENDER	\$75.00 <i>cut</i>
6	FRONT FORK ASSY R/L & L/H	\$450.00 <i>bt</i>
7	STEM STEERING	<i>bt</i> \$175.00 <i>cut</i>
8	CONE BEARING	<i>rel</i> \$75.00
9	HORN COVER	\$85.00 <i>cut</i>
10	HORN COVER INNER (matte black)	\$65.00 <i>cut</i>
11	FRONT SIGNAL LH	\$65.00 <i>cut</i>
12	FRONT FAIRING -WHITE RH LH	\$145.00 <i>cut</i>
13	LOWER FAIRING LH	\$60.00 <i>cut</i>
14	RADIATOR	\$185.00 <i>bt</i>
15	COOLANT X2	\$30.00 <i>rel</i>
16	FAN	\$110.00 <i>rel</i>
17	WATER PUMP ASSY	\$145.00 <i>rel</i>
18	HOSE WATER PUMP	\$20.00 <i>cut</i>
19	BRACKET RADIATOR	\$28.00 <i>bt</i>
20	RESERVOIR	\$45.00 <i>Xm</i>
21	BRACKET RESERVOIR	\$35.00 <i>bt</i>
22	HOSE A	\$25.00 <i>cut</i>
23	HOSE B	\$40.00 <i>cut</i>
24	BRACKET HOSE	\$28.00 <i>bt</i>
25	BACK SHIELD	\$65.00 <i>Xm</i>
26	GRILLE LH	\$55.00 <i>Xm</i>
27	BASKET	\$28.00 <i>bt</i>
28	FRONT FOOTRESTBAR	\$85.00 <i>bt</i>
29	FRONT FOOTREST RUBBER	\$16.00 <i>bt</i>
30	GEAR PEDAL & RUBBER	\$68.00 <i>bt</i>
31	ENGINE COVER LH	\$145.00 <i>Xm</i>



潘發展私人有限公司  
A. S. PHOON PTE LTD  
can do one else

Head Office  
Ubi  
Toh Guan  
Website

399 Changi Road Singapore 419846 Tel: (65) 6747 0770 Fax: (65) 6841 1283  
Bldg 3007 #01-432/436 Ubi Road 1, Singapore 408701 Tel: (65) 6744 0770 Fax: (65) 6742 0256  
Bldg 36 Toh Guan Road East #01-39 Singapore 608580 Tel: (65) 6515 0770 Fax: (65) 6515 0779  
www.asphoon.com Email: Enquiry@asphoon.com Co Reg No: 19770121384

# JRW2691 YAMAHA LC135MN REPAIR ESTIMATE

NO	DESCRIPTION	AMOUNT (SGD)
32	GASKET X1	\$15.00 <del>Xian</del>
33	ENGINE OIL	\$20.00 <del>Xian</del>
34	HANDLEBAR	\$85.00 <del>bt</del>
35	STAY HANDLE	\$65.00 <del>bt</del>
36	BALANCER LH & RH	\$40.00 <del>cut</del>
37	HANDLEGRIP	\$30.00 <del>cut</del>
38	BRAKE LEVER	\$20.00 <del>cut</del>
39	HANDLEBAR COVER - FRONT	\$65.00 <del>cut</del>
40	SIDE MIRRORS X2	\$75.00 <del>cut</del>
41	FRONT FAIRING - WHITE R/H	\$145.00 <del>cut</del>
42	LOWER SPOILER RH	\$60.00 <del>dis</del>
43	BRAKE PEDAL	\$68.00 <del>bt</del>
44	REAR SIDE FAIRING R/H	\$105.00 <del>cut</del>
45	REAR FOOTREST R/H	\$38.00 <del>cut</del>
46	REAR FOOTREST BRACKET RH	\$75.00 <del>Rx</del>
47	EXHAUST ASSY	\$390.00 <del>Rx</del>
48	HEAT PROTECTION -	\$48.00 <del>cut</del>
49	STICKER SET	\$150.00 <del>cut</del>
50	REAR TOP BOX	\$280.00 <del>cut</del> -180
51	BOX BRACKET	\$180.00 <del>bt</del>
52	WORKMANSHIP	\$350.00 <del>300</del>
53	TRANSPORTATION X2 @ \$60	\$120.00 <del>80</del>
54	BODY CHASSIS REPAIR	\$350.00 <del>cut</del>
55	TRANSPORTATION 2WAY TO REPAIR CHASSIS	\$120.00 <del>80</del> X

TOTAL \$5,640.00

Tan Jiah 97415749  
5 days  
Resuming new parts

Parts - 3734  
10% - 3360.60  
Labour - 380

\$3740.60 #

26/12  
Tan Jiah



### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Jun 2017		13 Jul 2017 11:07 <a href="#">Edit Adj Rpt</a>	<b>S\$3,740.60</b> <a href="#">Edit Estimates</a>	<b>S\$3,740.60</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: <b>HITACHI CAPITAL ASIA PACIFIC PTE LTD</b> , Co. Reg. No.: 199400399N									
Main Claimant: <b>LIAN TEAK YONG</b> , ID: 841127015987									
Vehicle Reg. No.: <b>JRW2691</b>		Date of Loss: 21/06/2017 17:00 - :59	MSD/VPCP/16-002198-00 (Comprehensive) Coverage: 11/10/2016 - 10/10/2017						
Claim Type: <b>TP / MSC/V/17-000967</b>		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): <b>SJY8700K</b>		Policy No. (Claimant):							
		Excess:	S\$750.00						
Repairer: <b>A S Phoon Pte Ltd (toh Guan ) (HQ)</b> BLK 36 TOH GUAN ROAD EAST ENTERPRISE HUB #01-35, 408701 Jurong Island - Tel:									
Handling Insurer: <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Elaine Ngu Siau Mei</b> - 6594 2540]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Imm.Advice due 14/07/2017]									
Driver/Custodian (Insured): <b>TAKAMASA YASUTAKE ()</b> , NRIC: G5951124L, Tel: +6596545460									
<b>ASSOCIATED MAIL RECEIVED</b>			<a href="#">View All</a>	<a href="#">Compose Case Mail</a>					
<ul style="list-style-type: none"> <li>MSIG_SG (30/01/2018): <b>Survey report - urgent</b></li> <li>MSIG_SG (25/01/2018): <b>Survey report - urgent</b></li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*JRW2691 (MSC/V/17-000967)**  
**[SJY8700K]**

TP

**LIAN TEAK YONG**

Jun 21 2017 5:00PM

**[HITACHI CAPITAL ASIA PACIFIC PTE LTD]**

**A S Phoon Pte Ltd (toh Guan )**

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)



















































**View** View in Browser

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Description	Thumbnail	Print
1	13/07/17 11:05	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> <b>Accident Statement</b> <small>From: OD - Reg. No: SJY8700K, Claimant: HITACHI CAPITAL ASIA PACIFIC PTE LTD</small>	 Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	Description	Thumbnail	Print
1	01/02/18 13:51	<b>LKK Auto Consultants Pte Ltd (HQ)</b>		
1	01/02/18 13:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
2	01/02/18 13:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
3	01/02/18 13:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
4	01/02/18 13:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
5	01/02/18 13:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
6	01/02/18 13:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
7	01/02/18 13:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
8	01/02/18 13:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
9	01/02/18 13:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
10	01/02/18 13:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
11	01/02/18 13:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
12	01/02/18 13:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
13	01/02/18 13:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
14	01/02/18 13:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
15	01/02/18 13:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
16	01/02/18 13:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
17	01/02/18 13:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
18	01/02/18 13:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
19	01/02/18 13:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
20	01/02/18 13:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
21	01/02/18 13:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
22	01/02/18 13:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
23	01/02/18 13:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
24	01/02/18 13:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
25	01/02/18 13:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
26	01/02/18 13:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
27	01/02/18 13:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
28	01/02/18 13:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
29	01/02/18 13:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
30	01/02/18 13:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
31	01/02/18 13:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>

32	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
33	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
34	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
35	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
36	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
37	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
38	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
39	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
40	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
41	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
42	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
43	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
44	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
45	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
46	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
47	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
48	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
49	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
50	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
51	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
52	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
53	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
54	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
55	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
56	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
57	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
58	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
59	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
60	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
61	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
62	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
63	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
64	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
65	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
66	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
67	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
68	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
69	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
70	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
71	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
72	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
73	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
74	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
75	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
76	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
77	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
78	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
79	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
80	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
81	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>

82	01/02/18 13:51	General View		Load JPG	<input checked="" type="checkbox"/>
83	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
84	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
85	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
86	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
87	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
88	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
89	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
90	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
91	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
92	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
93	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
94	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
95	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
96	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
97	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
98	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
99	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
100	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
101	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
102	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
103	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
104	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
105	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
106	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
107	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
108	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
109	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
110	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
111	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
112	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
113	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
114	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
115	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
116	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
117	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
118	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
119	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
120	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
121	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
122	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
123	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
124	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
125	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
126	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
127	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
128	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
129	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
130	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
131	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

132	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
133	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
134	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
135	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
136	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
137	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
138	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
139	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
140	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
141	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
142	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
143	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
144	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
145	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
146	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
147	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
148	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
149	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
150	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
151	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
152	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
153	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
154	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
155	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
156	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
157	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
158	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
159	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
160	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
161	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
162	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
163	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
164	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
165	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
166	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
167	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
168	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
169	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
170	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
171	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
172	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
173	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
174	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
175	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
176	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
177	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
178	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
179	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
180	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
181	02/02/18 11:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>



182	02/02/18 11:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
183	02/02/18 11:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
184	02/02/18 11:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
185	02/02/18 11:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
186	02/02/18 11:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
187	02/02/18 11:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
188	02/02/18 11:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
189	02/02/18 11:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
190	02/02/18 11:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
191	02/02/18 11:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
192	02/02/18 11:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
193	02/02/18 11:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
194	02/02/18 11:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
195	02/02/18 11:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
196	02/02/18 11:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
197	02/02/18 11:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
198	02/02/18 11:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
199	02/02/18 11:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
200	02/02/18 11:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
201	02/02/18 11:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
202	02/02/18 11:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
203	02/02/18 11:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
204	02/02/18 11:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
205	02/02/18 11:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
206	02/02/18 11:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
207	02/02/18 11:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
208	02/02/18 11:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
209	02/02/18 11:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
210	02/02/18 11:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
211	02/02/18 11:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
212	02/02/18 11:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
213	02/02/18 11:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
214	02/02/18 11:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
215	02/02/18 11:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
216	02/02/18 11:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
217	02/02/18 11:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>					1 per page <input type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	13/07/17 11:04	PRI	1	Load PDF	
2	13/07/17 11:04	Survey Agreement Email	1	Load PDF	
3	18/01/18 14:43	POLICE REPORT - JRW2691	1	Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			



**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17013573/T1TH3E2

Date: 05/02/2018

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VPCP/16-002198-00
Claimant Vehicle No :	JRW2691	Insured Vehicle No :	SJY8700K
Date of Loss:	21/06/2017	Nature of Claim:	TP
		Claim No:	MSC/V/17-000967

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	JRW2691	Engine No:	HIDDEN
Make & Model:	YAMAHA SPARK, 135cc	Chassis No:	HIDDEN
Reg. Date:	(Man. Year: )	Odometer:	91133 km
Colour:	Black		
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	70/90 R17	Rear Tyre Size:	80/90 R17
Front Left Side:	Maxxis 5 mm	Rear Left Side:	Maxxis 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,700.00	3,360.60	1,339.40	28.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	940.00	380.00	560.00	59.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>5,640.00</b>	<b>3,740.60</b>	<b>1,899.40</b>	<b>33.68</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>394.80</b>	<b>261.84</b>	<b>132.96</b>	<b>33.68</b>
<b>Nett Amount (S\$)</b>	<b>6,034.80</b>	<b>4,002.44</b>	<b>2,032.36</b>	<b>33.68</b>

## INSPECTION

Date of Assignment: 13/07/2017  
Date Inspected: 14/07/2017 Inspected At:

A S Phoon Pte Ltd (toh Guan ) (HQ)  
BLK 36 TOH GUAN ROAD EAST  
ENTERPRISE HUB #01-35  
Singapore 408701

Estimated Period of Repair: 5.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 02 Feb 2018)	
<b>Parts:</b>	N/A	YAMAHA SPARK 135cc (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for JRW2691)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WHEEL ASSY	Bent	320.00 F	*320.00 FL
2	1		*FRONT WHEEL AXLE	Bent	22.00 F	*22.00 FL
3	2		*FRONT WHEEL BEARING	Not Necessary	40.00 F	*- FL
4	2		*RUST COVER	Not Necessary	16.00 F	*- FL
5	1		*FRONT FENDER	Cut	75.00 F	*75.00 FL
6	1		*FRONT FORK ASSY R/L & L/H	Bent	450.00 F	*450.00 FL
7	1		*STEM STEERING	Bent	175.00 F	*175.00 FL
8	1		*CONE BEARING	Necessary	75.00 F	*75.00 FL
9	1		*HORN COVER	Cut	85.00 F	*85.00 FL
10	1		*HORN COVER INNER (MATTE BLACK)	Cut	65.00 F	*65.00 FL
11	1		*FRONT SIGNAL LH	Cut	65.00 F	*65.00 FL
12	1		*FRONT FAIRING - WHITE LH	Cut	145.00 F	*145.00 FL
13	1		*LOWER FAIRING LH	Cut	60.00 F	*60.00 FL
14	1		*RADIATOR	Bent	185.00 F	*185.00 FL
15	2		*COOLANT	Necessary	30.00 F	*30.00 FL
16	1		*FAN	Cracked	110.00 F	*110.00 FL
17	1		*WATER PUMP ASSY	Cracked	145.00 F	*145.00 FL
18	1		*HOSE WATER PUMP	Cut	20.00 F	*20.00 FL
19	1		*BRACKET RADIATOR	Bent	28.00 F	*28.00 FL
20	1		*RESERVOIR	Not Necessary	45.00 F	*- FL
21	1		*BRACKET RESERVOIR	Bent	35.00 F	*35.00 FL
22	1		*HOSE A	Cut	25.00 F	*25.00 FL
23	1		*HOSE B	Cut	40.00 F	*40.00 FL
24	1		*BRACKET HOSE	Bent	28.00 F	*28.00 FL
25	1		*BACK SHIELD	Not Necessary	65.00 F	*- FL
26	1		*GRILLE LH	Not Necessary	55.00 F	*- FL
27	1		*BASKET	Bent	28.00 F	*28.00 FL
28	1		*FRONT FOOTRESTBAR	Bent	85.00 F	*85.00 FL
29	1		*FRONT FOOTREST RUBBER	Torn	16.00 F	*16.00 FL
30	1		*GEAR PEDAL & RUBBER	Bent	68.00 F	*68.00 FL
31	1		*ENGINE COVER LH	Not Necessary	145.00 F	*- FL
32	1		*GASKET	Not Necessary	15.00 F	*- FL
33	1		*ENGINE OIL	Not Necessary	20.00 F	*- FL
34	1		*HANDLE BAR	Bent	85.00 F	*85.00 FL
35	1		*STAY HANDLE	Bent	65.00 F	*65.00 FL
36	1		*BALANCER LH & RH	Cut	40.00 F	*40.00 FL
37	1		*HANDLE GRIP	Cut	30.00 F	*30.00 FL
38	1		*BRAKE LEVER	Cut	20.00 F	*20.00 FL
39	1		*HANDLE BAR COVER - FRONT	Cut	65.00 F	*65.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	2		*SIDE MIRRORS	Cut	75.00 F	*75.00 FL
41	1		*FRONT FAIRING - WHITE R/H	Cut	145.00 F	*145.00 FL
42	1		*LOWER SPOILER RH	Distorted	60.00 F	*60.00 FL
43	1		*BRAKE PEDAL	Bent	68.00 F	*68.00 FL
44	1		*REAR SIDE FAIRING R/H	Cut	105.00 F	*105.00 FL
45	1		*REAR FOOTREST R/H	Cut	38.00 F	*38.00 FL
46	1		*REAR FOOTREST BRACKET RH	Repair	75.00 F	*- FL
47	1		*EXHAUST ASSY	Repair	390.00 F	*- FL
48	1		*HEAT PROTECTION	Cut	48.00 F	*48.00 FL
49	1		*SET STICKER	Necessary	150.00 F	*150.00 FL
50	1		*REAR TOP BOX	Cut	280.00 F	*180.00 FL
51	1		*BOX BRACKET	Bent	180.00 F	*180.00 FL

F=Franchise part, L=ListItemDisc.

Sub Total (\$\$)	4,700.00	3,734.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	373.40
Total Parts (\$\$)	4,700.00	3,360.60

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	WORKMANSHIP	New	350.00	300.00
2	TRANSPOTATION	New	120.00	80.00
3	BODY CHASSIS REPAIR	New	350.00	0.00
4	TRANSPORTATION 2WAY TO REPAIR CHASSIS	New	120.00	0.00
Gross Labour Cost (S\$)			940.00	380.00

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;