

Not Authored
11/10/17

AAD1707-109

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
SHD9722A -

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHD9722A - ROEL
 VF1ABL15AUC276066
 RENAULT
 LATITUDE
 12.07.2017
EQ

PART		LIST
1	1	BUMPER COVER FRT \$ <i>Sm</i> 1,259.42
2	1	BUMPER RETAINER FRT LH \$ <i>Sm</i> 151.41
3	1	BUMPER BRACKET FRT LH \$ <i>Sm</i> 181.75
4	1	HEADLAMP LH \$ <i>Sm</i> 1,184.43
5	1	HEADLAMP PANEL FRT LH \$ <i>R</i> 152.15
6	1	AIR CLEANER LOWER \$ <i>Sm</i> 352.64
7	1	AIR CLEANER HOSE \$ <i>Sm</i> 76.14
8	1	FENDER PANEL FRT LH \$ <i>R</i> 783.83
9	1	WHEELARCH FRT LH \$ <i>Sm</i> 278.84
10	1	DOOR PANEL FRT LH \$ <i>Pr</i> 2,844.66 ✓
11	1	DOOR HINGE UPPER LH \$ <i>R</i> 274.50 X
12	1	DOOR HINGE LOWER LH \$ <i>R</i> 300.55 A
13	1	DOOR CHECK FRT LH \$ <i>Sm</i> 194.77 X
14	1	DOOR LOCK FRT LH \$ <i>Ta</i> 908.75 ✓
15	1	DOOR CATCH FRT LH \$ <i>R</i> 131.23 X
16	1	DOOR GRAB HANDLE FRT LH \$ <i>Sm</i> 210.96 X
17	1	DOOR HANDLE OUTER FRT LH \$ <i>Bo</i> 258.12 ✓
18	1	DOOR HANDLE CAP FRT LH \$ <i>Bo</i> 26.44 ✓
19	1	DOOR HANDLE SEAL FRT LH \$ <i>Bo</i> 7.89 ✓
20	1	DOOR HANDLE COVER FRT LH \$ <i>Mi</i> 13.22 ✓
21	1	DOOR HANDLE MODULE FRT LH \$ <i>Sm</i> 133.60 ✓
22	1	DOOR REGULATOR FRT LH \$ 505.19 ?
23	1	DOOR REGULATOR MOTOR FRT LH \$ 796.46 ?
24	1	DOOR REGULATOR GUIDE FRT LH \$ <i>Sm</i> 120.97 X
25	1	DOOR FINISHER FRT LH \$ <i>Sm</i> 515.06 X
26	1	DOOR MOULDING FRT LH \$ <i>Bo</i> 176.82 ✓
27	1	DOOR GRAB HANDLE FRT LH \$ <i>Sm</i> 210.96 X
28	1	DOOR CASING FRT LH \$ <i>Sm</i> 1,509.06 X
29	1	DOOR WATER SHIELD FRT LH \$ 184.32 ?
30	1	DOOR GLASS FRT LH \$ <i>Shower</i> 722.26 ✓
31	1	DOOR MIRROR LH \$ <i>Sm</i> 1,483.40 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9722A -

AAD1707-109

32	1	DOOR MIRROR GLASS LH	\$	148.20 X
33	1	DOOR MIRROR BACK COVER LH	\$	218.46 X
34	1	DOOR WHETHERSTRIP FRT LH	\$	474.21 X
35	1	DOOR SEAL FRT LH	\$	68.67 X
36	1	DOOR GLASS RUNNER SEAL FRT LH	\$	626.36 X
37	1	DOOR WAIST SEAL OUTER FRT LH	\$	291.27 X
38	1	DOOR WAIST SEAL INNER FRT LH	\$	107.75 X
39	1	ROCKER PANEL OUTER LH	\$	987.49 X
40	1	DOOR PANEL REAR LH	\$	2,844.66 ✓
41	1	DOOR GUIDE REAR LH	\$	176.82 X
42	1	DOOR HINGE UPPER LH	\$	315.74 ✓
43	1	DOOR HINGE LOWER LH	\$	300.55 X
44	1	DOOR CHECK REAR LH	\$	203.06 ✓
45	1	DOOR LOCK REAR LH	\$	908.75 X
46	1	DOOR GRAB HANDLE REAR LH	\$	210.96 ✓
47	1	DOOR HANDLE OUTER REAR LH	\$	126.49 ✓
48	1	DOOR HANDLE CAP REAR LH	\$	35.52 X
49	1	DOOR HANDLE SEAL REAR LH	\$	7.89 X
50	1	DOOR HANDLE COVER REAR LH	\$	13.22 X
51	1	DOOR HANDLE MODULE REAR LH	\$	133.60 X
52	1	DOOR REGULATOR REAR LH	\$	665.63 ✓
53	1	DOOR REGULATOR MOTOR REAR LH	\$	893.75 ✓
54	1	DOOR SEAL RR LH	\$	75.54 X
55	1	DOOR GLASS REAR LH	\$	625.96 X
56	1	DOOR FINISHER REAR LH	\$	423.10 X
57	1	DOOR MOULDING REAR LH	\$	176.82 X
58	1	DOOR CASING REAR LH	\$	1,509.06 X
59	1	DOOR CASING LIGHT	\$	48.74 X
60	1	DOOR WATER SHIELD REAR LH	\$	36.31 X
61	1	DOOR WHEATHSTRIP REAR LH	\$	474.60 ✓
62	1	DOOR SEAL REAR LH	\$	187.08 X
63	1	DOOR GLASS RUNNER SEAL REAR LH	\$	229.31 7
64	1	DOOR WAIST SEAL OUTER REAR LH	\$	334.69 7
65	1	DOOR WAIST SEAL INNER REAR LH	\$	100.25 7
66	1	FENDER FINISHER COVER REAR LH	\$	271.22 7
67	1	FENDER PANEL REAR LH	\$	3,299.13 ✓
68	1	WHEELARCH REAR LH	\$	543.47 X
69	1	TAILLAMP LH	\$	552.55 X
70	1	BUMPER COVER REAR	\$	1,108.46 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9722A -**AAD1707-109**

71	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>Sm</i> 135.97 X
72	1	BUMEPR RETAINER LH REAR	\$	<i>Sm</i> 44.99 X

TOTAL	\$	35,886.13
10%	\$	3,588.61
	\$	32,297.52

Special Nett

1	1SET	WHEELARCH CLIP FRT LH	\$	<i>Sm</i> 66.00 X
2	1SET	FRONT BUMPER CLIP	\$	<i>Sm</i> 66.00 X
3	1	RIM LH FRT	\$	<i>Sm</i> 385.00 X
4	1	TYRE LH FRT	\$	<i>Sm</i> 330.00 X
5	1	DOOR CASING FRT CLIP LH (door inner trim)	\$	<i>Sm</i> 45.00 X
6	1	DOOR STICKER "Trans-cab"	\$	<i>Sm</i> 80.00 <i>60Sm</i>
7	1	DOOR STICKER "Classic"	\$	<i>Sm</i> 30.00 <i>15Sm</i>
8	1	DOOR STICKER "6555-3333"	\$	<i>Sm</i> 80.00 <i>60Sm</i>
9	2	Rear Windscreen Sealant	\$	<i>Sm</i> 100.00 <i>40Sm</i>
10	1	Rear Windscreen Inner Sponge Seal	\$	<i>Sm</i> 150.00 <i>30Sm</i>
11	1SET	WHEELARCH CLIP RR	\$	<i>Sm</i> 15.00 X
12	1	RIM LH RR	\$	<i>Sm</i> 385.00 X
13	1	TYRE LH RR	\$	<i>Sm</i> 330.00 X
14	1SET	WHEELARCH CLIP RR LH	\$	<i>Sm</i> 66.00 X
15	1	FENDER FINISHER COVER CLIP REAR LH	\$	<i>Sm</i> 20.00 X
16	1SET	REAR BUMPER CLIP	\$	<i>Sm</i> 66.00 X
17	1SET	BUMEPR RETAINER LH CLIP RR	\$	<i>Sm</i> 20.00 X

TOTAL	\$	2,234.00
TOTAL PARTS	\$	34,531.52

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 4,200.00 *9000*

To Check Electrical Lighting Concerned.

\$ 170.00 *200*

Putty and spray painting of the affected portion.

\$ 4,500.00 *8800*

To transfer of rear fender fittings, attachment and perform water seepage test.

\$ 380.00 *1000*

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9722A -**AAD1707-109**

To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 <i>X</i>
Towing fees	\$	120.00 <i>500</i>
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00 <i>1200</i>
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00 <i>1200</i>
To rust-proofing of the affected areas.	\$	170.00 <i>900</i>
TOTAL		\$ 10,100.00
Over All Total		\$ 44,631.52

(PARTS BY PARTS) Repair Days**15 Days***7 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: