

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9722A -*Not Notion
1/1/11/11/11*

AAD1707-109

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHD9722A - ROEL
 VF1ABL15AUC276066
 RENAULT
 LATITUDE
 12.07.2017

*EQ***PART****LIST**

QTY	PART	UNIT	PRICE	TOTAL
1	BUMPER COVER FRT	\$	1,259.42	
2	BUMPER RETAINER FRT LH	\$	151.41	
3	BUMPER BRACKET FRT LH	\$	181.75	
4	HEADLAMP LH	\$	1,184.43	
5	HEADLAMP PANEL FRT LH	\$	152.15	
6	AIR CLEANER LOWER	\$	352.64	
7	AIR CLEANER HOSE	\$	76.14	
8	FENDER PANEL FRT LH	\$	783.83	
9	WHEELARCH FRT LH	\$	278.84	
10	DOOR PANEL FRT LH	\$	2,844.66	
11	DOOR HINGE UPPER LH	\$	274.50	X
12	DOOR HINGE LOWER LH	\$	300.55	X
13	DOOR CHECK FRT LH	\$	194.77	X
14	DOOR LOCK FRT LH	\$	908.75	
15	DOOR CATCH FRT LH	\$	131.23	X
16	DOOR GRAB HANDLE FRT LH	\$	210.96	X
17	DOOR HANDLE OUTER FRT LH	\$	258.12	
18	DOOR HANDLE CAP FRT LH	\$	26.44	
19	DOOR HANDLE SEAL FRT LH	\$	7.89	
20	DOOR HANDLE COVER FRT LH	\$	13.22	
21	DOOR HANDLE MODULE FRT LH	\$	133.60	
22	DOOR REGULATOR FRT LH	\$	505.19	780
23	DOOR REGULATOR MOTOR FRT LH	\$	796.46	780
24	DOOR REGULATOR GUIDE FRT LH	\$	120.97	X
25	DOOR FINISHER FRT LH	\$	515.06	X
26	DOOR MOULDING FRT LH	\$	176.82	
27	DOOR GRAB HANDLE FRT LH	\$	210.96	X
28	DOOR CASING FRT LH	\$	1,509.06	X
29	DOOR WATER SHIELD FRT LH	\$	184.32	780
30	DOOR GLASS FRT LH	\$	722.26	
31	DOOR MIRROR LH	\$	1,483.40	X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9722A -

AAD1707-109

QTY	DESCRIPTION	UNIT	PRICE	TOTAL	REMARKS
32	DOOR MIRROR GLASS LH	\$	4.64	148.20	X
33	DOOR MIRROR BACK COVER LH	\$	6.62	218.46	X
34	DOOR WHETHERSTRIP FRT LH	\$	13.70	474.21	X
35	DOOR SEAL FRT LH	\$	2.51	68.67	X
36	DOOR GLASS RUNNER SEAL FRT LH	\$	9.14	626.36	X
37	DOOR WAIST SEAL OUTER FRT LH	\$	3.21	291.27	X
38	DOOR WAIST SEAL INNER FRT LH	\$	3.21	107.75	X
39	ROCKER PANEL OUTER LH	\$	25.32	987.49	X
40	DOOR PANEL REAR LH	\$	71.11	2,844.66	✓
41	DOOR GUIDE REAR LH	\$	5.17	176.82	X
42	DOOR HINGE UPPER LH	\$	7.81	315.74	✓
43	DOOR HINGE LOWER LH	\$	3.35	300.55	X
44	DOOR CHECK REAR LH	\$	4.51	203.06	✓
45	DOOR LOCK REAR LH	\$	22.31	908.75	X
46	DOOR GRAB HANDLE REAR LH	\$	3.54	210.96	✓
47	DOOR HANDLE OUTER REAR LH	\$	3.16	126.49	✓
48	DOOR HANDLE CAP REAR LH	\$	1.10	35.52	X
49	DOOR HANDLE SEAL REAR LH	\$	0.80	7.89	X
50	DOOR HANDLE COVER REAR LH	\$	1.20	13.22	X
51	DOOR HANDLE MODULE REAR LH	\$	1.20	133.60	X
52	DOOR REGULATOR REAR LH	\$	6.65	665.63	✓
53	DOOR REGULATOR MOTOR REAR LH	\$	12.60	893.75	✓
54	DOOR SEAL RR LH	\$	1.25	75.54	X
55	DOOR GLASS REAR LH	\$	8.74	625.96	X
56	DOOR FINISHER REAR LH	\$	5.70	423.10	X
57	DOOR MOULDING REAR LH	\$	4.70	176.82	X
58	DOOR CASING REAR LH	\$	15.09	1,509.06	X
59	DOOR CASING LIGHT	\$	1.60	48.74	X
60	DOOR WATER SHIELD REAR LH	\$	1.10	36.31	X
61	DOOR WHEATHESTRIIP REAR LH	\$	12.60	474.60	✓
62	DOOR SEAL REAR LH	\$	1.60	187.08	X
63	DOOR GLASS RUNNER SEAL REAR LH	\$	2.70	229.31	7
64	DOOR WAIST SEAL OUTER REAR LH	\$	5.70	334.69	7
65	DOOR WAIST SEAL INNER REAR LH	\$	1.50	100.25	7
66	FENDER FINISHER COVER REAR LH	\$	3.70	271.22	7
67	FENDER PANEL REAR LH	\$	71.11	3,299.13	✓
68	WHEELARCH REAR LH	\$	8.74	543.47	X
69	TAILLAMP LH	\$	8.74	552.55	X
70	BUMPER COVER REAR	\$	13.70	1,108.46	X

TRANS-CAB AUTO SERVICES PTE LTD

AAD1707-109

NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
SHD9722A -

71	1	BUMEPR BRACKET SIDE LH REAR	\$	Sn	135.97 X
72	1	BUMEPR RETAINER LH REAR	\$	Sn	44.99 X
TOTAL			\$		35,886.13
10%			\$		3,588.61
			\$		32,297.52

Special Nett

1	1SET	WHEELARCH CLIP FRT LH	\$	nn	66.00 X
2	1SET	FRONT BUMPER CLIP	\$	nn	66.00 X
3	1	RIM LH FRT	\$	Sn	385.00 X
4	1	TYRE LH FRT	\$	Sn	330.00 X
5	1	DOOR CASING FRT CLIP LH (door inner trim)	\$	nn	45.00 X
6	1	DOOR STICKER "Trans-cab"	\$	nn	80.00 60sn
7	1	DOOR STICKER "Classic"	\$	nn	30.00 15sn
8	1	DOOR STICKER "6555-3333"	\$	nn	80.00 60sn
9	2	Rear Windscreen Sealant	\$	nn	100.00 40sn
10	1	Rear Windscreen Inner Sponge Seal	\$	nn	150.00 30sn
11	1SET	WHEELARCH CLIP RR	\$	nn	15.00 X
12	1	RIM LH RR	\$	Sn	385.00 X
13	1	TYRE LH RR	\$	Sn	330.00 X
14	1SET	WHEELARCH CLIP RR LH	\$	nn	66.00 X
15	1	FENDER FINISHER COVER CLIP REAR LH	\$	nn	20.00 X
16	1SET	REAR BUMPER CLIP	\$	nn	66.00 X
17	1SET	BUMEPR RETAINER LH CLIP RR	\$	nn	20.00 X
TOTAL			\$		2,234.00
TOTAL PARTS			\$		34,531.52

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,200.00	900/
To Check Electrical Lighting Concerned.	\$	170.00	20/
Putty and spray painting of the affected portion.	\$	4,500.00	800/
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	100/

RANS-CAB AUTO SERVICES PTE LTD

AAD1707-109

NO.2 ANG MO KIO ST63 SINGAPORE 569111
TEL NO. 6287 6666 FAX NO. 6257 1330
CO/GST REG NO. 201019626G
SHD9722A -

To check steering geometry and computer wheel alignment	\$	<i>Nr</i> 220.00 X
Towing fees	\$	120.00 <i>300</i>
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00 <i>120</i>
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00 <i>120</i>
To rust-proofing of the affected areas.	\$	170.00 <i>900</i>
TOTAL		\$ 10,100.00
Over All Total		\$ 44,631.52

(PARTS BY PARTS) Repair Days

~~15 Days~~
7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: