

Toyota Vios. SHP 4194X

- 1) Rear Bumper — DO/DE ✓
- 2) " " clips — RE ✓
- 3) " " Retainer (2x) — MAX
- 4) " " reinforcement frame — R. X

(set 5) Reverse Sensor — SHL 2005.~

6) Rear Panel Trunk Garnish clips — 11X

7) Rear Bootlid ^{inner} Lock — 11X

Labour! -

1) Check Wisp — SHL 20

2) Anti Rust ^{rust proofing} — SHL 11X

3) Panel Beating — 300k. 280

4) ~~Paintwork~~ ^{To putty & spray painting} 480k. 400

STYTECH AUTO PTE. LTD.

2 Kaki Bukit Ave 2 #02-30
Kaki Bukit Autchub Singapore 417921
Tel: 6444 8125 Fax: 6445 3310
GST Reg. No.: 201601539K
Co. Reg. No.: 201601539K

LKH Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

20h.