

ASS. REC. BY:

REF:

CS/ALL17013913/Agbnz

Special Instruction:

Surveyor

Adrian

ASSIGNMENT (Office)

From (Person):

Mehd Tarran

of

AP

Date/Time:

18/07/2017 11:53am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGY 8243Z

Insured:

SLN 7912G

at Workshop m/s

Yi Heng

Tel:

6509 0052

of

Blk 1 Kater Bukit Ave 6 #02-19

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

16/07/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS w.p.

19/07/2017

H.O.D. Endorsement:

Date/Time:

18/07/2017 1:07pm

Person Contacted:

Wan Ping

Vehicle IN LOUR

Date/Time

Action/Instruction (✓) Estimate

SGY 8243Z - N/A / INC10011370 / j1

DOA: 11/06/2010

SLN 7912G - X

REF: ALG

ASSIGNMENT

09/10/07

From: _____ Date: 19/07/07

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: 56Y 8243Z
at Workshop m/s Yi Heng
of Bk 1 Kaki Bukit Ave 6 #02-49

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS Wp

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 56Y8243Z Yr Regn: 2007 OCT

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Axio c.c. 1496

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 168729 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NZE1416038199

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 19/07/17

Survey held at Yi Heng

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TPAIG.

45 \$ 6200 (Red: 18167.61, 75%).

RECEIVED 1 DEC 2017

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 8

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$)

) \$ + RS. \$

☐ : Interview (\$)

) Photos

☐ : Tech. Invs (\$)

) Others

☐ : Weekend (\$)

)

TOTAL

Report Format: TP

Lump Sum / I.B.I.: (\$ 6200)

250

20

270



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS/AIG17013913/Agb

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 18-07-2017



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLN 7912G	Veh. Inspected	SGY 8243Z
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MOHD IMRAN	Assign Date	18/07/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	16/07/2017	Inspection Date	19/07/2017
Survey held at	YI HENG MOTOR WORKSHOP BLK 1 KAKI BUKIT AVE 6 #02-19 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	5181B

Vehicle Details

Vehicle No.	SGY8243Z
Vehicle to be Exported	Yes
Intended De-registration Date	22 Nov 2017
Vehicle Make	TOYOTA
Vehicle Model	COROLLA AXIO 1.5X A
Primary Colour	Grey
Manufacturing Year	2007
Engine No.	1NZC633062
Chassis No.	NZE1416038199
Maximum Power Output	81.0 kW (108 bhp)
Open Market Value	\$12,660.00
Original Registration Date	09 Oct 2007
First Registration Date	09 Oct 2007
Transfer Count	3
Actual ARF Paid	\$13,926.00

Intended PARF Rebate Details

PARF Eligibility	Forfeited
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00

Intended COE Rebate Details

COE Expiry Date	08 Oct 2022
COE Category	E - Open Category
COE Period(Years)	5
PQP Paid	\$21,282.00
COE Rebate Amount	\$20,758.00
Total Rebate Amount	\$20,758.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 22 Nov 2017

OK

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Business

Owner ID: 7705J

Vehicle Details

Vehicle No.: SGY8243Z

Vehicle to be Exported: No

Intended De-registration
Date: 20 Jul 2017

Vehicle Make: TOYOTA

Vehicle Model: COROLLA AXIO 1.5X A

Primary Colour: Grey

Manufacturing Year: 2007

Engine No.: 1NZC633062

Chassis No.: NZE1416038199

Maximum Power
Output: 81.0 kW (108 bhp)

Open Market Value: \$12,660.00

Original Registration
Date: 09 Oct 2007

First Registration Date: 09 Oct 2007

Transfer Count: 2

Actual ARF Paid: \$13,926.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry
Date: 08 Oct 2017

PARF Rebate Amount: \$6,963.00

Intended COE Rebate Details

COE Expiry Date: 08 Oct 2017

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$2,642.00

COE Rebate Amount: \$175.00

Total Rebate Amount: \$7,138.00

The information contained herein is correct as at 20 Jul 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.
Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution
Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)
Last updated on 16 Jul 2017 at 12:47 AM

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Business

Owner ID: 7705J

Vehicle Details

Vehicle No.: SGY8243Z

Vehicle to be Exported: Yes

Intended De-registration
Date: 17 Jul 2017

Vehicle Make: TOYOTA

Vehicle Model: COROLLA AXIO 1.5X A

Primary Colour: Grey

Manufacturing Year: 2007

Engine No.: 1NZC633062

Chassis No.: NZE1416038199

Maximum Power Output: 81.0 kW (108 bhp)

Open Market Value: \$12,660.00

Original Registration
Date: 09 Oct 2007

First Registration Date: 09 Oct 2007

Transfer Count: 2

Actual ARF Paid: \$13,926.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry
Date: 08 Oct 2017

PARF Rebate Amount: \$6,963.00

Intended COE Rebate Details

COE Expiry Date: 08 Oct 2017

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$2,642.00

COE Rebate Amount: \$182.00

Total Rebate Amount: \$7,145.00

The information contained herein is correct as at 17 Jul 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)
Last updated on 01 Jul 2017 at 12:50 AM



facebook

our official
Facebook page now!

www.facebook.com/sgcarmart

Username / Email Add

password


[Sign Up New Account](#)
[Forgot Password](#)

toyota axio

Price Range ▾

Depreciation ▾

2007 ▾

Vehicle Type ▾

Advanced
Search

Used Car Comparison

--- Comparing 3 Vehicles ---

Toyota Corolla Axio 1.5M X

Toyota Corolla Axio 1.5A X

Toyota Corolla Axio 1.5A X



Clear All

Add all to Shortlist

Add to Shortlist

Add to Shortlist

Add to Shortlist

Use search bar above to se
to compare:

Back to search result

CAR DETAILS

Price	\$10,800	\$13,800	\$12,000
Instalment	\$7,579	\$4,854	\$2,121
Registration Date	07-Sep-2007	08-Oct-2007	15-Dec-2007
Manufactured	2007	2007	2007
Mileage	83,777 km	144,000 km	167,000 km
Transmission	Manual	Auto	Auto
Engine Cap	1,496 cc	1,496 cc	1,496 cc
Road Tax	\$682 /yr	\$682 /yr	\$682 /yr
Power	81.0 kW (108 bhp)	81.0 kW (108 bhp)	81.0 kW (108 bhp)
Curb Weight	1,100 kg	1,130 kg	1,130 kg
Features	1.5L DOHC Engine, 5 Speed Manual Transmission, SRS Airbags, Reverse Sensor.	NZE141 JDM Toyota Corolla Axio 1.5X A Powered By A 1NZ, 1.5 Litre Engine Producing 108BHP, 140 NM Of Torque Mated To A 5 Speed Automatic Gearbox.	NZE141 JDM Toyota Corolla Axio 1.5X A Powered By A 1NZ, 1.5 Litre Engine Producing 108BHP, 140 NM Of Torque Mated To A 5 Speed Automatic Gearbox.
Accessories	Sport Rims, Reverse Camera, Factory Fitted Audio System, Electrical Retractable Side Mirrors, Upholstery Leather Seats.	Factory In Car Entertainment System, SRS Airbags, Leather Seats, Sports Rims, Solar Film, Front Camera Recorder And Reverse Camera.	JDM Specification Vehicle, Factory In Car Entertainment System, SRS Airbags, New Seat Covers, Light Weight Alloy Wheels And More.
Description	Super Low Mileage Done! Free Accessories Equipped! Well Kept By Previous Owner! Extended Warranty Available! A Highly Fuel Efficient Yet Responsive Sedan, That Comes With Very Spacious Interior. Buy It From Us With A Peace Of Mind, A Company Accredited With Outstanding Awards, Professional After Sales Service Assured. Visit Us At Our Showroom To View It In Pristine Condition Now, Don't Miss It!	Good Conditions, Able To Renew Coe For 5 Years, High Parf Of \$9075, Call To View.	HKS Technical Factory Singapore/Garage R Approved Pre-Owned Vehicle, Passed Our Stringent 25 Points Safety Checks Covering Chassis, Mountings And Joints. An Ideal One Owner Vehicle For Those Considering Extending The COE, Excellent Condition, No Accident Records, No Leaks From Engine, Transmission One Would Expect From A High Quality Japanese Made Toyota. Viewing At Garage R Anytime.
COE	\$16,159	\$16,999	\$12,401
OMV	\$12,601	\$16,500	\$12,626
ARF	\$13,862	\$18,150	\$13,889
Depreciation	-	-	-
No. of Owners	1	2	1
Type of Vehicle	Sedan	Sedan	Sedan
Category	PARF Car, Low Mileage Car	PARF Car	PARF Car, Premium Ad Car
Availability	Available	Available	Available

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGY8243Z & SLN7912G ON 16/7/2017

From: Md Ishak, Mohd Imran
 To: assignments@kkauto.com, admin-a@kkauto.com
 Cc: Tan, Lily (AIG), Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baijit, Leong, Kah Yin, Lim, Sheng Yang, Abu Kassim, Noor Manesa, Hassim, Mohd Fitri
 Sent: Tuesday, 18 July, 2017 11:53:59 AM
 Attachments: 170718 Pre Repair Inspection SGY 8243 Z (AIG).pdf; 170717 Pre Repair Survey Notice SGY 8243 Z (AIG).pdf

Hi,

Please refer to the enclosed request from **MARCUS PHUAH & CO**

Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

You may proceed to appoint **Marcus Chua** as Single Joint Expert as requested

Thank you

Sincerely,

Imran

Mohd Imran Md Ishak

AIG

Express Claims Adjuster II, FNOL, SG Claims Operations - Auto
 Shared Services - Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)
 Menara Worldwide, Level 14, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
 Tel: +6 03 2749 6000 ext: 1012601 | Fax: +6 03 2685 5898

imran.ishak@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: legalasia@legalasia.net
 To: Imran.ishak@aig.com
 Cc: Lily.Tan@aig.com, Andy-SY.Fong@aig.com, Lee-Ying.Chin@aig.com, Baijit.Kaur@aig.com, KahYin.Leong@aig.com, ShengYang.Lim@aig.com, NoorManesa.AbuKassim@aig.com, marcus@legalasia.net, MohdFitri.Hassim@aig.com
 Subject: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGY8243Z & SLN7912G ON 16/7/2017
 Date: Tue, 18 Jul 2017 03:20:29 +0000

TO: AIG ASIA PACIFIC INSURANCE PTE. LTD
 Attn: Motor Claims
 AIG Building
 78 Shenton Way #09-16
 Singapore 079120
 ATTN: MOTOR CLAIMS
 VIA: EMAIL & FAX: 6835 7416
 YOUR REFERENCE: SLN 7912 G
 OUR REFERENCE: KNSM.MP.SGY8243Z. 20170716

Dear Sir / Madam

DATE OF ACCIDENT: 16 JULY 2017

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS PURSUANT TO PARAGRAPH 2.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

We refer to your email dated 18.07.2017 informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirms the appointment of Marcus Chua, LKK Auto Consultants Pte Ltd as the Single Joint Expert for this matter. Please be informed that the said vehicle can be inspected at:

Venue: YI HENG MOTOR WORKSHOP, Blk 1, Kaki Bukit Ave 6,
 #02-19, AUTOBAY BUILDING, S (417883)
 Contact Person: TEL: 6509 0052 (MR. LOUIS GAN)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

From: legalasia@legalasia.net
 To: MohdFitri.Hassim@aig.com
 Cc: Lily.Tan@aig.com, Andy-SY.Fong@aig.com, Lee-

Ying.Chin@aig.com ,Baljit.Kaur@aig.com ,KahYin.Leong@aig.com ,ShengYang.Lim@aig.com ,NoorMarisa.AbuKassim@aig.com ,Imran.Ishak@aig.com ,marcus@legalasia.net
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGY8243Z & SLN7912G ON 16/7/2017
Date: Mon, 17 Jul 2017 06:27:01 +0000

TO: AIG ASIA PACIFIC INSURANCE PTE. LTD.
 Attn: Motor Claims
 AIG Building
 78 Shenton Way #09-16
 Singapore 079120
 ATTN: MOTOR CLAIMS

VIA: EMAIL & FAX: 6835 7416

YOUR REFERENCE: SLN 7912 G

OUR REFERENCE: KNSM.MP.SGY8243Z 20170716

Dear Sir / Madam

DATE OF ACCIDENT: 16 JULY 2017

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS PURSUANT TO PARAGRAPH 2.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

1. We are instructed by YI HENG MOTOR WORKSHOP to notify you of a road traffic accident on 16 JULY 2017 at about 0900 HOURS AT WEST COAST ROAD involving our client's vehicle SGY 8243 Z and SLN 7912 G driven by your insured at the material time.
2. As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know **within 2 working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours sincerely,

Harry Wirdanis
 Personal Assistant to Mr. Marcus Phuah

Marcus Phuah & Co.
 Advocates & Solicitors

潘國良律師事務所

Income @ Raffles Building

16 Collyer Quay

Level 20 Suite 27

Singapore 049318

Website: <http://www.legalasia.net>

Email: legalasia@legalasia.net

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/07/2017 16:03
Date Of Accident	16/07/2017 09:00
Exact Location Of Accident	WEST COAST ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGY8243Z
Insured/Policyholder	
Name Of Registered Owner	R & N SERVICES
Co Reg No	5337705J
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-90290731

Vehicle Particulars

Manufacturer	TOYOTA
Model	AXIO
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5080489519
Cover Note Number	

Driver

Name of Driver	MOHAMED RAFFEE BIN SALLEH
NRIC No	S1675181B
Date Of Birth	02/08/1964
Occupation	INDOOR
Date Of Driving Pass	08/10/1984
Driving Experience	32 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90290731
Fax Number	
Contact Number	
E Mail Address	NOEMAIL

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - (a) my insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (Form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan





SINGAPORE POLICE FORCE



T/20170716/2111

Police Station Of Origin:
Woodlands West N.P.C.
9 Marsiling Lane SINGAPORE 739146
Tel No: 1800-363 9999

1 of 3

Report No. T/20170716/2111

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 16/07/2017 22:43		Vide Report No.:		Station Diary No.: 82	
Informant's Particulars					
Name of Informant: MOHAMED RAFFEE BIN SALLEH			Address: APT BLK 502A WOODLANDS DRIVE 14 #05-24 SINGAPORE 731502		
ID Type / ID No.: NRIC NO / S1675181B			Contact No.: Home/Office: Mobile: 90290731		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 52	Date of Birth: 02/08/1964	Type of Informant: Driver		
Race: Malay			Language: English		Institution / School Name:
Occupation: DESPATCH RIDER			Driving Licence Information: Class: 2B,2A,3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 16/07/2017 09:00	Type of Location: Straight Road
Location: Along Road 1 WEST COAST ROAD OPPOSITE VARSITY PARK				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGY8243Z	Car					0
SLN7912G	Car					0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20170716/2111

3 of 3

Police Station Of Origin:
Woodlands West N.P.C.
9 Marsiling Lane SINGAPORE 739146
Tel No: 1800-363 9999

Report No. T/20170716/2111

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

Staff Sgt LIN WUHUA

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

Staff Sgt TANG SIEW PING

Contact No.: 65476430

Signature Of Informant:

Date/Time:

16/07/2017 22:43

Classification Of Case:

Authentication Stamp


NP168



Signature :

Singapore Police Force

SN 127



MARCUS PHUAH & Co.
ADVOCATES & SOLICITORS

DATE: 18 July 2017

TO: AIG ASIA PACIFIC INSURANCE PTE. LTD
Attn: Motor Claims
AIG Building
78 Shenton Way #09-16
Singapore 079120
ATTN: MOTOR CLAIMS

VIA: EMAIL & FAX: 6835 7416

YOUR REFERENCE: SLN 7912 G

OUR REFERENCE: KNSM.MP.SGY8243Z. 20170716

Dear Sir / Madam

DATE OF ACCIDENT: 16 JULY 2017

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS
PURSUANT TO PARAGRAPH 2.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES**

We refer to your email dated 18.07.2017 informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirms the appointment of Marcus Chua, LKK Auto Consultants Pte Ltd as the Single Joint Expert for this matter. Please be informed that the said vehicle can be inspected at:

Venue: YI HENG MOTOR WORKSHOP, Blk 1, Kaki Bukit Ave 6.
#02-19, AUTOBAY BUILDING, S (417883)

Contact Person: TEL: 6509 0052 (MR. LOUIS GAN)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,

MARCUS PHUAH & CO.

MARCUS PHUAH & CO.

Copy to: clients (via email)

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor
(Name & Signature)

Date & Time of Inspection

潘国良律师事务所

Address: Income@Raffles Building, 16 Collyer Quay Level 20 Suite 27, Singapore 049318

Tel: (65) 6818 9111 | Skype: marcus_phuah

Reg. No.: 53211241E

Email: marcus@legasia.net | Website: <http://www.legasia.net>

Service of court documents by fax is not accepted

YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6
#02-19, SINGAPORE 417883
TEL: 6 5090052 FAX: 6 7479402

16751818

18-07-17

OUR REF NO. SGY 8243Z

R & N SERVICES

BLK 502A, WOODLANDS
DRIVE 14, #05-24
SINGAPORE 731502

TP AIG
Ai Phing

ESTIMATE BILL FOR VEHICLE NO. SGY 8243Z MODEL : TOYOTA AXIO

LIST ITEM

1) BONNET <i>Detached</i>		737.00 ✓
2) BONNET HINGE <i>new</i>	2 PCS @ \$ 141.00	282.00 +
3) BONNET RUBBER BEADING <i>new</i>		48.50 +
4) BONNET STOPPER <i>3 new</i>	4 PCS @ \$ 18.90	75.60 +
5) BONNET LOCK		77.00 +
6) BONNET GRILLE <i>3 new</i>		381.90 +
7) FRONT GRILLE STOPPER <i>new</i>	2 PCS @ \$ 18.90	37.80 +
8) FRONT GRILLE CLIP		12.90 +
9) HEAD LAMP (LH) <i>Cracked</i>		787.00 646.20
10) HEAD LAMP CLIP <i>new</i>	2 PCS @ \$ 10.50	21.00 -
11) FRONT BUMPER <i>Cracked</i>		1082.21 685.10
12) FRONT BUMPER CLIP <i>new</i>	8 PCS @ \$ 8.90	71.20 70
13) FRONT BUMPER SIDE ATTACHMENT <i>4+2 new</i>	2 PCS @ \$ 57.40	114.80 57.40
14) FRONT BUMPER REINFORCEMENT <i>Best</i>		458.00 329.50
15) FRONT BUMPER REINFORCEMENT BRACKET <i>new</i>	2 PCS @ \$ 58.20	116.40 *
16) FRONT BUMPER SPONGE <i>Cracked</i>		127.80 ✓
17) FRONT CHASSIS MEMBER (LH) <i>Ryri</i>		729.00 +
18) FRONT SUPPORT PANEL <i>Best</i>		1102.60 975.50
19) FRONT BRACE PANEL <i>new</i>		174.50 +
20) RADIATOR ASSY <i>new</i>		146.00 +

YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6
#02-19, SINGAPORE 417883
TEL: 6 5090052 FAX: 6 7479402

21) AIR - CON CONDENSOR	<i>new</i>	1134.00	+
22) RADIATOR TOP BRACKET	<i>new</i> 2 PCS @ \$ 31.00	62.00	+
23) BATTERY BRACKET	<i>sent</i>	71.40	✓
24) BATTERY TRAY	<i>new</i>	48.00	+
25) BATTERY PANEL	<i>new</i>	158.00	+
26) AIR DUCT HOSE W/TUBE	<i>new</i>	211.00	+
27) AIR DUCT HOSE CLIP	<i>new</i>	12.90	+
28) FRONT FENDER (LH)	<i>new</i>	587.00	✓
29) FRONT FENDER INNER COWLING (LH)	<i>new</i>	211.70	✓
30) FRONT FENDER INNER COWLING CLIP (LH)	<i>new</i> 10 PCS @ \$ 8.90	89.00	- 20
31) FRONT FENDER SIDE LAMP (LH)	<i>new</i>	67.00	+
32) FUSE BOX BASE	<i>new</i>	421.00	+
33) FUSE BOX BOTTOM COVER	<i>new</i>	141.00	+
34) FUSE BOX TOP CASING	<i>new</i>	118.00	+
35) FRONT WHEEL HOSING PANEL (LH)	<i>new</i>	687.50	+
36) FRONT FENDER ARCH GARNISH (LH)	<i>missing</i>	110.00	✓
37) FRONT FENDER SIDE RUBBER GARNISH (LH)	<i>new</i>	92.00	+
38) FRONT DOOR PILLER (LH)	<i>new</i>	384.00	+
39) FRONT DOOR (LH)	<i>new</i>	1014.00	+
40) FRONT DOOR STICKER (LH) VERTICAL	} <i>new</i>	89.00	+
41) FRONT DOOR STICKER (LH) HORIZONTAL		93.70	+
42) FRONT DOOR OUTER MOULDING		141.00	+
43) GEAR BOX SIDE COVER (LH)	<i>new</i>	171.00	+
44) FRONT SHOCK ABSORBER (LH)	<i>sent</i>	547.00	385
45) FRONT SHOCK TOP MOUNTING (LH)	<i>new</i>	182.70	+
46) FRONT SHOCK BUSH (LH)	<i>new</i>	87.00	+

YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6
#02-19, SINGAPORE 417883
TEL: 6 5090052 FAX: 6 7479402

47) FRONT KNUCKLE ARM (LH)	Best	488.50	✓
48) FRONT KNUCKLE BEARING (LH)	me	214.60	✓
49) FRONT KNUCKLE BEARING HUP (LH)	ang	287.00	✓
50) FRONT ANTI ROLL BAR LINK (LH)	Best	134.00	✓
51) FRONT ANTI ROLL BAR	me	271.00	✗
52) FRONT ANTI ROLL BAR BUSH	me 2 PCS @ \$ 27.00	54.00	✗
53) FRONT STEERING CROSS MEMBER	me	1574.00	✗
54) STEERING RACK ASSY	me	2089.00	✗
55) WINDSCREEN PILLER	me	287.00	+
56) WINDSCREEN MOULDING	me	132.00	+
57) FRONT LOWER BALL-JOINT (LH)	Best	211.00	✓
58) DRIVER SHAFT (LH)	me	1100.60	✗
		20356.81	
LESS DISCOUNT - 25%		5089.20	
		15267.61	

6329.70
A747.27

SPECIAL NETT ITEM

1) BATTERY ASSY	me	250.00	+
2) SPORT RIM (LH)	me	450.00	✓
3) FRONT WINDSCREEN INNERSEAL	me	60.00	+
4) FRONT WINDSCREEN GUM		60.00	+
		820.00	

LABOUR CHARGE

1) TOWING SERVICE		80.00	60
2) TO CHECK WIRING SYSTEM		120.00	30
3) TO APPLY UNDER SEALING ON AFFECTED AREAS		120.00	50
4) TO MOUNT VEHICLE ON CAR O LINER		380.00	+
5) TO CONDUCT 4 WHEEL ALIGNMENT		120.00	80
6) TO REMOVE AND REFIX ENGINE ASSY, BRACKET, WIRING, HARDNESS AND ETC		1200.00	+

YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6
#02-19, SINGAPORE 417883
TEL: 6 5090052 FAX: 6 7479402

- | | | |
|---|---------|------------------|
| 7) TO REMOVE AND REFIX GEAR BOX ASSY | 380.00 | x |
| 8) TO REMOVE AND REFIX FRONT UNDECERRIAGE ASSY | 480.00 | 2 250 |
| 9) TO REMOVE AND REFIX FRONT DOOR FIXING AND REALIGNMENT (LH) | 220.00 | x |
| 10) TO REMOVE AND REFIX CUSHION, FLOOR BOARD, ROOF LINNING, TRIM, GARNISH, UPHOLSTERY ETC | 220.00 | 60 |
| 11) TO REMOVE AND REFIX FRONT WINDSCREEN | 180.00 | 2550 x |
| 12) TO REPROGRAM ENGINE MANAGEMENT AND CODING, RESET AND PEFORM | 380.00 | x |
| 13) TO REPLACE NEW PARTS, CUT, WELD, KNOCK AND REALIGNMENT CHASSIS MEMBER | 2420.00 | 900 |
| 14) TO RESPRAY ON AFFECTED AREAS | 1980.00 | 1000 |
| 15) To remove and refix radiator and air con condenser and to top up air con gas. | | 8280.00 |
| | | 24367.61 |
| | 250 120 | 24617.61 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

L/s Adrian L
19/07/17
08 Days
total: 7747.27
L/s 62K
62K

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG17013913/AGBN2

Date: 06/12/2017

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999995090
 Claimant Vehicle No: SGY8243Z Insured Vehicle No: SLN7912G
 Date of Loss: 16/07/2017 Nature of Claim: TP Claim No: 4491672489SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGY8243Z
 Make & Model: TOYOTA AXIO, 1.5 (A) Engine No: 1N2C633062
 Reg. Date: 09/10/2007 (Man. Year: 2007) Chassis No: NZE1416038199
 Colour: Grey Odometer: 168729 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
 Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm
 Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	16,087.61	5,197.27	10,890.34	67.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,530.00	2,550.00	5,980.00	70.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	24,617.61	7,747.27	16,870.34	68.53
Approved Total (Overridden) (\$\$)		6,200.00		
Nett Amount (\$\$)	24,617.61	6,200.00	18,417.61	74.81

INSPECTION

Date of Assignment: 18/07/2017
 Date Inspected: 19/07/2017 Inspected At: Yi Heng Motor Workshop (HQ)
 Blk 1 Kaki Bt Ave 6 #02-19
 Singapore 417883

Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING

Manager: LOW AI PHING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	737.00 FL	*737.00 FL
2	2		*BONNET HINGE	Not Necessary	282.00 FL	*- FL
3	1		*BONNET RUBBER BEADING	Not Necessary	48.50 FL	*- FL
4	4		*BONNET STOPPER	Not Necessary	75.60 FL	*- FL
5	1		*BONNET LOCK	Not Necessary	77.00 FL	*- FL
6	1		*BONNET GRILLE	Not Necessary	381.90 FL	*- FL
7	2		*FRONT GRILLE STOPPER	Not Necessary	37.80 FL	*- FL
8	1		*FRONT GRILLE CLIP	Not Necessary	12.90 FL	*- FL
9	1		*HEAD LAMP (LH)	Cracked	787.00 FL	*646.20 FL
10	2		*HEAD LAMP CLIP	Necessary	21.00 FL	*21.00 FL
11	1		*FRONT BUMPER	Distorted	1,082.21 FL	*685.10 FL
12	8		*FRONT BUMPER CLIP	Necessary	71.20 FL	*30.00 FL
13	1		*FRONT BUMPER SIDE ATTACHMENT	N/s Damaged	114.80 FL	*57.40 FL
14	1		*FRONT BUMPER REINFORCEMENT	Bent	458.00 FL	*329.50 FL
15	2		*FRONT BUMPER REINFORCEMENT BRACKET	Not Necessary	116.40 FL	*- FL
16	1		*FRONT BUMPER SPONGE	Cracked	127.80 FL	*127.80 FL
17	1		*FRONT CHASSIS MEMBER (LH)	Repair	729.00 FL	*- FL
18	1		*FRONT SUPPORT PANEL	Bent	1,102.60 FL	*975.50 FL
19	1		*FRONT BRACE PANEL	Not Necessary	174.50 FL	*- FL
20	1		*RADIATOR ASSY	Not Necessary	146.00 FL	*- FL
21	1		*AIR-CON CONDENSOR	Not Necessary	1,134.00 FL	*- FL
22	2		*RADIATOR TOP BRACKET	Not Necessary	62.00 FL	*- FL
23	1		*BATTERY BRACKET	Bent	71.40 FL	*71.40 FL
24	1		*BATTERY TRAY	Not Necessary	48.00 FL	*- FL
25	1		*BATTERY PANEL	Not Necessary	158.00 FL	*- FL
26	1		*AIR DUCT HOSE W/TUBE	Not Necessary	211.00 FL	*- FL
27	1		*AIR DUCT HOSE CLIP	Not Necessary	12.90 FL	*- FL
28	1		*FRONT FENDER (LH)	Distorted	587.00 FL	*587.00 FL
29	1		*FRONT FENDER INNER COWLING (LH)	Deformed	211.70 FL	*211.70 FL
30	10		*FRONT FENDER INNER COWLING CLIP (LH)	Necessary	89.00 FL	*20.00 FL
31	1		*FRONT FENDER SIDE LAMP (LH)	Not Necessary	67.00 FL	*- FL
32	1		*FUSE BOX BASE	Not Necessary	421.00 FL	*- FL
33	1		*FUSE BOX BOTTOM COVER	Not Necessary	141.00 FL	*- FL
34	1		*FUSE BOX TOP CASING	Not Necessary	118.00 FL	*- FL
35	1		*FRONT WHEEL HOUSING PANEL (LH)	Repair	687.50 FL	*- FL
36	1		*FRONT FENDER ARCH GARNISH (LH)	Missing	110.00 FL	*110.00 FL
37	1		*FRONT FENDER SIDE RUBBER GARNISH (LH)	Not Necessary	92.00 FL	*- FL
38	1		*FRONT DOOR PILLER (LH)	Repair	384.00 FL	*- FL
39	1		*FRONT DOOR (LH)	Repair	1,014.00 FL	*- FL
40	1		*FRONT DOOR STICKER (LH) VERTICAL	Not Necessary	89.00 FL	*- FL
41	1		*FRONT DOOR STICKER (LH) HORIZONTAL	Not Necessary	93.70 FL	*- FL
42	1		*FRONT DOOR OUTER MOULDING	Not Necessary	141.00 FL	*- FL
43	1		*GEAR BOX SIDE COVER (LH)	Not Necessary	171.00 FL	*- FL
44	1		*FRONT SHOCK ABSORBER (LH)	Bent	547.00 FL	*385.00 FL
45	1		*FRONT SHOCK TOP MOUNTING (LH)	Not Necessary	182.70 FL	*- FL
46	1		*FRONT SHOCK BUSH (LH)	Not Necessary	87.00 FL	*- FL
47	1		*FRONT KNUCKLE ARM (LH)	Bent	488.50 FL	*488.50 FL
48	1		*FRONT KNUCKLE BEARING (LH)	Necessary	214.60 FL	*214.60 FL
49	1		*FRONT KNUCKLE BEARING HUP (LH)	Damaged	287.00 FL	*287.00 FL
50	1		*FRONT ANTI ROLL BAR LINK (LH)	Bent	134.00 FL	*134.00 FL
51	1		*FRONT ANTI ROLL BAR	Not Necessary	271.00 FL	*- FL
52	2		*FRONT ANTI ROLL BAR BUSH	Not Necessary	54.00 FL	*- FL
53	1		*FRONT STEERING CROSS MEMBER	Not Necessary	1,574.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*STEERING RACK ASSY	Not Necessary	2,089.00 FL	*- FL
55	1		*WINDSCREEN PILLER	Not Necessary	287.00 FL	*- FL
56	1		*WINDSCREEN MOULDING	Not Necessary	132.00 FL	*- FL
57	1		*FRONT LOWER BALL-JOINT (LH)	Bent	211.00 FL	*211.00 FL
58	1		*DRIVER SHAFT (LH)	Not Necessary	1,100.60 FL	*- FL
59	1		*BATTERY ASSY	Not Necessary	250.00 FS	*- FS
60	1		*SPORT RIM (LH)	Cut	450.00 FS	*450.00 FS
61	1		*FRONT WINDSCREEN INNERSEAL	Not Necessary	60.00 FS	*- FS
62	1		*FRONT WINDSCREEN GUM	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	21,176.81	6,779.70
- List Item Discount on L Items 25.00/25.00% (S\$)	5,089.20	1,582.43
Total Parts (S\$)	16,087.61	5,197.27

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING SERVICE	New	80.00	60.00
2	TO CHECK WIRING SYSTEM	New	120.00	30.00
3	TO APPLY UNDER SEALING ON AFFECTED AREAS	New	120.00	50.00
4	TO MOUNT VEHICLE ON CAR O LINER	New	380.00	-
5	TO CONDUCT 4 WHEEL ALIGNMENT	New	120.00	80.00
6	TO REMOVE AND REFIX ENGINE ASSY,BRACKET,WIRING,HARDNESS AND ETC	New	1,200.00	-
7	TO REMOVE AND REFIX GEAR BOX ASSY	New	380.00	-
8	TO REMOVE AND REFIX FRONT UNDERCARRIAGE ASSY	New	480.00	250.00
9	TO REMOVE AND REFIX FRONT DOOR FIXING AND REALIGNMENT (LH)	New	220.00	-
10	TO REMOVE AND REFIX CUSHION,FLOOR BOARD,ROOF LINING,TRIM,GARNISH,UPHOLSTERY ETC	New	220.00	60.00
11	TO REMOVE AND REFIX FRONT WINDSCREEN	New	180.00	-
12	TO REPROGRAM ENGINE MANAGEMENT AND CODING,RESET AND PEFORM	New	380.00	-
13	TO REPLACE NEW PARTS,CUT,WELD,KNOCK AND REALIGNMENT CHASSIS MEMBER	New	2,420.00	900.00
14	TO RESPRAY ON AFFECTED AREAS	New	1,980.00	1,000.00
15	TO REMOVE AND REFIX RADIATOR ABD AIR CON CONDENSER AND TO TOP UP AIR CON GAS	New	250.00	120.00
Gross Labour Cost (S\$)			8,530.00	2,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >