

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit Autohub
2 Kaki Bukit Ave 2, #01-17
Singapore 417921
Tel No. : +65 6744 0510 / 6842 0051 Fax No. : +65 6741 0510
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

Our Ref: **SGF 7012 E**
Your ref: **SJH 5885 U**

19 July 2017

AIG ASIA PACIFIC INSURANCE PTE. LTD. BY EMAIL Imran.Ishak@aig.com ONLY
NO: 78 SHENTON WAY
#07-16 CHARTIS BUILDING
SINGAPORE 079120
Attn: Motor Claims Department

Dear Sir/Madam,

NAME OF CLAIMANT : KUNG WAI QUEN
VEHICLE NUMBER : SGF 7012 E
YOUR INSURED VEHICLE NUMBER : SJH 5885 U
ACCIDENT ON 18 July 2017 ALONG DUNEARN ROAD TOWARDS WAYANG SATU FLYOVER
AT ABOUT 09:45 HOURS

We refer to your email / fax dated 19 July 2017 informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of **ADRIAN LING** of **LKK AUTO CONSULTANTS PTE LTD** as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

TWINCAR AUTOMOTIVE PTE LTD
Kaki Bukit Autohub
2 Kaki Bukit Avenue 2
#01-17
Singapore 417921
6842 0051 / 6744 0510 (Melody)

Contact Person:

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,



Twincar Automotive Pte Ltd

FOR SURVEYOR:

Please initial here after completion of pre-repair inspection. Thank you!

Appointed surveyor :

(Name & Signature) :

Date & Time of Inspection: