

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



## FINAL REPORT

Estimate No. : **b1 43488**  
Date Estimated : **20/07/2017**  
Prepared By : **Inthiran A/L Thurasamy**

Page No. :

**REPAIR FOR -**  
**Michelle Anne Ng Chai Ping**  
**159 Hougang Street 11**  
**#10-25**

**- ACCOUNT - 303**  
**First Capital Insurance Ltd**  
**36 Robinson Road**  
**#16-01 City House**  
**Singapore 068877**

**singapore 530159**

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SKR6201Y	VZ50665	26/02/2015	218iA AT	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments, boot lid and attachments include making good the tail end panel and knocking out dents caused by the accident	2550.00		2,550.00	
To spray paint rear bumper, boot lid and tail end panel	2399.00		2,399.00	
To remove and install boot compartment carpet and garnish to facilitate repairs	230.00		230.00	
To remove and install rear windscreen glass to facilitate repairs include conducting water leak tests.	649.00		649.00	
To reconnect electrical components and wirings at the rear section including conduct checks for proper function.	150.00		150.00	
To transfer lock mechanism from old to new boot lid including conduct checks on new boot lid central locking system for proper function.	451.00		451.00	
To remove and install boot lid smart opener assembly to facilitate repairs include programming and conducting checks for proper function	561.00		561.00	
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150.00		150.00	
To carry out body cavity preservation. (Per panel).	100.00		100.00	
Sundries.	150.00		150.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
BLIND RIVET NUT M6	2.60	3.00		7.80
TRUNK LID	1,146.30	1.00		1,146.30
REAR BUMPER PANEL PRIMED (PDC)	942.75	1.00		942.75
# EXPANDING NUT *	1.00	2.00		2.00

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## SUPPLEMENTARY

Estimate No. : b1 43488  
Date Estimated : 20/07/2017  
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -  
Michelle Anne Ng Chai Ping  
159 Hougang Street 11  
#10-25

singapore 530159

- ACCOUNT - 303  
First Capital Insurance Ltd  
36 Robinson Road  
#16-01 City House  
Singapore 068877

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SKR6201Y	VZ50665	26/02/2015	218iA AT	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING NUT *	1.00	2.00		2.00
# REAR BUMPER HEAT INSULATOR *	57.70	1.00		57.70

3(A) new  
PA

Total Labour :	0.00
Total Parts :	59.70
Total Labour & Parts :	59.70