

22/03/2017

ASS. REC. BY:

REF:

CS/CTU70111148/Rev 22

Special Instruction:

KIV for finalised.

Surveyor: Rasul

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

GIL

Date/Time: 21072017 1216pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKU 2923H

Insured:

GT 1374B

at Workshop m/s

Motor Image

Tel:

6703 8164

of

25 Leng Kee Road

Policy No:

DMEVSN303881700

Claim No:

94m17000405702

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

08072017

CA / REV / REP. / REV 24 HRS w/p

25-07-2017 @ 10am - 12pm

H.O.D. Endorsement:

Date/Time:

21072017 123pm

Person Contacted:

Dennis

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SKU 2923H - x

GT 1374B - GT / ALG10803446 / Ray

Dis: 23082008


ASSIGNMENT

From: _____ Date: 25/07/2017
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SKU 2923H
 at Workshop m/s Motor Image
 of 25 Leng Kee Road
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

10am - 12pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKU 2923H Yr Regn: 2015 / July
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: Subaru Forester 2.0 XT c.c 1998
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp.Reading: 029433 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: JFISJGKBSF0053167

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size: F: 235/55R18
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MID / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 03/07/17 D.O.I. 28/07/17

Survey held at Motor Image

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

20/2/2017 Part by Part \$6252.84 (\$890, 12%)

20/2/2017 File pass to typist

20/2/2017

RECEIVED 2310

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 7

Resurvey No. of Trip: _____

Survey Fee: 150

Transportation: _____

____ S + RS. ____ \$

) Photos

) Others

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

TOTAL

150

Report Format :

Lump Sum / I.B.I: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI17014148/R1gb		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 21-07-2017		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GT 1374B	Veh. Inspected	SKU 2923H	
Policy No.	DMCVSN3022881700	Coverage (\$)	0.00	
Claim No.	SNM17D04057C02	Excess (\$)	0.00	
Assign From	MERIMEN (IRENE TAY)	Assign Date	21/07/2017	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	08/07/2017	Inspection Date	25/07/2017	
Survey held at	25 LENG KEE ROAD			
Repairer	MOTOR IMAGE ENTERPRISES PTE LTD			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Survey Department Check List (Case Handler)

Reference No.: CS/CTI1701448/R1nb
Policy Type: OD / (TP) / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

C Reference No.
C Customer Code
N Assign From
C Assign Date
C Veh No (Inspected)
C Veh No (Insured)
C D.O.A
C Policy No
C Claim No
C Insurance Authorisation (CA /REV/REP)
C Report Type
C Weekend Charges
N Survey held at/Repairer
C Excess

Y-Date	N-Date	Y-Date	N-Date
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C Vehicle No
C Regn Month/Year
N Vehicle Type
N Make & Model
C Engine Capacity. (C.C)
N Colour
C Odometer. (Sp.Reading)
C Chassis No
N General Condition
N Steering
N Brake
N Modification (Modi)
C Tyre Size
N Tyre Make
C Tyre Balance
C Date of Inspection
N Survey held
N Des.of Damages

/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			

(2) System - (Views/Merimen)

C Damaged Vehicle Photographs Uploaded

--	--	--	--

(3) Workshop Estimate/Assignment Form

N ALL Parts condition
C Market Value for OD cases
C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
C Days of repair
C Finalised Amount
C Re-inspection Cases to Finalize within 5 Days

(4) System - (Views/Merimen)

C Resurvey photo Uploaded

--	--	--	--

Check By:

Rfa

20/2/18

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/201

Rasul (LKKAuto)

From: Rasul (LKKAuto)
Sent: Monday, 19 February, 2018 9:10 AM
To: 'Dennis Leong'
Subject: RE: finalize for SKU2923H

Hi Dennis,

Finalised amount at \$ 6,690.54 / 6 days after GST confirmed

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK Auto Consultants *Save the Earth. Print only when necessary.*

From: Dennis Leong [<mailto:dennisleong@motorimage.net>]
Sent: Tuesday, 31 October, 2017 2:20 PM
To: Rasul (LKKAuto)
Subject: finalize for SKU2923H

Hi Rasul,

Can I do the finalize with you,
Kindly refer to attachment as finalize \$6690.54 on 6 working days.

Best Regards,

Dennis Leong

Service Advisor
Motor Image Enterprises Pte Ltd
25 Leng Kee Road
Singapore 159097
DID:(65)6703 8161
FAX:(65)6479 1137
Email:dennisleong@motorimage.net



The all-new Subaru XV

GO FOR BOLD



JUMP ON IT



Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the addressee you may not copy, forward, disclose or use any part of this message. If you have received this message in error, please delete it and all copies from your system and notify the sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, secure, error-free or virus-free. The sender does not accept liability for any errors or omissions.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Jul 2017		21 Jul 2017 12:16 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:									
Main Claimant:	TAN JOO KEE, ID: S1113940Z								
Vehicle Reg. No.:	SKU2923H	Date of Loss:	08/07/2017 11:00 - :59						
Claim Type:	TP / SNM17D04057C02	Policy/Cover Note No.:	DMCVSN3022881700						
Vehicle Reg. No. (Insured):	GT1374B	Policy No. (Claimant):	2100421316-01000						
		Excess:	S\$0.00						
Repairer:	Motor Image Enterprises Pte Ltd (Leng Kee) 25 Leng Kee Road, 159097 Leng Kee - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 01/08/2017]								
Adj Asg. Remarks:	PLEASE ASSIST TO CONDUCT PRS AND REVERT WITH YOUR RECOMMENDATION								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All	Search Tasks	Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/LHI/031/2017
DATE : 12-JUL-2017

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
S(079120)
TEL :
FAX :

OWNER'S NAME : TAN JOO KEE (96382334 MR TAN) [5YRS/100K SVC]
ADDRESS : 12 ENG KONG GARDEN

S(599229)
TELEPHONE NO : 9752 2189

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100421316-01000
VEHICLE NO : SKU2923H
MODEL CODE : SJGCKKB
MODEL/YEAR : FORESTER 2.0XT AWD CVT
ENGINE NO : FA20K870729
CHASSIS NO : JF1SJGK85FG053107
MILEAGE : 1 KM
DATE IN : 12/07/2017
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DENNIS LEONG JIA HUI
ACCIDENT DATE : 08/07/2017

Print Date : 25/07/2017
Print Time : 12:44:57

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKU2923H

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	REPLACE REAR RHS FENDER, REAR BUMPER ASSY & BRACKET, SPORT RIM REAR RHS	3480.00	3480 2800 //
2	ZZ/002	RESPRAY REAR RHS FENDER, REAR BUMPER ASSY AND REAR RHS DOOR	1320.00	920 //
3	ZZ/003	TRANSFER/BALANCE TYRE/RIM REAR RHS	80.00	// //
4	ZZ/004	TO CONDUCT WATER SEEPAGE TEST	60.00	// //
5	ZZ/005	REMOVE & INSTALL RHS QUARTER GLASS	220.00	// //
6	ZZ/006	TO SUPPLY AND INSTALL RHS REAR QUARTER GLASS SOLAR FILM	55.00	// //
7	ZZ/007	SUNDRIES	100.00	50 //
TOTAL LABOUR CHARGES			5315.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097,

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKU2923H

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
1	PNL SD OUT QTR RPRH NEED 909400005/65475SG020	51439SG0019P	/ 864.00	pt /
2	BUMPER FACE R	57704SG012	/ 540.00	scr / - Genetla radiation murt take
3	REAR BUMPER BRACKET - RHS	57707SG080	/ 14.40	na /
4	BRKT SD R LH	57707SG090	/ 14.40	na /
5	WDW GL ASSY R QTR RH	65209SG041	/ 324.00	scr /
6	DAM RUBBER R WIND	65245SC000	/ 21.60	na /
7	DAM RUBBER 1/4 GL RH/LH	65245SG000	/ 14.40	na /
8	LENS & BODY COMPLRFR SEE 84912SG020	84912SG021	/ 388.80	scr /
9	TAPE DR SASH R F RH	90422SG060	/ 18.00	scr /
10	TAPE DR SASH R M RH	90422SG080	/ 10.80	scr /
11	TAPE DR SASH R R RH	90422SG100	/ 14.40	scr /
12	CLIP BMPR	909140007	/ 60.00	na /
SUB TOTAL			2284.80	0.00 0.00
LESS DISCOUNT (NETT-20 %)			456.96	0.00 0.00
GRAND TOTAL			1827.84	0.00 0.00
OVERALL TOTAL			1827.84	

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SKU2923H

TOTAL LABOUR CHARGES	5315.00	7322.84
TOTAL SPARE PARTS CHARGES	1827.84	
GRAND TOTAL	7142.84 *	

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE :
LIABILITY :
REMARKS :

Rasul / Hp 90010068
25/07/17 @ 1220
7 days

Resurvey 64 part

6 days

26/7/17

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/LHI/031/2017
DATE : 12-JUL-2017

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
S(079120)
TEL :
FAX :

OWNER'S NAME : TAN JOO KEE (96382334 MR TAN) [5YRS/100K SVC]
ADDRESS : 12 ENG KONG GARDEN

S(599229)
TELEPHONE NO : 9752 2189

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100421316-01000
VEHICLE NO : SKU2923H
MODEL CODE : SJGCKKB
MODEL/YEAR : FORESTER 2.0XT AWD CVT
ENGINE NO : FA20KB70729
CHASSIS NO : JF1SJGK85FG053107
MILEAGE : 1 KM
DATE IN : 12/07/2017
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DENNIS LEONG JIA HUI
ACCIDENT DATE : 08/07/2017

Print Date : 31/10/2017
Print Time : 14:14:48

MOTORIMAGE ENTERPRISES PTE. LTD.

25, LENG KEE ROAD

SINGAPORE 159097

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKU2923H

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ANTI	TO CONDUCT ANTI-RUST PROTECTION FOR UNDERCARRIAGE WITH ANTI RUST COATING (SUPP)	60.00	60.00 (A)
2	UNDERPANEL	TO CONDUCT PANEL PROTECTION FOR UNDERCARRIAGE (SUPP)	60.00	60.00 (A)
3	ZZ/001	REPLACE REAR RHS FENDER, REAR BUMPER ASSY & BRACKET, SPORT RIM REAR RHS	3480.00	2800.00 ✓
4	ZZ/002	RESPRAY REAR RHS FENDER, REAR BUMPER ASSY AND REAR RHS DOOR	1320.00	920.00 ✓
5	ZZ/003	TRANSFER/BALANCE TYRE/RIM REAR RHS	80.00	80.00 ✓
6	ZZ/004	TO CONDUCT WATER SEEPAGE TEST	60.00	60.00 ✓
7	ZZ/005	REMOVE & INSTALL RHS QUARTER GLASS	220.00	220.00 ✓
8	ZZ/006	TO SUPPLY AND INSTALL RHS REAR QUARTER GLASS SOLAR FILM	55.00	55.00 ✓
9	ZZ/007	SUNDRIES	100.00	50.00 ✓
10	ZZ/008	ADDITIONAL JOB		
11	ZZ/009	-REMOVE & REFIX REAR MUDGUARD TRIM -REMOVE & REFIX REAR SEAT <i>suppl</i>	120.00	120.00 (A)
TOTAL LABOUR CHARGES			5555.00	4425.00

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKU2923H

S/NO PARTS DESCRIPTION		PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	PNL SD OUT QTR RPRH NEED 909400005/65475SG020	51439SG0019P	864.00			OK
2	BUMPER FACE R	57704SG012	540.00			OK
3	REAR BUMPER BRACKET - RHS	57707SG080	14.40			OK
4	BRKT SD R LH	57707SG090	14.40			OK
5	WDW GL ASSY R QTR RH	65209SG041	324.00			OK
6	DAM RUBBER R WIND	65245SC000	21.60			OK
7	DAM RUBBER 1/4 GL RH/LH	65245SG000	14.40			OK
8	LENS & BODY COMPLRFR SEE 84912SG020	84912SG021	388.80			OK
9	TAPE DR SASH R F RH	90422SG060	18.00			OK
10	TAPE DR SASH R M RH	90422SG080	10.80			OK
11	TAPE DR SASH R R RH	90422SG100	14.40			OK
12	CLIP BMPR	909140007	60.00			OK
SUB TOTAL			2284.80	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)			456.96	0.00	0.00	0.00
GRAND TOTAL			1827.84	0.00	0.00	0.00
OVERALL TOTAL			1827.84			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SKU2923H

NETT ITEM 2284.80
LESS 20 % -456.96
NETT AMOUNT 1827.84

LIST ITEM 0.00
LESS 50 % 0.00
LIST AMOUNT 0.00





SPECIAL NETT AMOUNT 0.00

S/LIST ITEM 0.00
LESS 30 % 0.00
S/LIST AMOUNT 0.00

TOTAL LABOUR CHARGES 4425.00
TOTAL SPARE PARTS CHARGES 1827.84

TOTAL CHARGES 6252.84 ✓
ADD 7 % GST 437.70

GRAND TOTAL 6690.54



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/07/2017 15:01
Date Of Accident	08/07/2017 11:45
Exact Location Of Accident	JUNCTION JLN JURONG KECHIL / JLN ANAK BUKIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKU2923H
Insured/Policyholder	
Name Of Registered Owner	TAN JOO KEE
NRIC No	S1113940Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96399746
Alternative Phone No	OTHERS-96399746

Vehicle Particulars

Manufacturer	SUBARU
Model	FORESTER-2.0 XT (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100421316-01000
Cover Note Number	

Driver

Name of Driver	TAN JOO KEE
NRIC No	S1113940Z
Date Of Birth	18/03/1955
Occupation	OUTDOOR
Date Of Driving Pass	13/08/1977
Driving Experience	39 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96399746
Fax Number	
Contact Number	OTHERS-96399746
EMail Address	NOEMAIL

Singapore Accident Statement

Accident Date & Time: 8/7/2017 11:45am	
Accident Location: Junction Jln Jurong Kochi / JLN ANAK BUKIT	
Vehicle Number: SKU 2923H	Make/Model: SUBARU FORESTER
Policyholder Name: TAN JOO KEE	
NRIC: S111394012	Mobile: 96399746
Email:	
Insurance Company:	
Policy Number: 2100421316-01000	Cover Note:
Policy Coverage: Comprehensive(✓)	Third Party() Third Party Fire & Theft()
State Action Taken: Claim Own Policy()	Claim Third Party(✓) Reporting Only()
Driver Name: TAN JOO KEE	
NRIC: S111394012	Mobile: 96399746
Date Of Birth: 18/3/1955	Driving Pass Date: 13/8/1977
Gender: Male(✓) Female()	Occupation: Indoor() Outdoor(✓)
Address: 81, TOH YI DRIVE SPORE 596544	
Is driver an employee of the Insured's Company: Yes() No(✓)	
If No, Relationship of the Driver with the Insured:	
Owner(✓) Spouse() Friend() Relative() Children() Sibling()	
Weather Conditions: Clear(✓) Raining() Others()	
Road Surface: Dry(✓) Wet() Others()	
Was any foreign vehicle involved in this accident? Yes(✓) No()	
Was any body injured in the Accident? Yes() No(✓)	
Was there any video captured by Car Camera? Yes(✓) No()	
Number of Passengers (Including Driver): 2	
Was the accident reported to the police? Yes() No(✓) Attach Police Report, if any	
3 rd Party Name:	
Vehicle Number: GT 1374B	Make & Model:
NRIC:	Mobile:
Witness Details (if any):	
Other Details (if any): Refer to sketch plan	


Sketch Plan Pg. 3

Describe Circumstances of the Accident

I WAS going to Dunearn Rd from my house at 81 Tully Drive at about 11:40am on 9/7/2017 along Jln Jurong Kechil stopping at the Traffic light Junction with my vehicle SKU 2923H stopping at 2nd lane from the left. My lane allowed me to either go straight to slip road leading to PIE in direction of Changi Airport or turn right to Dunearn Road which was my destination vehicle GT 1374B was at my right side at the Traffic light Junction which only allow the vehicle to Turn right Only When the Traffic light turned green with the green Arrow to turn right I move forward and started to Turn right Keeping to my lane on the left lane into Jln Anak Bukit which is 3 lanes and as I was turning vehicle GT 1374B drove and crashed into my left hand back of my vehicle Right


Declaration

We declare the foregoing particulars are true in every respect.

 10/7/2017

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Jul 2017		21 Jul 2017 12:16 Edit Adj Rpt	S\$6,252.84 Edit Estimates	S\$6,252.84 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]
Insured:	-, Co. Reg. No.: -			
Main Claimant:	TAN JOO KEE, ID: S1113940Z			
Vehicle Reg. No.:	SKU2923H	Date of Loss:	08/07/2017 11:00 - :59	
Claim Type:	TP / SNM17D04057C02	Policy/Cover Note No.:	DMCVSN3022881700	
Vehicle Reg. No. (Insured):	GT1374B	Policy No. (Claimant):	2100421316-01000	
		Excess:	S\$0.00	
Repairer:	Motor Image Enterprises Pte Ltd (Leng Kee) 25 Leng Kee Road, 159097 Leng Kee - Tel:			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]			
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 01/08/2017]			
Adj Asg. Remarks:	PLEASE ASSIST TO CONDUCT PRS AND REVERT WITH YOUR RECOMMENDATION			

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS ☐										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

***SKU2923H (SNM17D04057C02)**
[GT1374B]

TP

TAN JOO KEE

Jul 8 2017 11:00AM

[-]

Motor Image Enterprises Pte Ltd

[Upload Documents](#) | [Upload Photos](#) | [Compose New Letter](#)

View [View in Browser](#) ▼

Assessment Reports			1 per page ▼	☒
No	Finalized On	Motor Image Enterprises Pte Ltd (Leng Kee)	Thumbnail	Print
1	10/07/17 15:31	Accident Statement	 Load HTM	
Photos/Images			3 per page ▼	☒
No	Finalized On	Motor Image Enterprises Pte Ltd (Leng Kee)	Thumbnail	Print
1	10/07/17 15:10	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
2	10/07/17 15:10	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
3	10/07/17 15:10	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
4	10/07/17 15:10	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
5	10/07/17 15:10	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
6	10/07/17 15:10	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
7	10/07/17 15:10	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
8	10/07/17 15:10	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
9	10/07/17 15:10	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
10	10/07/17 15:10	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
11	10/07/17 15:10	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
12	10/07/17 15:10	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
13	10/07/17 15:10	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
14	10/07/17 15:10	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
15	10/07/17 15:10	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
16	10/07/17 15:10	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
17	10/07/17 15:10	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
18	10/07/17 15:10	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
19	10/07/17 15:10	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
20	10/07/17 15:10	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
21	10/07/17 15:10	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
22	10/07/17 15:10	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/07/17 10:52	General View	Load JPG	

			1		☒
2	26/07/17 10:52	General View	1	Load JPG	☒
3	26/07/17 10:52	General View	1	Load JPG	☒
4	26/07/17 10:52	General View	1	Load JPG	☒
5	26/07/17 10:52	General View	1	Load JPG	☒
6	26/07/17 10:52	General View	1	Load JPG	☒
7	26/07/17 10:52	General View	1	Load JPG	☒
8	26/07/17 10:52	General View	1	Load JPG	☒
9	26/07/17 10:52	General View	1	Load JPG	☒
10	26/07/17 10:52	General View	1	Load JPG	☒
11	26/07/17 10:52	General View	1	Load JPG	☒
12	26/07/17 10:52	General View	1	Load JPG	☒
13	26/07/17 10:52	General View	1	Load JPG	☒
14	26/07/17 10:52	General View	1	Load JPG	☒
15	26/07/17 10:52	General View	1	Load JPG	☒
16	26/07/17 10:52	General View	1	Load JPG	☒
17	26/07/17 10:52	General View	1	Load JPG	☒
18	26/07/17 10:52	General View	1	Load JPG	☒
19	26/07/17 10:52	General View	1	Load JPG	☒
20	26/07/17 10:52	General View	1	Load JPG	☒
21	26/07/17 10:52	General View	1	Load JPG	☒
22	26/07/17 10:52	General View	1	Load JPG	☒
23	26/07/17 10:52	General View	1	Load JPG	☒
24	26/07/17 10:52	General View	1	Load JPG	☒
25	26/07/17 10:52	General View	1	Load JPG	☒
26	26/07/17 10:52	General View	1	Load JPG	☒
27	26/07/17 10:52	General View	1	Load JPG	☒
28	26/07/17 10:52	General View	1	Load JPG	☒
29	26/07/17 10:52	General View	1	Load JPG	☒
30	26/07/17 10:52	General View	1	Load JPG	☒
31	26/07/17 10:52	General View	1	Load JPG	☒
32	26/07/17 10:52	General View	1	Load JPG	☒
33	26/07/17 10:52	General View	1	Load JPG	☒
34	26/07/17 10:52	General View	1	Load JPG	☒
35	26/07/17 10:52	General View	1	Load JPG	☒
36	26/07/17 10:52	General View	1	Load JPG	☒
37	26/07/17 10:52	General View	1	Load JPG	☒
38	26/07/17 10:52	General View	1	Load JPG	☒
39	26/07/17 10:52	General View	1	Load JPG	☒
40	26/07/17 10:52	General View	1	Load JPG	☒
41	26/07/17 10:52	General View	1	Load JPG	☒
Documentation			1 per page ▼	☒	
No	Finalized On	Motor Image Enterprises Pte Ltd (Leng Kee)		Thumbnail	Print
1	10/07/17 15:10	Sketch Plan [Linked Accident Report Documents]	1	Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	21/02/18 11:20	Supplementary	1	Load PDF	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT117014148/R1NBE2

Date: 21/02/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3022881700
Claimant Vehicle No :	SKU2923H	Insured Vehicle No :	GT1374B
Date of Loss:	08/07/2017	Nature of Claim:	TP
		Claim No:	SNM17D04057C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU2923H	Engine No:	FA20K870729
Make & Model:	SUBARU FORESTER, 2.0 XT (A)	Chassis No:	JF1SJGK85FG053107
Reg. Date:	16/07/2015 (Man. Year: 2015)	Odometer:	29433 km
Colour:	Blue		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,927.84	1,877.84	50.00	2.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,455.00	4,375.00	1,080.00	19.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,382.84	6,252.84	1,130.00	15.31
+ GST 7.00/7.00% (S\$)	516.80	437.70	79.10	15.31
Nett Amount (S\$)	7,899.64	6,690.54	1,209.10	15.31

INSPECTION

Date of Assignment:	21/07/2017		
Date Inspected:	25/07/2017	Inspected At:	Motor Image Enterprises Pte Ltd (Leng Kee) 25 Leng Kee Road Singapore 159097
Estimated Period of Repair:	7.0 days		

Adjuster: MOHD RASUL

Manager: LOW AI PHING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Feb 2018)

Parts: M1-SUV SUBARU FORESTER 2.0 XT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKU2923H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
2	1		*PNL SD OUT QTR RPRH NEED 909400005/65475SG020	Bent	864.00 FN	*864.00 FN
3	1		*BUMPER FACE R	Scratched	540.00 FN	*540.00 FN
4	1		*REAR BUMPER BRACKET - RHS	Necessary	14.40 FN	*14.40 FN
5	1		*BRKT SD R LH	Necessary	14.40 FN	*14.40 FN
6	1		*WDW GL ASSY R QTR RH	Scratched	324.00 FN	*324.00 FN
7	1		*DAM RUBBER R WIND	Necessary	21.60 FN	*21.60 FN
8	1		*DAM RUBBER 1/4 GL RH / LH	Necessary	14.40 FN	*14.40 FN
9	1		*LENS & BODY COMPLRFR	Scratched	388.80 FN	*388.80 FN
10	1		*TAPE DR SASH R F RH	Scratched	18.00 FN	*18.00 FN
11	1		*TAPE DR SASH R M RH	Scratched	10.80 FN	*10.80 FN
12	1		*TAPE DR SASH R R RH	Scratched	14.40 FN	*14.40 FN
13	1		*CLIP BMPR	Necessary	60.00 FN	*60.00 FN

F=Franchise part, S=SpcNett, N=NettItemDisc.

Sub Total (\$)	2,384.80	2,334.80
- Nett Item Discount on N Items 20.00/20.00% (\$)	456.96	456.96
Total Parts (\$)	1,927.84	1,877.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE REAR RHS FENDER, REAR BUMPER ASSY & BRACKET, SPORT RIM REAR RHS	New	3,480.00	2,800.00
2	RESPRAY REAR RHS FENDER, REAR BUMPER ASSY AND REAR RHS DOOR	New	1,320.00	920.00
3	TRANSFER / BALANCE TYRE / RIM REAR RHS	New	80.00	80.00
4	TO CONDUCT WATER SEEPAGE TEST	New	60.00	60.00
5	REMOVE & INSTALL RHS QUARTER GLASS	New	220.00	220.00
6	TO SUPPLY AND INSTALL RHS REAR QUARTER GLASS SOLAR FILM	New	55.00	55.00
7	TO CONDUCT ANTI-RUST PROTECTION FOR UNDERCARRIAGE WITH ANTI RUST COATING	New	60.00	60.00
8	TO CONDUCT PANEL PROTECTION FOR UNDERCARRIAGE	New	60.00	60.00
9	-REMOVE & REFIX REAR MUDGUARD TRIM.-REMOVE & REFIX REAR SEAT	New	120.00	120.00
Gross Labour Cost (\$\$)			5,455.00	4,375.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >